

March 7, 2014

Product withdrawal RF transformers

To streamline the product range the following EPCOS RF transformers are being withdrawn without substitute types.

Affected products

Ordering code	Ordering code
B78408A1072A003	B78408A1841A003
B78408A1074A003	B78408A1842A003
B78408A1140A003	B78408A1897A003
B78408A1141A003	B78408A1898A003
B78408A1182A003	B78408A1899A003
B78408A1186A003	B78408A1900A003
B78408A1201A003	B78408A1901A003
B78408A1202A003	B78408A1902A003
B78408A1227A003	B78408A1950A003
B78408A1243A003	B78408A2075A003
B78408A1399A003	B78408A2094A003
B78408A1414A003	B78408A2095A003
B78408A1441A003	B78408A2096A003
B78408A1507A003	B78408A2097A003
B78408A1619A003	B78408B1218A003
B78408A1627A003	B78408B1382A003
B78408A1631A003	B78408B1405A003
B78408A1691A003	B78408E1075A003
B78408A1710A003	

Deadline for last orders: December 31, 2014
Last shipments by: March 31, 2015

Contact Gerhard Niedermeier, MAG TF T PMD, Munich

Customers are asked to address inquiries directly to their sales contacts.

EPCOS AG · A Member of TDK-EPC Corporation

Office: St.-Martin-Strasse 53, 81669 Munich · Post: P.O.Box 80 17 09, 81617 Munich, Germany

Headquarters: Munich · Commercial register of the local court (Amtsgericht): Munich HRB 127250

Chairman of the Supervisory Board: Dr. Werner Faber

Management Board: Joachim Zichlarz, Speaker · Joachim Thiele · Dr. Norbert Hess · Christian Block

www.epcos.com

Inductors

Internal / External

140307IN1e