u·p·t·o·d·a·t·e Newsletter 🐼 DK

September 15, 2017

PTN Withdrawal of EPCOS double-aperture transformers

To streamline the portfolio, the EPCOS double-aperture transformers listed below are being withdrawn without substitute types.

Affected products

| Ordering code | Ordering code |
|-----------------|-----------------|
| B78408A1185A003 | B78408A1681A003 |
| B78408A1208A003 | B78408A1682A003 |
| B78408A1226A003 | B78408A1683A003 |
| B78408A1231A003 | B78408A1723A003 |
| B78408A1246A003 | B78408A1734A003 |
| B78408A1444A003 | B78408A1794A003 |
| B78408A1630A003 | B78408A1798A003 |
| B78408A1679A003 | B78408C1383A003 |
| B78408A1680A003 | |

In the past years several types of double-aperture transformers have already been discontinued. This PTN affects all remaining B78408* EPCOS double-aperture transformers.

| Deadline for last orders: | June 30, 2018 |
|---------------------------|--------------------|
| Last shipments by: | September 30, 2018 |

Contact Gerhard Niedermeier, MAG TF T PM, Munich

Customers are asked to address inquiries directly to their sales contacts.