

Series	Row	Previous Contacts per row	New Contacts per row	Obsolete	See detail on sheet:
M20-782XXXX	SIL	From 02 to 40	From 02 to 20, 25, 32, 36	21 to 24, 26 to 31, 33 to 35, 37 to 40	Female
M20-783XXXX	DIL	From 02 to 40	From 02 to 20, 25, 32, 36	21 to 24, 26 to 31, 33 to 35, 37 to 40	Female
M20-785XXXX	DIL	From 02 to 40	From 02 to 20, 30	21 to 29, 31 to 40	Female
M20-786XXXX	SIL	From 02 to 40	From 02 to 20	21 to 40	Female
M20-786XXXXP	SIL	From 02 to 40	None	02 to 40	Female
M20-787XXXX	DIL	From 02 to 40	From 02 to 20	21 to 40	Female
M20-787XXXXP	DIL	From 02 to 40	From 02 to 20	21 to 40	Female
M20-788XXXX	DIL	From 02 to 40	From 02 to 20, 25, 35, 36	21 to 24, 26 to 34, 37 to 40	Female
M20-789XXXX	SIL	From 02 to 40	From 02 to 20, 25, 36, 40	21 to 24, 26 to 35, 37 to 39	Female
M20-876XXXX	DIL	From 02 to 36	From 02 to 20, 25, 36	21 to 24, 26 to 35	Male
M20-876XXXXP	DIL	From 02 to 36	From 02 to 20, 23	21, 22, 24 to 36	Male
M20-877XXXX	SIL	From 02 to 36	From 02 to 20, 25, 36	21 to 24, 26 to 35	Male
M20-877XXXXP	SIL	From 02 to 36	From 02 to 20	21 to 36	Male
M20-877XXXXR	SIL	02, 03, 04, 06, 08, 10, 15, 19, 28	02, 03, 04, 06, 08, 10, 15, 19	28	Male
M20-890XXXX	SIL	From 03 to 25	From 03 to 20	21 to 25	Male
M20-891XXXX	DIL	From 02 to 36	From 02 to 20	21 to 36	Male
M20-970XXXX	DIL	From 02 to 40	From 02 to 20, 22, 25, 27, 36, 40	21, 23, 24, 26, 28 to 35, 37 to 39	Male
M20-971XXXX	SIL	From 02 to 40	From 02 to 20, 22, 23, 26, 36, 40	21, 24, 25, 27 to 35, 37 to 39	Male
M20-972XXXX	DIL	From 02 to 40	From 02 to 20, 24, 25, 36, 40	21 to 23, 26 to 35, 37 to 39	Male
M20-973XXXX	SIL	From 02 to 40	From 02 to 20, 25 to 28, 36, 40	21 to 24, 29 to 35, 37 to 39	Male
M20-974XXXX	DIL	From 02 to 40	From 02 to 20, 25, 36, 40	21 to 24, 26 to 35, 37 to 39	Male
M20-975XXXX	SIL	From 02 to 40	From 02 to 20, 25, 36, 40	21 to 24, 26 to 35, 37 to 39	Male
M20-976XXXX	DIL	From 02 to 40	From 02 to 20, 25, 36, 40	21 to 24, 26 to 35, 37 to 39	Male
M20-977XXXX	SIL	From 02 to 40	From 02 to 20, 25, 26, 32, 36, 40	21 to 24, 27 to 31, 33 to 35, 37 to 39	Male
M20-995XXXX	DIL	From 02 to 40	From 02 to 20, 24, 25, 32, 36, 40	21 to 23, 26 to 31, 33 to 35, 37 to 39	Male
M20-996XXXX	SIL	From 02 to 40	From 02 to 20, 24, 25, 36, 40	21 to 23, 26 to 35, 37 to 39	Male
M20-997XXXX	DIL	From 01 to 40	From 02 to 20, 25, 36, 40	01, 21 to 24, 26 to 35, 37 to 39	Male
M20-998XXXX	DIL	From 02 to 40	From 02 to 20, 23 to 25, 32, 36, 40	21, 22, 26 to 31, 33 to 35, 37 to 39	Male
M20-999XXXX	SIL	From 02 to 40	From 02 to 20, 23, 25, 30 to 33, 36, 40	21, 22, 24, 26 to 29, 34, 35, 37 to 39	Male

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

Obsolete Product Notification from Harwin

Part number being made obsolete	Drawing for obsolete product	Last Time Buy date	Nearest standard alternative	Pin Header Variant alternative product (made-to-order)	Drawing for Pin Header Variant alternative product
M20-8762142	M20-876 obsolete.pdf	10 November 2017	M20-8762542	M20-058000S2145	HF159-S.pdf
M20-8762146	M20-876 obsolete.pdf	10 November 2017	M20-8762546	M20-058000S2146	HF159-S.pdf
M20-8762242	M20-876 obsolete.pdf	10 November 2017	M20-8762542	M20-058000S2245	HF159-S.pdf
M20-8762246	M20-876 obsolete.pdf	10 November 2017	M20-8762546	M20-058000S2246	HF159-S.pdf
M20-8762342	M20-876 obsolete.pdf	10 November 2017	M20-8762542	M20-058000S2345	HF159-S.pdf
M20-8762346	M20-876 obsolete.pdf	10 November 2017	M20-8762546	M20-058000S2346	HF159-S.pdf
M20-8762442	M20-876 obsolete.pdf	10 November 2017	M20-8762542	M20-058000S2445	HF159-S.pdf
M20-8762446	M20-876 obsolete.pdf	10 November 2017	M20-8762546	M20-058000S2446	HF159-S.pdf
M20-8762642	M20-876 obsolete.pdf	10 November 2017	M20-8763642	M20-058000S2645	HF159-S.pdf
M20-8762646	M20-876 obsolete.pdf	10 November 2017	M20-8763646	M20-058000S2646	HF159-S.pdf
M20-8762742	M20-876 obsolete.pdf	10 November 2017	M20-8763642	M20-058000S2745	HF159-S.pdf
M20-8762746	M20-876 obsolete.pdf	10 November 2017	M20-8763646	M20-058000S2746	HF159-S.pdf
M20-8762842	M20-876 obsolete.pdf	10 November 2017	M20-8763642	M20-058000S2845	HF159-S.pdf
M20-8762846	M20-876 obsolete.pdf	10 November 2017	M20-8763646	M20-058000S2846	HF159-S.pdf
M20-8762942	M20-876 obsolete.pdf	10 November 2017	M20-8763642	M20-058000S2945	HF159-S.pdf
M20-8762946	M20-876 obsolete.pdf	10 November 2017	M20-8763646	M20-058000S2946	HF159-S.pdf
M20-8763042	M20-876 obsolete.pdf	10 November 2017	M20-8763642	M20-058000S3045	HF159-S.pdf
M20-8763046	M20-876 obsolete.pdf	10 November 2017	M20-8763646	M20-058000S3046	HF159-S.pdf
M20-8763142	M20-876 obsolete.pdf	10 November 2017	M20-8763642	M20-058000S3145	HF159-S.pdf
M20-8763146	M20-876 obsolete.pdf	10 November 2017	M20-8763646	M20-058000S3146	HF159-S.pdf
M20-8763242	M20-876 obsolete.pdf	10 November 2017	M20-8763642	M20-058000S3245	HF159-S.pdf
M20-8763246	M20-876 obsolete.pdf	10 November 2017	M20-8763646	M20-058000S3246	HF159-S.pdf
M20-8763342	M20-876 obsolete.pdf	10 November 2017	M20-8763642	M20-058000S3345	HF159-S.pdf
M20-8763346	M20-876 obsolete.pdf	10 November 2017	M20-8763646	M20-058000S3346	HF159-S.pdf
M20-8763442	M20-876 obsolete.pdf	10 November 2017	M20-8763642	M20-058000S3445	HF159-S.pdf
M20-8763446	M20-876 obsolete.pdf	10 November 2017	M20-8763646	M20-058000S3446	HF159-S.pdf
M20-8763542	M20-876 obsolete.pdf	10 November 2017	M20-8763642	M20-058000S3545	HF159-S.pdf
M20-8763546	M20-876 obsolete.pdf	10 November 2017	M20-8763646	M20-058000S3546	HF159-S.pdf
M20-8762142P	M20-876P obsolete.pdf	10 November 2017	M20-8762342P	M20-058000S2145	HF159-S.pdf
M20-8762146P	M20-876P obsolete.pdf	10 November 2017	M20-8762346P	M20-058000S2146	HF159-S.pdf
M20-8762242P	M20-876P obsolete.pdf	10 November 2017	M20-8762342P	M20-058000S2245	HF159-S.pdf
M20-8762246P	M20-876P obsolete.pdf	10 November 2017	M20-8762346P	M20-058000S2246	HF159-S.pdf
M20-8762442P	M20-876P obsolete.pdf	10 November 2017	M20-8762542	M20-058000S2445	HF159-S.pdf
M20-8762446P	M20-876P obsolete.pdf	10 November 2017	M20-8762546	M20-058000S2446	HF159-S.pdf
M20-8762542P	M20-876P obsolete.pdf	10 November 2017	M20-8762542	M20-058000S2545	HF159-S.pdf
M20-8762546P	M20-876P obsolete.pdf	10 November 2017	M20-8762546	M20-058000S2546	HF159-S.pdf
M20-8762642P	M20-876P obsolete.pdf	10 November 2017	M20-8763642	M20-058000S2645	HF159-S.pdf
M20-8762646P	M20-876P obsolete.pdf	10 November 2017	M20-8763646	M20-058000S2646	HF159-S.pdf
M20-8762742P	M20-876P obsolete.pdf	10 November 2017	M20-8763642	M20-058000S2745	HF159-S.pdf
M20-8762746P	M20-876P obsolete.pdf	10 November 2017	M20-8763646	M20-058000S2746	HF159-S.pdf
M20-8762842P	M20-876P obsolete.pdf	10 November 2017	M20-8763642	M20-058000S2845	HF159-S.pdf
M20-8762846P	M20-876P obsolete.pdf	10 November 2017	M20-8763646	M20-058000S2846	HF159-S.pdf
M20-8762942P	M20-876P obsolete.pdf	10 November 2017	M20-8763642	M20-058000S2945	HF159-S.pdf
M20-8762946P	M20-876P obsolete.pdf	10 November 2017	M20-8763646	M20-058000S2946	HF159-S.pdf
M20-8763042P	M20-876P obsolete.pdf	10 November 2017	M20-8763642	M20-058000S3045	HF159-S.pdf
M20-8763046P	M20-876P obsolete.pdf	10 November 2017	M20-8763646	M20-058000S3046	HF159-S.pdf
M20-8763142P	M20-876P obsolete.pdf	10 November 2017	M20-8763642	M20-058000S3145	HF159-S.pdf
M20-8763146P	M20-876P obsolete.pdf	10 November 2017	M20-8763646	M20-058000S3146	HF159-S.pdf
M20-8763242P	M20-876P obsolete.pdf	10 November 2017	M20-8763642	M20-058000S3245	HF159-S.pdf
M20-8763246P	M20-876P obsolete.pdf	10 November 2017	M20-8763646	M20-058000S3246	HF159-S.pdf
M20-8763342P	M20-876P obsolete.pdf	10 November 2017	M20-8763642	M20-058000S3345	HF159-S.pdf
M20-8763346P	M20-876P obsolete.pdf	10 November 2017	M20-8763646	M20-058000S3346	HF159-S.pdf
M20-8763442P	M20-876P obsolete.pdf	10 November 2017	M20-8763642	M20-058000S3445	HF159-S.pdf
M20-8763446P	M20-876P obsolete.pdf	10 November 2017	M20-8763646	M20-058000S3446	HF159-S.pdf
M20-8763542P	M20-876P obsolete.pdf	10 November 2017	M20-8763642	M20-058000S3545	HF159-S.pdf
M20-8763546P	M20-876P obsolete.pdf	10 November 2017	M20-8763646	M20-058000S3546	HF159-S.pdf
M20-8763642P	M20-876P obsolete.pdf	10 November 2017	M20-8763642	M20-058000S3645	HF159-S.pdf
M20-8763646P	M20-876P obsolete.pdf	10 November 2017	M20-8763646	M20-058000S3646	HF159-S.pdf
M20-8772142	M20-877 obsolete.pdf	10 November 2017	M20-8772542	Not applicable	
M20-8772146	M20-877 obsolete.pdf	10 November 2017	M20-8772546	Not applicable	
M20-8772242	M20-877 obsolete.pdf	10 November 2017	M20-8772542	Not applicable	
M20-8772246	M20-877 obsolete.pdf	10 November 2017	M20-8772546	Not applicable	
M20-8772342	M20-877 obsolete.pdf	10 November 2017	M20-8772542	Not applicable	
M20-8772346	M20-877 obsolete.pdf	10 November 2017	M20-8772546	Not applicable	

Obsolete Product Notification from Harwin

[illegible]

Obsolete Product Notification from Harwin

Part number being made obsolete	Drawing for obsolete product	Last Time Buy date	Nearest standard alternative	Pin Header Variant alternative product (made-to-order)	Drawing for Pin Header Variant alternative product
M20-8912205	M20-891_obsolete.pdf	10 November 2017	M20-8912005	Not applicable	
M20-8912305	M20-891_obsolete.pdf	10 November 2017	M20-8912005	Not applicable	
M20-8912405	M20-891_obsolete.pdf	10 November 2017	M20-8912005	Not applicable	
M20-8912505	M20-891_obsolete.pdf	10 November 2017	M20-8912005	Not applicable	
M20-8912605	M20-891_obsolete.pdf	10 November 2017	M20-8912005	Not applicable	
M20-8912705	M20-891_obsolete.pdf	10 November 2017	M20-8912005	Not applicable	
M20-8912805	M20-891_obsolete.pdf	10 November 2017	M20-8912005	Not applicable	
M20-8912905	M20-891_obsolete.pdf	10 November 2017	M20-8912005	Not applicable	
M20-8913005	M20-891_obsolete.pdf	10 November 2017	M20-8912005	Not applicable	
M20-8913105	M20-891_obsolete.pdf	10 November 2017	M20-8912005	Not applicable	
M20-8913205	M20-891_obsolete.pdf	10 November 2017	M20-8912005	Not applicable	
M20-8913305	M20-891_obsolete.pdf	10 November 2017	M20-8912005	Not applicable	
M20-8913405	M20-891_obsolete.pdf	10 November 2017	M20-8912005	Not applicable	
M20-8913505	M20-891_obsolete.pdf	10 November 2017	M20-8912005	Not applicable	
M20-8913605	M20-891_obsolete.pdf	10 November 2017	M20-8912005	Not applicable	
M20-9702145	M20-970_obsolete.pdf	10 November 2017	M20-9702245	M20-070030J2145	HF159-J.pdf
M20-9702146	M20-970_obsolete.pdf	10 November 2017	M20-9702246	M20-070030J2146	HF159-J.pdf
M20-9702345	M20-970_obsolete.pdf	10 November 2017	M20-9702545	M20-070030J2345	HF159-J.pdf
M20-9702346	M20-970_obsolete.pdf	10 November 2017	M20-9702546	M20-070030J2346	HF159-J.pdf
M20-9702445	M20-970_obsolete.pdf	10 November 2017	M20-9702545	M20-070030J2445	HF159-J.pdf
M20-9702446	M20-970_obsolete.pdf	10 November 2017	M20-9702546	M20-070030J2446	HF159-J.pdf
M20-9702645	M20-970_obsolete.pdf	10 November 2017	M20-9702745	M20-070030J2645	HF159-J.pdf
M20-9702646	M20-970_obsolete.pdf	10 November 2017	M20-9702746	M20-070030J2646	HF159-J.pdf
M20-9702845	M20-970_obsolete.pdf	10 November 2017	M20-9703645	M20-070030J2845	HF159-J.pdf
M20-9702846	M20-970_obsolete.pdf	10 November 2017	M20-9703646	M20-070030J2846	HF159-J.pdf
M20-9702945	M20-970_obsolete.pdf	10 November 2017	M20-9703645	M20-070030J2945	HF159-J.pdf
M20-9702946	M20-970_obsolete.pdf	10 November 2017	M20-9703646	M20-070030J2946	HF159-J.pdf
M20-9703045	M20-970_obsolete.pdf	10 November 2017	M20-9703645	M20-070030J3045	HF159-J.pdf
M20-9703046	M20-970_obsolete.pdf	10 November 2017	M20-9703646	M20-070030J3046	HF159-J.pdf
M20-9703145	M20-970_obsolete.pdf	10 November 2017	M20-9703645	M20-070030J3145	HF159-J.pdf
M20-9703146	M20-970_obsolete.pdf	10 November 2017	M20-9703646	M20-070030J3146	HF159-J.pdf
M20-9703245	M20-970_obsolete.pdf	10 November 2017	M20-9703645	M20-070030J3245	HF159-J.pdf
M20-9703246	M20-970_obsolete.pdf	10 November 2017	M20-9703646	M20-070030J3246	HF159-J.pdf
M20-9703345	M20-970_obsolete.pdf	10 November 2017	M20-9703645	M20-070030J3345	HF159-J.pdf
M20-9703346	M20-970_obsolete.pdf	10 November 2017	M20-9703646	M20-070030J3346	HF159-J.pdf
M20-9703445	M20-970_obsolete.pdf	10 November 2017	M20-9703645	M20-070030J3445	HF159-J.pdf
M20-9703446	M20-970_obsolete.pdf	10 November 2017	M20-9703646	M20-070030J3446	HF159-J.pdf
M20-9703545	M20-970_obsolete.pdf	10 November 2017	M20-9703645	M20-070030J3545	HF159-J.pdf
M20-9703546	M20-970_obsolete.pdf	10 November 2017	M20-9703646	M20-070030J3546	HF159-J.pdf
M20-9703745	M20-970_obsolete.pdf	10 November 2017	M20-9704045	M20-070030J3745	<

Obsolete Product Notification from Harwin

Part number being made obsolete	Drawing for obsolete product	Last Time Buy date	Nearest standard alternative	Pin Header Variant alternative product (made-to-order)	Drawing for Pin Header Variant alternative product
M20-9713346	M20-971 obsolete.pdf	10 November 2017	M20-9713646	M20-070030H3346	HF159-H.pdf
M20-9713445	M20-971 obsolete.pdf	10 November 2017	M20-9713645	M20-070030H3445	HF159-H.pdf
M20-9713446	M20-971 obsolete.pdf	10 November 2017	M20-9713646	M20-070030H3446	HF159-H.pdf
M20-9713545	M20-971 obsolete.pdf	10 November 2017	M20-9713645	M20-070030H3545	HF159-H.pdf
M20-9713546	M20-971 obsolete.pdf	10 November 2017	M20-9713646	M20-070030H3546	HF159-H.pdf
M20-9713745	M20-971 obsolete.pdf	10 November 2017	M20-9714045	M20-070030H3745	HF159-H.pdf
M20-9713746	M20-971 obsolete.pdf	10 November 2017	M20-9714046	M20-070030H3746	HF159-H.pdf
M20-9713845	M20-971 obsolete.pdf	10 November 2017	M20-9714045	M20-070030H3845	HF159-H.pdf
M20-9713846	M20-971 obsolete.pdf	10 November 2017	M20-9714046	M20-070030H3846	HF159-H.pdf
M20-9713945	M20-971 obsolete.pdf	10 November 2017	M20-9714045	M20-070030H3945	HF159-H.pdf
M20-9713946	M20-971 obsolete.pdf	10 November 2017	M20-9714046	M20-070030H3946	HF159-H.pdf
M20-9722145	M20-972 obsolete.pdf	10 November 2017	M20-9722445	M20-070030W2145	HF159-W.pdf
M20-9722146	M20-972 obsolete.pdf	10 November 2017	M20-9722446	M20-070030W2146	HF159-W.pdf
M20-9722245	M20-972 obsolete.pdf	10 November 2017	M20-9722445	M20-070030W2245	HF159-W.pdf
M20-9722246	M20-972 obsolete.pdf	10 November 2017	M20-9722446	M20-070030W2246	HF159-W.pdf
M20-9722345	M20-972 obsolete.pdf	10 November 2017	M20-9722445	M20-070030W2345	HF159-W.pdf
M20-9722346	M20-972 obsolete.pdf	10 November 2017	M20-9722446	M20-070030W2346	HF159-W.pdf
M20-9722645	M20-972 obsolete.pdf	10 November 2017	M20-9723645	M20-070030W2645	HF159-W.pdf
M20-9722646	M20-972 obsolete.pdf	10 November 2017	M20-9723646	M20-070030W2646	HF159-W.pdf
M20-9722745	M20-972 obsolete.pdf	10 November 2017	M20-9723645	M20-070030W2745	HF159-W.pdf
M20-9722746	M20-972 obsolete.pdf	10 November 2017	M20-9723646	M20-070030W2746	HF159-W.pdf
M20-9722845	M20-972 obsolete.pdf	10 November 2017	M20-9723645	M20-070030W2845	HF159-W.pdf
M20-9722846	M20-972 obsolete.pdf	10 November 2017	M20-9723646	M20-070030W2846	HF159-W.pdf
M20-9722945	M20-972 obsolete.pdf	10 November 2017	M20-9723645	M20-070030W2945	HF159-W.pdf
M20-9722946	M20-972 obsolete.pdf	10 November 2017	M20-9723646	M20-070030W2946	HF159-W.pdf
M20-9723045	M20-972 obsolete.pdf	10 November 2017	M20-9723645	M20-070030W3045	HF159-W.pdf
M20-9723046	M20-972 obsolete.pdf	10 November 2017	M20-9723646	M20-070030W3046	HF159-W.pdf
M20-9723145	M20-972 obsolete.pdf	10 November 2017	M20-9723645	M20-070030W3145	HF159-W.pdf
M20-9723146	M20-972 obsolete.pdf	10 November 2017	M20-9723646	M20-070030W3146	HF159-W.pdf
M20-9723245	M20-972 obsolete.pdf	10 November 2017	M20-9723645	M20-070030W3245	HF159-W.pdf
M20-9723246	M20-972 obsolete.pdf	10 November 2017	M20-9723646	M20-070030W3246	HF159-W.pdf
M20-9723345	M20-972 obsolete.pdf	10 November 2017	M20-9723645	M20-070030W3345	HF159-W.pdf
M20-9723346	M20-972 obsolete.pdf	10 November 2017	M20-9723646	M20-070030W3346	HF159-W.pdf
M20-9723445	M20-972 obsolete.pdf	10 November 2017	M20-9723645	M20-070030W3445	HF159-W.pdf
M20-9723446	M20-972 obsolete.pdf	10 November 2017	M20-9723646	M20-070030W3446	HF159-W.pdf
M20-9723545	M20-972 obsolete.pdf	10 November 2017	M20-9723645	M20-070030W3545	HF159-W.pdf
M20-9723546	M20-972 obsolete.pdf	10 November 2017	M20-9723646	M20-070030W3546	HF

Obsolete Product Notification from Harwin

Part number being made obsolete	Drawing for obsolete product	Last Time Buy date	Nearest standard alternative	Pin Header Variant alternative product (made-to-order)	Drawing for Pin Header Variant alternative product
M20-9733546	M20-973 obsolete.pdf	10 November 2017	M20-9733646	M20-070030V3546	HF159-V.pdf
M20-9733745	M20-973 obsolete.pdf	10 November 2017	M20-9734045	M20-070030V3745	HF159-V.pdf
M20-9733746	M20-973 obsolete.pdf	10 November 2017	M20-9734046	M20-070030V3746	HF159-V.pdf
M20-9733845	M20-973 obsolete.pdf	10 November 2017	M20-9734045	M20-070030V3845	HF159-V.pdf
M20-9733846	M20-973 obsolete.pdf	10 November 2017	M20-9734046	M20-070030V3846	HF159-V.pdf
M20-9733945	M20-973 obsolete.pdf	10 November 2017	M20-9734045	M20-070030V3945	HF159-V.pdf
M20-9733946	M20-973 obsolete.pdf	10 November 2017	M20-9734046	M20-070030V3946	HF159-V.pdf
M20-9742142	M20-974 obsolete.pdf	10 November 2017	M20-9742542	M20-058030J2145	HF159-J.pdf
M20-9742146	M20-974 obsolete.pdf	10 November 2017	M20-9742546	M20-058030J2146	HF159-J.pdf
M20-9742242	M20-974 obsolete.pdf	10 November 2017	M20-9742542	M20-058030J2245	HF159-J.pdf
M20-9742246	M20-974 obsolete.pdf	10 November 2017	M20-9742546	M20-058030J2246	HF159-J.pdf
M20-9742342	M20-974 obsolete.pdf	10 November 2017	M20-9742542	M20-058030J2345	HF159-J.pdf
M20-9742346	M20-974 obsolete.pdf	10 November 2017	M20-9742546	M20-058030J2346	HF159-J.pdf
M20-9742442	M20-974 obsolete.pdf	10 November 2017	M20-9742542	M20-058030J2445	HF159-J.pdf
M20-9742446	M20-974 obsolete.pdf	10 November 2017	M20-9742546	M20-058030J2446	HF159-J.pdf
M20-9742642	M20-974 obsolete.pdf	10 November 2017	M20-9743642	M20-058030J2645	HF159-J.pdf
M20-9742646	M20-974 obsolete.pdf	10 November 2017	M20-9743646	M20-058030J2646	HF159-J.pdf
M20-9742742	M20-974 obsolete.pdf	10 November 2017	M20-9743642	M20-058030J2745	HF159-J.pdf
M20-9742746	M20-974 obsolete.pdf	10 November 2017	M20-9743646	M20-058030J2746	HF159-J.pdf
M20-9742842	M20-974 obsolete.pdf	10 November 2017	M20-9743642	M20-058030J2845	HF159-J.pdf
M20-9742846	M20-974 obsolete.pdf	10 November 2017	M20-9743646	M20-058030J2846	HF159-J.pdf
M20-9742942	M20-974 obsolete.pdf	10 November 2017	M20-9743642	M20-058030J2945	HF159-J.pdf
M20-9742946	M20-974 obsolete.pdf	10 November 2017	M20-9743646	M20-058030J2946	HF159-J.pdf
M20-9743042	M20-974 obsolete.pdf	10 November 2017	M20-9743642	M20-058030J3045	HF159-J.pdf
M20-9743046	M20-974 obsolete.pdf	10 November 2017	M20-9743646	M20-058030J3046	HF159-J.pdf
M20-9743142	M20-974 obsolete.pdf	10 November 2017	M20-9743642	M20-058030J3145	HF159-J.pdf
M20-9743146	M20-974 obsolete.pdf	10 November 2017	M20-9743646	M20-058030J3146	HF159-J.pdf
M20-9743242	M20-974 obsolete.pdf	10 November 2017	M20-9743642	M20-058030J3245	HF159-J.pdf
M20-9743246	M20-974 obsolete.pdf	10 November 2017	M20-9743646	M20-058030J3246	HF159-J.pdf
M20-9743342	M20-974 obsolete.pdf	10 November 2017	M20-9743642	M20-058030J3345	HF159-J.pdf
M20-9743346	M20-974 obsolete.pdf	10 November 2017	M20-9743646	M20-058030J3346	HF159-J.pdf
M20-9743442	M20-974 obsolete.pdf	10 November 2017	M20-9743642	M20-058030J3445	HF159-J.pdf
M20-9743446	M20-974 obsolete.pdf	10 November 2017	M20-9743646	M20-058030J3446	HF159-J.pdf
M20-9743542	M20-974 obsolete.pdf	10 November 2017	M20-9743642	M20-058030J3545	HF159-J.pdf
M20-9743546	M20-974 obsolete.pdf	10 November 2017	M20-9743646	M20-058030J3546	HF159-J.pdf
M20-9743742	M20-974 obsolete.pdf	10 November 2017	M20-9744042	M20-058030J3745	HF159-J.pdf
M20-9743746	M20-974 obsolete.pdf	10 November 2017	M20-9744046	M20-058030J3746	HF

Obsolete Product Notification from Harwin

Part number being made obsolete	Drawing for obsolete product	Last Time Buy date	Nearest standard alternative	Pin Header Variant alternative product (made-to-order)	Drawing for Pin Header Variant alternative product
M20-9753346	M20-975 obsolete.pdf	10 November 2017	M20-9753646	M20-058030H3346	HF159-H.pdf
M20-9753442	M20-975 obsolete.pdf	10 November 2017	M20-9753642	M20-058030H3445	HF159-H.pdf
M20-9753446	M20-975 obsolete.pdf	10 November 2017	M20-9753646	M20-058030H3446	HF159-H.pdf
M20-9753542	M20-975 obsolete.pdf	10 November 2017	M20-9753642	M20-058030H3545	HF159-H.pdf
M20-9753546	M20-975 obsolete.pdf	10 November 2017	M20-9753646	M20-058030H3546	HF159-H.pdf
M20-9753742	M20-975 obsolete.pdf	10 November 2017	M20-9754042	M20-058030H3745	HF159-H.pdf
M20-9753746	M20-975 obsolete.pdf	10 November 2017	M20-9754046	M20-058030H3746	HF159-H.pdf
M20-9753842	M20-975 obsolete.pdf	10 November 2017	M20-9754042	M20-058030H3845	HF159-H.pdf
M20-9753846	M20-975 obsolete.pdf	10 November 2017	M20-9754046	M20-058030H3846	HF159-H.pdf
M20-9753942	M20-975 obsolete.pdf	10 November 2017	M20-9754042	M20-058030H3945	HF159-H.pdf
M20-9753946	M20-975 obsolete.pdf	10 November 2017	M20-9754046	M20-058030H3946	HF159-H.pdf
M20-9762142	M20-976 obsolete.pdf	10 November 2017	M20-9762542	M20-058030W2145	HF159-W.pdf
M20-9762146	M20-976 obsolete.pdf	10 November 2017	M20-9762546	M20-058030W2146	HF159-W.pdf
M20-9762242	M20-976 obsolete.pdf	10 November 2017	M20-9762542	M20-058030W2245	HF159-W.pdf
M20-9762246	M20-976 obsolete.pdf	10 November 2017	M20-9762546	M20-058030W2246	HF159-W.pdf
M20-9762342	M20-976 obsolete.pdf	10 November 2017	M20-9762542	M20-058030W2345	HF159-W.pdf
M20-9762346	M20-976 obsolete.pdf	10 November 2017	M20-9762546	M20-058030W2346	HF159-W.pdf
M20-9762442	M20-976 obsolete.pdf	10 November 2017	M20-9762542	M20-058030W2445	HF159-W.pdf
M20-9762446	M20-976 obsolete.pdf	10 November 2017	M20-9762546	M20-058030W2446	HF159-W.pdf
M20-9762642	M20-976 obsolete.pdf	10 November 2017	M20-9763642	M20-058030W2645	HF159-W.pdf
M20-9762646	M20-976 obsolete.pdf	10 November 2017	M20-9763646	M20-058030W2646	HF159-W.pdf
M20-9762742	M20-976 obsolete.pdf	10 November 2017	M20-9763642	M20-058030W2745	HF159-W.pdf
M20-9762746	M20-976 obsolete.pdf	10 November 2017	M20-9763646	M20-058030W2746	HF159-W.pdf
M20-9762842	M20-976 obsolete.pdf	10 November 2017	M20-9763642	M20-058030W2845	HF159-W.pdf
M20-9762846	M20-976 obsolete.pdf	10 November 2017	M20-9763646	M20-058030W2846	HF159-W.pdf
M20-9762942	M20-976 obsolete.pdf	10 November 2017	M20-9763642	M20-058030W2945	HF159-W.pdf
M20-9762946	M20-976 obsolete.pdf	10 November 2017	M20-9763646	M20-058030W2946	HF159-W.pdf
M20-9763042	M20-976 obsolete.pdf	10 November 2017	M20-9763642	M20-058030W3045	HF159-W.pdf
M20-9763046	M20-976 obsolete.pdf	10 November 2017	M20-9763646	M20-058030W3046	HF159-W.pdf
M20-9763142	M20-976 obsolete.pdf	10 November 2017	M20-9763642	M20-058030W3145	HF159-W.pdf
M20-9763146	M20-976 obsolete.pdf	10 November 2017	M20-9763646	M20-058030W3146	HF159-W.pdf
M20-9763242	M20-976 obsolete.pdf	10 November 2017	M20-9763642	M20-058030W3245	HF159-W.pdf
M20-9763246	M20-976 obsolete.pdf	10 November 2017	M20-9763646	M20-058030W3246	HF159-W.pdf
M20-9763342	M20-976 obsolete.pdf	10 November 2017	M20-9763642	M20-058030W3345	HF159-W.pdf
M20-9763346	M20-976 obsolete.pdf	10 November 2017	M20-9763646	M20-058030W3346	HF159-W.pdf
M20-9763442	M20-976 obsolete.pdf	10 November 2017	M20-9763642	M20-058030W3445	HF159-W.pdf
M20-9763446	M20-976 obsolete.pdf	10 November 2017	M20-9763646	M20-058030W3446	HF

Obsolete Product Notification from Harwin

Part number being made obsolete	Drawing for obsolete product	Last Time Buy date	Nearest standard alternative	Pin Header Variant alternative product (made-to-order)	Drawing for Pin Header Variant alternative product
M20-9773346	M20-977 obsolete.pdf	10 November 2017	M20-9773646	M20-058030V3346	HF159-V.pdf
M20-9773442	M20-977 obsolete.pdf	10 November 2017	M20-9773642	M20-058030V3445	HF159-V.pdf
M20-9773446	M20-977 obsolete.pdf	10 November 2017	M20-9773646	M20-058030V3446	HF159-V.pdf
M20-9773542	M20-977 obsolete.pdf	10 November 2017	M20-9773642	M20-058030V3545	HF159-V.pdf
M20-9773546	M20-977 obsolete.pdf	10 November 2017	M20-9773646	M20-058030V3546	HF159-V.pdf
M20-9773742	M20-977 obsolete.pdf	10 November 2017	M20-9774042	M20-058030V3745	HF159-V.pdf
M20-9773746	M20-977 obsolete.pdf	10 November 2017	M20-9774046	M20-058030V3746	HF159-V.pdf
M20-9773842	M20-977 obsolete.pdf	10 November 2017	M20-9774042	M20-058030V3845	HF159-V.pdf
M20-9773846	M20-977 obsolete.pdf	10 November 2017	M20-9774046	M20-058030V3846	HF159-V.pdf
M20-9773942	M20-977 obsolete.pdf	10 November 2017	M20-9774042	M20-058030V3945	HF159-V.pdf
M20-9773946	M20-977 obsolete.pdf	10 November 2017	M20-9774046	M20-058030V3946	HF159-V.pdf
M20-9952145	M20-995 obsolete.pdf	10 November 2017	M20-9952445	M20-061030J2145	HF159-J.pdf
M20-9952146	M20-995 obsolete.pdf	10 November 2017	M20-9952446	M20-061030J2146	HF159-J.pdf
M20-9952245	M20-995 obsolete.pdf	10 November 2017	M20-9952445	M20-061030J2245	HF159-J.pdf
M20-9952246	M20-995 obsolete.pdf	10 November 2017	M20-9952446	M20-061030J2246	HF159-J.pdf
M20-9952345	M20-995 obsolete.pdf	10 November 2017	M20-9952445	M20-061030J2345	HF159-J.pdf
M20-9952346	M20-995 obsolete.pdf	10 November 2017	M20-9952446	M20-061030J2346	HF159-J.pdf
M20-9952645	M20-995 obsolete.pdf	10 November 2017	M20-9953245	M20-061030J2645	HF159-J.pdf
M20-9952646	M20-995 obsolete.pdf	10 November 2017	M20-9953246	M20-061030J2646	HF159-J.pdf
M20-9952745	M20-995 obsolete.pdf	10 November 2017	M20-9953245	M20-061030J2745	HF159-J.pdf
M20-9952746	M20-995 obsolete.pdf	10 November 2017	M20-9953246	M20-061030J2746	HF159-J.pdf
M20-9952845	M20-995 obsolete.pdf	10 November 2017	M20-9953245	M20-061030J2845	HF159-J.pdf
M20-9952846	M20-995 obsolete.pdf	10 November 2017	M20-9953246	M20-061030J2846	HF159-J.pdf
M20-9952945	M20-995 obsolete.pdf	10 November 2017	M20-9953245	M20-061030J2945	HF159-J.pdf
M20-9952946	M20-995 obsolete.pdf	10 November 2017	M20-9953246	M20-061030J2946	HF159-J.pdf
M20-9953045	M20-995 obsolete.pdf	10 November 2017	M20-9953245	M20-061030J3045	HF159-J.pdf
M20-9953046	M20-995 obsolete.pdf	10 November 2017	M20-9953246	M20-061030J3046	HF159-J.pdf
M20-9953145	M20-995 obsolete.pdf	10 November 2017	M20-9953245	M20-061030J3145	HF159-J.pdf
M20-9953146	M20-995 obsolete.pdf	10 November 2017	M20-9953246	M20-061030J3146	HF159-J.pdf
M20-9953345	M20-995 obsolete.pdf	10 November 2017	M20-9953645	M20-061030J3345	HF159-J.pdf
M20-9953346	M20-995 obsolete.pdf	10 November 2017	M20-9953646	M20-061030J3346	HF159-J.pdf
M20-9953445	M20-995 obsolete.pdf	10 November 2017	M20-9953645	M20-061030J3445	HF159-J.pdf
M20-9953446	M20-995 obsolete.pdf	10 November 2017	M20-9953646	M20-061030J3446	HF159-J.pdf
M20-9953545	M20-995 obsolete.pdf	10 November 2017	M20-9953645	M20-061030J3545	HF159-J.pdf
M20-9953546	M20-995 obsolete.pdf	10 November 2017	M20-9953646	M20-061030J3546	HF159-J.pdf
M20-9953745	M20-995 obsolete.pdf	10 November 2017	M20-9954045	M20-061030J3745	HF159-J.pdf
M20-9953746	M20-995 obsolete.pdf	10 November 2017	M20-9954046	M20-061030J3746	HF159-J.pdf
M20-9953845	M20-995 obsolete.pdf	10 November 2017	M20-9954045	M20-061030J3845	HF159-J.pdf
M20-9953846	M20-995 obsolete.pdf	10 November 2017	M20-9954046	M20-061030J3846	HF159-J.pdf
M20-9953945	M20-995 obsolete.pdf	10 November 2017	M20-9954045	M20-061030J3945	HF159-J.pdf
M20-9953946	M20-995 obsolete.pdf	10 November 2017	M20-9954046	M20-061030J3946	HF159-J.pdf
M20-9962145	M20-996 obsolete.pdf	10 November 2017	M20-9962445	M20-061030H2145	HF159-H.pdf
M20-9962146	M20-996 obsolete.pdf	10 November 2017	M20-9962446	M20-061030H2146	HF159-H.pdf
M20-9962245	M20-996 obsolete.pdf	10 November 2017	M20-9962445	M20-061030H2245	HF159-H.pdf
M20-9962246	M20-996 obsolete.pdf	10 November 2017	M20-9962446	M20-061030H2246	HF159-H.pdf
M20-9962345	M20-996 obsolete.pdf	10 November 2017	M20-9962445	M20-061030H2345	HF159-H.pdf
M20-9962346	M20-996 obsolete.pdf	10 November 2017	M20-9962446	M20-061030H2346	HF159-H.pdf
M20-9962645	M20-996 obsolete.pdf	10 November 2017	M20-9963645	M20-061030H2645	HF159-H.pdf
M20-9962646	M20-996 obsolete.pdf	10 November 2017	M20-9963646	M20-061030H2646	HF159-H.pdf
M20-9962745	M20-996 obsolete.pdf	10 November 2017	M20-9963645	M20-061030H2745	HF159-H.pdf
M20-9962746	M20-996 obsolete.pdf	10 November 2017	M20-9963646	M20-061030H2746	HF159-H.pdf
M20-9962845	M20-996 obsolete.pdf	10 November 2017	M20-9963645	M20-061030H2845	HF159-H.pdf
M20-9962846	M20-996 obsolete.pdf	10 November 2017	M20-9963646	M20-061030H2846	HF159-H.pdf
M20-9962945	M20-996 obsolete.pdf	10 November 2017	M20-9963645	M20-061030H2945	HF159-H.pdf
M20-9962946	M20-996 obsolete.pdf	10 November 2017	M20-9963646	M20-061030H2946	HF159-H.pdf
M20-9963045	M20-996 obsolete.pdf	10 November 2017	M20-9963645	M20-061030H3045	HF159-H.pdf
M20-9963046	M20-996 obsolete.pdf	10 November 2017	M20-9963646	M20-061030H3046	HF159-H.pdf
M20-9963145	M20-996 obsolete.pdf	10 November 2017	M20-9963645	M20-061030H3145	HF159-H.pdf
M20-9963146	M20-996 obsolete.pdf	10 November 2017	M20-9963646	M20-061030H3146	HF159-H.pdf
M20-9963245	M20-996 obsolete.pdf	10 November 2017	M20-9963645	M20-061030H3245	HF159-H.pdf
M20-9963246	M20-996 obsolete.pdf	10 November 2017	M20-9963646	M20-061030H3246	HF159-H.pdf
M20-9963345	M20-996 obsolete.pdf	10 November 2017	M20-9963645	M20-061030H3345	HF159-H.pdf
M20-9963346	M20-996 obsolete.pdf	10 November 2017	M20-9963646	M20-061030H3346	HF159-H.pdf
M20-9963445	M20-996 obsolete.pdf	10 November 2017	M20-9963645	M20-061030H3445	HF159-H.pdf

Obsolete Product Notification from Harwin

Part number being made obsolete	Drawing for obsolete product	Last Time Buy date	Nearest standard alternative	Pin Header Variant alternative product (made-to-order)	Drawing for Pin Header Variant alternative product
M20-9963446	M20-996 obsolete.pdf	10 November 2017	M20-9963646	M20-061030H3446	HF159-H.pdf
M20-9963545	M20-996 obsolete.pdf	10 November 2017	M20-9963645	M20-061030H3545	HF159-H.pdf
M20-9963546	M20-996 obsolete.pdf	10 November 2017	M20-9963646	M20-061030H3546	HF159-H.pdf
M20-9963745	M20-996 obsolete.pdf	10 November 2017	M20-9964045	M20-061030H3745	HF159-H.pdf
M20-9963746	M20-996 obsolete.pdf	10 November 2017	M20-9964046	M20-061030H3746	HF159-H.pdf
M20-9963845	M20-996 obsolete.pdf	10 November 2017	M20-9964045	M20-061030H3845	HF159-H.pdf
M20-9963846	M20-996 obsolete.pdf	10 November 2017	M20-9964046	M20-061030H3846	HF159-H.pdf
M20-9963945	M20-996 obsolete.pdf	10 November 2017	M20-9964045	M20-061030H3945	HF159-H.pdf
M20-9963946	M20-996 obsolete.pdf	10 November 2017	M20-9964046	M20-061030H3946	HF159-H.pdf
M20-9970145	M20-997 obsolete.pdf	10 November 2017	M20-9970245	M20-085030W0145	HF159-W.pdf
M20-9970146	M20-997 obsolete.pdf	10 November 2017	M20-9970246	M20-085030W0146	HF159-W.pdf
M20-9972145	M20-997 obsolete.pdf	10 November 2017	M20-9972545	M20-085030W2145	HF159-W.pdf
M20-9972146	M20-997 obsolete.pdf	10 November 2017	M20-9972546	M20-085030W2146	HF159-W.pdf
M20-9972245	M20-997 obsolete.pdf	10 November 2017	M20-9972545	M20-085030W2245	HF159-W.pdf
M20-9972246	M20-997 obsolete.pdf	10 November 2017	M20-9972546	M20-085030W2246	HF159-W.pdf
M20-9972345	M20-997 obsolete.pdf	10 November 2017	M20-9972545	M20-085030W2345	HF159-W.pdf
M20-9972346	M20-997 obsolete.pdf	10 November 2017	M20-9972546	M20-085030W2346	HF159-W.pdf
M20-9972445	M20-997 obsolete.pdf	10 November 2017	M20-9972545	M20-085030W2445	HF159-W.pdf
M20-9972446	M20-997 obsolete.pdf	10 November 2017	M20-9972546	M20-085030W2446	HF159-W.pdf
M20-9972645	M20-997 obsolete.pdf	10 November 2017	M20-9973645	M20-085030W2645	HF159-W.pdf
M20-9972646	M20-997 obsolete.pdf	10 November 2017	M20-9973646	M20-085030W2646	HF159-W.pdf
M20-9972745	M20-997 obsolete.pdf	10 November 2017	M20-9973645	M20-085030W2745	HF159-W.pdf
M20-9972746	M20-997 obsolete.pdf	10 November 2017	M20-9973646	M20-085030W2746	HF159-W.pdf
M20-9972845	M20-997 obsolete.pdf	10 November 2017	M20-9973645	M20-085030W2845	HF159-W.pdf
M20-9972846	M20-997 obsolete.pdf	10 November 2017	M20-9973646	M20-085030W2846	HF159-W.pdf
M20-9972945	M20-997 obsolete.pdf	10 November 2017	M20-9973645	M20-085030W2945	HF159-W.pdf
M20-9972946	M20-997 obsolete.pdf	10 November 2017	M20-9973646	M20-085030W2946	HF159-W.pdf
M20-9973045	M20-997 obsolete.pdf	10 November 2017	M20-9973645	M20-085030W3045	HF159-W.pdf
M20-9973046	M20-997 obsolete.pdf	10 November 2017	M20-9973646	M20-085030W3046	HF159-W.pdf
M20-9973145	M20-997 obsolete.pdf	10 November 2017	M20-9973645	M20-085030W3145	HF159-W.pdf
M20-9973146	M20-997 obsolete.pdf	10 November 2017	M20-9973646	M20-085030W3146	HF159-W.pdf
M20-9973245	M20-997 obsolete.pdf	10 November 2017	M20-9973645	M20-085030W3245	HF159-W.pdf
M20-9973246	M20-997 obsolete.pdf	10 November 2017	M20-9973646	M20-085030W3246	HF159-W.pdf
M20-9973345	M20-997 obsolete.pdf	10 November 2017	M20-9973645	M20-085030W3345	HF159-W.pdf
M20-9973346	M20-997 obsolete.pdf	10 November 2017	M20-9973646	M20-085030W3346	HF159-W.pdf
M20-9973445	M20-997 obsolete.pdf	10 November 2017	M20-9973645	M20-085030W3445	HF159-W.pdf
M20-9973446	M20-997 obsolete.pdf	10 November 2017	M20-9973646	M20-085030W3446	HF159-W.pdf
M20-9973545	M20-997 obsolete.pdf	10 November 2017	M20-9973645	M20-085030W3545	HF159-W.pdf
M20-9973546	M20-997 obsolete.pdf	10 November 2017	M20-9973646	M20-085030W3546	HF159-W.pdf
M20-9973745	M20-997 obsolete.pdf	10 November 2017	M20-9974045	M20-085030W3745	HF159-W.pdf
M20-9973746	M20-997 obsolete.pdf	10 November 2017	M20-9974046	M20-085030W3746	HF159-W.pdf
M20-9973845	M20-997 obsolete.pdf	10 November 2017	M20-9974045	M20-085030W3845	HF159-W.pdf
M20-9973846	M20-997 obsolete.pdf	10 November 2017	M20-9974046	M20-085030W3846	HF159-W.pdf
M20-9973945	M20-997 obsolete.pdf	10 November 2017	M20-9974045	M20-085030W3945	HF159-W.pdf
M20-9973946	M20-997 obsolete.pdf	10 November 2017	M20-9974046	M20-085030W3946	HF159-W.pdf
M20-9982145	M20-998 obsolete.pdf	10 November 2017	M20-9982345	M20-061030W2145	HF159-W.pdf
M20-9982146	M20-998 obsolete.pdf	10 November 2017	M20-9982346	M20-061030W2146	HF159-W.pdf
M20-9982245	M20-998 obsolete.pdf	10 November 2017	M20-9982345	M20-061030W2245	HF159-W.pdf
M20-9982246	M20-998 obsolete.pdf	10 November 2017	M20-9982346	M20-061030W2246	HF159-W.pdf
M20-9982645	M20-998 obsolete.pdf	10 November 2017	M20-9983245	M20-061030W2645	HF159-W.pdf
M20-9982646	M20-998 obsolete.pdf	10 November 2017	M20-9983246	M20-061030W2646	HF159-W.pdf
M20-9982745	M20-998 obsolete.pdf	10 November 2017	M20-9983245	M20-061030W2745	HF159-W.pdf
M20-9982746	M20-998 obsolete.pdf	10 November 2017	M20-9983246	M20-061030W2746	HF159-W.pdf
M20-9982845	M20-998 obsolete.pdf	10 November 2017	M20-9983245	M20-061030W2845	HF159-W.pdf
M20-9982846	M20-998 obsolete.pdf	10 November 2017	M20-9983246	M20-061030W2846	HF159-W.pdf
M20-9982945	M20-998 obsolete.pdf	10 November 2017	M20-9983245	M20-061030W2945	HF159-W.pdf
M20-9982946	M20-998 obsolete.pdf	10 November 2017	M20-9983246	M20-061030W2946	HF159-W.pdf
M20-9983045	M20-998 obsolete.pdf	10 November 2017	M20-9983245	M20-061030W3045	HF159-W.pdf
M20-9983046	M20-998 obsolete.pdf	10 November 2017	M20-9983246	M20-061030W3046	HF159-W.pdf
M20-9983145	M20-998 obsolete.pdf	10 November 2017	M20-9983245	M20-061030W3145	HF159-W.pdf
M20-9983146	M20-998 obsolete.pdf	10 November 2017	M20-9983246	M20-061030W3146	HF159-W.pdf
M20-9983345	M20-998 obsolete.pdf	10 November 2017	M20-9983645	M20-061030W3345	HF159-W.pdf
M20-9983346	M20-998 obsolete.pdf	10 November 2017	M20-9983646	M20-061030W3346	HF159-W.pdf
M20-9983445	M20-998 obsolete.pdf	10 November 2017	M20-9983645	M20-061030W3445	HF159-W.pdf

Obsolete Product Notification from Harwin

Part number being made obsolete	Drawing for obsolete product	Last Time Buy date	Nearest standard alternative	Pin Header Variant alternative product (made-to-order)	Drawing for Pin Header Variant alternative product
M20-9983446	M20-998_obsolete.pdf	10 November 2017	M20-9983646	M20-061030W3446	HF159-W.pdf
M20-9983545	M20-998_obsolete.pdf	10 November 2017	M20-9983645	M20-061030W3545	HF159-W.pdf
M20-9983546	M20-998_obsolete.pdf	10 November 2017	M20-9983646	M20-061030W3546	HF159-W.pdf
M20-9983745	M20-998_obsolete.pdf	10 November 2017	M20-9984045	M20-061030W3745	HF159-W.pdf
M20-9983746	M20-998_obsolete.pdf	10 November 2017	M20-9984046	M20-061030W3746	HF159-W.pdf
M20-9983845	M20-998_obsolete.pdf	10 November 2017	M20-9984045	M20-061030W3845	HF159-W.pdf
M20-9983846	M20-998_obsolete.pdf	10 November 2017	M20-9984046	M20-061030W3846	HF159-W.pdf
M20-9983945	M20-998_obsolete.pdf	10 November 2017	M20-9984045	M20-061030W3945	HF159-W.pdf
M20-9983946	M20-998_obsolete.pdf	10 November 2017	M20-9984046	M20-061030W3946	HF159-W.pdf
M20-9992145	M20-999_obsolete.pdf	10 November 2017	M20-9992345	M20-061030V2145	HF159-V.pdf
M20-9992146	M20-999_obsolete.pdf	10 November 2017	M20-9992346	M20-061030V2146	HF159-V.pdf
M20-9992245	M20-999_obsolete.pdf	10 November 2017	M20-9992345	M20-061030V2245	HF159-V.pdf
M20-9992246	M20-999_obsolete.pdf	10 November 2017	M20-9992346	M20-061030V2246	HF159-V.pdf
M20-9992445	M20-999_obsolete.pdf	10 November 2017	M20-9992545	M20-061030V2445	HF159-V.pdf
M20-9992446	M20-999_obsolete.pdf	10 November 2017	M20-9992546	M20-061030V2446	HF159-V.pdf
M20-9992645	M20-999_obsolete.pdf	10 November 2017	M20-9993045	M20-061030V2645	HF159-V.pdf
M20-9992646	M20-999_obsolete.pdf	10 November 2017	M20-9993046	M20-061030V2646	HF159-V.pdf
M20-9992745	M20-999_obsolete.pdf	10 November 2017	M20-9993045	M20-061030V2745	HF159-V.pdf
M20-9992746	M20-999_obsolete.pdf	10 November 2017	M20-9993046	M20-061030V2746	HF159-V.pdf
M20-9992845	M20-999_obsolete.pdf	10 November 2017	M20-9993045	M20-061030V2845	HF159-V.pdf
M20-9992846	M20-999_obsolete.pdf	10 November 2017	M20-9993046	M20-061030V2846	HF159-V.pdf
M20-9992945	M20-999_obsolete.pdf	10 November 2017	M20-9993045	M20-061030V2945	HF159-V.pdf
M20-9992946	M20-999_obsolete.pdf	10 November 2017	M20-9993046	M20-061030V2946	HF159-V.pdf
M20-9993445	M20-999_obsolete.pdf	10 November 2017	M20-9993645	M20-061030V3445	HF159-V.pdf
M20-9993446	M20-999_obsolete.pdf	10 November 2017	M20-9993646	M20-061030V3446	HF159-V.pdf
M20-9993545	M20-999_obsolete.pdf	10 November 2017	M20-9993645	M20-061030V3545	HF159-V.pdf
M20-9993546	M20-999_obsolete.pdf	10 November 2017	M20-9993646	M20-061030V3546	HF159-V.pdf
M20-9993745	M20-999_obsolete.pdf	10 November 2017	M20-9994045	M20-061030V3745	HF159-V.pdf
M20-9993746	M20-999_obsolete.pdf	10 November 2017	M20-9994046	M20-061030V3746	HF159-V.pdf
M20-9993845	M20-999_obsolete.pdf	10 November 2017	M20-9994045	M20-061030V3845	HF159-V.pdf
M20-9993846	M20-999_obsolete.pdf	10 November 2017	M20-9994046	M20-061030V3846	HF159-V.pdf
M20-9993945	M20-999_obsolete.pdf	10 November 2017	M20-9994045	M20-061030V3945	HF159-V.pdf
M20-9993946	M20-999_obsolete.pdf	10 November 2017	M20-9994046	M20-061030V3946	HF159-V.pdf