

CUSTOMER OPERATIONS 160 RIO ROBLES SAN JOSE, CA 95134 PDN #: M001102I

DATE: 05-Feb-2024

## PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommeded Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	01-00680	N/A	03-Feb-2025	06-Aug-2025	Part can no longer be manufactured
Discontinuance	01-00768	N/A	03-Feb-2025	06-Aug-2025	Part can no longer be manufactured
Discontinuance	01-00769	N/A	03-Feb-2025	06-Aug-2025	Part can no longer be manufactured
Discontinuance	01-00770	N/A	03-Feb-2025	06-Aug-2025	Part can no longer be manufactured
Discontinuance	01-00771	N/A	03-Feb-2025	06-Aug-2025	Part can no longer be manufactured
Discontinuance	01-00772	N/A	03-Feb-2025	06-Aug-2025	Part can no longer be manufactured
Discontinuance	02-00181	N/A	03-Feb-2025	06-Aug-2025	Part can no longer be manufactured
Discontinuance	DS2413X+U	N/A	03-Feb-2025	06-Aug-2025	Part can no longer be manufactured
Discontinuance	DS2413X-S+T	N/A	03-Feb-2025	06-Aug-2025	Part can no longer be manufactured
Discontinuance	DS28C36AQ+T	N/A	03-Feb-2025	06-Aug-2025	Part can no longer be manufactured
Discontinuance	DS28C36AQ+U	N/A	03-Feb-2025	06-Aug-2025	Part can no longer be manufactured
Discontinuance	DS28EL15Q-W44+1T	N/A	03-Feb-2025	06-Aug-2025	Part can no longer be manufactured
Discontinuance	DS28EL15Q-W44+1U	N/A	05-Feb-2024	05-Feb-2024	The part was not released
Discontinuance	MAX161CEWI+	N/A	03-Feb-2025	06-Aug-2025	Part can no longer be manufactured
Discontinuance	MAX16931ATLS/V+	N/A	03-Feb-2025	06-Aug-2025	Part can no longer be manufactured
Discontinuance	MAX16931ATLS/V+T	N/A	03-Feb-2025	06-Aug-2025	Part can no longer be manufactured
Discontinuance	MAX20800T-A00+	N/A	05-Feb-2024	05-Feb-2024	The part was not released
Discontinuance	MAX274AEWI+C01046	N/A	03-Feb-2025	06-Aug-2025	Part can no longer be manufactured
Discontinuance	MAX40010LAWT+	N/A	03-Feb-2025	06-Aug-2025	Part can no longer be manufactured
Discontinuance	MAX40010LAWT+T	N/A	03-Feb-2025	06-Aug-2025	Part can no longer be manufactured
Discontinuance	MAX44284FAZT+	N/A	03-Feb-2025	06-Aug-2025	Part can no longer be manufactured
Discontinuance	MAX44284FAZT+T	N/A	03-Feb-2025	06-Aug-2025	Part can no longer be manufactured
Discontinuance	MAX4559CPE+	N/A	03-Feb-2025	06-Aug-2025	Part can no longer be manufactured
Discontinuance	MAX5409EEE+	N/A	03-Feb-2025	06-Aug-2025	Part can no longer be manufactured
Discontinuance	MAX5409EEE+T	N/A	03-Feb-2025	06-Aug-2025	Part can no longer be manufactured
Discontinuance	MAX5855EXE+	N/A	03-Feb-2025	06-Aug-2025	Part can no longer be manufactured

Discontinuance	MAX5855EXE+T	N/A	03-Feb-2025	06-Aug-2025	Part can no longer be manufactured
Discontinuance	MAX6301CUA+CLH	N/A	03-Feb-2025	06-Aug-2025	Part can no longer be manufactured
Discontinuance	MAX6301CUA+TCLH	N/A	03-Feb-2025	06-Aug-2025	Part can no longer be manufactured
Discontinuance	MAX6316MUK47BY+	N/A	03-Feb-2025	06-Aug-2025	Part can no longer be manufactured
Discontinuance	MAX6316MUK47BY+T	N/A	03-Feb-2025	06-Aug-2025	Part can no longer be manufactured
Discontinuance	MAX6385XS29D3+	N/A	03-Feb-2025	06-Aug-2025	Part can no longer be manufactured
Discontinuance	MAX6385XS29D3+T	N/A	03-Feb-2025	06-Aug-2025	Part can no longer be manufactured
Discontinuance	MAX6845UKD3+	N/A	03-Feb-2025	06-Aug-2025	Part can no longer be manufactured
Discontinuance	MAX6845UKD3+T	N/A	03-Feb-2025	06-Aug-2025	Part can no longer be manufactured
Discontinuance	MAX6864UK31D1S+	N/A	03-Feb-2025	06-Aug-2025	Part can no longer be manufactured
Discontinuance	MAX6864UK31D1S+T	N/A	03-Feb-2025	06-Aug-2025	Part can no longer be manufactured
Discontinuance	MAX9120ESA+	N/A	03-Feb-2025	06-Aug-2025	Part can no longer be manufactured
Discontinuance	MAX9120ESA+T	N/A	03-Feb-2025	06-Aug-2025	Part can no longer be manufactured
Discontinuance	MAX98373EWA+CPP	N/A	03-Feb-2025	06-Aug-2025	Part can no longer be manufactured
Discontinuance	MAX98373EWA+TCPP	N/A	03-Feb-2025	06-Aug-2025	Part can no longer be manufactured
Discontinuance	MX7538KN+	N/A	03-Feb-2025	06-Aug-2025	Part can no longer be manufactured
Discontinuance	VT253FQ-ADJ	N/A	03-Feb-2025	06-Aug-2025	Part can no longer be manufactured
Discontinuance	VT254AFQ-ADJ	N/A	03-Feb-2025	06-Aug-2025	Part can no longer be manufactured
Discontinuance	VT254AFQ-ADJ-008	N/A	03-Feb-2025	06-Aug-2025	Part can no longer be manufactured