

PDN.PG91.10.24.2023 TA/TPF/TQC Series Affected Parts

Affected Series	Affected Part Numbers	Suggested Replacement Series	Suggested Replacement Part Numbers	Comments
TA	10TAE68M	TV	10TVE68M	
TPF	2R5TPF330M7L	TPF	2R5TPF470M7L	
TQC	16TQC10M	TQC	35TQC10MYFB	
TQC	16TQC47MW	TQC	16TQC47MYFD	
TQC	20TQC8R2M	TQC	35TQC10MYFB	
TQC	25TQC15MV	TQC	25TQC15MYFD	
TQC	25TQC22MV	TQC	25TQC22MYFD	
TQC	25TQC5R6M	TQC	35TQC10MYFB	
TQC	35TQC3R9MYF	TQC	35TQC10MYFB	