

8755 W. Higgins Road Suite 500

www.littelfuse.com

Chicago, IL 60631

To: Littelfuse Sales, Sales Support & Valued Customers

From: Littelfuse Product Management - Industrial Business Unit

Subject: 0LD & 0LS series part numbers obsolescence with replacements.

Document Number: LFPCN_PG0181

Date: 22nd March 2024

This notice is to inform Littelfuse Sales, Sales Support & Customers of the obsolescence of 0LD & 0LS series part numbers, these products are replaced by new part numbers listed below in Annexure A. Few part numbers don't have replacements. Please note these parts are addition to the earlier list we circulated by LFPCN_PG0167

This change is done due to the UL508A standards new requirement of listed product, product simplification and elimination of non-recyclable product lines.

This is a running change effective from October 2023.

Last time buy for the old part numbers will be 28th June 2024, at this time all remaining orders must be booked. Please note any existing orders will be honored. All orders received during this time for old part numbers will be non-cancellable and non-returnable (NC&NR).

Thank you for your continued business. If you have any questions, or need additional information please contact your Littelfuse representative.

Sincerely.

Prashant Kulkarni

Associate Product Manager Industrial Business Unit Littelfuse, Inc. Mobile: +91 9890937472

Email: pkulkarni@littelfuse.com

www.littelfuse.com

Annexure A:

| Old part number | New part number |
|-----------------|-----------------|
| 0LD04022Z | 0LD25702ZXDIN |
| 0LD29702Z | 0LD25702ZXDIN |
| 0LD04012Z | 0LD25702ZXDIN |
| 0LD35522Z | 0LD45531ZX (2X) |
| 0LD35532Z | 0LD45531ZX (2X) |
| 0LD35552Z | 0LD45551ZX (2X) |
| 0LD59861Z | No replacement |
| 0LD59862Z | No replacement |
| 0LS31233Z | 0LS45823ZX |
| 0LD59921Z | No replacement |
| 0LD59922Z | No replacement |