

Product Withdrawal Notice

To	Anglia Components Ltd.
From	Samsung Electro-Mechanics CO.,LTD. Strategic Marketing Center
Subject	EOL(End of Life) of MLCC models
Date	June 26 th , 2020

Dear. Valued customers,

Thank you very much for your great and continued support for business with SEMCO.
 This is the official notification that some of products will be discontinued as detailed below.
 Please review this, and indicate your feedback for this Notice in writing by Feedback Due.

Products	<i>Multilayer Ceramic Capacitor for General Purpose</i>
Product type	MLCC models designated in the attached parts list
Part Number	Please refer to the attached part list
Reasons	The demand for these targeted items has been decreasing, which makes it difficult to maintain their production continuously. We would like to stop the production of these items and focus on providing a more stable supply & Production of other MLCC (different value) in the future.
Withdrawal Schedule	Feedback Due: September 30, 2020 Last Time Order Due (*): November. 30, 2020 Last Production Date: May. 31, 2021 Last Shipment Date: Jun. 30, 2021 (*) Last Time Buy order is subject to Minimum Order Quantity and Package Quantity. Order Cancellation and Product Return will be accepted only in the case of quality issue. LTB is only available for the items which have supported within 1 year
Reply from Customers	Product Withdrawal detailed below is <input type="checkbox"/> subject to further Discussion. <input type="checkbox"/> Accepted. Product Type: Multilayer Ceramic Capacitor for General Purpose Last Time Order Due: November. 30, 2020
Comments, Question, Request, etc.	
Contact Window	Sales : frank.goebel@samsung.com

If you have any question or requirement regarding this Product Withdrawal Notice, please feel free to contact us.

Truly Yours;
Thank you.

Samsung Electro Mechanics Co., Ltd.

Title: Marketing Team Leader

Name: Peter Kim



Appendix #1

Affected Products List	
SEMCO Part Number (14 Digit)	Remark
CL02C120JO2NNN	
CL02C150JO2NNN	
CL02C470JO2NNN	
CL02C560JQ2ANN	
CL02C8R2DO2ANN	
CL03A103KO3NNN	
CL03A103KQ3N1N	
CL03A103KQ3NNN	
CL03A104KA3NN5	
CL03A104KP3NN5	
CL03A104KQ3NN5	
CL03A105MP3NS5	
CL03A105MQ3CS5	
CL03A223KP3NNN	
CL03A224MP3NNN	
CL03A333KQ3NNN	
CL03A473KP3NN5	
CL03A473KQ3NNX	
CL03A474MP3NNN	
CL03A474MR3NNN	
CL03B222KP3NNN	
CL03B331KO3NNN	
CL03B471KO3NN5	
CL03B472KP3NNN	
CL03B681JA3NNN	
CL03C020CA3GNN	
CL03C030CA3GNN	
CL03C090DA3GNN	
CL03C0R5BA3GNX	
CL03C101JA3ANN	
CL03C120GA3GNN	
CL03C120JA3GN5	
CL03C150JA3GNN	

Affected Products List	
SEMCO Part Number (14 Digit)	Remark
CL03C180GA3GNN	
CL03C1R5BA3GNN	
CL03C1R5CA3GN5	
CL03C3R3BA3GNN	
CL03C3R3CA3GNN	
CL03C3R9CA3GNN	
CL03C4R7BA3GNN	
CL03C4R7CA3GN5	
CL03C5R6BA3GNX	
CL03C8R2DA3GNN	
CL03X104KR3NNN	
CL05A104MP5NNN	
CL05A105KO5NN5	
CL05A105KP5NN5	
CL05A105KQ5NNX	
CL05A105MO5NNN	
CL05A105MP5NNN	
CL05A105MQ3LNN	
CL05A106MP5NUX	
CL05A106MR5NRN	
CL05A224MQ5NNN	
CL05A225KP5NS5	
CL05A225MQ5N1N	
CL05A334KP5NNN	
CL05A473KP5NNN	
CL05A475KP5NR5	
CL05A475MQ5NQN	
CL05A684KQ5NNN	
CL05A999XQ5NSN	
CL05B102KA5NNN	
CL05B102KO5NNN	
CL05B103JA5NNN	
CL05B103JB5NNN	

Affected Products List	
SEMCO Part Number (14 Digit)	Remark
CL05B103KP5NNN	
CL05B103MO5NNN	
CL05B104JP5NNN	
CL05B104KO5NN5	
CL05B122KB5NNN	
CL05B123KA5NNN	
CL05B123KO5NNN	
CL05B153KA5NNN	
CL05B153KO5NNN	
CL05B154KO5NNN	
CL05B183KO5NNN	
CL05B271KB5NNN	
CL05B332JB5NNN	
CL05B332KA5NNN	
CL05B333KA5NNN	
CL05B333KP5NNN	
CL05B392JB5NNN	
CL05B393KO5NNN	
CL05B471JB5NNN	
CL05B472JA5NNN	
CL05B472KO5NNN	
CL05B561KB5NNN	
CL05B563KO5NNN	
CL05B821KB5NNN	
CL05B823KO5NNN	
CL05C020BB5NNN	
CL05C020CB5NNN	
CL05C030BB5NNN	
CL05C030CB5NNN	
CL05C040BB5NNN	
CL05C040CB5NNN	
CL05C040CB5NNP	
CL05C080DB5NNN	

Affected Products List	
SEMCO Part Number (14 Digit)	Remark
CL05C0R5CB5NNN	
CL05C101JB5NN5	
CL05C102JA5NNN	
CL05C130JB5NNN	
CL05C160JB5NNN	
CL05C1R5CB5NNN	
CL05C1R8CB5NNN	
CL05C200JB5NNN	
CL05C221JA5NNN	
CL05C270FB5NNN	
CL05C2R2CB5NNN	
CL05C2R7CB5NNN	
CL05C300JB5NNN	
CL05C300JB5NNP	
CL05C3R9BB5NNN	
CL05C471JO5NNN	
CL05C4R3CB5NNN	
CL05C4R7BB5NNN	
CL05C510JB5NNN	
CL05C561JB5NNN	
CL05C5R6CB5NNN	
CL05C6R8BB5NNN	
CL05C6R8DB5NNN	
CL05C8R2BB5NNN	
CL05C8R2DB5NNN	
CL05CR75CB5NNN	
CL05F103ZB5NNN	
CL05F104ZA5NNN	
CL05X475MQ5NUN	
CL05X684JQ5NNN	
CL10A105KA5LNN	
CL10A105KO5LNN	
CL10A105MA8NNN	

Affected Products List	
SEMCO Part Number (14 Digit)	Remark
CL10A105MP8NNN	
CL10A105MQ8NNN	
CL10A106KP8NN5	
CL10A106MQ5LRN	
CL10A224KA8NNN	
CL10A225KP8NN5	
CL10A225MQ8NNN	
CL10A335MQ8NNN	
CL10A474KP8NNN	
CL10A475MP5LNN	
CL10A475MP8NNN	
CL10A475MQ5LNN	
CL10B101KB8NNN	
CL10B102JB8NNN	
CL10B102KA8NNN	
CL10B102KB8NN5	
CL10B102MB8NNN	
CL10B103JB8NNN	
CL10B103KB8NCN	
CL10B103KB8SFN	
CL10B104JO8NNN	
CL10B104MA8NNN	
CL10B104MO8NNN	
CL10B105KA8SFN	
CL10B106KQ8NRN	
CL10B122KB8NPN	
CL10B124KO8NNN	
CL10B152JB8NNN	
CL10B153JB8NNN	
CL10B154KA8NNN	
CL10B154KA8SFN	
CL10B181KB8NNN	
CL10B182KB8NNN	

Affected Products List	
SEMCO Part Number (14 Digit)	Remark
CL10B182KB8NNP	
CL10B183KB8NNN	
CL10B183KB8NNP	
CL10B222JB8NNN	
CL10B222KC8NNN	
CL10B223JB8NNN	
CL10B223KA8NNN	
CL10B224KP8NNN	
CL10B271KB8NNN	
CL10B332JB8NNN	
CL10B332KB8SFN	
CL10B333JB8NNN	
CL10B333KA8NNN	
CL10B333KO8NNN	
CL10B472JB8NNN	
CL10B473KA8NNN	
CL10B561KB8NNN	
CL10B563KB8NNN	
CL10B681KB8NNN	
CL10B683KO8NNN	
CL10B684KO8NNN	
CL10B751KB8NNN	
CL10B821KB8NNN	
CL10B822KB8NNN	
CL10B823KB8NNN	
CL10C010CB8NNN	
CL10C020BB8NNN	
CL10C030BB8NNN	
CL10C030CB8NNN	
CL10C050CB8NNN	
CL10C060CB8NNN	
CL10C080CB8NNN	
CL10C080DB8NNN	

Affected Products List	
SEMCO Part Number (14 Digit)	Remark
CL10C090CB8NNN	
CL10C090DB8NNN	
CL10C0R2BB8NNN	
CL10C0R3CB8NNN	
CL10C0R5BB8NNN	
CL10C100DB8NNN	
CL10C101FB8NNN	
CL10C101KB8NNN	
CL10C103JA8NNN	
CL10C120FB8NNN	
CL10C131JB8NNN	
CL10C150JC8NNN	
CL10C160JB8NNN	
CL10C180FB8NNN	
CL10C1R2BB8NNN	
CL10C1R2CB8NNN	
CL10C1R5BB8NNN	
CL10C1R5CB8NNN	
CL10C1R8CB8NNN	
CL10C220FB8NNN	
CL10C221JC8NNN	
CL10C240JB8NNN	
CL10C271FB8NNN	
CL10C2R2BB8NNN	
CL10C2R5CB8NNN	
CL10C2R7BB8NNN	
CL10C2R7CB8NNN	
CL10C300JB8NNN	
CL10C301JB8NNN	
CL10C330JC8NNN	
CL10C360JB8NNN	
CL10C390JB8NNN	
CL10C390JB8NNP	

Affected Products List	
SEMCO Part Number (14 Digit)	Remark
CL10C391JB8NNN	
CL10C3R3BB8NNN	
CL10C3R3CB8NNN	
CL10C3R9BB8NNN	
CL10C3R9CB8NNN	
CL10C470KB8NNN	
CL10C471FB8NNN	
CL10C4R3CB8NNN	
CL10C4R7CB8NNN	
CL10C5R6CB8NNN	
CL10C680FB8NNN	
CL10C6R8BB8NNN	
CL10C6R8DB8NNN	
CL10C750JB8NNN	
CL10C820FB8NNN	
CL10C820JB8NNN	
CL10C820JB8NNP	
CL10C821JB8NNN	
CL10C8R2BB8NNN	
CL10C8R2CB8NNN	
CL10CR47BB8NNN	
CL10CR68BB8NNN	
CL10CR75BB8NNN	
CL10CR82BB8NNN	
CL10F105ZO8NNN	
CL10F105ZP8NNN	
CL10F224ZA8NNN	
CL10F224ZB8NNN	
CL10F224ZO8NNN	
CL10F473ZA8NNN	
CL10F473ZB8NNN	
CL10F474ZB8NNN	
CL10J225KO8N3P	

Affected Products List	
SEMCO Part Number (14 Digit)	Remark
CL10X105KA8NNN	
CL10X106MR8N6O	
CL21A105KAFNNN	
CL21A105KBFNNN	
CL21A105KOFNNN	
CL21A106KQ7LQN	
CL21A106KQQNNN	
CL21A106MOQNNN	
CL21A225KQFNNN	
CL21A226MAIUNN	
CL21A226MAQNNP	
CL21A226MAYN1N	
CL21A226MPCLR5	
CL21A226MQCLQN	
CL21A335KOFNNN	
CL21A475KQQNNN	
CL21A476MQMNRN	
CL21B102JBANNN	
CL21B102KDCNNN	
CL21B103JBANNN	
CL21B104JBCNNN	
CL21B104MBCNNN	
CL21B123KBANNN	
CL21B151KBANNN	
CL21B152KBANNN	
CL21B153KBANNN	
CL21B155KAFNNN	
CL21B182KBANNN	
CL21B221KBANNN	
CL21B221KCANNN	
CL21B222KCANNN	
CL21B222KDCNNN	
CL21B223KBCNNN	

Affected Products List	
SEMCO Part Number (14 Digit)	Remark
CL21B224KOCNNN	
CL21B225KAFN3N	
CL21B225KBYNNN	
CL21B271KBANNN	
CL21B331KBANNN	
CL21B332KBANFN	
CL21B332KBANNN	
CL21B333JBANNN	
CL21B333KBANNN	
CL21B334KAFNNN	
CL21B335KAFNNN	
CL21B391KBANNN	
CL21B471KBANNN	
CL21B471KCANNN	
CL21B471KDCNNN	
CL21B472JBANNN	
CL21B472KCANNN	
CL21B473JBCNNN	
CL21B473KBANNN	
CL21B475KQFNNN	
CL21B475KQQNNN	
CL21B561KBANNN	
CL21B681KBANNN	
CL21B682JBANNN	
CL21B682KBANNN	
CL21B683KBCNNN	
CL21B684KOFNNN	
CL21B821KBANNN	
CL21C010CBANNN	
CL21C020CBANNN	
CL21C0R5BBANNN	
CL21C0R5CBANNN	
CL21C100DBANNN	

Affected Products List	
SEMCO Part Number (14 Digit)	Remark
CL21C100JBANN	
CL21C100JCANN	
CL21C101GBANN	
CL21C102JBCNN	
CL21C120JBANN	
CL21C121JBANN	
CL21C150JBANN	
CL21C150JCANN	
CL21C151JCANN	
CL21C152JBFNN	
CL21C180JBANN	
CL21C220JCANN	
CL21C221JCANN	
CL21C221KBANN	
CL21C270GBANN	
CL21C270JBANN	
CL21C2R2CBANN	
CL21C300JBANN	
CL21C330JBANN	
CL21C330JCANN	
CL21C331JBANN	
CL21C332JBFNN	
CL21C3R3BBANN	
CL21C3R3CBANN	
CL21C3R9BBANN	
CL21C471JBANN	
CL21C471JCCNN	
CL21C4R7CBANN	
CL21C560JBANN	
CL21C561JBANN	
CL21C680JBANN	
CL21C681JBCNN	
CL21C820JBANN	

Affected Products List	
SEMCO Part Number (14 Digit)	Remark
CL21C821JBCNNN	
CL21C8R2CBANNN	
CL21F104ZBCNNN	
CL21F105ZBFNNP	
CL21F105ZOCNNN	
CL21F105ZOFNNN	
CL21F224ZBFNNN	
CL21F225ZAFNNN	
CL21F474ZBFNNN	
CL21F475ZOFNNN	
CL21X106MAYNNN	
CL21X226MQQN6O	
CL31A106MPHNNN	
CL31A225KAHNNN	
CL31A225KBHNNN	
CL31A475KPHNNN	
CL31B102KCCNNN	
CL31B102KHFNNN	
CL31B103JBCNNN	
CL31B103KBCNNN	
CL31B103KCCNNN	
CL31B103KDCNNN	
CL31B103KGFNNN	
CL31B104JBCNNN	
CL31B104KDHNNN	
CL31B104KEHSNN	
CL31B106KAHSNN	
CL31B153KBCNNN	
CL31B222KBCNNN	
CL31B222KGFNNN	
CL31B222KHFNNN	
CL31B223JBCNNN	
CL31B223KBCNNN	

Affected Products List	
SEMCO Part Number (14 Digit)	Remark
CL31B223KDCNNN	
CL31B224JBFNNN	
CL31B332KGFNNN	
CL31B333KBCNNN	
CL31B471KBCNNN	
CL31B472KBCNNN	
CL31B472KGFNNN	
CL31B473KCCNNN	
CL31B473KDFNNN	
CL31B474KAFNNN	
CL31B475KBHNNF	
CL31B684KBHNNN	
CL31C101JBCNNN	
CL31C101JCCNNN	
CL31C102GBCNNN	
CL31C102JBCNNN	
CL31C102JCCNNN	
CL31C102JGHNNN	
CL31C151JBCNNN	
CL31C272JBFNNN	
CL31C330JBCNNN	
CL31C330JJHNNN	
CL31C331JGFNNN	
CL31C470JBCNNN	
CL31C471JBCNNN	
CL31C472JBFNNN	
CL31C680JBCNNN	
CL31F106ZOHNNN	
CL31F106ZPENNN	
CL31F226ZPHNNN	
CL32A106KA9LNN	
CL32A106MLULNN	
CL32A226MAJNNP	

Affected Products List	
SEMCO Part Number (14 Digit)	Remark
CL32A475KAULNN	
CL32A476MPJNNN	
CL32B102KJFNNN	
CL32B104KBFNNN	
CL32B104KCFNNN	
CL32B104KCFNNW	
CL32B223KGFNNN	
CL32B224KBFNNN	
CL32B224KCHNNN	
CL32B226MAJNNN	
CL32B334KBFNNN	
CL32B474JBFNNN	
CL32C103JBFNNN	
CLL5Z105MS3NLN	
CLL6A435MR4NLN	

- End of document