

10 July 2017

Dear Customer

We have been advised by the Taicom factory that the tooling used for crimp socket **TM4014** is broken and has gone beyond its serviceable life. Unfortunately, it is not commercially viable to repair or open a new tool.

There is no direct replacement but we recommend moving over to part number **TM4012** which is the same except that it has a wire gauge of 18-24 AWG instead of 16-22 AWG for the EOL Part.

We have limited stocks of **TM4014** available on a first come first served basis until the stocks have been exhausted, please contact our sales desk with your requirement. Samples of **TM4012** are now available.

Please make the relevant person(s) in your purchasing and engineering departments aware of this change to prevent disruption to your production schedule.

Yours Sincerely

Anglia