

OFFICIAL ANNOUNCEMENT
- Discontinuation Note -

TOSHIBA

Please find the **official announcement** that TOSHIBA, in line with previous verbal information, will stop all promotion and sales activities for products in following attachment (69 pages / 2429 items worldwide / 257 items active in TEE)

Related products:

BU	P/N	Discon- tinue	Phase-Out = Last date of order entry	Obsolete = Last date of delivery	Substi- tution	Replacement Company	Replacement P/N	Reason	Active in TEE
X35	100EXG15	202004	202104	202110	3	KYOCERA	120FLCS300	4	
X35	100EXH15	202004	202104	202110	3	KYOCERA	120FLCS300	4	
X33	2SJ360(F)	202004	202104	202110	3	TOSHIBA	SSM3J356R	2	
X33	2SJ360(T2LASTI,F)	202004	202104	202110	3	TOSHIBA	SSM3J356R	2	
X33	2SJ360(T2LATUM,F)	202004	202104	202110	3	TOSHIBA	SSM3J356R	2	
X33	2SJ360(T2LFURUKA,F)	202004	202104	202110	3	TOSHIBA	SSM3J356R	2	
X33	2SJ360(T2LHILX,F)	202004	202104	202110	3	TOSHIBA	SSM3J356R	2	
X33	2SJ360(T2LIMASEN,F)	202004	202104	202110	3	TOSHIBA	SSM3J356R	2	
X33	2SJ360(T2LMBS-S,F)	202004	202104	202110	3	TOSHIBA	SSM3J356R	2	
X33	2SJ360(T2LMBSSM,F)	202004	202104	202110	3	TOSHIBA	SSM3J356R	2	
X33	2SJ360(T2LPANA,F)	202004	202104	202110	3	TOSHIBA	SSM3J356R	2	
X33	2SJ360(T2LPED,F)	202004	202104	202110	3	TOSHIBA	SSM3J356R	2	
X33	2SJ360(T2LPED-WA,F)	202004	202104	202110	3	TOSHIBA	SSM3J356R	2	
X33	2SJ360(T2LPSDS,F)	202004	202104	202110	3	TOSHIBA	SSM3J356R	2	
X33	2SJ360(T2LPSN,F)	202004	202104	202110	3	TOSHIBA	SSM3J356R	2	
X33	2SJ360(T2LRT,F)	202004	202104	202110	3	TOSHIBA	SSM3J356R	2	
X33	2SJ360(T2LSACOM,F)	202004	202104	202110	3	TOSHIBA	SSM3J356R	2	
X33	2SJ360(T2LSEP,F)	202004	202104	202110	3	TOSHIBA	SSM3J356R	2	
X33	2SJ360(T2LSONY,F)	202004	202104	202110	3	TOSHIBA	SSM3J356R	2	
X33	2SJ360(T2LSUZUKI,F)	202004	202104	202110	3	TOSHIBA	SSM3J356R	2	
X33	2SJ360(T2LTOJS,F)	202004	202104	202110	3	TOSHIBA	SSM3J356R	2	
X33	2SJ360(T2LTOYOG,F)	202004	202104	202110	3	TOSHIBA	SSM3J356R	2	

X33	2SJ360(T2LVALEO,ZF	202004	202104	202110	3	TOSHIBA	SSM3J356R	2	Y
X33	2SJ360(T2LYNS,F)	202004	202104	202110	3	TOSHIBA	SSM3J356R	2	
X33	2SJ360(T2RALPSTK,F	202004	202104	202110	3	TOSHIBA	SSM3J356R	2	
X33	2SJ360(T2ROME,F)	202004	202104	202110	3	TOSHIBA	SSM3J356R	2	
X33	2SJ360(TE12L,F)	202004	202104	202110	3	TOSHIBA	SSM3J356R	2	Y
X33	2SJ360(TE12R,F)	202004	202104	202110	3	TOSHIBA	SSM3J356R	2	Y
X33	2SJ377(T6L1AD,NQ)	202004	202104	202110	2	TOSHIBA	TJ8S06M3L	2	
X33	2SJ377(T6L1AISI,NQ	202004	202104	202110	2	TOSHIBA	TJ8S06M3L	2	
X33	2SJ377(T6L1CANO,NQ	202004	202104	202110	2	TOSHIBA	TJ8S06M3L	2	
X33	2SJ377(T6L1FJTN,NQ	202004	202104	202110	2	TOSHIBA	TJ8S06M3L	2	Y
X33	2SJ377(T6L1MDN,NQ)	202004	202104	202110	2	TOSHIBA	TJ8S06M3L	2	
X33	2SJ377(T6L1ND,NQ)	202004	202104	202110	2	TOSHIBA	TJ8S06M3L	2	
X33	2SJ377(T6L1NLS,NQ)	202004	202104	202110	2	TOSHIBA	TJ8S06M3L	2	
X33	2SJ377(T6L1NS,NQ)	202004	202104	202110	2	TOSHIBA	TJ8S06M3L	2	
X33	2SJ377(T6L1PCC,NQ)	202004	202104	202110	2	TOSHIBA	TJ8S06M3L	2	
X33	2SJ377(T6L1PP,NQ)	202004	202104	202110	2	TOSHIBA	TJ8S06M3L	2	
X33	2SJ377(T6L1PSD,NQ)	202004	202104	202110	2	TOSHIBA	TJ8S06M3L	2	
X33	2SJ377(T6L1SMC,NQ)	202004	202104	202110	2	TOSHIBA	TJ8S06M3L	2	
X33	2SJ377(T6L1SUMISNQ	202004	202104	202110	2	TOSHIBA	TJ8S06M3L	2	
X33	2SJ377(T6L1TOJS,NQ	202004	202104	202110	2	TOSHIBA	TJ8S06M3L	2	
X33	2SJ377(T6L1TOLT,NQ	202004	202104	202110	2	TOSHIBA	TJ8S06M3L	2	
X33	2SJ377(T6L1TOYOGNQ	202004	202104	202110	2	TOSHIBA	TJ8S06M3L	2	
X33	2SJ377(T6L1YAZK,NQ	202004	202104	202110	2	TOSHIBA	TJ8S06M3L	2	
X33	2SJ377(TE16L1,NQ)	202004	202104	202110	2	TOSHIBA	TJ8S06M3L	2	Y
X33	2SJ377(TE16R1,NQ)	202004	202104	202110	2	TOSHIBA	TJ8S06M3L	2	
X33	2SJ439(TE16L1,NQ)	202004	202104	202110	3	TOSHIBA	SSM6J424TU	2	
X33	2SJ465(T2LDNSO,F)	202004	202104	202110	3	TOSHIBA	SSM6J422TU	2	
X33	2SJ511(T2LAD,F)	202004	202104	202110	3	TOSHIBA	SSM3J374R	2	
X33	2SJ511(T2LCANO,F)	202004	202104	202110	3	TOSHIBA	SSM3J374R	2	Y
X33	2SJ511(T2LDNSO,F)	202004	202104	202110	3	TOSHIBA	SSM3J374R	2	
X33	2SJ511(T2LHANSHINF	202004	202104	202110	3	TOSHIBA	SSM3J374R	2	
X33	2SJ511(T2LMATUD,F)	202004	202104	202110	3	TOSHIBA	SSM3J374R	2	
X33	2SJ511(T2LNKOD,F)	202004	202104	202110	3	TOSHIBA	SSM3J374R	2	
X33	2SJ511(T2LOMII,F)	202004	202104	202110	3	TOSHIBA	SSM3J374R	2	
X33	2SJ511(T2LPANA,F)	202004	202104	202110	3	TOSHIBA	SSM3J374R	2	
X33	2SJ511(T2LPP,F)	202004	202104	202110	3	TOSHIBA	SSM3J374R	2	

X33	2SJ511(T2LYAZK,F)	202004	202104	202110	3	TOSHIBA	SSM3J374R	2	Y
X33	2SJ511(TE12L,F)	202004	202104	202110	3	TOSHIBA	SSM3J374R	2	
X33	2SJ668(T6L1APN,NQ)	202004	202104	202110	2	TOSHIBA	TJ8S06M3L	2	
X33	2SJ668(T6L1ASN,NQ)	202004	202104	202110	2	TOSHIBA	TJ8S06M3L	2	
X33	2SJ668(T6L1ASN1,NQ)	202004	202104	202110	2	TOSHIBA	TJ8S06M3L	2	
X33	2SJ668(T6L1AST,NQ)	202004	202104	202110	2	TOSHIBA	TJ8S06M3L	2	
X33	2SJ668(T6L1CANO,NQ)	202004	202104	202110	2	TOSHIBA	TJ8S06M3L	2	
X33	2SJ668(T6L1DW,NQ)	202004	202104	202110	2	TOSHIBA	TJ8S06M3L	2	
X33	2SJ668(T6L1HNP,NQ)	202004	202104	202110	2	TOSHIBA	TJ8S06M3L	2	
X33	2SJ668(T6L1HTA,NQ)	202004	202104	202110	2	TOSHIBA	TJ8S06M3L	2	
X33	2SJ668(T6L1KOYO,NQ)	202004	202104	202110	2	TOSHIBA	TJ8S06M3L	2	
X33	2SJ668(T6L1MBS-SNQ)	202004	202104	202110	2	TOSHIBA	TJ8S06M3L	2	
X33	2SJ668(T6L1MTD,NQ)	202004	202104	202110	2	TOSHIBA	TJ8S06M3L	2	
X33	2SJ668(T6L1NET,NQ)	202004	202104	202110	2	TOSHIBA	TJ8S06M3L	2	
X33	2SJ668(T6L1N-JRC,Q)	202004	202104	202110	2	TOSHIBA	TJ8S06M3L	2	
X33	2SJ668(T6L1PP,NQ)	202004	202104	202110	2	TOSHIBA	TJ8S06M3L	2	
X33	2SJ668(T6L1PP1,NQ)	202004	202104	202110	2	TOSHIBA	TJ8S06M3L	2	
X33	2SJ668(T6L1ROM,NQ)	202004	202104	202110	2	TOSHIBA	TJ8S06M3L	2	
X33	2SJ668(T6L1SHRP,NQ)	202004	202104	202110	2	TOSHIBA	TJ8S06M3L	2	
X33	2SJ668(T6L1SONY,NQ)	202004	202104	202110	2	TOSHIBA	TJ8S06M3L	2	
X33	2SJ668(T6L1SUMISNQ)	202004	202104	202110	2	TOSHIBA	TJ8S06M3L	2	
X33	2SJ668(TE16L1,NQ)	202004	202104	202110	2	TOSHIBA	TJ8S06M3L	2	Y
X33	2SJ668(TE16R1,NQ)	202004	202104	202110	2	TOSHIBA	TJ8S06M3L	2	
X33	2SK1381(DSL,F)	202004	202104	202110	3	TOSHIBA	TK33S10N1L	2	
X33	2SK1381(F)	202004	202104	202110	3	TOSHIBA	TK33S10N1L	2	Y
X33	2SK1382(Q)	202004	202104	202110	3	TOSHIBA	TK33S10N1L	2	Y
X33	2SK2173(F)	202004	202104	202110	3	TOSHIBA	TK90S06N1L	2	Y
X33	2SK2201(T6L1OMI,NQ)	202004	202104	202110	2	TOSHIBA	TK11S10N1L	2	
X33	2SK2201(T6L1PP,NQ)	202004	202104	202110	2	TOSHIBA	TK11S10N1L	2	
X33	2SK2201(T6L1PP1,NQ)	202004	202104	202110	2	TOSHIBA	TK11S10N1L	2	
X33	2SK2201(T6L1PSD,NQ)	202004	202104	202110	2	TOSHIBA	TK11S10N1L	2	
X33	2SK2201(T6L1SUMINQ)	202004	202104	202110	2	TOSHIBA	TK11S10N1L	2	
X33	2SK2201(TE16L1,NQ)	202004	202104	202110	2	TOSHIBA	TK11S10N1L	2	Y
X33	2SK2231(6L1PSD1,NQ)	202004	202104	202110	2	TOSHIBA	TK25S06N1L	2	
X33	2SK2231(T6L1AD,NQ)	202004	202104	202110	2	TOSHIBA	TK25S06N1L	2	
X33	2SK2231(T6L1AISINQ)	202004	202104	202110	2	TOSHIBA	TK25S06N1L	2	

X33	2SK2231(T6L1APN,NQ	202004	202104	202110	2	TOSHIBA	TK25S06N1L	2	
X33	2SK2231(T6L1AUT,NQ	202004	202104	202110	2	TOSHIBA	TK25S06N1L	2	Y
X33	2SK2231(T6L1CNO,NQ	202004	202104	202110	2	TOSHIBA	TK25S06N1L	2	
X33	2SK2231(T6L1EPS,NQ	202004	202104	202110	2	TOSHIBA	TK25S06N1L	2	
X33	2SK2231(T6L1KO,NQ)	202004	202104	202110	2	TOSHIBA	TK25S06N1L	2	
X33	2SK2231(T6L1MTD,NQ	202004	202104	202110	2	TOSHIBA	TK25S06N1L	2	
X33	2SK2231(T6L1ND,NQ)	202004	202104	202110	2	TOSHIBA	TK25S06N1L	2	
X33	2SK2231(T6L1NSANNQ	202004	202104	202110	2	TOSHIBA	TK25S06N1L	2	
X33	2SK2231(T6L1SMC,NQ	202004	202104	202110	2	TOSHIBA	TK25S06N1L	2	
X33	2SK2231(T6L1SONYNQ	202004	202104	202110	2	TOSHIBA	TK25S06N1L	2	
X33	2SK2231(T6L1SUM1NQ	202004	202104	202110	2	TOSHIBA	TK25S06N1L	2	
X33	2SK2231(T6L1TOYONQ	202004	202104	202110	2	TOSHIBA	TK25S06N1L	2	
X33	2SK2231(T6L1WMATNQ	202004	202104	202110	2	TOSHIBA	TK25S06N1L	2	
X33	2SK2231(T6R1OTS,NQ	202004	202104	202110	2	TOSHIBA	TK25S06N1L	2	Y
X33	2SK2231(TE16L1,NQ)	202004	202104	202110	2	TOSHIBA	TK25S06N1L	2	Y
X33	2SK2231(TE16R1,NQ)	202004	202104	202110	2	TOSHIBA	TK25S06N1L	2	Y
X33	2SK2233(F)	202004	202104	202110	3	TOSHIBA	TK90S06N1L	2	
X33	2SK2267(Q)	202004	202104	202110	3	TOSHIBA	TK90S06N1L	2	
X33	2SK2399(T6L1MDN1NQ	202004	202104	202110	2	TOSHIBA	TK11S10N1L	2	
X33	2SK2399(T6L1MDN3NQ	202004	202104	202110	2	TOSHIBA	TK11S10N1L	2	
X33	2SK2399(T6L1MDNSNQ	202004	202104	202110	2	TOSHIBA	TK11S10N1L	2	
X33	2SK2399(T6L1NS,NQ)	202004	202104	202110	2	TOSHIBA	TK11S10N1L	2	
X33	2SK2399(T6L1PAV,NQ	202004	202104	202110	2	TOSHIBA	TK11S10N1L	2	
X33	2SK2399(T6L1PP,NQ)	202004	202104	202110	2	TOSHIBA	TK11S10N1L	2	
X33	2SK2399(T6L1PP1,NQ	202004	202104	202110	2	TOSHIBA	TK11S10N1L	2	
X33	2SK2399(T6L1TOJSNQ	202004	202104	202110	2	TOSHIBA	TK11S10N1L	2	
X33	2SK2399(TE16L1,NQ)	202004	202104	202110	2	TOSHIBA	TK11S10N1L	2	Y
X33	2SK2399(TE16R1,NQ)	202004	202104	202110	2	TOSHIBA	TK11S10N1L	2	
X33	2SK2615(2LDIAMO,ZF	202004	202104	202110	3	TOSHIBA	SSM3K2615R	2	
X33	2SK2615(F)	202004	202104	202110	3	TOSHIBA	SSM3K2615R	2	Y
X33	2SK2615(T2LAD,F)	202004	202104	202110	3	TOSHIBA	SSM3K2615R	2	
X33	2SK2615(T2LAISIN,F	202004	202104	202110	3	TOSHIBA	SSM3K2615R	2	
X33	2SK2615(T2LALPS,F)	202004	202104	202110	3	TOSHIBA	SSM3K2615R	2	
X33	2SK2615(T2LALPSA,F	202004	202104	202110	3	TOSHIBA	SSM3K2615R	2	Y
X33	2SK2615(T2LAST,F)	202004	202104	202110	3	TOSHIBA	SSM3K2615R	2	
X33	2SK2615(T2LDNSO,F)	202004	202104	202110	3	TOSHIBA	SSM3K2615R	2	

X33	2SK2615(T2LDNSO1,F	202004	202104	202110	3	TOSHIBA	SSM3K2615R	2	
X33	2SK2615(T2LFURUKAF	202004	202104	202110	3	TOSHIBA	SSM3K2615R	2	
X33	2SK2615(T2LHITJ,F)	202004	202104	202110	3	TOSHIBA	SSM3K2615R	2	
X33	2SK2615(T2LHYMO,F)	202004	202104	202110	3	TOSHIBA	SSM3K2615R	2	
X33	2SK2615(T2LIMASENF	202004	202104	202110	3	TOSHIBA	SSM3K2615R	2	
X33	2SK2615(T2LJRC,F)	202004	202104	202110	3	TOSHIBA	SSM3K2615R	2	
X33	2SK2615(T2LKD,F)	202004	202104	202110	3	TOSHIBA	SSM3K2615R	2	
X33	2SK2615(T2LKEHIN,F	202004	202104	202110	3	TOSHIBA	SSM3K2615R	2	
X33	2SK2615(T2LKOITS,F	202004	202104	202110	3	TOSHIBA	SSM3K2615R	2	
X33	2SK2615(T2LKOITS1F	202004	202104	202110	3	TOSHIBA	SSM3K2615R	2	
X33	2SK2615(T2LMBSH,ZF	202004	202104	202110	3	TOSHIBA	SSM3K2615R	2	
X33	2SK2615(T2LNALD,F)	202004	202104	202110	3	TOSHIBA	SSM3K2615R	2	
X33	2SK2615(T2LNCERA,F	202004	202104	202110	3	TOSHIBA	SSM3K2615R	2	
X33	2SK2615(T2LNILES,F	202004	202104	202110	3	TOSHIBA	SSM3K2615R	2	
X33	2SK2615(T2LNKOD,F)	202004	202104	202110	3	TOSHIBA	SSM3K2615R	2	
X33	2SK2615(T2LNSWT,F)	202004	202104	202110	3	TOSHIBA	SSM3K2615R	2	
X33	2SK2615(T2LPP,F)	202004	202104	202110	3	TOSHIBA	SSM3K2615R	2	
X33	2SK2615(T2LPSDS,F)	202004	202104	202110	3	TOSHIBA	SSM3K2615R	2	
X33	2SK2615(T2LRBNT,F)	202004	202104	202110	3	TOSHIBA	SSM3K2615R	2	
X33	2SK2615(T2LSONY,F)	202004	202104	202110	3	TOSHIBA	SSM3K2615R	2	
X33	2SK2615(T2LSTANR,F	202004	202104	202110	3	TOSHIBA	SSM3K2615R	2	
X33	2SK2615(T2LSUMID,F	202004	202104	202110	3	TOSHIBA	SSM3K2615R	2	
X33	2SK2615(T2LSUZUKIF	202004	202104	202110	3	TOSHIBA	SSM3K2615R	2	
X33	2SK2615(T2LSWF,F)	202004	202104	202110	3	TOSHIBA	SSM3K2615R	2	
X33	2SK2615(T2LTOJS,F)	202004	202104	202110	3	TOSHIBA	SSM3K2615R	2	
X33	2SK2615(T2LTORIK,F	202004	202104	202110	3	TOSHIBA	SSM3K2615R	2	
X33	2SK2615(T2LTOYOG,F	202004	202104	202110	3	TOSHIBA	SSM3K2615R	2	
X33	2SK2615(T2LUSNH,F)	202004	202104	202110	3	TOSHIBA	SSM3K2615R	2	
X33	2SK2615(T2LYAZK,F)	202004	202104	202110	3	TOSHIBA	SSM3K2615R	2	Y
X33	2SK2615(TE12L,F)	202004	202104	202110	3	TOSHIBA	SSM3K2615R	2	Y
X33	2SK2963(T2LHILX,F)	202004	202104	202110	3	TOSHIBA	SSM3K361R	2	
X33	2SK2963(T2LPP,F)	202004	202104	202110	3	TOSHIBA	SSM3K361R	2	
X33	2SK2963(T2LPSDS,F)	202004	202104	202110	3	TOSHIBA	SSM3K361R	2	
X33	2SK2963(T2LTDKY,F)	202004	202104	202110	3	TOSHIBA	SSM3K361R	2	
X33	2SK2964(T2LDNSO,F)	202004	202104	202110	3	TOSHIBA	SSM3K336R	2	
X33	2SK2964(T2LMDNSI,F	202004	202104	202110	3	TOSHIBA	SSM3K336R	2	

X33	2SK2964(T2LPP,F)	202004	202104	202110	3	TOSHIBA	SSM3K336R	2	
X33	2SK2964(TE12L,F)	202004	202104	202110	3	TOSHIBA	SSM3K336R	2	Y
X33	2SK2968(F)	202004	202104	202110	2	TOSHIBA	TK9J90E,S1E(S	2	Y
X33	2SK2968(S1TET,F)	202004	202104	202110	2	TOSHIBA	TK9J90E,S1E(S	2	
X33	2SK3017(F)	202004	202104	202110	3	TOSHIBA	TK9J90E,S1E(S	4	
X33	2SK3176(F)	202004	202104	202110	2	TOSHIBA	TK40J20D,S1F(O	2	Y
X33	2SK3205(6L1MBSI,NQ	202004	202104	202110	2	infineon	AUIRFR4620	2	
X33	2SK3205(T6L1HITJNQ	202004	202104	202110	2	infineon	AUIRFR4620	2	Y
X33	2SK3205(T6L1THA,NQ	202004	202104	202110	2	infineon	AUIRFR4620	2	
X33	2SK3205(T6L1TJM,NQ	202004	202104	202110	2	infineon	AUIRFR4620	2	
X33	2SK3205(T6L1TOJ,NQ	202004	202104	202110	2	infineon	AUIRFR4620	2	
X33	2SK3205(TE16L1,NQ)	202004	202104	202110	2	infineon	AUIRFR4620	2	
X33	2SK3205(TE16R1,NQ)	202004	202104	202110	2	infineon	AUIRFR4620	2	
X33	2SK3314(Q)	202004	202104	202110	2	TOSHIBA	TK16J60W5,S1VQ(O	2	
X33	2SK3314(SONY1,Q)	202004	202104	202110	2	TOSHIBA	TK16J60W5,S1VQ(O	2	
X33	2SK3506(LBMBSH,F)	202004	202104	202110	3	TOSHIBA	TK1R5R04PB	2	
X33	2SK3562,NCNQ(M	202004	202104	202110	2	TOSHIBA	TK1K2A60F,S4X(S	2	
X33	2SK3562,S5X(M	202004	202104	202110	2	TOSHIBA	TK1K2A60F,S4X(S	2	
X33	2SK3567,S5X(M	202004	202104	202110	2	TOSHIBA	TK2K2A60F,S4X(S	2	
X33	2SK3658(T2LNET,F)	202004	202104	202110	3	TOSHIBA	SSM3K341R	2	
X33	2SK3658(T2LPAV,F)	202004	202104	202110	3	TOSHIBA	SSM3K341R	2	
X33	2SK3658(T2LVALE,ZF	202004	202104	202110	3	TOSHIBA	SSM3K2615R	2	
X33	2SK3658(T2RNET,F)	202004	202104	202110	3	TOSHIBA	SSM3K341R	2	
X33	2SK3658(TE12L,F)	202004	202104	202110	3	TOSHIBA	SSM3K341R	2	Y
X33	2SK3669(T6L1S-OLNQ	202004	202104	202110	2	TOSHIBA	TK7S10N1Z	2	
X33	2SK3669(T6L1SOY1NQ	202004	202104	202110	2	TOSHIBA	TK7S10N1Z	2	
X33	2SK3669(TE16L1,NQ)	202004	202104	202110	2	TOSHIBA	TK7S10N1Z	2	Y
X33	2SK3767(Q,M)	202004	202104	202110	2	TOSHIBA	TK4K1A60F,S4X(S	2	
X33	2SK3767(STA4,A,Q)	202004	202104	202110	2	TOSHIBA	TK4K1A60F,S4X(S	2	
X33	2SK3767(STA4,Q,M)	202004	202104	202110	2	TOSHIBA	TK4K1A60F,S4X(S	2	Y
X33	2SK3767(STA4,X,M)	202004	202104	202110	2	TOSHIBA	TK4K1A60F,S4X(S	2	
X33	2SK3767,S5Q(J	202004	202104	202110	2	TOSHIBA	TK4K1A60F,S4X(S	2	
X33	2SK3797,S5X(M	202004	202104	202110	2	TOSHIBA	TK430A60F,S4X(S	2	
X33	2SK3845(Q)	202004	202104	202110	3	TOSHIBA	TK58E06N1	2	Y
X33	2SK3845(SENDD,Q)	202004	202104	202110	3	TOSHIBA	TK58E06N1	2	
X33	2SK3868(STA4,A,Q)	202004	202104	202110	2	TOSHIBA	TK7A60W5,S5VX(M	3	

X33	2SK3877(S1DNSO2,F)	202004	202104	202110	1	TOSHIBA	2SK3877,S1DNSO3F(O	5	
X33	2SK3878(COSEL,F)	202004	202104	202110	1	TOSHIBA	TK9J90E	3	
X33	2SK3878(F)	202004	202104	202110	1	TOSHIBA	TK9J90E	3	Y
X33	2SK3878(HIT,F)	202004	202104	202110	1	TOSHIBA	TK9J90E	3	
X33	2SK3878(LBTMEIC,F)	202004	202104	202110	1	TOSHIBA	TK9J90E	3	
X33	2SK3878(PAIRCO1,F)	202004	202104	202110	1	TOSHIBA	TK9J90E	3	
X33	2SK3878(PAIRCO2,F)	202004	202104	202110	1	TOSHIBA	TK9J90E	3	
X33	2SK3878(PAIRTDL,F)	202004	202104	202110	1	TOSHIBA	TK9J90E	3	
X33	2SK3878(STA1,E,S)	202004	202104	202110	1	TOSHIBA	TK9J90E	3	
X33	2SK3880(SNKD,F)	202004	202104	202110	3	TOSHIBA	TK6A80E	4	
X33	2SK3934,S5WNLQ(J	202004	202104	202110	1	TOSHIBA	TK15A50D	3	
X33	2SK3940(LBS2DNS2,Q	202004	202104	202110	3	TOSHIBA	TK160F10N1L	2	
X33	2SK3940(LBS2DNS3,Q	202004	202104	202110	3	TOSHIBA	TK160F10N1L	2	
X33	2SK3940(LBS2DNSO,Q	202004	202104	202110	3	TOSHIBA	TK160F10N1L	2	
X33	2SK3940(LBS2DNSO1Q	202004	202104	202110	3	TOSHIBA	TK160F10N1L	2	
X33	2SK3940(Q)	202004	202104	202110	3	TOSHIBA	TK160F10N1L	2	
X33	2SK3940(S1DNSO,Q)	202004	202104	202110	3	TOSHIBA	TK160F10N1L	2	
X33	2SK4017(CANO,Q)	202004	202104	202110	2	TOSHIBA	TK25S06N1L	2	
X33	2SK4017(HTL,Q)	202004	202104	202110	2	TOSHIBA	TK25S06N1L	2	
X33	2SK4017(MIYAH,Q)	202004	202104	202110	2	TOSHIBA	TK25S06N1L	2	
X33	2SK4017(PP,Q)	202004	202104	202110	2	TOSHIBA	TK25S06N1L	2	
X33	2SK4017(PP1,Q)	202004	202104	202110	2	TOSHIBA	TK25S06N1L	2	
X33	2SK4017(Q)	202004	202104	202110	2	TOSHIBA	TK25S06N1L	2	Y
X33	2SK4017(YAZS,Q)	202004	202104	202110	2	TOSHIBA	TK25S06N1L	2	
X33	2SK4018(PP,Q)	202004	202104	202110	2	TOSHIBA	TK11S10N1L	2	
X33	2SK4018(PP1,Q)	202004	202104	202110	2	TOSHIBA	TK11S10N1L	2	
X33	2SK4018(Q)	202004	202104	202110	2	TOSHIBA	TK11S10N1L	2	Y
X33	2SK4019(PP,Q)	202004	202104	202110	2	TOSHIBA	TK11S10N1L	2	
X33	2SK4019(PP1,Q)	202004	202104	202110	2	TOSHIBA	TK11S10N1L	2	
X33	2SK4019(Q)	202004	202104	202110	2	TOSHIBA	TK11S10N1L	2	Y
X33	2SK4033(T6L1AUT,NQ	202004	202104	202110	2	TOSHIBA	TK25S06N1L	2	
X33	2SK4033(T6L1MYH,NQ	202004	202104	202110	2	TOSHIBA	TK25S06N1L	2	
X33	2SK4033(T6L1SIN,NQ	202004	202104	202110	2	TOSHIBA	TK25S06N1L	2	
X33	2SK4033(T6L1TAN,NQ	202004	202104	202110	2	TOSHIBA	TK25S06N1L	2	
X33	2SK4107(STA1,E,S)	202004	202104	202110	1	TOSHIBA	TK15J50D(STA1,E,S)	2	
X33	2SK4108(STA1,E,S)	202004	202104	202110	1	TOSHIBA	TK20J50D(STA1,E,S)	2	

X35	CUS01(T5L,DNSO,QM)	202004	202104	202110	3	TOSHIBA	CRS03,LXGQ(M	4	
X35	CUS01(T5L,TEM,Q)	202004	202104	202110	3	TOSHIBA	CRS03(T5L,TEMQ)	4	
X35	CUS01(T5RSONY,Q,M)	202004	202104	202110	3	TOSHIBA	CRS03(TE85R,Q,M)	4	
X35	CUS01(TE85L,C,X,M)	202004	202104	202110	3	TOSHIBA	CRS03(T5L,TEMQ)	4	
X35	CUS01(TE85L,PP,A,Q	202004	202104	202110	3	TOSHIBA	CRS03(TE85L,PP,A,Q	4	
X35	CUS01(TE85L,PP,Q,M	202004	202104	202110	3	TOSHIBA	CRS03(TE85L,PP,A,Q	4	
X35	CUS01(TE85L,Q,M)	202004	202104	202110	3	TOSHIBA	CRS03(T5L,TEMQ)	4	Y
X35	CUS01(TE85LCANO,AQ	202004	202104	202110	3	TOSHIBA	CRS03(T5L,TEMQ)	4	
X35	CUS01(TE85LCANO,QM	202004	202104	202110	3	TOSHIBA	CRS03(T5L,TEMQ)	4	
X35	CUS01(TE85R,Q,M)	202004	202104	202110	3	TOSHIBA	CRS03(TE85R,Q,M)	4	
X35	CUS01,LCLARQ(M	202004	202104	202110	3	TOSHIBA	CRS03,LXGQ(M	4	
X35	CUS01,LPANAQ(M	202004	202104	202110	3	TOSHIBA	CRS03,LXGQ(M	4	
X35	CUS02(T5L,SONYD,QM	202004	202104	202110	3	TOSHIBA	CRS03(TE85R,Q,M)	4	
X35	CUS02(T5L,TEM,Q)	202004	202104	202110	3	TOSHIBA	CRS03(T5L,TEMQ)	4	Y
X35	CUS02(T5RSONY,A,Q)	202004	202104	202110	3	TOSHIBA	CRS03(TE85R,Q,M)	4	
X35	CUS02(T5RSONY,Q,M)	202004	202104	202110	3	TOSHIBA	CRS03(TE85R,Q,M)	4	
X35	CUS02(T5RSONY2,QM)	202004	202104	202110	3	TOSHIBA	CRS03(TE85R,Q,M)	4	
X35	CUS02(TE85L,PP,A,Q	202004	202104	202110	3	TOSHIBA	CRS03(TE85L,PP,A,Q	4	
X35	CUS02(TE85L,Q,M)	202004	202104	202110	3	TOSHIBA	CRS03(T5L,TEMQ)	4	Y
X35	CUS02(TE85LCANO,QM	202004	202104	202110	3	TOSHIBA	CRS03(T5L,TEMQ)	4	
X35	CUS02(TE85R,Q,M)	202004	202104	202110	3	TOSHIBA	CRS03(TE85R,Q,M)	4	
X35	CUS02,LAPNQ(J	202004	202104	202110	3	TOSHIBA	CRS03,LXGQ(M	4	
X35	CUS02,LAPNQ(M	202004	202104	202110	3	TOSHIBA	CRS03,LXGQ(M	4	Y
X35	CUS02,LHOKQ(M	202004	202104	202110	3	TOSHIBA	CRS03,LXGQ(M	4	
X35	CUS02,LJDIQ(M	202004	202104	202110	3	TOSHIBA	CRS03,LXGQ(M	4	
X35	CUS02,LPANAQ(M	202004	202104	202110	3	TOSHIBA	CRS03,LXGQ(M	4	
X35	CUS02,LPSEQ(J	202004	202104	202110	3	TOSHIBA	CRS03,LXGQ(M	4	
X35	CUS03(T5L,DNSO,QM)	202004	202104	202110	3	TOSHIBA	CRS04,LXGQ(M	4	
X35	CUS03(T5L,TEM,Q)	202004	202104	202110	3	TOSHIBA	CRS04(T5L,TEMQ)	4	
X35	CUS03(TE85L,Q,M)	202004	202104	202110	3	TOSHIBA	CRS04(T5L,TEMQ)	4	
X35	CUS03(TE85LCANO,QM	202004	202104	202110	3	TOSHIBA	CRS04(TE85LCANO,AQ	4	
X35	CUS03,LCKQ(M	202004	202104	202110	3	TOSHIBA	CRS04,LXGQ(M	4	
X35	CUS03,LMBSK2Q(M	202004	202104	202110	3	TOSHIBA	CRS04,LXGQ(M	4	
X35	CUS03,LNISANQ(J	202004	202104	202110	3	TOSHIBA	CRS04,LXGQ(M	4	
X35	CUS03,LVALEOQ(M	202004	202104	202110	3	TOSHIBA	CRS04,LXGQ(M	4	
X35	CUS03,LWNLQ(J	202004	202104	202110	3	TOSHIBA	CRS04(T5L,TEMQ)	4	

X35	CUS04(T5L,TEM,Q)	202004	202104	202110	3	TOSHIBA	CRS12(T5L,TEMQ)	4	
X35	CUS04(T5RSONY,Q,M)	202004	202104	202110	3	TOSHIBA	CRS12(T5RSONY,Q,M)	4	
X35	CUS04(TE85L,PP,AQ	202004	202104	202110	3	TOSHIBA	CRS12(TE85L,PP,Q,M	4	
X35	CUS04(TE85L,PP,Q,M	202004	202104	202110	3	TOSHIBA	CRS12(TE85L,PP,Q,M	4	
X35	CUS04(TE85L,Q,M)	202004	202104	202110	3	TOSHIBA	CRS12(T5L,TEMQ)	4	Y
X35	CUS04(TE85R,Q,M)	202004	202104	202110	3	TOSHIBA	CRS12(TE85R,Q,M)	4	
X35	CUS04,LWNLQ(J	202004	202104	202110	3	TOSHIBA	CRS12(T5L,TEMQ)	4	
X35	CUS04,LXGQ(M	202004	202104	202110	3	TOSHIBA	CRS12,LXGQ(M	4	
X35	CUS05(T5L,TEM,Q)	202004	202104	202110	3	TOSHIBA	CRS06(T5L,TEMQ)	4	
X35	CUS05(T5RSONY,Q,M)	202004	202104	202110	3	TOSHIBA	CRS06(TE85R,Q,M)	4	
X35	CUS05(TE85L,Q,M)	202004	202104	202110	3	TOSHIBA	CRS06(T5L,TEMQ)	4	
X35	CUS06(T5L,TEM,Q)	202004	202104	202110	3	TOSHIBA	CRS10I30A(T5L,TEMQ	4	
X35	CUS06(TE85L,Q,M)	202004	202104	202110	3	TOSHIBA	CRS10I30A(T5L,TEMQ	4	
X35	CUS10I30A(LNKOD,AQ	202004	202104	202110	3	TOSHIBA	CRS10I30A(T5L,TEMQ	4	
X35	CUS10I30A(RSONY,QM	202004	202104	202110	3	TOSHIBA	CRS10I30A,LSONYQ(M	4	
X35	CUS10I30A(T5L,TEMQ	202004	202104	202110	3	TOSHIBA	CRS10I30A(T5L,TEMQ	4	
X35	CUS10I30A(TE85L,QM	202004	202104	202110	3	TOSHIBA	CRS10I30A(T5L,TEMQ	4	Y
X35	CUS10I30A,LALPSQ(M	202004	202104	202110	3	TOSHIBA	CRS10I30A(T5L,TEMQ	4	
X35	CUS10I30A,LWDQ(M	202004	202104	202110	3	TOSHIBA	CRS10I30A(T5L,TEMQ	4	
X35	CUS10I30A,RQ(M	202004	202104	202110	3	TOSHIBA	CRS10I30A(T5R,Q,M)	4	
X35	CUS10I40A(RSONY,QM	202004	202104	202110	3	TOSHIBA	CRS10I40A(T5L,TEMQ	4	
X35	CUS10I40A(T5L,TEMQ	202004	202104	202110	3	TOSHIBA	CRS10I40A(T5L,TEMQ	4	
X35	CUS10I40A(TE85L,QM	202004	202104	202110	3	TOSHIBA	CRS10I40A(T5L,TEMQ	4	Y
X35	CUS10I40A,LALPGQ(M	202004	202104	202110	3	TOSHIBA	CRS10I40A(T5L,TEMQ	4	
X35	CUS10I40A,LAPNQ(M	202004	202104	202110	3	TOSHIBA	CRS10I40A(T5L,TEMQ	4	
X35	CUS15I30A(LCA-O,QM	202004	202104	202110	3	TOSHIBA	CRS15I30A(T5L,TEMQ	4	
X35	CUS15I30A(LSONY,AQ	202004	202104	202110	3	TOSHIBA	CRS15I30A(T5L,TEMQ	4	
X35	CUS15I30A(T5L,TEMQ	202004	202104	202110	3	TOSHIBA	CRS15I30A(T5L,TEMQ	4	
X35	CUS15I30A(TE85L,QM	202004	202104	202110	3	TOSHIBA	CRS15I30A(T5L,TEMQ	4	Y
X35	CUS15I30A(TE85R,QM	202004	202104	202110	3	TOSHIBA	CRS15I30A(TE85R,QM	4	
X35	ES2Y50G-AS(ES)	202004	202104	202110	0			5	
X35	ES2Z30-AS(ES)	202004	202104	202110	0			5	
X35	GT30F124(LBS1LG,QM	202004	202104	202110	0			5	
X35	GT30F124(Q,M)	202004	202104	202110	0			5	
X35	GT30F124(STA4,Q,M)	202004	202104	202110	0			5	
X35	GT30F126(LBS1LG,QM	202004	202104	202110	0			5	

X35	GT30F126,LS1CHAQ(M	202004	202104	202110	0			5	
X35	GT30F133,RLGQ(S	202004	202104	202110	0			5	
X35	GT30F133,RQ(S	202004	202104	202110	0			5	
X35	GT30F133,RSDIQ(S	202004	202104	202110	0			5	
X35	GT30G124(LBS1SD2QM	202004	202104	202110	0			5	
X35	GT30G124(Q,M)	202004	202104	202110	0			5	
X35	GT30G124(STA4,Q,M)	202004	202104	202110	0			5	
X35	GT30J122(GREE,Q)	202004	202104	202110	3	TOSHIBA	GT50J123	3	
X35	GT30J122(H,Q)	202004	202104	202110	3	TOSHIBA	GT50J123	3	
X35	GT30J122(LBDAIKINQ	202004	202104	202110	3	TOSHIBA	GT50J123	3	
X35	GT30J122(Q)	202004	202104	202110	3	TOSHIBA	GT50J123	3	
X35	GT30J122(TEAL,Q)	202004	202104	202110	3	TOSHIBA	GT50J123	3	
X35	GT30J126(HITAP,Q)	202004	202104	202110	3	TOSHIBA	GT50J123	4	
X35	GT30J126(HSN,Q)	202004	202104	202110	3	TOSHIBA	GT50J123	4	
X35	GT30J126(Q)	202004	202104	202110	3	TOSHIBA	GT50J123	4	
X35	GT30J127(LBS1LG,QM	202004	202104	202110	0			5	
X35	GT30J127(LBS1SD,QM	202004	202104	202110	0			5	
X35	GT30J127(Q,M)	202004	202104	202110	0			5	
X35	GT30J127(STA4,Q,M)	202004	202104	202110	0			5	
X35	GT30J127,LS1CHAQ(M	202004	202104	202110	0			5	
X35	GT30J322(LBMBSS,Q)	202004	202104	202110	3	TOSHIBA	GT30J341	3	
X35	GT30J322(LBMBSS1,Q	202004	202104	202110	3	TOSHIBA	GT30J341	3	
X35	GT30J322(Q)	202004	202104	202110	3	TOSHIBA	GT30J341	3	Y
X35	GT30J322(S1MA,Q)	202004	202104	202110	3	TOSHIBA	GT30J341,STA1E(S	3	
X35	GT30J322(S1MATJ,Q)	202004	202104	202110	3	TOSHIBA	GT30J341,STA1E(S	3	
X35	GT30J322(TIGER,Q)	202004	202104	202110	3	TOSHIBA	GT30J341	3	
X35	GT30J322(TRAHIHO,Q	202004	202104	202110	3	TOSHIBA	GT30J341	3	
X35	GT30J324(LBYASK,Q)	202004	202104	202110	1	TOSHIBA	GT30J341,Q(O	1	
X35	GT30J324(Q)	202004	202104	202110	1	TOSHIBA	GT30J341,STA1E(S	1	Y
X35	GT30J324(S1DNSO,Q)	202004	202104	202110	1	TOSHIBA	GT30J341,Q(O	1	
X35	GT30J324(S1DNSOA,Q	202004	202104	202110	1	TOSHIBA	GT30J341,Q(O	1	
X35	GT30J324(S1DNSOB,Q	202004	202104	202110	1	TOSHIBA	GT30J341,Q(O	1	
X35	GT30J324(S1DNSOC,Q	202004	202104	202110	1	TOSHIBA	GT30J341,Q(O	1	
X35	GT30J324(TOJS1,Q)	202004	202104	202110	1	TOSHIBA	GT30J341,Q(O	1	
X35	GT30J324(TOJS2,Q)	202004	202104	202110	1	TOSHIBA	GT30J341,Q(O	1	
X35	GT30J324(TOJS3,Q)	202004	202104	202110	1	TOSHIBA	GT30J341,Q(O	1	

X35	GT30J324(TOJS4,Q)	202004	202104	202110	1	TOSHIBA	GT30J341,Q(O	1	
X35	GT30J324(TOJS5,Q)	202004	202104	202110	1	TOSHIBA	GT30J341,Q(O	1	
X35	GT35J321(MAT-R,Q)	202004	202104	202110	3	TOSHIBA	GT30J341,STA1E(S	3	
X35	GT35J321(MAT-R1,Q)	202004	202104	202110	3	TOSHIBA	GT30J341,STA1E(S	3	
X35	GT35J321(Q)	202004	202104	202110	3	TOSHIBA	GT30J341,STA1E(S	3	
X35	GT35J321(S1MAT-R,Q)	202004	202104	202110	3	TOSHIBA	GT30J341,STA1E(S	3	
X35	GT35MR21,LBPHSQ(O	202004	202104	202110	3	TOSHIBA	S1PA6[UD]	3	
X35	GT35MR21,PHSQ(O	202004	202104	202110	3	TOSHIBA	S1PA6[UD]	3	
X35	GT35MR21,Q(O	202004	202104	202110	3	TOSHIBA	S1PA6[UD]	3	
X35	GT40J121,HSNQ(O	202004	202104	202110	3	TOSHIBA	GT50J123	4	
X35	GT40J121,Q(O	202004	202104	202110	3	TOSHIBA	GT50J123	4	
X35	GT40J321(MAT-DT,Q)	202004	202104	202110	3	TOSHIBA	GT30J341,STA1E(S	3	
X35	GT40J321(Q)	202004	202104	202110	3	TOSHIBA	GT30J341,STA1E(S	3	
X35	GT40J324,Q(O	202004	202104	202110	2	TOSHIBA	GT50JR22	5	
X35	GT40J325,Q(O	202004	202104	202110	3	TOSHIBA	GT30J341	4	
X35	GT40T321,Q(O	202004	202104	202110	2	TOSHIBA	GT40WR21,Q(O	4	
X35	GT50J121(LBHITKU,Q	202004	202104	202110	3	TOSHIBA	S1PA7[UD]	4	
X35	GT50J122(Q)	202004	202104	202110	3	TOSHIBA	GT50J123	3	
X35	GT50J322(AITI,Q)	202004	202104	202110	3	TOSHIBA	GT30J341,STA1E(S	3	
X35	GT50J322(HIHO1,Q)	202004	202104	202110	3	TOSHIBA	GT30J341,STA1E(S	3	
X35	GT50J322(HIHO2,Q)	202004	202104	202110	3	TOSHIBA	GT30J341,STA1E(S	3	
X35	GT50J322(LBTABCH,Q	202004	202104	202110	3	TOSHIBA	GT30J341,STA1E(S	3	
X35	GT50J322(Q)	202004	202104	202110	3	TOSHIBA	GT30J341,STA1E(S	3	
X35	GT50J322(S1MATJ,Q)	202004	202104	202110	3	TOSHIBA	GT30J341,STA1E(S	3	
X35	GT50J322H(Q)	202004	202104	202110	3	TOSHIBA	GT30J341,STA1E(S	3	
X35	GT50J323(S1MATJ,Q)	202004	202104	202110	3	TOSHIBA	GT30J341,STA1E(S	3	
X35	GT50J325(DNSO,Q)	202004	202104	202110	3	TOSHIBA	GT30J341,STA1E(S	3	
X35	GT50J325(LBMBSS,Q)	202004	202104	202110	3	TOSHIBA	GT30J341,STA1E(S	3	
X35	GT50J325(LBYASK,Q)	202004	202104	202110	3	TOSHIBA	GT30J341,STA1E(S	3	
X35	GT50J325(MWSC,Q)	202004	202104	202110	3	TOSHIBA	GT30J341,STA1E(S	3	
X35	GT50J325(Q)	202004	202104	202110	3	TOSHIBA	GT30J341,STA1E(S	3	Y
X35	GT50J325(S1DNSO,Q)	202004	202104	202110	3	TOSHIBA	GT30J341,STA1E(S	3	
X35	GT50J325(S1DNSOA,Q	202004	202104	202110	3	TOSHIBA	GT30J341,STA1E(S	3	
X35	GT50J325(S1DNSOB,Q	202004	202104	202110	3	TOSHIBA	GT30J341,STA1E(S	3	
X35	GT50J325(S1MBS,Q)	202004	202104	202110	3	TOSHIBA	GT30J341	3	
X35	GT50J325(SANKEN,Q)	202004	202104	202110	3	TOSHIBA	GT30J341,STA1E(S	3	

X35	GT50J327(MAT-R,Q)	202004	202104	202110	3	TOSHIBA	GT30J341,STA1E(S	3	Y
X35	GT50J327(MAT-R1,Q)	202004	202104	202110	3	TOSHIBA	GT30J341,STA1E(S	3	
X35	GT50J327(Q)	202004	202104	202110	3	TOSHIBA	GT30J341,STA1E(S	3	Y
X35	GT50J327(S1FGB,Q)	202004	202104	202110	3	TOSHIBA	GT30J341,STA1E(S	3	Y
X35	GT50J327(S1MAT-R,Q	202004	202104	202110	3	TOSHIBA	GT30J341,STA1E(S	3	
X35	GT50J328(MBSHO,Q)	202004	202104	202110	2	TOSHIBA	GT50JR22	3	
X35	GT50J328(Q)	202004	202104	202110	2	TOSHIBA	GT50JR22	3	
X35	GT50J342,Q(O	202004	202104	202110	0			3	Y
X35	GT50J342,STA1E(S	202004	202104	202110	0			3	
X35	GT50M322(Q)	202004	202104	202110	3	TOSHIBA	S1PA6[UD]	3	
X35	GT50M322(S1MBSHO,Q	202004	202104	202110	3	TOSHIBA	S1PA6[UD]	3	
X35	GT50MR21,Q(O	202004	202104	202110	0			3	
X35	GT50MR21,S1MBSHQ(O	202004	202104	202110	1	TOSHIBA	S1PA7[UD]	3	
X35	GT50N321(NKOD,Q)	202004	202104	202110	2	TOSHIBA	S1PA6[UD]	3	
X35	GT50N322A(NKOD,Q)	202004	202104	202110	1	TOSHIBA	S1PA7[UD]	3	
X35	GT5G134,LV(O	202004	202104	202110	1	RENESAS	RJP4013ASP	4	
X35	GT60J323(HITAP,Q)	202004	202104	202110	3	TOSHIBA	GT50JR22	3	
X35	GT60J323(Q)	202004	202104	202110	3	TOSHIBA	GT50JR22	3	Y
X35	GT60J323(SANHT,Q)	202004	202104	202110	3	TOSHIBA	GT50JR22	3	
X35	GT60J323H(Q)	202004	202104	202110	3	TOSHIBA	GT50JR22	3	
X35	GT60M303(DNSO,Q)	202004	202104	202110	3	TOSHIBA	S1PA7[UD]	3	
X35	GT60M303(HANSHIN,Q	202004	202104	202110	3	TOSHIBA	S1PA7[UD]	3	
X35	GT60M303(LBRYUS,Q)	202004	202104	202110	3	TOSHIBA	S1PA7[UD]	3	
X35	GT60M303(LBRYUS1,Q	202004	202104	202110	3	TOSHIBA	S1PA7[UD]	3	
X35	GT60M303(LBZO,Q)	202004	202104	202110	3	TOSHIBA	S1PA7[UD]	3	
X35	GT60M303(MA,Q)	202004	202104	202110	3	TOSHIBA	S1PA7[UD]	3	
X35	GT60M303(MAT-R1,Q)	202004	202104	202110	3	TOSHIBA	S1PA7[UD]	3	
X35	GT60M303(MAT-R2,Q)	202004	202104	202110	3	TOSHIBA	S1PA7[UD]	3	
X35	GT60M303(NKOD,Q)	202004	202104	202110	3	TOSHIBA	S1PA7[UD]	3	
X35	GT60M303(Q)	202004	202104	202110	3	TOSHIBA	S1PA7[UD]	3	Y
X35	GT60M303(S1MAT-R,Q	202004	202104	202110	3	TOSHIBA	S1PA7[UD]	3	
X35	GT60M303(S1MAT-R1Q	202004	202104	202110	3	TOSHIBA	S1PA7[UD]	3	
X35	GT60M303(S1MBSHO,Q	202004	202104	202110	3	TOSHIBA	S1PA7[UD]	3	
X35	GT60M303(SANHT,Q)	202004	202104	202110	3	TOSHIBA	S1PA7[UD]	3	
X35	GT60M303(SANRA,Q)	202004	202104	202110	3	TOSHIBA	S1PA7[UD]	3	
X35	GT60M303N(LBMA,Q)	202004	202104	202110	3	TOSHIBA	S1PA7[UD]	3	

X35	GT60M303N(MA,Q)	202004	202104	202110	3	TOSHIBA	S1PA7[UD]	3	
X35	GT60M324(Q)	202004	202104	202110	3	TOSHIBA	S1PA7[UD]	3	Y
X35	GT60N321(MAT-DT1,Q)	202004	202104	202110	2	TOSHIBA	S1PA6[UD]	4	
X35	HMG02(T5L,SUMIS,Q)	202004	202104	202110	3	TOSHIBA	CRG09A,LXGQ(M	4	
X35	HMG02(TE85L,Q)	202004	202104	202110	3	TOSHIBA	CRG09A,LQ(M	4	
X33	JS2J73-A1S(ASAW)	202004	202104	202110	0			4	
X35	JS2Y48-AS(ES,AST)	202004	202104	202110	0			5	
X35	JS2Y50G-AS(ES,AST)	202004	202104	202110	0			5	
X35	JS2Y50G-AS(KEHINEV	202004	202104	202110	0			5	
X35	JS2Y50G-AS(PL,ES)	202004	202104	202110	0			5	
X35	JS5M89-AS(ES)	202004	202104	202110	0			5	
X35	JS5N33-AS(DN4TR,ES	202004	202104	202110	0			5	
X35	MG1200V2JS71(P)	202004	202104	202110	0			5	
X35	MG1200V2YS71(DAE)	202004	202104	202110	2	MITSUBISHI	CMH1200DC-34S	5	
X35	MG1200V2YS71(P)	202004	202104	202110	2	MITSUBISHI	CMH1200DC-34S	5	
X35	MG1500FXF1US61(P)	202004	202104	202110	2	MITSUBISHI	CM1500HC-66R	5	
X35	MG1500FXF1US62(DAE	202004	202104	202110	2	MITSUBISHI	CM1500HC-66R	5	
X35	MG1500FXF1US62(HI1	202004	202104	202110	2	MITSUBISHI	CM1500HC-66R	5	
X35	MG1500FXF1US62(P)	202004	202104	202110	2	MITSUBISHI	CM1500HC-66R	5	
X35	MG1500FXF1US63(P)	202004	202104	202110	2	MITSUBISHI	CM1500HC-66R	5	
X35	MG900GXH1US53(DAE)	202004	202104	202110	0			5	
X35	MG900GXH1US53(P6)	202004	202104	202110	0			3	
X35	MG900GXH-P66	202004	202104	202110	2	MITSUBISHI	CM1200HC-90R	5	
X35	S2Z49(TAEC-ES)	202004	202104	202110	0			5	
X35	TA4800AF(T6L1,Q)	202004	202104	202110	3	NEWJAPANRADIO	NJM2387ADL3	4	
X35	TA4800AF(T6L1PP,Q)	202004	202104	202110	3	NEWJAPANRADIO	NJM2387ADL3	4	
X35	TA4800AF(T6L1PP1,Q	202004	202104	202110	3	NEWJAPANRADIO	NJM2387ADL3	4	
X35	TA48015BF(6L1FJTNQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2855DL1-15	4	Y
X35	TA48015BF(6L1HLSNQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2855DL1-15	4	
X35	TA48015BF(6L1MB,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2855DL1-15	4	
X35	TA48015BF(6L1NIENQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2855DL1-15	4	
X35	TA48015BF(6L1PA,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2855DL1-15	4	Y
X35	TA48015BF(6L1PP,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2855DL1-15	4	
X35	TA48015BF(6L1PS,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2855DL1-15	4	
X35	TA48015BF(6L1TO,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2855DL1-15	4	Y
X35	TA48015BF(L1PP1,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2855DL1-15	4	

X35	TA48015BF(T6L1,NQ)	202004	202104	202110	2	NEWJAPANRADIO	NJM2855DL1-15	4	Y
X35	TA48018BF(6L1FJ,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2855DL1-18	4	
X35	TA48018BF(6L1HO,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2855DL1-18	4	
X35	TA48018BF(6L1XN,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2855DL1-18	4	
X35	TA48018BF(L1PP1,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2855DL1-18	4	
X35	TA48018BF(L1SAPPNQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2855DL1-18	4	
X35	TA48018BF(T6L1,NQ)	202004	202104	202110	2	NEWJAPANRADIO	NJM2855DL1-18	4	
X35	TA48018BF(T6L1PPNQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2855DL1-18	4	
X35	TA48025BF(6L1AP,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2855DL1-25	4	
X35	TA48025BF(6L1NE,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2855DL1-25	4	
X35	TA48025BF(6L1SI,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2855DL1-25	4	
X35	TA48025BF(L1AL1,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2855DL1-25	4	
X35	TA48025BF(L1AL2,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2855DL1-25	4	
X35	TA48025BF(L1PP1,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2855DL1-25	4	
X35	TA48025BF(NHF,NQ)	202004	202104	202110	2	NEWJAPANRADIO	NJM2855DL1-25	4	
X35	TA48025BF(T6L1,NQ)	202004	202104	202110	2	NEWJAPANRADIO	NJM2855DL1-25	4	
X35	TA48025BF(T6L1ALNQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2855DL1-25	4	
X35	TA48033BF(6L1AL,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2855DL1-33	4	
X35	TA48033BF(6L1AT,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2855DL1-33	4	
X35	TA48033BF(6L1CL,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2855DL1-33	4	
X35	TA48033BF(6L1DN,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2855DL1-33	4	
X35	TA48033BF(6L1FJ,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2855DL1-33	4	
X35	TA48033BF(6L1HL,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2855DL1-33	4	
X35	TA48033BF(6L1JK,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2855DL1-33	4	
X35	TA48033BF(6L1MB,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2855DL1-33	4	
X35	TA48033BF(6L1SA,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2855DL1-33	4	
X35	TA48033BF(6L1TO,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2855DL1-33	4	
X35	TA48033BF(L1PP1,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2855DL1-33	4	
X35	TA48033BF(L1SAPP1Q	202004	202104	202110	2	NEWJAPANRADIO	NJM2855DL1-33	4	
X35	TA48033BF(T6L1,NQ)	202004	202104	202110	2	NEWJAPANRADIO	NJM2855DL1-33	4	Y
X35	TA48033BF(T6L1,NY)	202004	202104	202110	2	NEWJAPANRADIO	NJM2855DL1-33	4	
X35	TA48033BF(T6L1PANQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2855DL1-33	4	
X35	TA48033BF(T6L1PPNQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2855DL1-33	4	
X35	TA48033BF(T6L1SINQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2855DL1-33	4	
X35	TA4805BF(6L1AD,NQ)	202004	202104	202110	2	NEWJAPANRADIO	NJM2855DL1-05	4	
X35	TA4805BF(6L1CLA,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2855DL1-05	4	

X35	TA4805BF(6L1HIL,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2855DL1-05	4	
X35	TA4805BF(6L1NET,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2855DL1-05	4	
X35	TA4805BF(6L1PP1,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2855DL1-05	4	
X35	TA4805BF(6L1SIW,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2855DL1-05	4	
X35	TA4805BF(6L1YZS,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2855DL1-05	4	
X35	TA4805BF(L1NCNLXNQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2855DL1-05	4	
X35	TA4805BF(L1NKOD,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2855DL1-05	4	
X35	TA4805BF(L1SAPP,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2855DL1-05	4	
X35	TA4805BF(T6L1,NQ)	202004	202104	202110	2	NEWJAPANRADIO	NJM2855DL1-05	4	
X35	TA4805BF(T6L1NIENQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2855DL1-05	4	
X35	TA4805BF(T6L1PP,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2855DL1-05	4	
X35	TA4808BF(T6L1,NQ)	202004	202104	202110	3	NEWJAPANRADIO	NJM2386ADL3-08	4	
X35	TA4809BF(T6L1,NQ)	202004	202104	202110	3	NEWJAPANRADIO	NJM2386ADL3-09	4	
X35	TA4809BF(T6L1NIENQ	202004	202104	202110	3	NEWJAPANRADIO	NJM2386ADL3-09	4	
X35	TA48L018F(F)	202004	202104	202110	3	NEWJAPANRADIO	NJU7780U1-18	4	
X35	TA48L018F(OLD,F)	202004	202104	202110	3	NEWJAPANRADIO	NJU7780U1-18	4	
X35	TA48L018F(T2LNS,F)	202004	202104	202110	3	NEWJAPANRADIO	NJU7780U1-18	4	
X35	TA48L018F(T2LOLD,F)	202004	202104	202110	3	NEWJAPANRADIO	NJU7780U1-18	4	
X35	TA48L018F(T2LPP,F)	202004	202104	202110	3	NEWJAPANRADIO	NJU7780U1-18	4	
X35	TA48L018F(TE12L,F)	202004	202104	202110	3	NEWJAPANRADIO	NJU7780U1-18	4	
X35	TA48L025F(2LDNSO,F)	202004	202104	202110	2	NEWJAPANRADIO	NJW4184U3-25B	4	
X35	TA48L025F(T2LKOY,F)	202004	202104	202110	2	NEWJAPANRADIO	NJW4184U3-25B	4	
X35	TA48L025F(T2LOLD,F)	202004	202104	202110	2	NEWJAPANRADIO	NJW4184U3-25B	4	
X35	TA48L025F(T2LPP,F)	202004	202104	202110	2	NEWJAPANRADIO	NJW4184U3-25B	4	
X35	TA48L025F(TE12L,F)	202004	202104	202110	2	NEWJAPANRADIO	NJW4184U3-25B	4	Y
X35	TA48L02F(T2LOLD,F)	202004	202104	202110	3	NEWJAPANRADIO	NJM2884U1-02	4	
X35	TA48L02F(TE12L,F)	202004	202104	202110	3	NEWJAPANRADIO	NJM2884U1-02	4	
X35	TA48L033F(2LDNMA,F)	202004	202104	202110	2	NEWJAPANRADIO	NJW4184U3-33B	4	
X35	TA48L033F(2LOMII,F)	202004	202104	202110	2	NEWJAPANRADIO	NJW4184U3-33B	4	
X35	TA48L033F(T2LALP,F)	202004	202104	202110	2	NEWJAPANRADIO	NJW4184U3-33B	4	
X35	TA48L033F(T2LHO,F)	202004	202104	202110	2	NEWJAPANRADIO	NJW4184U3-33B	4	
X35	TA48L033F(T2LHY-AF	202004	202104	202110	2	NEWJAPANRADIO	NJW4184U3-33B	4	
X35	TA48L033F(T2LOLD,F)	202004	202104	202110	2	NEWJAPANRADIO	NJW4184U3-33B	4	
X35	TA48L033F(T2LPP,F)	202004	202104	202110	2	NEWJAPANRADIO	NJW4184U3-33B	4	
X35	TA48L033F(T2LYAZKF	202004	202104	202110	2	NEWJAPANRADIO	NJW4184U3-33B	4	
X35	TA48L033F(TE12L,F)	202004	202104	202110	2	NEWJAPANRADIO	NJW4184U3-33B	4	Y

X35	TA48L03F(T2LKYSA,E	202004	202104	202110	3	NEWJAPANRADIO	NJU7780U1-03	4	
X35	TA48L03F(T2LMATUDF	202004	202104	202110	3	NEWJAPANRADIO	NJU7780U1-03	4	
X35	TA48L03F(T2LOLD,F	202004	202104	202110	3	NEWJAPANRADIO	NJU7780U1-03	4	
X35	TA48L03F(T2LYOKOOF	202004	202104	202110	3	NEWJAPANRADIO	NJU7780U1-03	4	
X35	TA48L03F(TE12L,F)	202004	202104	202110	3	NEWJAPANRADIO	NJU7780U1-03	4	
X35	TA48L05F(F)	202004	202104	202110	2	NEWJAPANRADIO	NJW4184U3-05B	4	
X35	TA48L05F(OLD,F)	202004	202104	202110	2	NEWJAPANRADIO	NJW4184U3-05B	4	
X35	TA48L05F(T2LMYM,F)	202004	202104	202110	2	NEWJAPANRADIO	NJW4184U3-05B	4	
X35	TA48L05F(T2LNKOD,F	202004	202104	202110	2	NEWJAPANRADIO	NJW4184U3-05B	4	
X35	TA48L05F(T2LOLD,F	202004	202104	202110	2	NEWJAPANRADIO	NJW4184U3-05B	4	
X35	TA48L05F(T2LPP,F)	202004	202104	202110	2	NEWJAPANRADIO	NJW4184U3-05B	4	
X35	TA48L05F(T2LSONY,F	202004	202104	202110	2	NEWJAPANRADIO	NJW4184U3-05B	4	
X35	TA48L05F(TE12L,F)	202004	202104	202110	2	NEWJAPANRADIO	NJW4184U3-05B	4	
X35	TA48LS00F(5LKMC1,F	202004	202104	202110	0			4	
X35	TA48LS00F(T5LAPN,F	202004	202104	202110	0			4	Y
X35	TA48LS00F(T5LFJT,F	202004	202104	202110	0			4	
X35	TA48LS00F(T5LFUM,F	202004	202104	202110	0			4	
X35	TA48LS00F(T5LKMC,F	202004	202104	202110	0			4	
X35	TA48LS00F(TE85L,F)	202004	202104	202110	0			4	Y
X35	TA48LS015F(5LHIT,F	202004	202104	202110	3	NEWJAPANRADIO	NJU7780U1-15	4	
X35	TA48LS015F(5LPP1,F	202004	202104	202110	3	NEWJAPANRADIO	NJU7780U1-15	4	
X35	TA48LS015F(TE85L,F	202004	202104	202110	3	NEWJAPANRADIO	NJU7780U1-15	4	
X35	TA48LS018F(TE85L,F	202004	202104	202110	3	NEWJAPANRADIO	NJU7780U1-18	4	
X35	TA48LS025F(5LJKT,F	202004	202104	202110	3	NEWJAPANRADIO	NJW4184U2-25A	4	
X35	TA48LS025F(TE85L,F	202004	202104	202110	3	NEWJAPANRADIO	NJW4184U2-25A	4	
X35	TA48LS033F(5LFJT,F	202004	202104	202110	3	NEWJAPANRADIO	NJW4184U2-33A	4	
X35	TA48LS033F(5LHDE,F	202004	202104	202110	3	NEWJAPANRADIO	NJW4184U2-33A	4	
X35	TA48LS033F(5LHLS,F	202004	202104	202110	3	NEWJAPANRADIO	NJW4184U2-33A	4	
X35	TA48LS033F(5LJKT,F	202004	202104	202110	3	NEWJAPANRADIO	NJW4184U2-33A	4	
X35	TA48LS033F(5LPAI,F	202004	202104	202110	3	NEWJAPANRADIO	NJW4184U2-33A	4	
X35	TA48LS033F(5LPAN,F	202004	202104	202110	3	NEWJAPANRADIO	NJW4184U2-33A	4	
X35	TA48LS033F(5LYZK,F	202004	202104	202110	3	NEWJAPANRADIO	NJW4184U2-33A	4	
X35	TA48LS033F(TE85L,F	202004	202104	202110	3	NEWJAPANRADIO	NJW4184U2-33A	4	Y
X35	TA48LS05F(5LFJTN,F	202004	202104	202110	3	NEWJAPANRADIO	NJW4184U2-05A	4	
X35	TA48LS05F(T5LFUM,F	202004	202104	202110	3	NEWJAPANRADIO	NJW4184U2-05A	4	
X35	TA48LS05F(TE85L,F)	202004	202104	202110	3	NEWJAPANRADIO	NJW4184U2-05A	4	

X35	TA48M025F(L1AD,SNQ	202004	202104	202110	3	NEWJAPANRADIO	NJU7223DL1-25	4	
X35	TA48M025F(L1DA,SNQ	202004	202104	202110	3	NEWJAPANRADIO	NJU7223DL1-25	4	
X35	TA48M025F(L1NK,SNQ	202004	202104	202110	3	NEWJAPANRADIO	NJU7223DL1-25	4	
X35	TA48M025F(L1TE,SNQ	202004	202104	202110	3	NEWJAPANRADIO	NJU7223DL1-25	4	
X35	TA48M025F(L1YK,SNQ	202004	202104	202110	3	NEWJAPANRADIO	NJU7223DL1-25	4	
X35	TA48M025F(T6L1,SNQ	202004	202104	202110	3	NEWJAPANRADIO	NJU7223DL1-25	4	Y
X35	TA48M033F(L1AD,SNQ	202004	202104	202110	3	NEWJAPANRADIO	NJU7223DL1-33	4	
X35	TA48M033F(L1HN,SNQ	202004	202104	202110	3	NEWJAPANRADIO	NJU7223DL1-33	4	
X35	TA48M033F(L1HO,SNQ	202004	202104	202110	3	NEWJAPANRADIO	NJU7223DL1-33	4	
X35	TA48M033F(L1NK,SNQ	202004	202104	202110	3	NEWJAPANRADIO	NJU7223DL1-33	4	
X35	TA48M033F(L1PP1,NQ	202004	202104	202110	3	NEWJAPANRADIO	NJU7223DL1-33	4	
X35	TA48M033F(L1PS,SNQ	202004	202104	202110	3	NEWJAPANRADIO	NJU7223DL1-33	4	
X35	TA48M033F(L1SW,SNQ	202004	202104	202110	3	NEWJAPANRADIO	NJU7223DL1-33	4	
X35	TA48M033F(L1YK,SNQ	202004	202104	202110	3	NEWJAPANRADIO	NJU7223DL1-33	4	
X35	TA48M033F(T6L1,SNQ	202004	202104	202110	3	NEWJAPANRADIO	NJU7223DL1-33	4	Y
X35	TA48M0345F(6L1,SNQ	202004	202104	202110	3	NEWJAPANRADIO	NJM2887DL3	4	Y
X35	TA48M0345F(L1PP1SQ	202004	202104	202110	3	NEWJAPANRADIO	NJM2887DL3	4	
X35	TA48M0345F(L1TESNQ	202004	202104	202110	3	NEWJAPANRADIO	NJM2887DL3	4	
X35	TA48M03F(6L1SY,SNQ	202004	202104	202110	3	NEWJAPANRADIO	NJU7223DL1-30	4	
X35	TA48M03F(L1MKA,SNQ	202004	202104	202110	3	NEWJAPANRADIO	NJU7223DL1-30	4	
X35	TA48M03F(T6L1,SNQ)	202004	202104	202110	3	NEWJAPANRADIO	NJU7223DL1-30	4	
X35	TA48M04F(T6L1,SNQ)	202004	202104	202110	3	NEWJAPANRADIO	NJM2887DL3	4	
X35	TA48M05F(6L1AD,SNQ	202004	202104	202110	3	NEWJAPANRADIO	NJU7223DL1-50	4	
X35	TA48M05F(6L1HN,SNQ	202004	202104	202110	3	NEWJAPANRADIO	NJU7223DL1-50	4	
X35	TA48M05F(6L1OM,SNX	202004	202104	202110	3	NEWJAPANRADIO	NJU7223DL1-50	4	
X35	TA48M05F(6L1PP1,NQ	202004	202104	202110	3	NEWJAPANRADIO	NJU7223DL1-50	4	
X35	TA48M05F(6L1SW,SNQ	202004	202104	202110	3	NEWJAPANRADIO	NJU7223DL1-50	4	
X35	TA48M05F(T6L1,SNQ)	202004	202104	202110	3	NEWJAPANRADIO	NJU7223DL1-50	4	Y
X35	TA48S00AF(6L1APN,Q	202004	202104	202110	3	NEWJAPANRADIO	NJM2387ADL3	4	Y
X35	TA48S00AF(6L1ASA,X	202004	202104	202110	3	NEWJAPANRADIO	NJM2387ADL3	4	
X35	TA48S00AF(6L1DNS,Q	202004	202104	202110	3	NEWJAPANRADIO	NJM2387ADL3	4	
X35	TA48S00AF(6L1GPP,Q	202004	202104	202110	3	NEWJAPANRADIO	NJM2387ADL3	4	
X35	TA48S00AF(6L1KEN,Q	202004	202104	202110	3	NEWJAPANRADIO	NJM2387ADL3	4	
X35	TA48S00AF(6L1PAS,Q	202004	202104	202110	3	NEWJAPANRADIO	NJM2387ADL3	4	
X35	TA48S00AF(T6L1,Q)	202004	202104	202110	3	NEWJAPANRADIO	NJM2387ADL3	4	Y
X35	TA48S00AF(T6L1LG,Q	202004	202104	202110	3	NEWJAPANRADIO	NJM2387ADL3	4	

X35	TA48S015AF(6L1AP,Q	202004	202104	202110	2	NEWJAPANRADIO	NJM2856DL3-15	4	
X35	TA48S015AF(6L1JK,Q	202004	202104	202110	2	NEWJAPANRADIO	NJM2856DL3-15	4	
X35	TA48S015AF(T6L1,Q)	202004	202104	202110	2	NEWJAPANRADIO	NJM2856DL3-15	4	
X35	TA48S015AF(T6L1KEQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2856DL3-15	4	
X35	TA48S015AF(T6L1VOQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2856DL3-15	4	
X35	TA48S018AF(6L1AP,Q	202004	202104	202110	2	NEWJAPANRADIO	NJM2856DL3-18	4	
X35	TA48S018AF(T6L1,Q)	202004	202104	202110	2	NEWJAPANRADIO	NJM2856DL3-18	4	
X35	TA48S018AF(T6L1VOQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2856DL3-18	4	
X35	TA48S025AF(6L1AP,Q	202004	202104	202110	2	NEWJAPANRADIO	NJM2856DL3-25	4	
X35	TA48S025AF(L1PP1,Q	202004	202104	202110	2	NEWJAPANRADIO	NJM2856DL3-25	4	
X35	TA48S025AF(T6L1,Q)	202004	202104	202110	2	NEWJAPANRADIO	NJM2856DL3-25	4	
X35	TA48S025AF(T6L1VOQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2856DL3-25	4	
X35	TA48S033AF(6L1AP,Q	202004	202104	202110	2	NEWJAPANRADIO	NJM2856DL3-33	4	Y
X35	TA48S033AF(6L1FJ,Q	202004	202104	202110	2	NEWJAPANRADIO	NJM2856DL3-33	4	
X35	TA48S033AF(6L1JK,Q	202004	202104	202110	2	NEWJAPANRADIO	NJM2856DL3-33	4	
X35	TA48S033AF(T6L1,Q)	202004	202104	202110	2	NEWJAPANRADIO	NJM2856DL3-33	4	Y
X35	TA48S033AF(T6L1KEQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2856DL3-33	4	
X35	TA48S033AF(T6L1VOQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2856DL3-33	4	
X35	TA48S05AF(6L1APN,Q	202004	202104	202110	2	NEWJAPANRADIO	NJM2856DL3-05	4	
X35	TA48S05AF(T6L1,Q)	202004	202104	202110	2	NEWJAPANRADIO	NJM2856DL3-05	4	
X35	TA48S05AF(T6L1VOQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2856DL3-05	4	
X35	TA48S09AF(T6L1,Q)	202004	202104	202110	3	NEWJAPANRADIO	NJM2386ADL3-09	4	
X35	TA48S09AF(T6L1VOQ	202004	202104	202110	3	NEWJAPANRADIO	NJM2386ADL3-09	4	
X35	TA58L05F(6L1AST,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-05	4	
X35	TA58L05F(6L1AST,NX	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-05	4	
X35	TA58L05F(6L1DIA,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-05	4	
X35	TA58L05F(6L1DNS,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-05	4	
X35	TA58L05F(6L1ENG,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-05	4	
X35	TA58L05F(6L1HAR,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-05	4	
X35	TA58L05F(6L1HIL,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-05	4	
X35	TA58L05F(6L1HSD,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-05	4	
X35	TA58L05F(6L1HTA,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-05	4	
X35	TA58L05F(6L1KEH,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-05	4	
X35	TA58L05F(6L1MBH,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-05	4	
X35	TA58L05F(6L1MSD,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-05	4	
X35	TA58L05F(6L1MTD,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-05	4	

X35	TA58L05F(6L1NDS,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-05	4
X35	TA58L05F(6L1OMI,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-05	4
X35	TA58L05F(6L1PEW,NX	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-05	4
X35	TA58L05F(6L1PIC,NX	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-05	4
X35	TA58L05F(6L1SAN,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-05	4
X35	TA58L05F(6L1STN1NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-05	4
X35	TA58L05F(6L1TY1,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-05	4
X35	TA58L05F(6L1USN,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-05	4
X35	TA58L05F(T6L1ALPNQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-05	4
X35	TA58L05F(T6L1APNNQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-05	4
X35	TA58L05F(T6L1ASHNQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-05	4
X35	TA58L05F(T6L1ASNNQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-05	4
X35	TA58L05F(T6L1FD,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-05	4
X35	TA58L05F(T6L1FJTNQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-05	4
X35	TA58L05F(T6L1HYANQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-05	4
X35	TA58L05F(T6L1KENNQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-05	4
X35	TA58L05F(T6L1MATNQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-05	4
X35	TA58L05F(T6L1MKANQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-05	4
X35	TA58L05F(T6L1NILNQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-05	4
X35	TA58L05F(T6L1PEVNBQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-05	4
X35	TA58L05F(T6L1PEWNBQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-05	4
X35	TA58L05F(T6L1PP,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-05	4
X35	TA58L05F(T6L1SANNQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-05	4
X35	TA58L05F(T6L1SAWNBQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-05	4
X35	TA58L05F(T6L1STNNQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-05	4
X35	TA58L05F(T6L1TOJNBQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-05	4
X35	TA58L05F(T6L1TYSNBQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-05	4
X35	TA58L05F(T6L1USNNQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-05	4
X35	TA58L05F(T6L1VISNBQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-05	4
X35	TA58L05F(T6L1YAZNBQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-05	4
X35	TA58L05F(T6L1YMNQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-05	4
X35	TA58L05F(T6L1YNSNBQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-05	4
X35	TA58L05F(TE16L1,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-05	4
X35	TA58L06F(6L1HTA,NQ	202004	202104	202110	3	NEWJAPANRADIO	NJM2886DL3-06	4
X35	TA58L06F(6L1HYA,NQ	202004	202104	202110	3	NEWJAPANRADIO	NJM2886DL3-06	4
X35	TA58L06F(6L1MBH,NQ	202004	202104	202110	3	NEWJAPANRADIO	NJM2886DL3-06	4

X35	TA58L06F(T6L1DNSNQ	202004	202104	202110	3	NEWJAPANRADIO	NJM2886DL3-06	4
X35	TA58L06F(T6L1HSZ)	202004	202104	202110	3	NEWJAPANRADIO	NJM2886DL3-06	4
X35	TA58L06F(T6L1PEVNO	202004	202104	202110	3	NEWJAPANRADIO	NJM2886DL3-06	4
X35	TA58L06F(T6L1SMINQ	202004	202104	202110	3	NEWJAPANRADIO	NJM2886DL3-06	4
X35	TA58L06F(TE16L1,NQ	202004	202104	202110	3	NEWJAPANRADIO	NJM2886DL3-06	4
X35	TA58L08F(6L1AST,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-08	4
X35	TA58L08F(6L1AST,NX	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-08	4
X35	TA58L08F(6L1CK,NQ)	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-08	4
X35	TA58L08F(6L1HAR,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-08	4
X35	TA58L08F(6L1HYM,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-08	4
X35	TA58L08F(6L1KEN,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-08	4
X35	TA58L08F(6L1NIS,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-08	4
X35	TA58L08F(6L1PTU,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-08	4
X35	TA58L08F(6L1SHR,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-08	4
X35	TA58L08F(T6L1ASNNO	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-08	4
X35	TA58L08F(T6L1CK,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-08	4
X35	TA58L08F(T6L1DNSNQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-08	4
X35	TA58L08F(T6L1FJTNO	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-08	4
X35	TA58L08F(T6L1HITNO	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-08	4
X35	TA58L08F(T6L1JECNO	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-08	4
X35	TA58L08F(T6L1TOJNO	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-08	4
X35	TA58L08F(T6L1YOKNO	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-08	4
X35	TA58L08F(TE16L1,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-08	4
X35	TA58L09F(6L1HTA,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-09	4
X35	TA58L09F(T6L1DNSNQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-09	4
X35	TA58L09F(T6L1HSZ)	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-09	4
X35	TA58L09F(T6L1JECNO	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-09	4
X35	TA58L09F(TE16L1,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-09	4
X35	TA58L10F(6L1DNS,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-10	4
X35	TA58L10F(6L1USN,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-10	4
X35	TA58L10F(T6L1HSZ)	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-10	4
X35	TA58L10F(T6L1JE,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-10	4
X35	TA58L10F(T6L1TYGNO	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-10	4
X35	TA58L10F(TE16L1,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-10	4
X35	TA58L12F(6L1SWF,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-12	4
X35	TA58L12F(T6L1ASTNO	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-12	4

X35	TA58L12F(T6L1JECNQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-12	4
X35	TA58L12F(T6L1MBJNQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-12	4
X35	TA58L12F(T6L1NKINQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-12	4
X35	TA58L12F(T6L1YZKNQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-12	4
X35	TA58L12F(TE16L1,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-12	4
X35	TA58L15F(6L1DNS,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-15	4
X35	TA58L15F(6L1HIT,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-15	4
X35	TA58L15F(T6L1YM,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-15	4
X35	TA58L15F(TE16L1,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-15	4
X35	TA58LT00F(T6L1,Q)	202004	202104	202110	2	infineon	TLE4252D	4
X35	TA58LT00F(T6L1A1Q	202004	202104	202110	2	infineon	TLE4252D	4
X35	TA58LT00F(T6L1AW,X	202004	202104	202110	2	infineon	TLE4252D	4
X35	TA58LT00F(T6L1BO,Q	202004	202104	202110	2	infineon	TLE4252D	4
X35	TA58LT00F(T6L1CK,Q	202004	202104	202110	2	infineon	TLE4252D	4
X35	TA58LT00F(T6L1DN,X	202004	202104	202110	2	infineon	TLE4252D	4
X35	TA58LT00F(T6L1HI,Q	202004	202104	202110	2	infineon	TLE4252D	4
X35	TA58LT00F(T6L1MBSQ	202004	202104	202110	2	infineon	TLE4252D	4
X35	TA58LT00F(T6L1PASQ	202004	202104	202110	2	infineon	TLE4252D	4
X35	TA58M05F(6L1AIT,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-05	4
X35	TA58M05F(6L1AST,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-05	4
X35	TA58M05F(6L1HIL,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-05	4
X35	TA58M05F(6L1HNJ,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-05	4
X35	TA58M05F(6L1MSD,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-05	4
X35	TA58M05F(6L1NLS,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-05	4
X35	TA58M05F(6L1SHI,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-05	4
X35	TA58M05F(T6L1BO,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-05	4
X35	TA58M05F(T6L1DNSNQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-05	4
X35	TA58M05F(T6L1OMINQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-05	4
X35	TA58M05F(T6L1TOJNQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-05	4
X35	TA58M05F(TE16L1,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-05	4
X35	TA58M06F(6L1AST,NQ	202004	202104	202110	3	NEWJAPANRADIO	NJM2886DL3-06	4
X35	TA58M06F(TE16L1,NQ	202004	202104	202110	3	NEWJAPANRADIO	NJM2886DL3-06	4
X35	TA58M08F(6L1SHR,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-08	4
X35	TA58M08F(6L1UME,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-08	4
X35	TA58M08F(T6L1HYANQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-08	4
X35	TA58M08F(TE16L1,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-08	4

X35	TA58M09F(6L1MTD,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-09	4	
X35	TA58M09F(T6L1HSZ)	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-09	4	
X35	TA58M09F(TE16L1,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-09	4	
X35	TA58M10F(T6L1HSZ)	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-10	4	
X35	TA58M10F(TE16L1,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-10	4	
X35	TA58M12F(T6L1DI,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-12	4	
X35	TA58M12F(TE16L1,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-12	4	Y
X35	TA58M15F(T6L1TO,NX	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-15	4	
X35	TA58M15F(TE16L1,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM2835DL1-15	4	Y
X35	TA58MS00F(6L1APN,Q	202004	202104	202110	3	NEWJAPANRADIO	NJM2387ADL3	4	Y
X35	TA58MS00F(6L1PAI,Q	202004	202104	202110	3	NEWJAPANRADIO	NJM2387ADL3	4	
X35	TA58MS00F(6L1SNKDQ	202004	202104	202110	3	NEWJAPANRADIO	NJM2387ADL3	4	
X35	TA58MS00F(TE16L1,Q	202004	202104	202110	3	NEWJAPANRADIO	NJM2387ADL3	4	Y
X35	TA58MS033F(6L1AP,Q	202004	202104	202110	2	NEWJAPANRADIO	NJW4185DL3-33A	4	
X35	TA58MS033F(6L1AS,X	202004	202104	202110	2	NEWJAPANRADIO	NJW4185DL3-33A	4	
X35	TA58MS033F(6L1TO,Q	202004	202104	202110	2	NEWJAPANRADIO	NJW4185DL3-33A	4	
X35	TA58MS033F(L1TOJ,X	202004	202104	202110	2	NEWJAPANRADIO	NJW4185DL3-33A	4	
X35	TA58MS033F(TE16L1Q	202004	202104	202110	2	NEWJAPANRADIO	NJW4185DL3-33A	4	
X35	TA58MS05F(6L1DNS,Q	202004	202104	202110	2	NEWJAPANRADIO	NJW4185DL3-05A	4	
X35	TA58MS05F(6L1FJT,Q	202004	202104	202110	2	NEWJAPANRADIO	NJW4185DL3-05A	4	
X35	TA58MS05F(6L1TOR,X	202004	202104	202110	2	NEWJAPANRADIO	NJW4185DL3-05A	4	
X35	TA58MS05F(6L1YME,Q	202004	202104	202110	2	NEWJAPANRADIO	NJW4185DL3-05A	4	
X35	TA58MS05F(6L1YZK,Q	202004	202104	202110	2	NEWJAPANRADIO	NJW4185DL3-05A	4	
X35	TA58MS05F(TE16L1,Q	202004	202104	202110	2	NEWJAPANRADIO	NJW4185DL3-05A	4	
X35	TA58MS06F(6L1DNS,Q	202004	202104	202110	3	NEWJAPANRADIO	NJM2387ADL3	4	
X35	TA58MS06F(6L1PAI,Q	202004	202104	202110	3	NEWJAPANRADIO	NJM2387ADL3	4	
X35	TA58MS06F(T6L1AW,Q	202004	202104	202110	3	NEWJAPANRADIO	NJM2387ADL3	4	
X35	TA58MS06F(T6L1CK,Q	202004	202104	202110	3	NEWJAPANRADIO	NJM2387ADL3	4	
X35	TA58MS06F(T6L1DNSQ	202004	202104	202110	3	NEWJAPANRADIO	NJM2387ADL3	4	
X35	TA58MS06F(TE16L1,Q	202004	202104	202110	3	NEWJAPANRADIO	NJM2387ADL3	4	
X35	TA58MS08F(6L1PAI,Q	202004	202104	202110	2	NEWJAPANRADIO	NJW4185DL3-08A	4	
X35	TA58MS08F(6L1SHR,Q	202004	202104	202110	2	NEWJAPANRADIO	NJW4185DL3-08A	4	
X35	TA58MS08F(T6L1DNSQ	202004	202104	202110	2	NEWJAPANRADIO	NJW4185DL3-08A	4	
X35	TA58MS08F(TE16L1,Q	202004	202104	202110	2	NEWJAPANRADIO	NJW4185DL3-08A	4	
X35	TA58MS09F(6L1HTA,Q	202004	202104	202110	3	NEWJAPANRADIO	NJM2386ADL3-09	4	
X35	TA58MS09F(T6L1PAIQ	202004	202104	202110	3	NEWJAPANRADIO	NJM2386ADL3-09	4	

X35	TA58MS09F(TE16L1,Q	202004	202104	202110	3	NEWJAPANRADIO	NJM2386ADL3-09	4	Y
X35	TA58MS12F(6L1HTA,Q	202004	202104	202110	3	NEWJAPANRADIO	NJM2386ADL3-12	4	
X35	TA58MS12F(6L1YME,Q	202004	202104	202110	3	NEWJAPANRADIO	NJM2386ADL3-12	4	
X35	TA58MS12F(T6L1DNSQ	202004	202104	202110	3	NEWJAPANRADIO	NJM2386ADL3-12	4	
X35	TA58MS12F(TE16L1,Q	202004	202104	202110	3	NEWJAPANRADIO	NJM2386ADL3-12	4	
X35	TA76431AF(2LSONY,F	202004	202104	202110	2	NEWJAPANRADIO	NJM2390AU	4	
X35	TA76431AF(F)	202004	202104	202110	2	NEWJAPANRADIO	NJM2390AU	4	
X35	TA76431AF(OLD,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM2390AU	4	
X35	TA76431AF(T2LCANOF	202004	202104	202110	2	NEWJAPANRADIO	NJM2390AU	4	
X35	TA76431AF(T2LFUJDF	202004	202104	202110	2	NEWJAPANRADIO	NJM2390AU	4	
X35	TA76431AF(T2LOLD,F	202004	202104	202110	2	NEWJAPANRADIO	NJM2390AU	4	
X35	TA76431AF(T2LYZK,F	202004	202104	202110	2	NEWJAPANRADIO	NJM2390AU	4	
X35	TA76431AF(TE12L,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM2390AU	4	
X35	TA76431F(F)	202004	202104	202110	2	NEWJAPANRADIO	NJM2390U	4	Y
X35	TA76431F(OLD,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM2390U	4	
X35	TA76431F(S-OLY,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM2390U	4	
X35	TA76431F(T2L,HIT,F	202004	202104	202110	2	NEWJAPANRADIO	NJM2390U	4	
X35	TA76431F(T2LASAW,F	202004	202104	202110	2	NEWJAPANRADIO	NJM2390U	4	
X35	TA76431F(T2LCLAR,F	202004	202104	202110	2	NEWJAPANRADIO	NJM2390U	4	
X35	TA76431F(T2LFDKK,F	202004	202104	202110	2	NEWJAPANRADIO	NJM2390U	4	
X35	TA76431F(T2LFJTN,F	202004	202104	202110	2	NEWJAPANRADIO	NJM2390U	4	
X35	TA76431F(T2LHND,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM2390U	4	
X35	TA76431F(T2LKMC,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM2390U	4	
X35	TA76431F(T2LKOYO,F	202004	202104	202110	2	NEWJAPANRADIO	NJM2390U	4	
X35	TA76431F(T2LMATUDF	202004	202104	202110	2	NEWJAPANRADIO	NJM2390U	4	
X35	TA76431F(T2LMBHA,F	202004	202104	202110	2	NEWJAPANRADIO	NJM2390U	4	
X35	TA76431F(T2LMURATF	202004	202104	202110	2	NEWJAPANRADIO	NJM2390U	4	
X35	TA76431F(T2LNORITF	202004	202104	202110	2	NEWJAPANRADIO	NJM2390U	4	
X35	TA76431F(T2LOKI,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM2390U	4	
X35	TA76431F(T2LOLD,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM2390U	4	
X35	TA76431F(T2LOMII,F	202004	202104	202110	2	NEWJAPANRADIO	NJM2390U	4	
X35	TA76431F(T2LPAS,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM2390U	4	Y
X35	TA76431F(T2LPP,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM2390U	4	
X35	TA76431F(T2LSAWAFF	202004	202104	202110	2	NEWJAPANRADIO	NJM2390U	4	
X35	TA76431F(T2LSHRP,F	202004	202104	202110	2	NEWJAPANRADIO	NJM2390U	4	
X35	TA76431F(T2LSIST,F	202004	202104	202110	2	NEWJAPANRADIO	NJM2390U	4	

X35	TA76431F(T2LSUMIKF	202004	202104	202110	2	NEWJAPANRADIO	NJM2390U	4	
X35	TA76431F(T2LTOJS,F	202004	202104	202110	2	NEWJAPANRADIO	NJM2390U	4	
X35	TA76431F(T2LTYG,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM2390U	4	
X35	TA76431F(T2LYASK,F	202004	202104	202110	2	NEWJAPANRADIO	NJM2390U	4	
X35	TA76431F(T2LYAZK,F	202004	202104	202110	2	NEWJAPANRADIO	NJM2390U	4	
X35	TA76431F(T2LYM,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM2390U	4	
X35	TA76431F(TE12L,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM2390U	4	Y
X35	TA76431FR(T2LMATUF	202004	202104	202110	2	NEWJAPANRADIO	NJM2380U	4	
X35	TA76431FR(T2LOKI,F	202004	202104	202110	2	NEWJAPANRADIO	NJM2380U	4	
X35	TA76431FR(T2LOLD,F	202004	202104	202110	2	NEWJAPANRADIO	NJM2380U	4	
X35	TA76431FR(T2LPAL,F	202004	202104	202110	2	NEWJAPANRADIO	NJM2380U	4	
X35	TA76431FR(T2LPP,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM2380U	4	
X35	TA76431FR(T2LSHR,F	202004	202104	202110	2	NEWJAPANRADIO	NJM2380U	4	
X35	TA76431FR(TE12L,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM2380U	4	
X35	TA76432AF(2LDNS2,F	202004	202104	202110	2	NEWJAPANRADIO	NJM2376U	4	
X35	TA76432AF(F)	202004	202104	202110	2	NEWJAPANRADIO	NJM2376U	4	
X35	TA76432AF(OLD,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM2376U	4	
X35	TA76432AF(T2LDNSOF	202004	202104	202110	2	NEWJAPANRADIO	NJM2376U	4	
X35	TA76432AF(T2LFD,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM2376U	4	
X35	TA76432AF(T2LFD1,F	202004	202104	202110	2	NEWJAPANRADIO	NJM2376U	4	
X35	TA76432AF(T2LOLD,F	202004	202104	202110	2	NEWJAPANRADIO	NJM2376U	4	
X35	TA76432AF(T2LTYG,F	202004	202104	202110	2	NEWJAPANRADIO	NJM2376U	4	
X35	TA76432AF(TE12L,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM2376U	4	
X35	TA76432AFR(F)	202004	202104	202110	2	NEWJAPANRADIO	NJM2373AU	4	
X35	TA76432AFR(OLD,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM2373AU	4	
X35	TA76432AFR(T2LJV,F	202004	202104	202110	2	NEWJAPANRADIO	NJM2373AU	4	
X35	TA76432AFR(T2LOLDF	202004	202104	202110	2	NEWJAPANRADIO	NJM2373AU	4	
X35	TA76432AFR(TE12L,F	202004	202104	202110	2	NEWJAPANRADIO	NJM2373AU	4	
X35	TA76432AFT(5LCOS,F	202004	202104	202110	2	NEWJAPANRADIO	NJM2822F	4	
X35	TA76432AFT(5LMTD,F	202004	202104	202110	2	NEWJAPANRADIO	NJM2822F	4	
X35	TA76432AFT(5LNKO,F	202004	202104	202110	2	NEWJAPANRADIO	NJM2822F	4	
X35	TA76432AFT(T5LMURF	202004	202104	202110	2	NEWJAPANRADIO	NJM2822F	4	
X35	TA76432AFT(T5LTOF)	202004	202104	202110	2	NEWJAPANRADIO	NJM2822F	4	
X35	TA76432AFT(TE85L,F	202004	202104	202110	2	NEWJAPANRADIO	NJM2822F	4	
X35	TA76432F(F)	202004	202104	202110	2	NEWJAPANRADIO	NJM2376U	4	
X35	TA76432F(OLD,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM2376U	4	

X35	TA76432F(T2LASAW,F	202004	202104	202110	2	NEWJAPANRADIO	NJM2376U	4	
X35	TA76432F(T2LDNSO,F	202004	202104	202110	2	NEWJAPANRADIO	NJM2376U	4	
X35	TA76432F(T2LFD,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM2376U	4	
X35	TA76432F(T2LMURATF	202004	202104	202110	2	NEWJAPANRADIO	NJM2376U	4	
X35	TA76432F(T2LOLD,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM2376U	4	
X35	TA76432F(T2LOMII,F	202004	202104	202110	2	NEWJAPANRADIO	NJM2376U	4	
X35	TA76432F(T2LPCA,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM2376U	4	
X35	TA76432F(T2LTOYOGF	202004	202104	202110	2	NEWJAPANRADIO	NJM2376U	4	
X35	TA76432F(TE12L,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM2376U	4	
X35	TA76432FC(T5LASH,F	202004	202104	202110	2	NEWJAPANRADIO	NJM2822F	4	
X35	TA76432FC(T5LCANOF	202004	202104	202110	2	NEWJAPANRADIO	NJM2822F	4	
X35	TA76432FC(T5LCA-OF	202004	202104	202110	2	NEWJAPANRADIO	NJM2822F	4	
X35	TA76432FC(T5LMATUF	202004	202104	202110	2	NEWJAPANRADIO	NJM2822F	4	
X35	TA76432FC(T5LNCN,F	202004	202104	202110	2	NEWJAPANRADIO	NJM2822F	4	
X35	TA76432FC(T5LPAV,F	202004	202104	202110	2	NEWJAPANRADIO	NJM2822F	4	Y
X35	TA76432FC(T5LSAN,F	202004	202104	202110	2	NEWJAPANRADIO	NJM2822F	4	
X35	TA76432FC(TE85L,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM2822F	4	Y
X35	TA76432FR(T2LOLD,F	202004	202104	202110	2	NEWJAPANRADIO	NJM2373AU	4	
X35	TA76432FR(TE12L,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM2373AU	4	
X35	TA76432FT(5LMBHA,F	202004	202104	202110	2	NEWJAPANRADIO	NJM2822F	4	
X35	TA76432FT(5LTOJ1,F	202004	202104	202110	2	NEWJAPANRADIO	NJM2822F	4	
X35	TA76432FT(5LTOJS,F	202004	202104	202110	2	NEWJAPANRADIO	NJM2822F	4	
X35	TA76432FT(T5LDAI,F	202004	202104	202110	2	NEWJAPANRADIO	NJM2822F	4	
X35	TA76432FT(T5LFJT2F	202004	202104	202110	2	NEWJAPANRADIO	NJM2822F	4	
X35	TA76432FT(T5LFJTNF	202004	202104	202110	2	NEWJAPANRADIO	NJM2822F	4	
X35	TA76432FT(T5LMURAF	202004	202104	202110	2	NEWJAPANRADIO	NJM2822F	4	
X35	TA76432FT(T8LFJTNF	202004	202104	202110	2	NEWJAPANRADIO	NJM2822F	4	
X35	TA76432FT(TE85L,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM2822F	4	
X35	TA76L431FB(5LHOS,F	202004	202104	202110	3	NEWJAPANRADIO	NJM2380AF	4	
X35	TA76L431FB(5LMDN,F	202004	202104	202110	3	NEWJAPANRADIO	NJM2380AF	4	
X35	TA76L431FB(5LPAI,F	202004	202104	202110	3	NEWJAPANRADIO	NJM2380AF	4	
X35	TA76L431FB(T5LCO,F	202004	202104	202110	3	NEWJAPANRADIO	NJM2380AF	4	
X35	TA76L431FB(T5LKO,F	202004	202104	202110	3	NEWJAPANRADIO	NJM2380AF	4	Y
X35	TA76L431FB(T5LMI,F	202004	202104	202110	3	NEWJAPANRADIO	NJM2380AF	4	
X35	TA76L431FB(T5LPEDF	202004	202104	202110	3	NEWJAPANRADIO	NJM2380AF	4	
X35	TA76L431FB(T5LPP,F	202004	202104	202110	3	NEWJAPANRADIO	NJM2380AF	4	

X35	TA76L431FB(TE85L,F	202004	202104	202110	3	NEWJAPANRADIO	NJM2380AF	4	
X35	TA76L431FT(5LKMC,F	202004	202104	202110	2	NEWJAPANRADIO	NJM2380AF	4	
X35	TA76L431FT(5LMTD,F	202004	202104	202110	2	NEWJAPANRADIO	NJM2380AF	4	
X35	TA76L431FT(5LNIT,F	202004	202104	202110	2	NEWJAPANRADIO	NJM2380AF	4	
X35	TA76L431FT(5LOMI,F	202004	202104	202110	2	NEWJAPANRADIO	NJM2380AF	4	
X35	TA76L431FT(5LPP1,F	202004	202104	202110	2	NEWJAPANRADIO	NJM2380AF	4	
X35	TA76L431FT(5LTO1,F	202004	202104	202110	2	NEWJAPANRADIO	NJM2380AF	4	
X35	TA76L431FT(5LTOJ,F	202004	202104	202110	2	NEWJAPANRADIO	NJM2380AF	4	
X35	TA76L431FT(T5LFJ,F	202004	202104	202110	2	NEWJAPANRADIO	NJM2380AF	4	
X35	TA76L431FT(T5LKOYF	202004	202104	202110	2	NEWJAPANRADIO	NJM2380AF	4	
X35	TA76L431FT(T5LPP,F	202004	202104	202110	2	NEWJAPANRADIO	NJM2380AF	4	
X35	TA76L431FT(T5LTOJF	202004	202104	202110	2	NEWJAPANRADIO	NJM2380AF	4	
X35	TA76L431FT(TE85L,F	202004	202104	202110	2	NEWJAPANRADIO	NJM2380AF	4	
X35	TA76L431FT,LTOHF(O	202004	202104	202110	2	NEWJAPANRADIO	NJM2380AF	4	
X35	TA7804AF(6L1KYS,NX	202004	202104	202110	0			4	
X35	TA78057F(6L1PES,NQ	202004	202104	202110	0			4	
X35	TA78057F(TE16L1,NQ	202004	202104	202110	0			4	
X35	TA7805F(6L1HTA,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM7805SDL1	4	
X35	TA7805F(6L1NANT,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM7805SDL1	4	
X35	TA7805F(6L1NLS,NQ)	202004	202104	202110	2	NEWJAPANRADIO	NJM7805SDL1	4	
X35	TA7805F(T6L1ALP,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM7805SDL1	4	
X35	TA7805F(T6L1AST,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM7805SDL1	4	
X35	TA7805F(T6L1DIA,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM7805SDL1	4	
X35	TA7805F(T6L1DLP,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM7805SDL1	4	
X35	TA7805F(T6L1MBS,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM7805SDL1	4	
X35	TA7805F(T6L1NKO,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM7805SDL1	4	
X35	TA7805F(T6L1PHA,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM7805SDL1	4	
X35	TA7805F(T6L1PP1,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM7805SDL1	4	
X35	TA7805F(T6L1TKT,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM7805SDL1	4	
X35	TA7805F(TE16L1,NQ)	202004	202104	202110	2	NEWJAPANRADIO	NJM7805SDL1	4	Y
X35	TA7806F(TE16L1,NQ)	202004	202104	202110	2	NEWJAPANRADIO	NJM7806DL1A	4	
X35	TA7807F(6L1NANT,NQ	202004	202104	202110	2	ROHM	BA17807FP	4	
X35	TA7807F(6L1NLS,NQ)	202004	202104	202110	2	ROHM	BA17807FP	4	
X35	TA7807F(T6L1CK,NQ)	202004	202104	202110	2	ROHM	BA17807FP	4	
X35	TA7807F(T6L1FIG,NQ	202004	202104	202110	2	ROHM	BA17807FP	4	
X35	TA7807F(TE16L1,NQ)	202004	202104	202110	2	ROHM	BA17807FP	4	

X35	TA7808F(T6L1FJT,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM7808SDL1	4
X35	TA7808F(T6L1HAR,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM7808SDL1	4
X35	TA7808F(T6L1MBS,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM7808SDL1	4
X35	TA7808F(T6L1NAN,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM7808SDL1	4
X35	TA7808F(TE16L1,NQ)	202004	202104	202110	2	NEWJAPANRADIO	NJM7808SDL1	4
X35	TA7809F(T6L1ALP,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM7809DL1A	4
X35	TA7809F(T6L1MBS,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM7809DL1A	4
X35	TA7809F(T6L1PP1,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM7809DL1A	4
X35	TA7809F(TE16L1,NQ)	202004	202104	202110	2	NEWJAPANRADIO	NJM7809DL1A	4
X35	TA7810F(TE16L1,NQ)	202004	202104	202110	2	NEWJAPANRADIO	NJM7810DL1A	4
X35	TA7812F(T6L1TAN,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM7812SDL1	4
X35	TA7812F(T6L1TME,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM7812SDL1	4
X35	TA7812F(TE16L1,NQ)	202004	202104	202110	2	NEWJAPANRADIO	NJM7812SDL1	4
X35	TA7815F(TE16L1,NQ)	202004	202104	202110	2	NEWJAPANRADIO	NJM7815SDL1	4
X35	TA7818F(6L1NOHM,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM7818DL1A	4
X35	TA7818F(TE16L1,NQ)	202004	202104	202110	2	NEWJAPANRADIO	NJM7818DL1A	4
X35	TA7820F(TE16L1,NQ)	202004	202104	202110	2	NEWJAPANRADIO	NJM7820DL1A	4
X35	TA7824F(6L1ASHI,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM7824SDL1	4
X35	TA7824F(TE16L1,NQ)	202004	202104	202110	2	NEWJAPANRADIO	NJM7824SDL1	4
X35	TA78DS05AF(2LASN,F	202004	202104	202110	2	NEWJAPANRADIO	NJW4182U3-05	4
X35	TA78DS05AF(2LFJI,F	202004	202104	202110	2	NEWJAPANRADIO	NJW4182U3-05	4
X35	TA78DS05AF(2LTYG,F	202004	202104	202110	2	NEWJAPANRADIO	NJW4182U3-05	4
X35	TA78DS05AF(2LVIS,F	202004	202104	202110	2	NEWJAPANRADIO	NJW4182U3-05	4
X35	TA78DS05AF(T2LASWF	202004	202104	202110	2	NEWJAPANRADIO	NJW4182U3-05	4
X35	TA78DS05AF(T2LCK,F	202004	202104	202110	2	NEWJAPANRADIO	NJW4182U3-05	4
X35	TA78DS05AF(T2LDN1F	202004	202104	202110	2	NEWJAPANRADIO	NJW4182U3-05	4
X35	TA78DS05AF(T2LDNSF	202004	202104	202110	2	NEWJAPANRADIO	NJW4182U3-05	4
X35	TA78DS05AF(T2LHITF	202004	202104	202110	2	NEWJAPANRADIO	NJW4182U3-05	4
X35	TA78DS05AF(T2LKO,F	202004	202104	202110	2	NEWJAPANRADIO	NJW4182U3-05	4
X35	TA78DS05AF(T2LKO1F	202004	202104	202110	2	NEWJAPANRADIO	NJW4182U3-05	4
X35	TA78DS05AF(T2LNHEF	202004	202104	202110	2	NEWJAPANRADIO	NJW4182U3-05	4
X35	TA78DS05AF(T2LNS,F	202004	202104	202110	2	NEWJAPANRADIO	NJW4182U3-05	4
X35	TA78DS05AF(T2LNSNF	202004	202104	202110	2	NEWJAPANRADIO	NJW4182U3-05	4
X35	TA78DS05AF(T2LOLDF	202004	202104	202110	2	NEWJAPANRADIO	NJW4182U3-05	4
X35	TA78DS05AF(T2LSUMF	202004	202104	202110	2	NEWJAPANRADIO	NJW4182U3-05	4
X35	TA78DS05AF(T2LWMAF	202004	202104	202110	2	NEWJAPANRADIO	NJW4182U3-05	4

X35	TA78DS05AF(TE12L,F	202004	202104	202110	2	NEWJAPANRADIO	NJW4182U3-05	4	Y
X35	TA78DS05F(T2LAL,F)	202004	202104	202110	3	NEWJAPANRADIO	NJM2831F-05	4	
X35	TA78DS05F(T2LHO,F)	202004	202104	202110	3	NEWJAPANRADIO	NJM2831F-05	4	
X35	TA78DS05F(T2LMKA,F	202004	202104	202110	3	NEWJAPANRADIO	NJM2831F-05	4	
X35	TA78DS05F(T2LNS,F)	202004	202104	202110	3	NEWJAPANRADIO	NJM2831F-05	4	
X35	TA78DS05F(T2LOKI,F	202004	202104	202110	3	NEWJAPANRADIO	NJM2831F-05	4	Y
X35	TA78DS05F(T2LOLD,F	202004	202104	202110	3	NEWJAPANRADIO	NJM2831F-05	4	
X35	TA78DS05F(T2LPAS,F	202004	202104	202110	3	NEWJAPANRADIO	NJM2831F-05	4	
X35	TA78DS05F(T2LPEW,F	202004	202104	202110	3	NEWJAPANRADIO	NJM2831F-05	4	
X35	TA78DS05F(T2LSHINF	202004	202104	202110	3	NEWJAPANRADIO	NJM2831F-05	4	
X35	TA78DS05F(T2LSINDF	202004	202104	202110	3	NEWJAPANRADIO	NJM2831F-05	4	
X35	TA78DS05F(T2LSONYF	202004	202104	202110	3	NEWJAPANRADIO	NJM2831F-05	4	
X35	TA78DS05F(T2LTORKF	202004	202104	202110	3	NEWJAPANRADIO	NJM2831F-05	4	
X35	TA78DS05F(T2LVIS,F	202004	202104	202110	3	NEWJAPANRADIO	NJM2831F-05	4	
X35	TA78DS05F(T2ROLD,F	202004	202104	202110	3	NEWJAPANRADIO	NJM2831F-05	4	
X35	TA78DS05F(T2RTORKF	202004	202104	202110	3	NEWJAPANRADIO	NJM2831F-05	4	
X35	TA78DS05F(T2RTOYOF	202004	202104	202110	3	NEWJAPANRADIO	NJM2831F-05	4	
X35	TA78DS05F(TE12L,F)	202004	202104	202110	3	NEWJAPANRADIO	NJM2831F-05	4	Y
X35	TA78DS05F(TE12R,F)	202004	202104	202110	3	NEWJAPANRADIO	NJM2831F-05	4	
X35	TA78DS06F(T2LDNS,F	202004	202104	202110	3	NEWJAPANRADIO	NJM2831F-06	4	
X35	TA78DS06F(T2LOLD,F	202004	202104	202110	3	NEWJAPANRADIO	NJM2831F-06	4	
X35	TA78DS06F(TE12L,F)	202004	202104	202110	3	NEWJAPANRADIO	NJM2831F-06	4	
X35	TA78DS08F(2LKENW,F	202004	202104	202110	3	NEWJAPANRADIO	NJM2831F-08	4	
X35	TA78DS08F(2LOMII,F	202004	202104	202110	3	NEWJAPANRADIO	NJM2831F-08	4	
X35	TA78DS08F(T2LDNSF	202004	202104	202110	3	NEWJAPANRADIO	NJM2831F-08	4	
X35	TA78DS08F(T2LFDS,F	202004	202104	202110	3	NEWJAPANRADIO	NJM2831F-08	4	
X35	TA78DS08F(T2LNSE,F	202004	202104	202110	3	NEWJAPANRADIO	NJM2831F-08	4	
X35	TA78DS08F(T2LOLD,F	202004	202104	202110	3	NEWJAPANRADIO	NJM2831F-08	4	
X35	TA78DS08F(T2LTRS,F	202004	202104	202110	3	NEWJAPANRADIO	NJM2831F-08	4	
X35	TA78DS08F(TE12L,F)	202004	202104	202110	3	NEWJAPANRADIO	NJM2831F-08	4	Y
X35	TA78DS09F(2LDNSO,F	202004	202104	202110	3	NEWJAPANRADIO	NJM2831F-09	4	
X35	TA78DS09F(T2LOLD,F	202004	202104	202110	3	NEWJAPANRADIO	NJM2831F-09	4	
X35	TA78DS09F(TE12L,F)	202004	202104	202110	3	NEWJAPANRADIO	NJM2831F-09	4	
X35	TA78DS10F(T2LDNSOF	202004	202104	202110	3	NEWJAPANRADIO	NJM2831F-10	4	
X35	TA78DS10F(T2LMTSAF	202004	202104	202110	3	NEWJAPANRADIO	NJM2831F-10	4	
X35	TA78DS10F(T2LOLD,F	202004	202104	202110	3	NEWJAPANRADIO	NJM2831F-10	4	

X35	TA78DS10F(T2LTYG,F	202004	202104	202110	3	NEWJAPANRADIO	NJM2831F-10	4	
X35	TA78DS10F(TE12L,F)	202004	202104	202110	3	NEWJAPANRADIO	NJM2831F-10	4	Y
X35	TA78DS12F(F)	202004	202104	202110	3	NEWJAPANRADIO	NJM2831F-12	4	
X35	TA78DS12F(OLD,F)	202004	202104	202110	3	NEWJAPANRADIO	NJM2831F-12	4	
X35	TA78DS12F(T2LOLD,F	202004	202104	202110	3	NEWJAPANRADIO	NJM2831F-12	4	
X35	TA78DS12F(TE12L,F)	202004	202104	202110	3	NEWJAPANRADIO	NJM2831F-12	4	
X35	TA78DS15F(T2LOLD,F	202004	202104	202110	3	NEWJAPANRADIO	NJM2831F-15	4	
X35	TA78DS15F(TE12L,F)	202004	202104	202110	3	NEWJAPANRADIO	NJM2831F-15	4	
X35	TA78L05F(2LALPSA,F	202004	202104	202110	2	NEWJAPANRADIO	NJM78L05SU3	4	
X35	TA78L05F(2LPSD2,ZF	202004	202104	202110	2	NEWJAPANRADIO	NJM78L05SU3	4	
X35	TA78L05F(F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L05SU3	4	Y
X35	TA78L05F(SONY,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L05SU3	4	
X35	TA78L05F(T2LAISI2F	202004	202104	202110	2	NEWJAPANRADIO	NJM78L05SU3	4	
X35	TA78L05F(T2LARRK,F	202004	202104	202110	2	NEWJAPANRADIO	NJM78L05SU3	4	
X35	TA78L05F(T2LCANONF	202004	202104	202110	2	NEWJAPANRADIO	NJM78L05SU3	4	
X35	TA78L05F(T2LFUEF,F	202004	202104	202110	2	NEWJAPANRADIO	NJM78L05SU3	4	
X35	TA78L05F(T2LFUJDSF	202004	202104	202110	2	NEWJAPANRADIO	NJM78L05SU3	4	
X35	TA78L05F(T2LFUJT,F	202004	202104	202110	2	NEWJAPANRADIO	NJM78L05SU3	4	
X35	TA78L05F(T2LFUJT2F	202004	202104	202110	2	NEWJAPANRADIO	NJM78L05SU3	4	
X35	TA78L05F(T2LFUJT3F	202004	202104	202110	2	NEWJAPANRADIO	NJM78L05SU3	4	
X35	TA78L05F(T2LINN,ZF	202004	202104	202110	2	NEWJAPANRADIO	NJM78L05SU3	4	
X35	TA78L05F(T2LKENW,F	202004	202104	202110	2	NEWJAPANRADIO	NJM78L05SU3	4	
X35	TA78L05F(T2LMATIMF	202004	202104	202110	2	NEWJAPANRADIO	NJM78L05SU3	4	
X35	TA78L05F(T2LMATU1F	202004	202104	202110	2	NEWJAPANRADIO	NJM78L05SU3	4	
X35	TA78L05F(T2LMATUDF	202004	202104	202110	2	NEWJAPANRADIO	NJM78L05SU3	4	
X35	TA78L05F(T2LMBSS,F	202004	202104	202110	2	NEWJAPANRADIO	NJM78L05SU3	4	
X35	TA78L05F(T2LMIK,ZF	202004	202104	202110	2	NEWJAPANRADIO	NJM78L05SU3	4	
X35	TA78L05F(T2LMKAI,F	202004	202104	202110	2	NEWJAPANRADIO	NJM78L05SU3	4	
X35	TA78L05F(T2LMTD,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L05SU3	4	
X35	TA78L05F(T2LNANT,F	202004	202104	202110	2	NEWJAPANRADIO	NJM78L05SU3	4	
X35	TA78L05F(T2LNS,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L05SU3	4	
X35	TA78L05F(T2LNSEIKF	202004	202104	202110	2	NEWJAPANRADIO	NJM78L05SU3	4	
X35	TA78L05F(T2LOMII,F	202004	202104	202110	2	NEWJAPANRADIO	NJM78L05SU3	4	
X35	TA78L05F(T2LOPTEXF	202004	202104	202110	2	NEWJAPANRADIO	NJM78L05SU3	4	
X35	TA78L05F(T2LPP,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L05SU3	4	
X35	TA78L05F(T2LPP2,ZF	202004	202104	202110	2	NEWJAPANRADIO	NJM78L05SU3	4	

X35	TA78L05F(T2LPSD,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L05SU3	4	
X35	TA78L05F(T2LPSD1,F	202004	202104	202110	2	NEWJAPANRADIO	NJM78L05SU3	4	
X35	TA78L05F(T2LPSD2,F	202004	202104	202110	2	NEWJAPANRADIO	NJM78L05SU3	4	
X35	TA78L05F(T2LPSIL,F	202004	202104	202110	2	NEWJAPANRADIO	NJM78L05SU3	4	
X35	TA78L05F(T2LRBCONF	202004	202104	202110	2	NEWJAPANRADIO	NJM78L05SU3	4	
X35	TA78L05F(T2LRUKO,F	202004	202104	202110	2	NEWJAPANRADIO	NJM78L05SU3	4	
X35	TA78L05F(T2LSEP,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L05SU3	4	
X35	TA78L05F(T2LSHRP,F	202004	202104	202110	2	NEWJAPANRADIO	NJM78L05SU3	4	
X35	TA78L05F(T2LSNAB,F	202004	202104	202110	2	NEWJAPANRADIO	NJM78L05SU3	4	
X35	TA78L05F(T2LSONY,F	202004	202104	202110	2	NEWJAPANRADIO	NJM78L05SU3	4	
X35	TA78L05F(T2LTKE,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L05SU3	4	
X35	TA78L05F(T2LTOAD,F	202004	202104	202110	2	NEWJAPANRADIO	NJM78L05SU3	4	
X35	TA78L05F(T2LTOJS,F	202004	202104	202110	2	NEWJAPANRADIO	NJM78L05SU3	4	
X35	TA78L05F(T2LTOKO,F	202004	202104	202110	2	NEWJAPANRADIO	NJM78L05SU3	4	
X35	TA78L05F(T2LTOYB,F	202004	202104	202110	2	NEWJAPANRADIO	NJM78L05SU3	4	
X35	TA78L05F(T2LUSN,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L05SU3	4	
X35	TA78L05F(T2LYM,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L05SU3	4	
X35	TA78L05F(T2LYTKD,F	202004	202104	202110	2	NEWJAPANRADIO	NJM78L05SU3	4	
X35	TA78L05F(T2RASMO,F	202004	202104	202110	2	NEWJAPANRADIO	NJM78L05SU3	4	
X35	TA78L05F(T2RMAT-HF	202004	202104	202110	2	NEWJAPANRADIO	NJM78L05SU3	4	
X35	TA78L05F(T2RND,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L05SU3	4	
X35	TA78L05F(T2RTOJS,F	202004	202104	202110	2	NEWJAPANRADIO	NJM78L05SU3	4	
X35	TA78L05F(T2RTOYO,F	202004	202104	202110	2	NEWJAPANRADIO	NJM78L05SU3	4	
X35	TA78L05F(TE12L,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L05SU3	4	Y
X35	TA78L05F(TE12L,ZF)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L05SU3	4	
X35	TA78L05F(TE12LCK,F	202004	202104	202110	2	NEWJAPANRADIO	NJM78L05SU3	4	
X35	TA78L05F(TE12R,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L05SU3	4	
X35	TA78L05F(TE12R,ZF)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L05SU3	4	
X35	TA78L05F(TORIKA,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L05SU3	4	
X35	TA78L05F(ZF)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L05SU3	4	
X35	TA78L05F,LASN2ZF(O	202004	202104	202110	2	NEWJAPANRADIO	NJM78L05SU3	4	
X35	TA78L05PF(5LCANO,F	202004	202104	202110	3	NEWJAPANRADIO	NJM78L05SU3	4	
X35	TA78L05PF(T5LKEH,F	202004	202104	202110	3	NEWJAPANRADIO	NJM78L05SU3	4	
X35	TA78L05PF(T5LSNY,F	202004	202104	202110	3	NEWJAPANRADIO	NJM78L05SU3	4	
X35	TA78L05PF(T5LYKO,F	202004	202104	202110	3	NEWJAPANRADIO	NJM78L05SU3	4	
X35	TA78L05PF(TE85L,F)	202004	202104	202110	3	NEWJAPANRADIO	NJM78L05SU3	4	Y

X35	TA78L06F(F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L06SU3	4	
X35	TA78L06F(SONY,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L06SU3	4	
X35	TA78L06F(T2LCK,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L06SU3	4	
X35	TA78L06F(T2LDNSO,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L06SU3	4	
X35	TA78L06F(T2LKENW,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L06SU3	4	
X35	TA78L06F(T2LSONY,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L06SU3	4	
X35	TA78L06F(T2RTORIKF)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L06SU3	4	
X35	TA78L06F(TE12L,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L06SU3	4	Y
X35	TA78L06F(TE12L,ZF)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L06SU3	4	
X35	TA78L06F(ZF)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L06SU3	4	
X35	TA78L06PF(T5LHIL,F)	202004	202104	202110	3	NEWJAPANRADIO	NJM78L06SU3	4	
X35	TA78L06PF(TE85L,F)	202004	202104	202110	3	NEWJAPANRADIO	NJM78L06SU3	4	
X35	TA78L07F(T2LFJTN,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L07UA	4	
X35	TA78L07F(T2LMATUDF)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L07UA	4	
X35	TA78L07F(T2LSONY,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L07UA	4	
X35	TA78L07F(TE12L,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L07UA	4	
X35	TA78L07F(TE12L,ZF)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L07UA	4	
X35	TA78L07PF(T5LSNY,F)	202004	202104	202110	3	NEWJAPANRADIO	NJM78L07UA	4	
X35	TA78L07PF(TE85L,F)	202004	202104	202110	3	NEWJAPANRADIO	NJM78L07UA	4	
X35	TA78L08F(F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L08SU3	4	
X35	TA78L08F(SONY,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L08SU3	4	
X35	TA78L08F(T2LAD,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L08SU3	4	
X35	TA78L08F(T2LAISINF)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L08SU3	4	
X35	TA78L08F(T2LFJTN,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L08SU3	4	
X35	TA78L08F(T2LKENW,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L08SU3	4	
X35	TA78L08F(T2LND,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L08SU3	4	
X35	TA78L08F(T2LNKOD,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L08SU3	4	
X35	TA78L08F(T2LSONY,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L08SU3	4	
X35	TA78L08F(T2LYOKOOF)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L08SU3	4	
X35	TA78L08F(TE12L,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L08SU3	4	Y
X35	TA78L08F(TE12L,ZF)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L08SU3	4	
X35	TA78L08F(TE12LCK,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L08SU3	4	
X35	TA78L08F(ZF)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L08SU3	4	
X35	TA78L08F,LASNZF(O	202004	202104	202110	2	NEWJAPANRADIO	NJM78L08SU3	4	
X35	TA78L08PF(T5LSHRPF)	202004	202104	202110	3	NEWJAPANRADIO	NJM78L08SU3	4	
X35	TA78L08PF(T5LYOK,F)	202004	202104	202110	3	NEWJAPANRADIO	NJM78L08SU3	4	

X35	TA78L08PF(TE85L,F)	202004	202104	202110	3	NEWJAPANRADIO	NJM78L08SU3	4	
X35	TA78L09F(SONY,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L09UA	4	Y
X35	TA78L09F(T2LDNSO,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L09UA	4	
X35	TA78L09F(T2LHDE,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L09UA	4	
X35	TA78L09F(T2LPSD,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L09UA	4	
X35	TA78L09F(T2LSONY,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L09UA	4	
X35	TA78L09F(T2LTOLT,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L09UA	4	
X35	TA78L09F(TE12L,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L09UA	4	Y
X35	TA78L09F(TE12L,ZF)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L09UA	4	
X35	TA78L09F(TE12R,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L09UA	4	
X35	TA78L09F(TE12R,ZF)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L09UA	4	
X35	TA78L09PF(TE85L,F)	202004	202104	202110	3	NEWJAPANRADIO	NJM78L09UA	4	
X35	TA78L10F(F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L10SU3	4	Y
X35	TA78L10F(SONY,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L10SU3	4	
X35	TA78L10F(T2LDNSO,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L10SU3	4	
X35	TA78L10F(T2LFUJDSF)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L10SU3	4	
X35	TA78L10F(T2LINN,ZF)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L10SU3	4	
X35	TA78L10F(T2LPEV,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L10SU3	4	
X35	TA78L10F(TE12L,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L10SU3	4	Y
X35	TA78L10F(TE12L,ZF)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L10SU3	4	
X35	TA78L10F(TE12R,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L10SU3	4	
X35	TA78L10F(TE12R,ZF)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L10SU3	4	
X35	TA78L10F(ZF)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L10SU3	4	
X35	TA78L10PF(TE85L,F)	202004	202104	202110	3	NEWJAPANRADIO	NJM78L10SU3	4	
X35	TA78L12F(F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L12SU3	4	Y
X35	TA78L12F(SONY,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L12SU3	4	
X35	TA78L12F(T2LCANONF)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L12SU3	4	
X35	TA78L12F(T2LDNSO,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L12SU3	4	
X35	TA78L12F(T2LFJTN,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L12SU3	4	
X35	TA78L12F(T2LNSEIKF)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L12SU3	4	
X35	TA78L12F(T2LRBCONF)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L12SU3	4	
X35	TA78L12F(T2LSONY,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L12SU3	4	
X35	TA78L12F(T2LTOJS,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L12SU3	4	
X35	TA78L12F(T2LYASK,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L12SU3	4	
X35	TA78L12F(TE12L,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L12SU3	4	Y
X35	TA78L12F(TE12L,ZF)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L12SU3	4	

X35	TA78L12F(ZF)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L12SU3	4	
X35	TA78L12PF(TE85L,F)	202004	202104	202110	3	NEWJAPANRADIO	NJM78L12SU3	4	
X35	TA78L15F(F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L15SU3	4	Y
X35	TA78L15F(SONY,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L15SU3	4	
X35	TA78L15F(T2LDNSO,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L15SU3	4	
X35	TA78L15F(T2LFJTN,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L15SU3	4	
X35	TA78L15F(T2LMBSJKF)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L15SU3	4	
X35	TA78L15F(T2LPES,ZF)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L15SU3	4	
X35	TA78L15F(T2LSONY,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L15SU3	4	
X35	TA78L15F(T2LTAKEXF)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L15SU3	4	
X35	TA78L15F(T2LTOJS,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L15SU3	4	
X35	TA78L15F(T2LYAZK,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L15SU3	4	
X35	TA78L15F(TE12L,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L15SU3	4	Y
X35	TA78L15F(TE12L,ZF)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L15SU3	4	
X35	TA78L15F(TE12R,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L15SU3	4	
X35	TA78L15F(TE12R,ZF)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L15SU3	4	
X35	TA78L15F(ZF)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L15SU3	4	
X35	TA78L15PF(TE85L,F)	202004	202104	202110	3	NEWJAPANRADIO	NJM78L15SU3	4	
X35	TA78L18F(F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L18UA	4	Y
X35	TA78L18F(SONY,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L18UA	4	
X35	TA78L18F(T2LOMII,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L18UA	4	
X35	TA78L18F(TE12L,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L18UA	4	Y
X35	TA78L18F(TE12L,ZF)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L18UA	4	
X35	TA78L18F(ZF)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L18UA	4	
X35	TA78L20F(F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L20UA	4	
X35	TA78L20F(SONY,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L20UA	4	
X35	TA78L20F(T2LSONY,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L20UA	4	
X35	TA78L20F(TE12L,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L20UA	4	Y
X35	TA78L20F(TE12L,ZF)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L20UA	4	
X35	TA78L20F(ZF)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L20UA	4	
X35	TA78L24F(F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L24UA	4	Y
X35	TA78L24F(SONY,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L24UA	4	
X35	TA78L24F(TE12L,F)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L24UA	4	Y
X35	TA78L24F(TE12L,ZF)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L24UA	4	
X35	TA78L24F(ZF)	202004	202104	202110	2	NEWJAPANRADIO	NJM78L24UA	4	
X35	TA78M05F(6L1ARR,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM78M05SDL1	4	

X35	TA78M05F(6L1HO,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM78M05SDL1	4	
X35	TA78M05F(6L1KOY,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM78M05SDL1	4	
X35	TA78M05F(6L1NKI,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM78M05SDL1	4	
X35	TA78M05F(6L1PAP,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM78M05SDL1	4	
X35	TA78M05F(6L1PP1,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM78M05SDL1	4	
X35	TA78M05F(6L1PSC,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM78M05SDL1	4	
X35	TA78M05F(6L1SIN,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM78M05SDL1	4	
X35	TA78M05F(6L1YZS,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM78M05SDL1	4	
X35	TA78M05F(T6L1TOJNX	202004	202104	202110	2	NEWJAPANRADIO	NJM78M05SDL1	4	
X35	TA78M05F(TE16L1,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM78M05SDL1	4	
X35	TA78M06F(6L1NSA,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM78M06DL1A	4	
X35	TA78M06F(TE16L1,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM78M06DL1A	4	
X35	TA78M08F(6L1MBS,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM78M08DL1A	4	
X35	TA78M08F(TE16L1,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM78M08DL1A	4	
X35	TA78M09F(6L1ARR,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM78M09SDL1	4	
X35	TA78M09F(TE16L1,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM78M09SDL1	4	
X35	TA78M10F(TE16L1,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM7810DL1A	4	
X35	TA78M12F(6L1PSD,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM78M12SDL1	4	
X35	TA78M12F(TE16L1,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM78M12SDL1	4	
X35	TA78M15F(6L1MKA,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM78M15SDL1	4	
X35	TA78M15F(T6L1TOJNX	202004	202104	202110	2	NEWJAPANRADIO	NJM78M15SDL1	4	
X35	TA78M15F(TE16L1,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM78M15SDL1	4	
X35	TA78M18F(TE16L1,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM78M18DL1A	4	Y
X35	TA78M20F(TE16L1,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM78M20DL1A	4	Y
X35	TA78M24F(TE16L1,NQ	202004	202104	202110	2	NEWJAPANRADIO	NJM78M24DL1A	4	
X33	TJ120F06J3(4LAST,Q	202004	202104	202110	0			2	
X33	TJ120F06J3(4LMTS,Q	202004	202104	202110	0			2	
X33	TJ120F06J3(T4LHITQ	202004	202104	202110	0			2	
X33	TJ120F06J3(TE24L,Q	202004	202104	202110	0			2	Y
X33	TJ150F04M3L(4LPE,Q	202004	202104	202110	1	TOSHIBA	TJ200F04M3L	3	Y
X33	TJ150F04M3L(T4L,Q)	202004	202104	202110	1	TOSHIBA	TJ200F04M3L	3	
X33	TJ150F04M3L,LCHQ(O	202004	202104	202110	1	TOSHIBA	TJ200F04M3L	3	
X33	TJ150F04M3L,LTYQ(O	202004	202104	202110	1	TOSHIBA	TJ200F04M3L	3	
X35	TJT2361-A(P)	202004	202104	202110	0			4	
X33	TK100E03G1,S1X(S	202004	202104	202110	3	TOSHIBA	TPH2R003PL	2	
X33	TK100E10NE,S1AQ(S	202004	202104	202110	3	TOSHIBA	TK160F10N1L	3	

X33	TK100E10NE,S1BQ(S	202004	202104	202110	3	TOSHIBA	TK160F10N1L	3	
X33	TK100E10NE,S1Q(AS	202004	202104	202110	3	TOSHIBA	TK160F10N1L	3	
X33	TK100E10NE,S1Q(BS	202004	202104	202110	3	TOSHIBA	TK160F10N1L	3	
X33	TK100E10NE,S1Q(S	202004	202104	202110	3	TOSHIBA	TK160F10N1L	3	
X33	TK100J10NE,S1E(S	202004	202104	202110	3	TOSHIBA	TK160F10N1L	3	
X33	TK10A60D(LS1CN,A,Q	202004	202104	202110	2	TOSHIBA	TK750A60F,S4X(S	5	
X33	TK10A60D(LS1SDI,QM	202004	202104	202110	2	TOSHIBA	TK750A60F,S4X(S	5	
X33	TK10A60D(LS1SO6,AQ	202004	202104	202110	2	TOSHIBA	TK750A60F,S4X(S	5	
X33	TK10A60D(LS1SP6,QM	202004	202104	202110	2	TOSHIBA	TK750A60F,S4X(S	5	
X33	TK10A60D(MURATA,QM	202004	202104	202110	2	TOSHIBA	TK750A60F,S4X(S	5	
X33	TK10A60D(Q,M)	202004	202104	202110	2	TOSHIBA	TK750A60F,S4X(S	5	Y
X33	TK10A60D(S4LIT,XM)	202004	202104	202110	2	TOSHIBA	TK750A60F,S4X(S	5	
X33	TK10A60D(S4SA6,QM	202004	202104	202110	2	TOSHIBA	TK750A60F,S4X(S	5	
X33	TK10A60D(S4SAN6,QM	202004	202104	202110	2	TOSHIBA	TK750A60F,S4X(S	5	
X33	TK10A60D(S4SHR6,QM	202004	202104	202110	2	TOSHIBA	TK750A60F,S4X(S	5	
X33	TK10A60D(S4TET,X,M	202004	202104	202110	2	TOSHIBA	TK750A60F,S4X(S	5	
X33	TK10A60D(S4TET6,XM	202004	202104	202110	2	TOSHIBA	TK750A60F,S4X(S	5	
X33	TK10A60D(STA4,A,Q)	202004	202104	202110	2	TOSHIBA	TK750A60F,S4X(S	5	
X33	TK10A60D(STA4,Q,M)	202004	202104	202110	2	TOSHIBA	TK750A60F,S4X(S	5	Y
X33	TK10A60D(STA4,X,M)	202004	202104	202110	2	TOSHIBA	TK750A60F,S4X(S	5	Y
X33	TK10A60D(STA4,X,S)	202004	202104	202110	2	TOSHIBA	TK750A60F,S4X(S	5	
X33	TK10A60D,S5MU6Q(J	202004	202104	202110	2	TOSHIBA	TK750A60F,S4X(S	5	
X33	TK10A60D,S5Q(J	202004	202104	202110	2	TOSHIBA	TK750A60F,S4X(S	5	
X33	TK10A60D,S5SA6Q(J	202004	202104	202110	2	TOSHIBA	TK750A60F,S4X(S	5	
X33	TK10A60D,S5SAN6Q(J	202004	202104	202110	2	TOSHIBA	TK750A60F,S4X(S	5	
X33	TK10A60D5(Q,M)	202004	202104	202110	1	TOSHIBA	TK7A60W5	3	
X33	TK10A60D5(S4PHI,QM	202004	202104	202110	1	TOSHIBA	TK7A60W5	3	Y
X33	TK10A60DR(Q,M)	202004	202104	202110	2	TOSHIBA	TK750A60F,S4X(S	5	
X33	TK10A60DR(S4TEV,QM	202004	202104	202110	2	TOSHIBA	TK750A60F,S4X(S	2	
X33	TK10A60DR(S4TEV,XM	202004	202104	202110	2	TOSHIBA	TK750A60F,S4X(S	2	
X33	TK10A60DR(S4TEV,XS	202004	202104	202110	2	TOSHIBA	TK750A60F,S4X(S	2	
X33	TK10A60DR(S5TEV,AX	202004	202104	202110	2	TOSHIBA	TK750A60F,S4X(S	2	
X33	TK10A60DR(STA4,A,Q	202004	202104	202110	2	TOSHIBA	TK750A60F,S4X(S	5	
X33	TK10A60DR(STA4,Q,M	202004	202104	202110	2	TOSHIBA	TK750A60F,S4X(S	5	
X33	TK10A60DR(STA4,X,M	202004	202104	202110	1	TOSHIBA	TK750A60F,S4X(S	2	
X33	TK10A60DR,S4X(S	202004	202104	202110	2	TOSHIBA	TK750A60F,S4X(S	5	

X33	TK10A60DR,S5X(J	202004	202104	202110	2	TOSHIBA	TK750A60F,S4X(S	5	
X33	TK10A60E,S4X(S	202004	202104	202110	2	TOSHIBA	TK750A60F,S4X(S	2	Y
X33	TK10A60E,S5X(M	202004	202104	202110	2	TOSHIBA	TK750A60F,S4X(S	2	
X33	TK10A60W,S4VCX(M	202004	202104	202110	1	TOSHIBA	TK10A60W,S4VX(M	1	Y
X33	TK10A60W,S5X(J	202004	202104	202110	1	TOSHIBA	TK10A60W,S4VX(M	1	
X33	TK10P60W,RVCQ(S	202004	202104	202110	1	TOSHIBA	TK10P60W,RVQ(S	1	
X33	TK10X40D(T4LPSD,Q)	202004	202104	202110	3	TOSHIBA	TK12P60W,RPESQ(S	5	
X33	TK10X40D,LPESQ(O	202004	202104	202110	3	TOSHIBA	TK12P60W,RPESQ(S	5	
X33	TK11A60D(LBS1CN,QM	202004	202104	202110	2	TOSHIBA	TK650A60F,S4X(S	5	
X33	TK11A60D(LBS1TY,QM	202004	202104	202110	2	TOSHIBA	TK650A60F,S4X(S	5	
X33	TK11A60D(Q,M)	202004	202104	202110	2	TOSHIBA	TK650A60F,S4X(S	5	
X33	TK11A60D(S4SH6,Q,M	202004	202104	202110	2	TOSHIBA	TK650A60F,S4X(S	5	
X33	TK11A60D(S4TETV,XM	202004	202104	202110	2	TOSHIBA	TK650A60F,S4X(S	5	
X33	TK11A60D(S4TETV,XS	202004	202104	202110	2	TOSHIBA	TK650A60F,S4X(S	5	
X33	TK11A60D(S5TETV,XM	202004	202104	202110	2	TOSHIBA	TK650A60F,S4X(S	5	
X33	TK11A60D(STA4,A,Q)	202004	202104	202110	2	TOSHIBA	TK650A60F,S4X(S	5	
X33	TK11A60D(STA4,Q,M)	202004	202104	202110	2	TOSHIBA	TK650A60F,S4X(S	5	Y
X33	TK11A60D(STA4,X,M)	202004	202104	202110	2	TOSHIBA	TK650A60F,S4X(S	5	
X33	TK11A60D(STA4,X,S)	202004	202104	202110	2	TOSHIBA	TK650A60F,S4X(S	5	
X33	TK11A60D,S5Q(J	202004	202104	202110	2	TOSHIBA	TK650A60F,S4X(S	5	
X33	TK11A60DR(STA4,X,S	202004	202104	202110	2	TOSHIBA	TK650A60F,S4X(S	5	
X33	TK120F04J3(T4LHITQ	202004	202104	202110	3	TOSHIBA	TK1R5R04PB	2	
X33	TK12A50D5(Q,M)	202004	202104	202110	1	TOSHIBA	TK7A60W5	3	
X33	TK12A50D5,Q(M	202004	202104	202110	1	TOSHIBA	TK7A60W5	3	
X33	TK12A50D5,S5NDSQ(J	202004	202104	202110	1	TOSHIBA	TK7A60W5	3	
X33	TK12A50D5,S5NDSQ(M	202004	202104	202110	1	TOSHIBA	TK7A60W5	3	
X33	TK12A50E,S4X(S	202004	202104	202110	2	TOSHIBA	TK12A50D(STA4,X,M)	3	Y
X33	TK12A50E,S5X(M	202004	202104	202110	2	TOSHIBA	TK12A50D(STA4,X,M)	3	
X33	TK12A60U(LS1CNO,AQ	202004	202104	202110	2	TOSHIBA	TK380A60Y,S4X(S	5	
X33	TK12A60U(Q,M)	202004	202104	202110	2	TOSHIBA	TK380A60Y,S4X(S	5	
X33	TK12A60U(S4PHIL,QM	202004	202104	202110	2	TOSHIBA	TK380A60Y,S4X(S	5	Y
X33	TK12A60U(STA4,A,Q)	202004	202104	202110	2	TOSHIBA	TK380A60Y,S4X(S	5	
X33	TK12A60U(STA4,Q,M)	202004	202104	202110	2	TOSHIBA	TK380A60Y,S4X(S	2	Y
X33	TK12A60U(STA4,X,M)	202004	202104	202110	2	TOSHIBA	TK380A60Y,S4X(S	2	
X33	TK12A60U(STA4,X,S)	202004	202104	202110	2	TOSHIBA	TK380A60Y,S4X(S	2	
X33	TK12A60U,LS1NA1Q(J	202004	202104	202110	2	TOSHIBA	TK380A60Y,S4X(S	2	

X33	TK12A60U,S5HILQ(J	202004	202104	202110	2	TOSHIBA	TK380A60Y,S4X(S	5	
X33	TK12A60U,S5Q(J	202004	202104	202110	2	TOSHIBA	TK380A60Y,S4X(S	2	
X33	TK12E60U,S1X(S	202004	202104	202110	2	TOSHIBA	TK10E60W,S4VX(M	2	Y
X33	TK12J60U(F)	202004	202104	202110	2	TOSHIBA	TK12J60W,S1VE(S	2	Y
X33	TK12J60U(S1TEAL,F)	202004	202104	202110	2	TOSHIBA	TK12J60W,S1VE(S	5	
X33	TK12J60U(S1TEKR,F)	202004	202104	202110	2	TOSHIBA	TK12J60W,S1VE(S	5	
X33	TK12J60U(S1TET,F)	202004	202104	202110	2	TOSHIBA	TK12J60W,S1VE(S	2	
X33	TK12J60U(STA1,F)	202004	202104	202110	2	TOSHIBA	TK12J60W,S1VE(S	5	
X33	TK12X53D(T4LPSD,Q)	202004	202104	202110	3	TOSHIBA	TK12P60W,RPESQ(S	3	
X33	TK13A65U(LS1CAN,QM	202004	202104	202110	2	TOSHIBA	TK380A65Y,S4X(S	5	
X33	TK13A65U(LS1CANOQM	202004	202104	202110	2	TOSHIBA	TK380A65Y,S4X(S	5	
X33	TK13A65U(Q,M)	202004	202104	202110	2	TOSHIBA	TK380A65Y,S4X(S	5	
X33	TK13A65U(STA4,A,Q)	202004	202104	202110	2	TOSHIBA	TK380A65Y,S4X(S	2	
X33	TK13A65U(STA4,Q,M)	202004	202104	202110	2	TOSHIBA	TK380A65Y,S4X(S	2	Y
X33	TK13A65U(STA4,X,M)	202004	202104	202110	2	TOSHIBA	TK380A65Y,S4X(S	2	Y
X33	TK13A65U(STA4,X,S)	202004	202104	202110	2	TOSHIBA	TK380A65Y,S4X(S	2	Y
X33	TK13A65U,S4PHIQ(M	202004	202104	202110	2	TOSHIBA	TK380A65Y,S4X(S	5	
X33	TK13A65U,S5Q(J	202004	202104	202110	2	TOSHIBA	TK380A65Y,S4X(S	5	
X33	TK13A65U,S5SYEDQ(M	202004	202104	202110	2	TOSHIBA	TK380A65Y,S4X(S	2	
X33	TK13J65U(F)	202004	202104	202110	3	TOSHIBA	TK14N65W,S1F(S	5	
X33	TK13J65U(STA1,F)	202004	202104	202110	3	TOSHIBA	TK14N65W,S1F(S	5	
X33	TK150E09NE,S1Q(AS	202004	202104	202110	3	TOSHIBA	TK160F10N1L	3	
X33	TK150E09NE,S1Q(BS	202004	202104	202110	3	TOSHIBA	TK160F10N1L	3	
X33	TK150E09NE,S1Q(S	202004	202104	202110	3	TOSHIBA	TK160F10N1L	3	
X33	TK150E10NE,S1Q(AS	202004	202104	202110	3	TOSHIBA	TK160F10N1L	3	
X33	TK150E10NE,S1Q(BS	202004	202104	202110	3	TOSHIBA	TK160F10N1L	3	
X33	TK150E10NE,S1Q(S	202004	202104	202110	3	TOSHIBA	TK160F10N1L	3	
X33	TK150F04K3(4LHLS,Q	202004	202104	202110	1	TOSHIBA	TK200F04N1L	3	
X33	TK150F04K3(4LSOY,Q	202004	202104	202110	1	TOSHIBA	TK200F04N1L	3	
X33	TK150F04K3(TE24L,Q	202004	202104	202110	1	TOSHIBA	TK200F04N1L	3	Y
X33	TK150F04K3,LCHQ(O	202004	202104	202110	1	TOSHIBA	TK200F04N1L	3	
X33	TK15A60U(Q,M)	202004	202104	202110	2	TOSHIBA	TK290A60Y,S4X(S	5	
X33	TK15A60U(STA4,A,Q)	202004	202104	202110	2	TOSHIBA	TK290A60Y,S4X(S	5	
X33	TK15A60U(STA4,Q,M)	202004	202104	202110	2	TOSHIBA	TK290A60Y,S4X(S	2	Y
X33	TK15A60U(STA4,X,M)	202004	202104	202110	2	TOSHIBA	TK290A60Y,S4X(S	2	
X33	TK15A60U(STA4,X,S)	202004	202104	202110	2	TOSHIBA	TK290A60Y,S4X(S	2	

X33	TK15A60U,S5Q(J	202004	202104	202110	2	TOSHIBA	TK290A60Y,S4X(S	2	
X33	TK15E60U,S1X(S	202004	202104	202110	2	TOSHIBA	TK12E60W,S1VX(S	2	Y
X33	TK15J50D(S1V,E,S)	202004	202104	202110	1	TOSHIBA	TK15J50D(STA1,E,S)	3	
X33	TK15J60U(F)	202004	202104	202110	2	TOSHIBA	TK12J60W,S1VE(S	2	Y
X33	TK15J60U(S1TEAL,F)	202004	202104	202110	2	TOSHIBA	TK12J60W,S1VE(S	5	
X33	TK15J60U(S1TEKR,F)	202004	202104	202110	2	TOSHIBA	TK12J60W,S1VE(S	5	
X33	TK15J60U(S1TET,F)	202004	202104	202110	2	TOSHIBA	TK12J60W,S1VE(S	2	
X33	TK15J60U(SANKEN,F)	202004	202104	202110	2	TOSHIBA	TK12J60W,S1VE(S	5	
X33	TK15J60U(STA1,F)	202004	202104	202110	2	TOSHIBA	TK12J60W,S1VE(S	2	
X33	TK16A60W5,S5HIAX(J	202004	202104	202110	1	TOSHIBA	TK16A60W5,S5VX(J	3	
X33	TK17A65U(Q,M)	202004	202104	202110	2	TOSHIBA	TK290A65Y,S4X(S	5	
X33	TK17A65U(S5PHI,Q,M	202004	202104	202110	2	TOSHIBA	TK290A65Y,S4X(S	5	
X33	TK17A65U(STA4,A,Q)	202004	202104	202110	2	TOSHIBA	TK290A65Y,S4X(S	5	
X33	TK17A65U(STA4,Q,M)	202004	202104	202110	2	TOSHIBA	TK290A65Y,S4X(S	2	
X33	TK17A65U(STA4,X,M)	202004	202104	202110	2	TOSHIBA	TK290A65Y,S4X(S	2	
X33	TK17A65U(STA4,X,S)	202004	202104	202110	2	TOSHIBA	TK290A65Y,S4X(S	5	
X33	TK17A65U,S5Q(J	202004	202104	202110	2	TOSHIBA	TK290A65Y,S4X(S	5	
X33	TK17A65U,S5SOYX(M	202004	202104	202110	2	TOSHIBA	TK290A65Y,S4X(S	2	
X33	TK17J65U(F)	202004	202104	202110	3	TOSHIBA	TK14N65W,S1F(S	5	
X33	TK17J65U(STA1,F)	202004	202104	202110	3	TOSHIBA	TK14N65W,S1F(S	5	
X33	TK18A60V(S4V,X,S)	202004	202104	202110	2	TOSHIBA	TK16A60W,S4VX(M	2	
X33	TK18A60V(STA4,X,S)	202004	202104	202110	2	TOSHIBA	TK16A60W,S4VX(M	5	
X33	TK18A60V,LS1MBSX(J	202004	202104	202110	2	TOSHIBA	TK16A60W,S4VX(M	5	
X33	TK18A60V,LS1PA2X(M	202004	202104	202110	2	TOSHIBA	TK16A60W,S4VX(M	5	
X33	TK18A60V,LS1SEEQ(M	202004	202104	202110	2	TOSHIBA	TK16A60W,S4VX(M	5	
X33	TK18A60V,LS1SHRX(M	202004	202104	202110	2	TOSHIBA	TK16A60W,S4VX(M	5	
X33	TK18A60V,S4Q(M	202004	202104	202110	2	TOSHIBA	TK16A60W,S4VX(M	5	
X33	TK18A60V,S4VX(M	202004	202104	202110	2	TOSHIBA	TK16A60W,S4VX(M	2	
X33	TK18A60V,S5VX(J	202004	202104	202110	2	TOSHIBA	TK16A60W,S4VX(M	5	
X33	TK18A60V,VQ(M	202004	202104	202110	2	TOSHIBA	TK16A60W,S4VX(M	5	Y
X33	TK18A60V,VX(M	202004	202104	202110	2	TOSHIBA	TK16A60W,S4VX(M	5	
X33	TK18E60V,S1VX(S	202004	202104	202110	2	TOSHIBA	TK16E60W,S1VX(S	5	Y
X33	TK18E60V,S1X(S	202004	202104	202110	2	TOSHIBA	TK16E60W,S1VX(S	5	
X33	TK18G60V,RVQ(S	202004	202104	202110	2	TOSHIBA	TK16G60W,RVQ(S	5	
X33	TK18J60V,S1VE(S	202004	202104	202110	2	TOSHIBA	TK16J60W,S1VE(S	5	
X33	TK18J60V,S1VQ(O	202004	202104	202110	2	TOSHIBA	TK16J60W,S1VE(S	5	Y

X33	TK1P90A,LQ(O	202004	202104	202110	1	TOSHIBA	TK2P90E,RQ(S	3	Y
X33	TK20A60U(LBS1SP,QM	202004	202104	202110	2	TOSHIBA	TK16A60W,S4VX(M	5	
X33	TK20A60U(Q,M)	202004	202104	202110	2	TOSHIBA	TK16A60W,S4VX(M	2	Y
X33	TK20A60U(S4LIT,Q,M	202004	202104	202110	2	TOSHIBA	TK16A60W,S4VX(M	5	
X33	TK20A60U(STA4,A,Q)	202004	202104	202110	2	TOSHIBA	TK16A60W,S4VX(M	5	
X33	TK20A60U(STA4,Q,M)	202004	202104	202110	2	TOSHIBA	TK16A60W,S4VX(M	2	Y
X33	TK20A60U(STA4,X,M)	202004	202104	202110	2	TOSHIBA	TK16A60W,S4VX(M	2	
X33	TK20A60U(STA4,X,S)	202004	202104	202110	2	TOSHIBA	TK16A60W,S4VX(M	2	
X33	TK20A60U,S5COSEQ(J	202004	202104	202110	2	TOSHIBA	TK16A60W,S4VX(M	5	
X33	TK20A60U,S5PP1X(M	202004	202104	202110	2	TOSHIBA	TK16A60W,S4VX(M	5	
X33	TK20A60U,S5Q(J	202004	202104	202110	2	TOSHIBA	TK16A60W,S4VX(M	2	
X33	TK20E60U,S1X(S	202004	202104	202110	2	TOSHIBA	TK16E60W,S1VX(S	2	Y
X33	TK20J50D(S1V,E,S)	202004	202104	202110	1	TOSHIBA	TK20J50D(STA1,E,S)	3	
X33	TK20J60U(COSEL,F)	202004	202104	202110	2	TOSHIBA	TK16J60W,S1VE(S	5	
X33	TK20J60U(F)	202004	202104	202110	2	TOSHIBA	TK16J60W,S1VE(S	2	Y
X33	TK20J60U(PED,F)	202004	202104	202110	2	TOSHIBA	TK16J60W,S1VE(S	5	
X33	TK20J60U(S1PED1,F)	202004	202104	202110	2	TOSHIBA	TK16J60W,S1VE(S	5	
X33	TK20J60U(S1SHRP,F)	202004	202104	202110	2	TOSHIBA	TK16J60W,S1VE(S	5	
X33	TK20J60U(S1TEKR,F)	202004	202104	202110	2	TOSHIBA	TK16J60W,S1VE(S	5	
X33	TK20J60U(S1TET,F)	202004	202104	202110	2	TOSHIBA	TK16J60W,S1VE(S	2	
X33	TK20J60U(STA1,F)	202004	202104	202110	2	TOSHIBA	TK16J60W,S1VE(S	5	
X33	TK22A60V,LS1PA2X(M	202004	202104	202110	2	TOSHIBA	TK20A60W,S5VX(M	5	
X33	TK22A60V,S4VX(M	202004	202104	202110	2	TOSHIBA	TK20A60W,S5VX(M	2	
X33	TK22A60V,S5VX(J	202004	202104	202110	2	TOSHIBA	TK20A60W,S5VX(M	2	
X33	TK22A60V,VX(M	202004	202104	202110	2	TOSHIBA	TK20A60W,S5VX(M	5	Y
X33	TK22G60V,RVQ(S	202004	202104	202110	2	TOSHIBA	TK20G60W,RVQ(S	2	Y
X33	TK22J60V,S1VQ(O	202004	202104	202110	2	TOSHIBA	TK20J60W,S1VE(S	2	
X33	TK22J60V,VQ(O	202004	202104	202110	2	TOSHIBA	TK20J60W,S1VE(S	5	Y
X33	TK22N60V,S1VF(S	202004	202104	202110	2	TOSHIBA	TK20N60W,S1VF(S	5	
X33	TK25E06K3,S1X(S	202004	202104	202110	1	TOSHIBA	TK30E06N1	3	
X33	TK2P60D(TE16L1,NQ)	202004	202104	202110	1	TOSHIBA	TK2P60D(TE16L1,NV)	3	Y
X33	TK2P60D(TE16R1,NQ)	202004	202104	202110	1	TOSHIBA	TK2P60D(TE16R1,NV)	3	Y
X33	TK30A06J3A(A,Q)	202004	202104	202110	2	TOSHIBA	TK30A06N1	2	
X33	TK30A06J3A(LBS2PQM	202004	202104	202110	2	TOSHIBA	TK30A06N1	2	
X33	TK30A06J3A(Q,M)	202004	202104	202110	2	TOSHIBA	TK30A06N1	2	
X33	TK30A06J3A(STA4,QM	202004	202104	202110	2	TOSHIBA	TK30A06N1	2	

X33	TK30A06J3A,LS2PQ(J	202004	202104	202110	2	TOSHIBA	TK30A06N1	2	
X33	TK30A06J3A,S5Q(J	202004	202104	202110	2	TOSHIBA	TK30A06N1	2	
X33	TK33A60V,S4VX(M	202004	202104	202110	2	TOSHIBA	TK090A65Z,S4X(S	5	
X33	TK33A60V,S5VX(J	202004	202104	202110	2	TOSHIBA	TK090A65Z,S4X(S	5	
X33	TK33A60V,VX(M	202004	202104	202110	2	TOSHIBA	TK090A65Z,S4X(S	5	Y
X33	TK33J60V,S1VQ(O	202004	202104	202110	3	TOSHIBA	TK090N65Z,S1F(S	2	Y
X33	TK33N60V,S1VF(S	202004	202104	202110	2	TOSHIBA	TK090N65Z,S1F(S	5	
X33	TK35E10K3(S1SS-Q)	202004	202104	202110	2	TOSHIBA	TK11S10N1L	1	
X33	TK3R3E03GL,S1X(S	202004	202104	202110	3	TOSHIBA	TPH2R003PL	2	Y
X33	TK40A08K3(A,Q)	202004	202104	202110	1	TOSHIBA	TK46A08N1	3	
X33	TK40A08K3(LS2PA,AQ	202004	202104	202110	1	TOSHIBA	TK46A08N1	3	
X33	TK40A08K3(LS2PA,QM	202004	202104	202110	1	TOSHIBA	TK46A08N1	3	
X33	TK40A08K3(Q,M)	202004	202104	202110	1	TOSHIBA	TK46A08N1	3	
X33	TK40A08K3(STA4,QM)	202004	202104	202110	1	TOSHIBA	TK46A08N1	3	
X33	TK40A08K3,LS2PAQ(J	202004	202104	202110	1	TOSHIBA	TK46A08N1	3	
X33	TK40A08K3,LS2PAQ(M	202004	202104	202110	1	TOSHIBA	TK46A08N1	3	
X33	TK40A08K3,S5Q(J	202004	202104	202110	1	TOSHIBA	TK46A08N1	3	
X33	TK40A10J1,S4Q(M	202004	202104	202110	1	TOSHIBA	TK110A10PL	2	
X33	TK40A10J1,S5Q(J	202004	202104	202110	1	TOSHIBA	TK110A10PL	2	
X33	TK40A10K3(A,Q)	202004	202104	202110	1	TOSHIBA	TK22A10N1	3	
X33	TK40A10K3(Q,M)	202004	202104	202110	1	TOSHIBA	TK22A10N1	3	
X33	TK40A10K3(STA4,QM)	202004	202104	202110	1	TOSHIBA	TK22A10N1	3	Y
X33	TK40A10K3,S5Q(J	202004	202104	202110	1	TOSHIBA	TK22A10N1	3	
X33	TK40E10K3,S1X(S	202004	202104	202110	1	TOSHIBA	TK22E10N1	3	Y
X33	TK40J60U(F)	202004	202104	202110	3	TOSHIBA	TK065N65Z,S1F(S	2	Y
X33	TK40J60U(HEV,F)	202004	202104	202110	3	TOSHIBA	TK065N65Z,S1F(S	5	
X33	TK40J60U(STA1,F)	202004	202104	202110	3	TOSHIBA	TK065N65Z,S1F(S	5	
X33	TK40P03M1(T6RDS-Q)	202004	202104	202110	3	TOSHIBA	TPH8R903NL	3	
X33	TK40P04M1(T6LOS,Q)	202004	202104	202110	0			3	
X33	TK40P04M1(T6RSS,Q)	202004	202104	202110	0			3	
X33	TK45J60V,S1VQ(O	202004	202104	202110	3	TOSHIBA	TK065N65Z,S1F(S	2	Y
X33	TK45J60V,VQ(O	202004	202104	202110	3	TOSHIBA	TK065N65Z,S1F(S	5	Y
X33	TK4A60DB(PHIL,Q,M)	202004	202104	202110	2	TOSHIBA	TK1K9A60F,S4X(S	5	Y
X33	TK4A60DB(Q,M)	202004	202104	202110	2	TOSHIBA	TK1K9A60F,S4X(S	5	Y
X33	TK4A60DB(S4PHI,QM)	202004	202104	202110	2	TOSHIBA	TK1K9A60F,S4X(S	5	Y
X33	TK4A60DB(S4PHI,X,S	202004	202104	202110	2	TOSHIBA	TK1K9A60F,S4X(S	5	Y

X33	TK4A60DB(STA4,A,Q)	202004	202104	202110	2	TOSHIBA	TK1K9A60F,S4X(S	5	
X33	TK4A60DB(STA4,Q,M)	202004	202104	202110	2	TOSHIBA	TK1K9A60F,S4X(S	5	Y
X33	TK4A60DB(STA4,X,S)	202004	202104	202110	2	TOSHIBA	TK1K9A60F,S4X(S	5	
X33	TK4A60DB,S5Q(J	202004	202104	202110	2	TOSHIBA	TK1K9A60F,S4X(S	5	
X33	TK4Q70V,S1VQ(S	202004	202104	202110	3	TOSHIBA	TK4A80E,S4X(S	5	
X33	TK50E06K3(S1,Q,D)	202004	202104	202110	3	TOSHIBA	TK40S06N1L	3	
X33	TK50E06K3(S1,Q,D2)	202004	202104	202110	3	TOSHIBA	TK40S06N1L	3	
X33	TK50E06K3(S1SS2,Q)	202004	202104	202110	3	TOSHIBA	TK40S06N1L	3	
X33	TK50E06K3(S1SS-Q)	202004	202104	202110	3	TOSHIBA	TK40S06N1L	3	
X33	TK50E06K3A,S1X(S	202004	202104	202110	3	TOSHIBA	TK33S10N1L	1	Y
X33	TK50E08K3,S1X(S	202004	202104	202110	3	TOSHIBA	TK33S10N1L	1	
X33	TK50E10K3(S1SS-Q)	202004	202104	202110	3	TOSHIBA	TK33S10N1L	1	
X33	TK50F15J1(T4LMTD,Q	202004	202104	202110	1	infineon	AUIRFS4115	2	
X33	TK50F15J1(TE24L,Q)	202004	202104	202110	1	infineon	AUIRFS4115	2	Y
X33	TK50J60U(HEV,Q)	202004	202104	202110	3	TOSHIBA	TK065N65Z,S1F(S	5	
X33	TK50J60U(Q)	202004	202104	202110	3	TOSHIBA	TK065N65Z,S1F(S	2	Y
X33	TK50J60U(STA1,Q)	202004	202104	202110	3	TOSHIBA	TK065N65Z,S1F(S	5	
X33	TK5A50D5(Q,M)	202004	202104	202110	2	TOSHIBA	TK7A60W5	3	
X33	TK5A50D5,S4Q(M	202004	202104	202110	2	TOSHIBA	TK7A60W5	3	
X33	TK5A60V,S4VX(M	202004	202104	202110	2	TOSHIBA	TK6A60W,S4VX(M	2	
X33	TK5A60V,S5VX(J	202004	202104	202110	2	TOSHIBA	TK6A60W,S4VX(M	5	
X33	TK5A60V,VX(M	202004	202104	202110	2	TOSHIBA	TK6A60W,S4VX(M	5	
X33	TK5P60V,RQ(S	202004	202104	202110	2	TOSHIBA	TK6P60W,RVQ(S	5	
X33	TK5P60V,RVQ(S	202004	202104	202110	2	TOSHIBA	TK6P60W,RVQ(S	2	Y
X33	TK5Q60V,S1APQ(S	202004	202104	202110	2	TOSHIBA	TK6Q60W,S1VQ(S	2	
X33	TK5Q60V,S1VQ(S	202004	202104	202110	2	TOSHIBA	TK6Q60W,S1VQ(S	5	
X33	TK60E08K3,S1X(S	202004	202104	202110	1	TOSHIBA	TK46E08N1	3	Y
X33	TK60P03M1,RQ(S	202004	202104	202110	3	TOSHIBA	TPN6R003NL	3	
X33	TK65G10NE,RQ(S	202004	202104	202110	3	TOSHIBA	TK160F10N1L,LXGQ(O	9	
X33	TK65L60V,UPVQ(O	202004	202104	202110	3	TOSHIBA	TK040N65Z,S1F(S	5	
X33	TK65L60V,VQ(O	202004	202104	202110	3	TOSHIBA	TK040N65Z,S1F(S	2	Y
X33	TK6A60D(PHIL,Q,M)	202004	202104	202110	2	TOSHIBA	TK1K2A60F,S4X(S	5	Y
X33	TK6A60D(Q,M)	202004	202104	202110	2	TOSHIBA	TK1K2A60F,S4X(S	5	Y
X33	TK6A60D(S4SH6,Q,M)	202004	202104	202110	2	TOSHIBA	TK1K2A60F,S4X(S	5	
X33	TK6A60D(S4SY,A,Q)	202004	202104	202110	2	TOSHIBA	TK1K2A60F,S4X(S	5	
X33	TK6A60D(S4SY,Q,M)	202004	202104	202110	2	TOSHIBA	TK1K2A60F,S4X(S	5	

X33	TK6A60D(STA4,A,Q)	202004	202104	202110	2	TOSHIBA	TK1K2A60F,S4X(S	5	
X33	TK6A60D(STA4,Q,M)	202004	202104	202110	2	TOSHIBA	TK1K2A60F,S4X(S	5	Y
X33	TK6A60D(STA4,X,M)	202004	202104	202110	2	TOSHIBA	TK1K2A60F,S4X(S	5	
X33	TK6A60D(STA4,X,S)	202004	202104	202110	2	TOSHIBA	TK1K2A60F,S4X(S	5	
X33	TK6A60D,S5HITAPQ(J	202004	202104	202110	2	TOSHIBA	TK1K2A60F,S4X(S	5	
X33	TK6A60D,S5Q(J	202004	202104	202110	2	TOSHIBA	TK1K2A60F,S4X(S	5	
X33	TK6A60DR(Q,M)	202004	202104	202110	2	TOSHIBA	TK1K2A60F,S4X(S	5	
X33	TK6A60DR(STA4,Q,M)	202004	202104	202110	2	TOSHIBA	TK1K2A60F,S4X(S	5	
X33	TK6A60DR(STA4,X,M)	202004	202104	202110	2	TOSHIBA	TK1K2A60F,S4X(S	5	
X33	TK6A60DR,S4X(S	202004	202104	202110	2	TOSHIBA	TK1K2A60F,S4X(S	5	
X33	TK6A60E,S4X(S	202004	202104	202110	2	TOSHIBA	TK1K2A60F,S4X(S	2	
X33	TK6A60V,S4VX(M	202004	202104	202110	2	TOSHIBA	TK6A60W,S4VX(M	5	
X33	TK6A60V,S5VX(J	202004	202104	202110	2	TOSHIBA	TK6A60W,S4VX(M	5	
X33	TK6A60V,VX(M	202004	202104	202110	2	TOSHIBA	TK6A60W,S4VX(M	5	
X33	TK6P60V,RQ(S	202004	202104	202110	2	TOSHIBA	TK6P60W,RVQ(S	5	
X33	TK6P60V,RVQ(S	202004	202104	202110	2	TOSHIBA	TK6P60W,RVQ(S	2	Y
X33	TK6Q60V,S1VQ(S	202004	202104	202110	2	TOSHIBA	TK6Q60W,S1VQ(S	5	
X33	TK70J04J3(HLDAMY,Q	202004	202104	202110	3	TOSHIBA	TK100S04N1L	2	
X33	TK70J04J3(LBS3HLSQ	202004	202104	202110	3	TOSHIBA	TK100S04N1L	2	
X33	TK70J04J3(Q)	202004	202104	202110	3	TOSHIBA	TK100S04N1L	2	
X33	TK75A06K3(STA4,X,M	202004	202104	202110	1	TOSHIBA	TK58A06N1	3	
X33	TK75A06K3,Q(M	202004	202104	202110	1	TOSHIBA	TK58A06N1	3	
X33	TK75A06K3,S4Q(M	202004	202104	202110	1	TOSHIBA	TK58A06N1	3	
X33	TK75A06K3,S5NDSX(M	202004	202104	202110	1	TOSHIBA	TK58A06N1	3	
X33	TK75A06K3,S5Q(J	202004	202104	202110	1	TOSHIBA	TK58A06N1	3	
X33	TK75A06K3,S5Q(M	202004	202104	202110	1	TOSHIBA	TK58A06N1	3	
X33	TK7A50D5(Q,M)	202004	202104	202110	2	TOSHIBA	TK7A60W5	3	
X33	TK7A50D5,Q(M	202004	202104	202110	2	TOSHIBA	TK7A60W5	3	
X33	TK7A50D5,S4Q(M	202004	202104	202110	2	TOSHIBA	TK7A60W5	3	
X33	TK7A60V,S4VX(M	202004	202104	202110	2	TOSHIBA	TK7A60W,S4VX(M	5	
X33	TK7A60V,S5VX(J	202004	202104	202110	2	TOSHIBA	TK7A60W,S4VX(M	5	
X33	TK7A60V,VX(M	202004	202104	202110	2	TOSHIBA	TK7A60W,S4VX(M	5	
X33	TK7P60V,RQ(S	202004	202104	202110	2	TOSHIBA	TK7P60W,RVQ(S	5	
X33	TK7P60V,RVQ(S	202004	202104	202110	2	TOSHIBA	TK7P60W,RVQ(S	2	Y
X33	TK7Q60V,S1VQ(S	202004	202104	202110	2	TOSHIBA	TK7Q60W,S1VQ(S	5	
X33	TK80A08K3A(Q,M)	202004	202104	202110	2	TOSHIBA	TK46A08N1	1	

X33	TK80A08K3A(STA4,QM	202004	202104	202110	2	TOSHIBA	TK46A08N1	1	
X33	TK80A08K3A,S4Q(M	202004	202104	202110	2	TOSHIBA	TK46A08N1	1	
X33	TK80A08K3A,S5Q(J	202004	202104	202110	2	TOSHIBA	TK46A08N1	1	
X33	TK80E06K3(S1,Q,D)	202004	202104	202110	3	TOSHIBA	TK90S06N1L	3	
X33	TK80E06K3(S1,Q,D2)	202004	202104	202110	3	TOSHIBA	TK90S06N1L	3	
X33	TK80E06K3(S1SS2,Q)	202004	202104	202110	3	TOSHIBA	TK90S06N1L	3	
X33	TK80E06K3(S1SS-Q)	202004	202104	202110	3	TOSHIBA	TK90S06N1L	3	Y
X33	TK80E06K3A,S1X(S	202004	202104	202110	1	TOSHIBA	TK58E06N1	3	
X33	TK80E06NE,S1Q(S	202004	202104	202110	3	TOSHIBA	TK90S06N1L	3	
X33	TK80E07NE,S1Q(S	202004	202104	202110	3	TOSHIBA	TK55S10N1	3	
X33	TK80E08K3(S1,Q,D)	202004	202104	202110	3	TOSHIBA	TK55S10N1	3	
X33	TK80E08K3(S1SS-Q)	202004	202104	202110	3	TOSHIBA	TK55S10N1	3	
X33	TK80E08K3A(S1,Q,D)	202004	202104	202110	3	TOSHIBA	TK55S10N1	3	
X33	TK80E08K3A(S1,Q,D2	202004	202104	202110	3	TOSHIBA	TK55S10N1	3	
X33	TK80E08K3A(S1SS2,Q	202004	202104	202110	3	TOSHIBA	TK55S10N1	3	
X33	TK80E08K3A(S1SS-Q)	202004	202104	202110	3	TOSHIBA	TK55S10N1	3	Y
X33	TK80F04K3L(TE24L,Q	202004	202104	202110	3	TOSHIBA	TK100S04N1L	3	
X33	TK80F06K3L(TE24L,Q	202004	202104	202110	3	TOSHIBA	TK90S06N1L	3	
X33	TK80K04K3Z(LS2DN,Q	202004	202104	202110	3	TOSHIBA	TK1R5R04PB	3	
X33	TK80K04K3Z(LS5D2,Q	202004	202104	202110	3	TOSHIBA	TK1R5R04PB	3	
X33	TK80K04K3Z(LS5D3,Q	202004	202104	202110	3	TOSHIBA	TK1R5R04PB	3	
X33	TK80K04K3Z(LS5D4,Q	202004	202104	202110	3	TOSHIBA	TK1R5R04PB	3	
X33	TK80K04K3Z(LS5DN,Q	202004	202104	202110	3	TOSHIBA	TK1R5R04PB	3	
X33	TK80L60V,Q(O	202004	202104	202110	2	TOSHIBA	TK100L60W,VQ(O	5	
X33	TK80L60V,VQ(O	202004	202104	202110	2	TOSHIBA	TK100L60W,VQ(O	2	Y
X33	TK8A50E,S4X(S	202004	202104	202110	2	TOSHIBA	TK8A50D(STA4,X,M)	3	
X33	TK8A60EA,S4X(S	202004	202104	202110	2	TOSHIBA	TK1K0A60F	3	
X33	TK8A60V,S4VX(M	202004	202104	202110	2	TOSHIBA	TK8A60W,S4VX(M	5	
X33	TK8A60V,S5VX(J	202004	202104	202110	2	TOSHIBA	TK8A60W,S4VX(M	5	
X33	TK8A60V,VX(M	202004	202104	202110	2	TOSHIBA	TK8A60W,S4VX(M	5	Y
X33	TK8P60V,RQ(S	202004	202104	202110	2	TOSHIBA	TK8P60W,RVQ(S	5	
X33	TK8P60V,RVQ(S	202004	202104	202110	2	TOSHIBA	TK8P60W,RVQ(S	2	Y
X33	TK8Q60V,S1VQ(S	202004	202104	202110	2	TOSHIBA	TK8Q60W,S1VQ(S	5	
X33	TPC8027(T2LSAN2,XM	202004	202104	202110	3	TOSHIBA	TPN2R703NL	4	
X33	TPC8028(T2LMDK,Q)	202004	202104	202110	3	TOSHIBA	TPN4R203NC	4	
X33	TPC8028(T2LMDK,X)	202004	202104	202110	3	TOSHIBA	TPN4R203NC	4	

X33	TPC8028(T2LSAN2,VM	202004	202104	202110	3	TOSHIBA	TPN4R203NC	4	
X33	TPC8028(T2LSAN2,X)	202004	202104	202110	3	TOSHIBA	TPN4R203NC	4	
X33	TPC8028(T2LSAN2,XM	202004	202104	202110	3	TOSHIBA	TPN4R203NC	4	
X33	TPC8028(T2LSONY,XM	202004	202104	202110	3	TOSHIBA	TPN4R203NC	4	
X33	TPC8028(T2LTET,V,M	202004	202104	202110	3	TOSHIBA	TPN4R203NC	4	
X33	TPC8028(TE12L,Q,M)	202004	202104	202110	3	TOSHIBA	TPN4R203NC	4	
X33	TPC8028(TE12L,V,M)	202004	202104	202110	3	TOSHIBA	TPN4R203NC	4	
X33	TPC8029(TE12L,Q)	202004	202104	202110	3	TOSHIBA	TPN2R903PL	4	
X33	TPC8035-H(TE12L,Q)	202004	202104	202110	3	TOSHIBA	TPN2R903PL	4	
X33	TPC8035-H(TE12L,VM	202004	202104	202110	3	TOSHIBA	TPN2R903PL	4	
X33	TPC8036-H(T2L,A,Q)	202004	202104	202110	3	TOSHIBA	TPN4R203NC	4	
X33	TPC8036-H(TE12L,VM	202004	202104	202110	3	TOSHIBA	TPN4R203NC	4	
X33	TPC8037-H(TE12L,Q)	202004	202104	202110	3	TOSHIBA	TPN8R903NL	4	
X33	TPC8037-H(TE12L,QM	202004	202104	202110	3	TOSHIBA	TPN8R903NL	4	Y
X33	TPC8037-H(TE12L,VM	202004	202104	202110	3	TOSHIBA	TPN8R903NL	4	
X33	TPC8039-H(T2L,A,Q)	202004	202104	202110	3	TOSHIBA	TPN5R203PL	4	
X33	TPC8039-H(TE12L,VM	202004	202104	202110	3	TOSHIBA	TPN5R203PL	4	
X33	TPC8040-H(2LSIND,Q	202004	202104	202110	3	TOSHIBA	SSM6K818R	4	
X33	TPC8040-H(TE12L,Q)	202004	202104	202110	3	TOSHIBA	TPN8R903NL	4	
X33	TPC8040-H(TE12LQM)	202004	202104	202110	3	TOSHIBA	TPN8R903NL	4	
X33	TPC8041(T2LSAN2,AX	202004	202104	202110	3	TOSHIBA	TPN6R303NC	4	
X33	TPC8041(T2LSAN2,V)	202004	202104	202110	3	TOSHIBA	TPN6R303NC	4	
X33	TPC8041(T2LSAN2,VM	202004	202104	202110	3	TOSHIBA	TPN6R303NC	4	
X33	TPC8041(T2LSAN2,X)	202004	202104	202110	3	TOSHIBA	TPN6R303NC	4	
X33	TPC8041(T2LSAN2,XM	202004	202104	202110	3	TOSHIBA	TPN6R303NC	4	
X33	TPC8041(TE12L,V,M)	202004	202104	202110	3	TOSHIBA	TPN6R303NC	4	
X33	TPC8045-H(TE12L,Q)	202004	202104	202110	3	TOSHIBA	TPH3R704PC	4	
X33	TPC8045-H(TE12L,QM	202004	202104	202110	3	TOSHIBA	TPH3R704PC	4	
X33	TPC8045-H(TE12L,VM	202004	202104	202110	3	TOSHIBA	TPH3R704PC	4	
X33	TPC8045-H,LSOYQ(CM	202004	202104	202110	3	TOSHIBA	TPH3R704PC	4	
X33	TPC8046-H(TE12L,Q)	202004	202104	202110	3	TOSHIBA	TPH6R004PL	4	
X33	TPC8046-H,LQ(CM	202004	202104	202110	3	TOSHIBA	TPH6R004PL	4	
X33	TPC8047-H(T2LMTS,Q	202004	202104	202110	3	TOSHIBA	TPH6R004PL	4	
X33	TPC8047-H(TE12L,Q)	202004	202104	202110	3	TOSHIBA	TPH6R004PL	4	
X33	TPC8047-H(TE12L,QM	202004	202104	202110	3	TOSHIBA	TPH6R004PL	4	
X33	TPC8047-H(TE12L,VM	202004	202104	202110	3	TOSHIBA	TPH6R004PL	4	

X33	TPC8047-H,LSOYQ(CM	202004	202104	202110	3	TOSHIBA	TPH6R004PL	4	
X33	TPC8048-H(TE12L,Q)	202004	202104	202110	3	TOSHIBA	TPH7R006PL	4	Y
X33	TPC8048-H,LQ(CM	202004	202104	202110	3	TOSHIBA	TPH7R006PL	4	
X33	TPC8048-H,LSOYQ(CM	202004	202104	202110	3	TOSHIBA	TPH7R006PL	4	
X33	TPC8049-H(T2LPP,X)	202004	202104	202110	3	TOSHIBA	TPH11006NL	4	
X33	TPC8049-H(TE12L,Q)	202004	202104	202110	3	TOSHIBA	TPH11006NL	4	
X33	TPC8049-H,LQ(CM	202004	202104	202110	3	TOSHIBA	TPH11006NL	4	
X33	TPC8050-H(TE12L,Q)	202004	202104	202110	3	TOSHIBA	TPH11006NL	4	Y
X33	TPC8050-H,LQ(CM	202004	202104	202110	3	TOSHIBA	TPH11006NL	4	
X33	TPC8051-H(TE12L,Q)	202004	202104	202110	3	TOSHIBA	TPH8R008NH	4	
X33	TPC8051-H(TE12L,QM	202004	202104	202110	3	TOSHIBA	TPH8R008NH	4	Y
X33	TPC8051-H(TE12L,VM	202004	202104	202110	3	TOSHIBA	TPH8R008NH	4	Y
X33	TPC8052-H(TE12L,Q)	202004	202104	202110	3	TOSHIBA	TPH7R204PL	4	
X33	TPC8052-H,LPAVQ(CM	202004	202104	202110	3	TOSHIBA	TPH7R204PL	4	
X33	TPC8052-H,LQ(CM	202004	202104	202110	3	TOSHIBA	TPH7R204PL	4	
X33	TPC8053-H(TE12L,Q)	202004	202104	202110	3	TOSHIBA	TPH11006NL	4	
X33	TPC8053-H,LQ(CM	202004	202104	202110	3	TOSHIBA	TPH11006NL	4	
X33	TPC8055-H,LQ(J	202004	202104	202110	3	TOSHIBA	TPN1R603PL	4	
X33	TPC8055-H,LQ(M	202004	202104	202110	3	TOSHIBA	TPN1R603PL	4	
X33	TPC8056-H,LQ(J	202004	202104	202110	3	TOSHIBA	TPN2R203NC	4	
X33	TPC8056-H,LQ(M	202004	202104	202110	3	TOSHIBA	TPN2R203NC	4	
X33	TPC8057-H,LQ(J	202004	202104	202110	3	TOSHIBA	TPN2R703NL	4	
X33	TPC8057-H,LQ(M	202004	202104	202110	3	TOSHIBA	TPN2R703NL	4	
X33	TPC8058-H,LQ(J	202004	202104	202110	3	TOSHIBA	TPH3R003PL	4	
X33	TPC8058-H,LQ(M	202004	202104	202110	3	TOSHIBA	TPH3R003PL	4	
X33	TPC8059-H,LADQ(J	202004	202104	202110	3	TOSHIBA	TPH4R003NL	4	
X33	TPC8059-H,LQ(J	202004	202104	202110	3	TOSHIBA	TPH4R003NL	4	
X33	TPC8059-H,LQ(M	202004	202104	202110	3	TOSHIBA	TPH4R003NL	4	
X33	TPC8061-H,LQ(S	202004	202104	202110	3	TOSHIBA	SSM6K504NU	3	
X33	TPC8062-H,LQ(CJ	202004	202104	202110	3	TOSHIBA	TPH6R003NL	4	
X33	TPC8062-H,LQ(CM	202004	202104	202110	3	TOSHIBA	TPH6R003NL	4	
X33	TPC8062-H,LQ(J	202004	202104	202110	3	TOSHIBA	TPH6R003NL	4	
X33	TPC8062-H,LQ(M	202004	202104	202110	3	TOSHIBA	TPH6R003NL	4	
X33	TPC8063-H,LQ(CJ	202004	202104	202110	3	TOSHIBA	TPH6R003NL	4	
X33	TPC8063-H,LQ(CM	202004	202104	202110	3	TOSHIBA	TPH6R003NL	4	Y
X33	TPC8063-H,LQ(J	202004	202104	202110	3	TOSHIBA	TPH6R003NL	4	

X33	TPC8063-H,LQ(M	202004	202104	202110	3	TOSHIBA	TPH6R003NL	4	
X33	TPC8064-H,LNKODQ(J	202004	202104	202110	3	TOSHIBA	TPH8R903NL	4	
X33	TPC8064-H,LQ(CJ	202004	202104	202110	3	TOSHIBA	TPH8R903NL	4	
X33	TPC8064-H,LQ(CM	202004	202104	202110	3	TOSHIBA	TPH8R903NL	4	
X33	TPC8064-H,LQ(J	202004	202104	202110	3	TOSHIBA	TPH8R903NL	4	
X33	TPC8064-H,LQ(M	202004	202104	202110	3	TOSHIBA	TPH8R903NL	4	
X33	TPC8065-H,LPAVQ(S	202004	202104	202110	1	TOSHIBA	TP89R103NL	1	
X33	TPC8065-H,LQ(S	202004	202104	202110	1	TOSHIBA	TP89R103NL	1	Y
X33	TPC8066-H,LQ(S	202004	202104	202110	1	TOSHIBA	TP89R103NL	1	
X33	TPC8066-H,LSONYQ(S	202004	202104	202110	1	TOSHIBA	TP89R103NL	1	
X33	TPC8067-H,LQ(S	202004	202104	202110	3	TOSHIBA	SSM6K504NU	3	
X33	TPC8073,LQ(CJ	202004	202104	202110	3	TOSHIBA	TPH4R003NL	4	
X33	TPC8073,LQ(CM	202004	202104	202110	3	TOSHIBA	TPH4R003NL	4	
X33	TPC8073,LQ(J	202004	202104	202110	3	TOSHIBA	TPH4R003NL	4	
X33	TPC8073,LQ(M	202004	202104	202110	3	TOSHIBA	TPH4R003NL	4	
X33	TPC8073,LSONYQ(CM	202004	202104	202110	3	TOSHIBA	TPH4R003NL	4	
X33	TPC8074,LQ(CJ	202004	202104	202110	3	TOSHIBA	TPH6R003NL	4	
X33	TPC8074,LQ(CM	202004	202104	202110	3	TOSHIBA	TPH6R003NL	4	
X33	TPC8074,LQ(J	202004	202104	202110	3	TOSHIBA	TPH6R003NL	4	
X33	TPC8074,LQ(M	202004	202104	202110	3	TOSHIBA	TPH6R003NL	4	
X33	TPC8074,LSONYQ(CJ	202004	202104	202110	3	TOSHIBA	TPH6R003NL	4	
X33	TPC8074,LSONYQ(CM	202004	202104	202110	3	TOSHIBA	TPH6R003NL	4	
X33	TPC8074,LSONYQ(J	202004	202104	202110	3	TOSHIBA	TPH6R003NL	4	
X33	TPC8074,LSONYQ(M	202004	202104	202110	3	TOSHIBA	TPH6R003NL	4	
X33	TPC8075(TE12L,Q,M)	202004	202104	202110	3	TOSHIBA	TPH2R104PL	4	
X33	TPC8075,LQ(J	202004	202104	202110	3	TOSHIBA	TPH2R104PL	4	
X33	TPC8075,LQ(M	202004	202104	202110	3	TOSHIBA	TPH2R104PL	4	
X33	TPC8076,LQ(CJ	202004	202104	202110	3	TOSHIBA	TPH4R304NC	4	
X33	TPC8076,LQ(CM	202004	202104	202110	3	TOSHIBA	TPH4R304NC	4	
X33	TPC8076,LQ(J	202004	202104	202110	3	TOSHIBA	TPH4R304NC	4	
X33	TPC8076,LQ(M	202004	202104	202110	3	TOSHIBA	TPH4R304NC	4	
X33	TPC8078(TE12L,Q,M)	202004	202104	202110	3	TOSHIBA	TPH2R104PL	4	
X33	TPC8078,LQ(J	202004	202104	202110	3	TOSHIBA	TPH2R104PL	4	
X33	TPC8078,LQ(M	202004	202104	202110	3	TOSHIBA	TPH2R104PL	4	
X33	TPC8080(TE12L,Q,M)	202004	202104	202110	3	TOSHIBA	TPN2R703NL	4	
X33	TPC8080,LQ(J	202004	202104	202110	3	TOSHIBA	TPN2R703NL	4	

X33	TPC8080,LQ(M	202004	202104	202110	3	TOSHIBA	TPN2R703NL	4	Y
X33	TPC8081(TE12L,Q,M)	202004	202104	202110	3	TOSHIBA	TPH3R003PL	4	
X33	TPC8081,LQ(J	202004	202104	202110	3	TOSHIBA	TPH3R003PL	4	
X33	TPC8081,LQ(M	202004	202104	202110	3	TOSHIBA	TPH3R003PL	4	
X33	TPC8082(TE12L,Q,M)	202004	202104	202110	3	TOSHIBA	TPH4R003NL	4	
X33	TPC8082,LQ(J	202004	202104	202110	3	TOSHIBA	TPH4R003NL	4	
X33	TPC8082,LQ(M	202004	202104	202110	3	TOSHIBA	TPH4R003NL	4	
X33	TPC8084,LQ(CJ	202004	202104	202110	3	TOSHIBA	TPH6R004PL	4	
X33	TPC8084,LQ(CM	202004	202104	202110	3	TOSHIBA	TPH6R004PL	4	
X33	TPC8084,LQ(J	202004	202104	202110	3	TOSHIBA	TPH6R004PL	4	
X33	TPC8084,LQ(M	202004	202104	202110	3	TOSHIBA	TPH6R004PL	4	
X33	TPC8085,LQ(CJ	202004	202104	202110	3	TOSHIBA	TPH4R003NL	4	
X33	TPC8085,LQ(CM	202004	202104	202110	3	TOSHIBA	TPH4R003NL	4	
X33	TPC8085,LQ(J	202004	202104	202110	3	TOSHIBA	TPH4R003NL	4	
X33	TPC8085,LQ(M	202004	202104	202110	3	TOSHIBA	TPH4R003NL	4	
X33	TPC8086,LQ(CJ	202004	202104	202110	3	TOSHIBA	TPH6R003NL	4	
X33	TPC8086,LQ(CM	202004	202104	202110	3	TOSHIBA	TPH6R003NL	4	
X33	TPC8086,LQ(J	202004	202104	202110	3	TOSHIBA	TPH6R003NL	4	
X33	TPC8086,LQ(M	202004	202104	202110	3	TOSHIBA	TPH6R003NL	4	
X33	TPC8087(TE12L,Q,M)	202004	202104	202110	3	TOSHIBA	TPN1R603PL	4	
X33	TPC8087,LQ(J	202004	202104	202110	3	TOSHIBA	TPN1R603PL	4	
X33	TPC8087,LQ(M	202004	202104	202110	3	TOSHIBA	TPN1R603PL	4	
X33	TPC8088(TE12L,Q,M)	202004	202104	202110	3	TOSHIBA	TPN2R203NC	4	
X33	TPC8088,LQ(J	202004	202104	202110	3	TOSHIBA	TPN2R203NC	4	
X33	TPC8088,LQ(M	202004	202104	202110	3	TOSHIBA	TPN2R203NC	4	Y
X33	TPC8092,LQ(S	202004	202104	202110	3	TOSHIBA	TPN8R903NL	2	
X33	TPC8117(T2LMDK,XM)	202004	202104	202110	3	TOSHIBA	TPCA8120	4	
X33	TPC8117(T2LSAN,X)	202004	202104	202110	3	TOSHIBA	TPCA8120	4	
X33	TPC8117(TE12L,Q)	202004	202104	202110	3	TOSHIBA	TPCA8120	4	
X33	TPC8117(TE12L,Q,M)	202004	202104	202110	3	TOSHIBA	TPCA8120	4	Y
X33	TPC8117(TE12L,V,M)	202004	202104	202110	3	TOSHIBA	TPCA8120	4	
X33	TPC8118(T2LCANOQ,M	202004	202104	202110	3	TOSHIBA	TPCA8128	4	
X33	TPC8118(T2LSAN,X)	202004	202104	202110	3	TOSHIBA	TPCA8128	4	
X33	TPC8118(TE12L,Q)	202004	202104	202110	3	TOSHIBA	TPCA8128	4	
X33	TPC8118(TE12L,Q,M)	202004	202104	202110	3	TOSHIBA	TPCA8128	4	
X33	TPC8118(TE12L,V,M)	202004	202104	202110	3	TOSHIBA	TPCA8128	4	

X33	TPC8119(T2LSONY,Q)	202004	202104	202110	3	TOSHIBA	TPCC8104	4	Y
X33	TPC8119(TE12L,Q)	202004	202104	202110	3	TOSHIBA	TPCC8104	4	
X33	TPC8119(TE12L,V,M)	202004	202104	202110	3	TOSHIBA	TPCC8104	4	
X33	TPC8120(T2LPAE,A,V	202004	202104	202110	3	TOSHIBA	TPCA8120	4	
X33	TPC8120(T2LPAE,AX)	202004	202104	202110	3	TOSHIBA	TPCA8120	4	
X33	TPC8120(T2LPAE,X)	202004	202104	202110	3	TOSHIBA	TPCA8120	4	
X33	TPC8120(T2LSAN,A,V	202004	202104	202110	3	TOSHIBA	TPCA8120	4	
X33	TPC8120(T2LSAN,AX)	202004	202104	202110	3	TOSHIBA	TPCA8120	4	
X33	TPC8120(T2LSAN,V,M	202004	202104	202110	3	TOSHIBA	TPCA8120	4	
X33	TPC8120(T2LSAN,XM)	202004	202104	202110	3	TOSHIBA	TPCA8120	4	
X33	TPC8120(TE12L,Q)	202004	202104	202110	3	TOSHIBA	TPCA8120	4	
X33	TPC8120(TE12L,Q,M)	202004	202104	202110	3	TOSHIBA	TPCA8120	4	Y
X33	TPC8120(TE12L,V,M)	202004	202104	202110	3	TOSHIBA	TPCA8120	4	Y
X33	TPC8120,LPAEQ(CM	202004	202104	202110	3	TOSHIBA	TPCA8120	4	
X33	TPC8120,LPANAQ(CJ	202004	202104	202110	3	TOSHIBA	TPCA8120	4	
X33	TPC8120,LPANAQ(CM	202004	202104	202110	3	TOSHIBA	TPCA8120	4	
X33	TPC8120,LPANAQ(J	202004	202104	202110	3	TOSHIBA	TPCA8120	4	
X33	TPC8120,LQ(CJ	202004	202104	202110	3	TOSHIBA	TPCA8120	4	
X33	TPC8120,LQ(CM	202004	202104	202110	3	TOSHIBA	TPCA8120	4	
X33	TPC8121(T2LKOITS,Q	202004	202104	202110	3	TOSHIBA	TPCC8104	4	
X33	TPC8121(T2LSAN,X)	202004	202104	202110	3	TOSHIBA	TPCC8104	4	
X33	TPC8121(T2LVG25,QM	202004	202104	202110	3	TOSHIBA	TPCC8104	4	
X33	TPC8121(T2LVG25,VM	202004	202104	202110	3	TOSHIBA	TPCC8104	4	
X33	TPC8121(TE12L,Q)	202004	202104	202110	3	TOSHIBA	TPCC8104	4	
X33	TPC8123(T2LPP,X)	202004	202104	202110	3	TOSHIBA	TPCA8109	4	
X33	TPC8123(T2LPSE,Q)	202004	202104	202110	3	TOSHIBA	TPCA8109	4	
X33	TPC8123(TE12L,Q)	202004	202104	202110	3	TOSHIBA	TPCA8109	4	
X33	TPC8123(TE12L,Q,M)	202004	202104	202110	3	TOSHIBA	TPCA8109	4	
X33	TPC8123(TE12L,V,M)	202004	202104	202110	3	TOSHIBA	TPCA8109	4	
X33	TPC8123,LPANAQ(CJ	202004	202104	202110	3	TOSHIBA	TPCA8109	4	
X33	TPC8123,LPANAQ(CM	202004	202104	202110	3	TOSHIBA	TPCA8109	4	
X33	TPC8123,LPANAQ(J	202004	202104	202110	3	TOSHIBA	TPCA8109	4	
X33	TPC8123,LPANAQ(M	202004	202104	202110	3	TOSHIBA	TPCA8109	4	
X33	TPC8123,LPSEQ(CM	202004	202104	202110	3	TOSHIBA	TPCA8109	4	
X33	TPC8124(T2LAST,Q)	202004	202104	202110	3	TOSHIBA	TJ60S04M3L	4	
X33	TPC8124(T2LCLAR,Q)	202004	202104	202110	3	TOSHIBA	TJ60S04M3L	4	Y

X33	TPC8124(T2LDW,Q)	202004	202104	202110	3	TOSHIBA	TJ60S04M3L	4	
X33	TPC8124(T2LHSN,Q)	202004	202104	202110	3	TOSHIBA	TJ60S04M3L	4	
X33	TPC8124(TE12L,Q)	202004	202104	202110	3	TOSHIBA	TJ60S04M3L	4	
X33	TPC8124(TE12L,Q,M)	202004	202104	202110	3	TOSHIBA	TJ60S04M3L	4	Y
X33	TPC8124(TE12L,V,M)	202004	202104	202110	3	TOSHIBA	TJ60S04M3L	4	Y
X33	TPC8124,LCANOQ(CM	202004	202104	202110	3	TOSHIBA	TJ60S04M3L	4	
X33	TPC8124,LCANOQ(CO	202004	202104	202110	3	TOSHIBA	TJ60S04M3L	4	
X33	TPC8124,LNKODQ(CM	202004	202104	202110	3	TOSHIBA	TJ60S04M3L	4	
X33	TPC8124,LPAVQ(CJ	202004	202104	202110	3	TOSHIBA	TJ60S04M3L	4	
X33	TPC8124,LPAVQ(CM	202004	202104	202110	3	TOSHIBA	TJ60S04M3L	4	
X33	TPC8124,LPAVQ(CO	202004	202104	202110	3	TOSHIBA	TJ60S04M3L	4	
X33	TPC8124,LSONYQ(CM	202004	202104	202110	3	TOSHIBA	TJ60S04M3L	4	
X33	TPC8126,LNKODQ(J	202004	202104	202110	3	TOSHIBA	TPCA8109	4	
X33	TPC8126,LQ(CJ	202004	202104	202110	3	TOSHIBA	TPCA8109	4	
X33	TPC8126,LQ(CM	202004	202104	202110	3	TOSHIBA	TPCA8109	4	
X33	TPC8126,LQ(J	202004	202104	202110	3	TOSHIBA	TPCA8109	4	
X33	TPC8126,LQ(M	202004	202104	202110	3	TOSHIBA	TPCA8109	4	
X33	TPC8126,LSONYQ(CJ	202004	202104	202110	3	TOSHIBA	TPCA8109	4	
X33	TPC8126,LSONYQ(CM	202004	202104	202110	3	TOSHIBA	TPCA8109	4	
X33	TPC8127,LCANOQ(CM	202004	202104	202110	3	TOSHIBA	TPCA8128	4	
X33	TPC8127,LCANOQ(M	202004	202104	202110	3	TOSHIBA	TPCA8128	4	
X33	TPC8127,LQ(CJ	202004	202104	202110	3	TOSHIBA	TPCA8128	4	
X33	TPC8127,LQ(CM	202004	202104	202110	3	TOSHIBA	TPCA8128	4	
X33	TPC8127,LQ(J	202004	202104	202110	3	TOSHIBA	TPCA8128	4	
X33	TPC8127,LQ(M	202004	202104	202110	3	TOSHIBA	TPCA8128	4	
X33	TPC8127,LSANX(CJ	202004	202104	202110	3	TOSHIBA	TPCA8128	4	
X33	TPC8127,LSANX(CM	202004	202104	202110	3	TOSHIBA	TPCA8128	4	
X33	TPC8127,LSONYQ(CJ	202004	202104	202110	3	TOSHIBA	TPCA8128	4	
X33	TPC8127,LSONYQ(CM	202004	202104	202110	3	TOSHIBA	TPCA8128	4	
X33	TPC8127,LSONYQ(J	202004	202104	202110	3	TOSHIBA	TPCA8128	4	
X33	TPC8127,LSONYQ(M	202004	202104	202110	3	TOSHIBA	TPCA8128	4	
X33	TPC8127,LXGQ(CM	202004	202104	202110	3	TOSHIBA	TPCA8128	4	
X33	TPC8128(T2LSAN,A,V	202004	202104	202110	3	TOSHIBA	TPCA8128	4	
X33	TPC8128(T2LSAN,AX)	202004	202104	202110	3	TOSHIBA	TPCA8128	4	
X33	TPC8128(T2LSAN,V,M	202004	202104	202110	3	TOSHIBA	TPCA8128	4	
X33	TPC8128(T2LSAN,X)	202004	202104	202110	3	TOSHIBA	TPCA8128	4	

X33	TPC8128(T2LSAN,XM)	202004	202104	202110	3	TOSHIBA	TPCA8128	4	
X33	TPC8128(TE12L,Q)	202004	202104	202110	3	TOSHIBA	TPCA8128	4	Y
X33	TPC8128(TE12L,Q,M)	202004	202104	202110	3	TOSHIBA	TPCA8128	4	Y
X33	TPC8128(TE12L,V,M)	202004	202104	202110	3	TOSHIBA	TPCA8128	4	Y
X33	TPC8128,LPPQ(CO	202004	202104	202110	3	TOSHIBA	TPCA8128	4	
X33	TPC8223-H,LQ(S	202004	202104	202110	3	TOSHIBA	SSM6N55NU	4	Y
X33	TPC8224-H,LQ(S	202004	202104	202110	3	TOSHIBA	SSM6N55NU	4	Y
X33	TPC8407,LEBMQ(S	202004	202104	202110	2	ROHM	SP8M10FRA	4	Y
X33	TPC8407,LQ(S	202004	202104	202110	2	ROHM	SP8M10FRA	4	Y
X33	TPC8A03-H(TE12L,Q)	202004	202104	202110	3	TOSHIBA	TPN5R203PL	4	
X33	TPC8A03-H(TE12LQM)	202004	202104	202110	3	TOSHIBA	TPN5R203PL	4	
X33	TPC8A03-H,LSQ(CM	202004	202104	202110	3	TOSHIBA	TPN5R203PL	4	
X33	TPC8A04-H(TE12L,Q)	202004	202104	202110	3	TOSHIBA	TPN2R903PL	4	
X33	TPC8A05-H(T2L,A,V)	202004	202104	202110	1	TOSHIBA	TP89R103NL	4	
X33	TPC8A06-H(T2L,A,V)	202004	202104	202110	1	TOSHIBA	TP89R103NL	4	
X33	TPCA8006-H(T2LMU1Q	202004	202104	202110	3	TOSHIBA	TPN3300ANH	2	
X33	TPCA8006-H(T2LMU2Q	202004	202104	202110	3	TOSHIBA	TPN3300ANH	2	
X33	TPCA8006-H(T2LSO1Q	202004	202104	202110	3	TOSHIBA	TPN3300ANH	2	
X33	TPCA8006H(T2LSO1QM	202004	202104	202110	3	TOSHIBA	TPN3300ANH	2	
X33	TPCA8006-H(T2LS-OQ	202004	202104	202110	3	TOSHIBA	TPN3300ANH	2	
X33	TPCA8006-H(TE12L,Q	202004	202104	202110	3	TOSHIBA	TPN3300ANH	2	Y
X33	TPCA8006-H(TE12LQM	202004	202104	202110	3	TOSHIBA	TPN3300ANH	2	Y
X33	TPCA8015-H(2LJTE,X	202004	202104	202110	3	TOSHIBA	TK65S04N1L	2	
X33	TPCA8015-H(2LTYG,Q	202004	202104	202110	3	TOSHIBA	TK65S04N1L	2	
X33	TPCA8016-H(2LHTA,Q	202004	202104	202110	3	TOSHIBA	TK25S06N1L	2	Y
X33	TPCA8016-H(2LMBS,Q	202004	202104	202110	3	TOSHIBA	TK25S06N1L	2	
X33	TPCA8016-H(2LYZS,Q	202004	202104	202110	3	TOSHIBA	TK25S06N1L	2	
X33	TPCA8016-H,L1DNQ(O	202004	202104	202110	3	TOSHIBA	TK25S06N1L	2	
X33	TPCA8020-H(T2LCN,Q	202004	202104	202110	1	TOSHIBA	TPH7R204PL	2	
X33	TPCA8020-H(TE12L,Q	202004	202104	202110	1	TOSHIBA	TPH7R204PL	2	
X33	TPCA8020-H(TE12LQM	202004	202104	202110	1	TOSHIBA	TPH7R204PL	2	
X33	TPCA8022-H(2LHTA,Q	202004	202104	202110	3	TOSHIBA	TK11S10N1L	2	Y
X33	TPCA8022-H(2LKDN,Q	202004	202104	202110	3	TOSHIBA	TK11S10N1L	2	
X33	TPCA8022-H(2LNMBQM	202004	202104	202110	3	TOSHIBA	TK11S10N1L	2	
X33	TPCA8024(2LSAN2,AX	202004	202104	202110	1	TOSHIBA	TPH3R003PL	3	
X33	TPCA8024(TE12L,Q,M	202004	202104	202110	1	TOSHIBA	TPH3R003PL	3	

X33	TPCA8024(TE12L,V,M	202004	202104	202110	1	TOSHIBA	TPH3R003PL	3	
X33	TPCA8025(T2LSONYXM	202004	202104	202110	1	TOSHIBA	TPH3R003PL	3	
X33	TPCA8025(TE12L,V,M	202004	202104	202110	1	TOSHIBA	TPH3R003PL	3	
X33	TPCA8026(T2LSAN,X)	202004	202104	202110	1	TOSHIBA	TPH2R003PL	3	
X33	TPCA8026(TE12L,Q)	202004	202104	202110	1	TOSHIBA	TPH2R003PL	3	
X33	TPCA8026(TE12L,Q,M	202004	202104	202110	1	TOSHIBA	TPH2R003PL	3	Y
X33	TPCA8026(TE12L,V,M	202004	202104	202110	1	TOSHIBA	TPH2R003PL	3	
X33	TPCA8026(TE12L1,VM	202004	202104	202110	1	TOSHIBA	TPH2R003PL	3	Y
X33	TPCA8027-H(2LHIJ,Q	202004	202104	202110	1	TOSHIBA	TPH1R104PB	3	
X33	TPCA8028-H(2L1S2VM	202004	202104	202110	1	TOSHIBA	TPH2R003PL	3	
X33	TPCA8028-H(2LS2,XM	202004	202104	202110	1	TOSHIBA	TPH2R003PL	3	
X33	TPCA8028-H(T2L,A,Q	202004	202104	202110	1	TOSHIBA	TPH2R003PL	3	
X33	TPCA8028-H(T2LSO,Q	202004	202104	202110	1	TOSHIBA	TPH2R003PL	3	
X33	TPCA8028-H(T2LSOQM	202004	202104	202110	1	TOSHIBA	TPH2R003PL	3	
X33	TPCA8028-H(TE12L,Q	202004	202104	202110	1	TOSHIBA	TPH2R003PL	3	
X33	TPCA8028-H(TE12LQM	202004	202104	202110	1	TOSHIBA	TPH2R003PL	3	
X33	TPCA8028-H(TE12LVM	202004	202104	202110	1	TOSHIBA	TPH2R003PL	3	
X33	TPCA8030-H(TE12L,Q	202004	202104	202110	1	TOSHIBA	TPH4R803PL	3	
X33	TPCA8030-H(TE12LQM	202004	202104	202110	1	TOSHIBA	TPH4R803PL	3	
X33	TPCA8030-H(TE12LVM	202004	202104	202110	1	TOSHIBA	TPH4R803PL	3	
X33	TPCA8036-H(TE12LQM	202004	202104	202110	1	TOSHIBA	TPH3R003PL	3	
X33	TPCA8036-H(TE12LVM	202004	202104	202110	1	TOSHIBA	TPH3R003PL	3	
X33	TPCA8039-H(2LCO1,Q	202004	202104	202110	1	TOSHIBA	TPH4R803PL	3	
X33	TPCA8039-H(TE12L,Q	202004	202104	202110	1	TOSHIBA	TPH4R803PL	3	
X33	TPCA8039-H(TE12LVM	202004	202104	202110	1	TOSHIBA	TPH4R803PL	3	
X33	TPCA8040-H(TE12LQM	202004	202104	202110	1	TOSHIBA	TPH4R803PL	3	
X33	TPCA8040-H(TE12LVM	202004	202104	202110	1	TOSHIBA	TPH4R803PL	3	
X33	TPCA8045-H(TE12L,Q	202004	202104	202110	1	TOSHIBA	TPH2R104PL	3	
X33	TPCA8045-H(TE12LQM	202004	202104	202110	1	TOSHIBA	TPH2R104PL	3	
X33	TPCA8046-H(TE12L,Q	202004	202104	202110	1	TOSHIBA	TPH3R704PC	3	
X33	TPCA8046-H(TE12LQM	202004	202104	202110	1	TOSHIBA	TPH3R704PC	3	
X33	TPCA8047-H(TE12L,Q	202004	202104	202110	1	TOSHIBA	TPH7R204PL	3	
X33	TPCA8047-H(TE12LQM	202004	202104	202110	1	TOSHIBA	TPH7R204PL	3	
X33	TPCA8048-H(TE12L,Q	202004	202104	202110	1	TOSHIBA	TPH3R506PL	3	Y
X33	TPCA8048-H(TE12LQM	202004	202104	202110	1	TOSHIBA	TPH3R506PL	3	
X33	TPCA8049-H(TE12L,Q	202004	202104	202110	1	TOSHIBA	TPH9R506PL	3	Y

X33	TPCA8049-H(TE12LQM	202004	202104	202110	1	TOSHIBA	TPH9R506PL	3	
X33	TPCA8050-H(T2L1,V)	202004	202104	202110	1	TOSHIBA	TPH9R506PL	3	
X33	TPCA8050-H(T2L1,VM	202004	202104	202110	1	TOSHIBA	TPH9R506PL	3	
X33	TPCA8050-H(TE12L,Q	202004	202104	202110	1	TOSHIBA	TPH9R506PL	3	Y
X33	TPCA8050-H(TE12LQM	202004	202104	202110	1	TOSHIBA	TPH9R506PL	3	
X33	TPCA8051-H(TE12L,Q	202004	202104	202110	1	TOSHIBA	TPH8R008NH	3	
X33	TPCA8051-H(TE12LQM	202004	202104	202110	1	TOSHIBA	TPH8R008NH	3	
X33	TPCA8052-H(2LPHC,Q	202004	202104	202110	1	TOSHIBA	TPH7R204PL	3	
X33	TPCA8052-H(T2LDN,Q	202004	202104	202110	1	TOSHIBA	TPH7R204PL	3	
X33	TPCA8052-H(TE12L,Q	202004	202104	202110	1	TOSHIBA	TPH7R204PL	3	
X33	TPCA8052-H(TE12LQM	202004	202104	202110	1	TOSHIBA	TPH7R204PL	3	
X33	TPCA8052-H,L1DIV(O	202004	202104	202110	3	TOSHIBA	TK65S04N1L	3	
X33	TPCA8053-H(2LHLS,Q	202004	202104	202110	3	TOSHIBA	XPN12006NC	3	
X33	TPCA8053-H(T2L,A,Q	202004	202104	202110	1	TOSHIBA	TPH9R506PL	3	
X33	TPCA8053-H(T2LPP,X	202004	202104	202110	1	TOSHIBA	TPH9R506PL	3	
X33	TPCA8053-H(TE12L,Q	202004	202104	202110	1	TOSHIBA	TPH9R506PL	3	Y
X33	TPCA8053-H(TE12LQM	202004	202104	202110	1	TOSHIBA	TPH9R506PL	3	
X33	TPCA8055-H(TE12L,Q	202004	202104	202110	1	TOSHIBA	TPH1R403NL	2	
X33	TPCA8055-H,LQ(J	202004	202104	202110	1	TOSHIBA	TPH1R403NL	2	
X33	TPCA8055-H,LQ(M	202004	202104	202110	1	TOSHIBA	TPH1R403NL	2	
X33	TPCA8056-H,LQ(J	202004	202104	202110	1	TOSHIBA	TPH2R003PL	2	
X33	TPCA8056-H,LQ(M	202004	202104	202110	1	TOSHIBA	TPH2R003PL	2	Y
X33	TPCA8057-H,L1SOQ(M	202004	202104	202110	1	TOSHIBA	TPH2R003PL	2	
X33	TPCA8057-H,LQ(J	202004	202104	202110	1	TOSHIBA	TPH2R003PL	2	
X33	TPCA8057-H,LQ(M	202004	202104	202110	1	TOSHIBA	TPH2R003PL	2	
X33	TPCA8057-H,LSOYQ(J	202004	202104	202110	1	TOSHIBA	TPH2R003PL	2	
X33	TPCA8057-H,LSOYQ(M	202004	202104	202110	1	TOSHIBA	TPH2R003PL	2	
X33	TPCA8058-H,LQ(J	202004	202104	202110	2	TOSHIBA	TPH2R903PL	2	
X33	TPCA8058-H,LQ(M	202004	202104	202110	2	TOSHIBA	TPH2R903PL	2	
X33	TPCA8059-H,L1Q(J	202004	202104	202110	1	TOSHIBA	TPH3R203NL	2	
X33	TPCA8059-H,L1Q(M	202004	202104	202110	1	TOSHIBA	TPH3R203NL	2	Y
X33	TPCA8059-H,L1SOQ(M	202004	202104	202110	1	TOSHIBA	TPH3R203NL	2	
X33	TPCA8059-H,LADQ(J	202004	202104	202110	1	TOSHIBA	TPH3R203NL	2	
X33	TPCA8059-H,LQ(J	202004	202104	202110	1	TOSHIBA	TPH3R203NL	2	
X33	TPCA8059-H,LQ(M	202004	202104	202110	1	TOSHIBA	TPH3R203NL	2	Y
X33	TPCA8059-H,LQ(S	202004	202104	202110	1	TOSHIBA	TPH3R203NL	2	

X33	TPCA8059-H,LSOYQ(J	202004	202104	202110	1	TOSHIBA	TPH3R203NL	2
X33	TPCA8059-H,LSOYQ(M	202004	202104	202110	1	TOSHIBA	TPH3R203NL	2
X33	TPCA8060-H(2LSO,QM	202004	202104	202110	1	TOSHIBA	TPH3R003PL	3
X33	TPCA8060-H(2LSO1AQ	202004	202104	202110	1	TOSHIBA	TPH3R003PL	3
X33	TPCA8060-H(2LSO1QM	202004	202104	202110	1	TOSHIBA	TPH3R003PL	3
X33	TPCA8060-H(TE12LQM	202004	202104	202110	1	TOSHIBA	TPH3R003PL	3
X33	TPCA8060-H(TE12LVM	202004	202104	202110	1	TOSHIBA	TPH3R003PL	3
X33	TPCA8062-H,L1Q(CJ	202004	202104	202110	1	TOSHIBA	TPH4R803PL	2
X33	TPCA8062-H,L1Q(CM	202004	202104	202110	1	TOSHIBA	TPH4R803PL	2
X33	TPCA8062-H,LQ(CM	202004	202104	202110	1	TOSHIBA	TPH4R803PL	2
X33	TPCA8062-H,LQ(J	202004	202104	202110	1	TOSHIBA	TPH4R803PL	2
X33	TPCA8062-H,LQ(M	202004	202104	202110	1	TOSHIBA	TPH4R803PL	2
X33	TPCA8062-H,LQ(S	202004	202104	202110	1	TOSHIBA	TPH4R803PL	2
X33	TPCA8063-H,L1Q(CJ	202004	202104	202110	1	TOSHIBA	TPH6R003NL	2
X33	TPCA8063-H,L1Q(CM	202004	202104	202110	1	TOSHIBA	TPH6R003NL	2
X33	TPCA8063-H,LQ(CM	202004	202104	202110	1	TOSHIBA	TPH6R003NL	2
X33	TPCA8063-H,LQ(J	202004	202104	202110	1	TOSHIBA	TPH6R003NL	2
X33	TPCA8063-H,LQ(M	202004	202104	202110	1	TOSHIBA	TPH6R003NL	2
X33	TPCA8064-H,L1Q(CJ	202004	202104	202110	1	TOSHIBA	TPH6R003NL	2
X33	TPCA8064-H,L1Q(CM	202004	202104	202110	1	TOSHIBA	TPH6R003NL	2
X33	TPCA8064-H,L1QQ(CM	202004	202104	202110	1	TOSHIBA	TPH6R003NL	2
X33	TPCA8064-H,L1SQ(CJ	202004	202104	202110	1	TOSHIBA	TPH6R003NL	2
X33	TPCA8064-H,L1SQ(CM	202004	202104	202110	1	TOSHIBA	TPH6R003NL	2
X33	TPCA8064-H,LQ(CM	202004	202104	202110	1	TOSHIBA	TPH6R003NL	2
X33	TPCA8064-H,LQ(J	202004	202104	202110	1	TOSHIBA	TPH6R003NL	2
X33	TPCA8064-H,LQ(M	202004	202104	202110	1	TOSHIBA	TPH6R003NL	2
X33	TPCA8064-H,LQ(S	202004	202104	202110	1	TOSHIBA	TPH6R003NL	2
X33	TPCA8064-H,LSOQ(J	202004	202104	202110	1	TOSHIBA	TPH6R003NL	2
X33	TPCA8064-H,LSOQ(M	202004	202104	202110	1	TOSHIBA	TPH6R003NL	2
X33	TPCA8064-H,LSOYQ(M	202004	202104	202110	1	TOSHIBA	TPH6R003NL	2
X33	TPCA8065-H,LQ(S	202004	202104	202110	1	TOSHIBA	TPH6R003NL	2
X33	TPCA8068-H,LQ(S	202004	202104	202110	1	TOSHIBA	TPH8R903NL	2
X33	TPCA8075,L1Q(M	202004	202104	202110	1	TOSHIBA	TPH2R104PL	2
X33	TPCA8075,L1SAN2X(J	202004	202104	202110	1	TOSHIBA	TPH2R104PL	2
X33	TPCA8075,L1SAN2X(M	202004	202104	202110	1	TOSHIBA	TPH2R104PL	2
X33	TPCA8075,LQ(J	202004	202104	202110	1	TOSHIBA	TPH2R104PL	2

X33	TPCA8075,LQ(M	202004	202104	202110	1	TOSHIBA	TPH2R104PL	2
X33	TPCA8077(2L1SON,AV	202004	202104	202110	2	TOSHIBA	TPH2R003PL	2
X33	TPCA8077(2L1SON,VM	202004	202104	202110	2	TOSHIBA	TPH2R003PL	2
X33	TPCA8077(2L1SONY,V	202004	202104	202110	2	TOSHIBA	TPH2R003PL	2
X33	TPCA8077(2LSONY,AQ	202004	202104	202110	2	TOSHIBA	TPH2R003PL	2
X33	TPCA8077(2LSONY,Q)	202004	202104	202110	2	TOSHIBA	TPH2R003PL	2
X33	TPCA8077(2LSONY,QM	202004	202104	202110	2	TOSHIBA	TPH2R003PL	2
X33	TPCA8077(TE12L,Q)	202004	202104	202110	2	TOSHIBA	TPH2R003PL	2
X33	TPCA8077(TE12L,Q,M	202004	202104	202110	2	TOSHIBA	TPH2R003PL	2
X33	TPCA8077(TE12L1,V)	202004	202104	202110	2	TOSHIBA	TPH2R003PL	2
X33	TPCA8077(TE12L1,VM	202004	202104	202110	2	TOSHIBA	TPH2R003PL	2
X33	TPCA8077,LSONYQ(CJ	202004	202104	202110	2	TOSHIBA	TPH2R003PL	2
X33	TPCA8077,LSONYQ(CM	202004	202104	202110	2	TOSHIBA	TPH2R003PL	2
X33	TPCA8078,L1Q(M	202004	202104	202110	2	TOSHIBA	TPH2R104PL	2
X33	TPCA8078,L1SAN2X(M	202004	202104	202110	2	TOSHIBA	TPH2R104PL	2
X33	TPCA8078,LQ(J	202004	202104	202110	2	TOSHIBA	TPH2R104PL	2
X33	TPCA8078,LQ(M	202004	202104	202110	2	TOSHIBA	TPH2R104PL	2
X33	TPCA8080,L1Q(CJ	202004	202104	202110	1	TOSHIBA	TPH2R003PL	2
X33	TPCA8080,L1Q(CM	202004	202104	202110	1	TOSHIBA	TPH2R003PL	2
X33	TPCA8080,LQ(CM	202004	202104	202110	1	TOSHIBA	TPH2R003PL	2
X33	TPCA8080,LQ(J	202004	202104	202110	1	TOSHIBA	TPH2R003PL	2
X33	TPCA8080,LQ(M	202004	202104	202110	1	TOSHIBA	TPH2R003PL	2
X33	TPCA8081,L1Q(CJ	202004	202104	202110	2	TOSHIBA	TPH2R903PL	2
X33	TPCA8081,L1Q(CM	202004	202104	202110	2	TOSHIBA	TPH2R903PL	2
X33	TPCA8081,LQ(CM	202004	202104	202110	2	TOSHIBA	TPH2R903PL	2
X33	TPCA8081,LQ(J	202004	202104	202110	2	TOSHIBA	TPH2R903PL	2
X33	TPCA8081,LQ(M	202004	202104	202110	2	TOSHIBA	TPH2R903PL	2
X33	TPCA8082,L1Q(CJ	202004	202104	202110	1	TOSHIBA	TPH3R203NL	2
X33	TPCA8082,L1Q(CM	202004	202104	202110	1	TOSHIBA	TPH3R203NL	2
X33	TPCA8082,LQ(CM	202004	202104	202110	1	TOSHIBA	TPH3R203NL	2
X33	TPCA8082,LQ(J	202004	202104	202110	1	TOSHIBA	TPH3R203NL	2
X33	TPCA8082,LQ(M	202004	202104	202110	1	TOSHIBA	TPH3R203NL	2
X33	TPCA8087,L1APQ(M	202004	202104	202110	1	TOSHIBA	TPH1R403NL	2
X33	TPCA8087,L1Q(CJ	202004	202104	202110	1	TOSHIBA	TPH1R403NL	2
X33	TPCA8087,L1Q(CM	202004	202104	202110	1	TOSHIBA	TPH1R403NL	2
X33	TPCA8087,LQ(CM	202004	202104	202110	1	TOSHIBA	TPH1R403NL	2

X33	TPCA8087,LQ(J	202004	202104	202110	1	TOSHIBA	TPH1R403NL	2	
X33	TPCA8087,LQ(M	202004	202104	202110	1	TOSHIBA	TPH1R403NL	2	
X33	TPCA8088,L1PAEX(CJ	202004	202104	202110	1	TOSHIBA	TPH2R003PL	2	
X33	TPCA8088,L1PAEX(CM	202004	202104	202110	1	TOSHIBA	TPH2R003PL	2	
X33	TPCA8088,L1Q(CJ	202004	202104	202110	1	TOSHIBA	TPH2R003PL	2	
X33	TPCA8088,L1Q(CM	202004	202104	202110	1	TOSHIBA	TPH2R003PL	2	
X33	TPCA8088,LPAEX(J	202004	202104	202110	1	TOSHIBA	TPH2R003PL	2	
X33	TPCA8088,LPAEX(M	202004	202104	202110	1	TOSHIBA	TPH2R003PL	2	
X33	TPCA8088,LQ(CM	202004	202104	202110	1	TOSHIBA	TPH2R003PL	2	
X33	TPCA8088,LQ(J	202004	202104	202110	1	TOSHIBA	TPH2R003PL	2	
X33	TPCA8088,LQ(M	202004	202104	202110	1	TOSHIBA	TPH2R003PL	2	
X33	TPCA8091-H,LQ(S	202004	202104	202110	1	TOSHIBA	TPH6R003NL	2	
X33	TPCA8091-H,LSQ(S	202004	202104	202110	1	TOSHIBA	TPH6R003NL	2	
X33	TPCA8092-H,LQ(S	202004	202104	202110	1	TOSHIBA	TPH6R004PL	2	
X33	TPCA8103(T2LAD,Q)	202004	202104	202110	2	TOSHIBA	TPCA8128	2	
X33	TPCA8104(T2LAPN,Q)	202004	202104	202110	3	TOSHIBA	TJ50S06M3L	2	
X33	TPCA8104(T2LASAW,Q	202004	202104	202110	3	TOSHIBA	TJ50S06M3L	2	
X33	TPCA8104(T2LFJTN,Q	202004	202104	202110	3	TOSHIBA	TJ50S06M3L	2	Y
X33	TPCA8104(T2LHITJ,Q	202004	202104	202110	3	TOSHIBA	TJ50S06M3L	2	Y
X33	TPCA8104(T2LJTEK,X	202004	202104	202110	3	TOSHIBA	TJ50S06M3L	2	
X33	TPCA8104(T2LNMB,Q)	202004	202104	202110	3	TOSHIBA	TJ50S06M3L	2	
X33	TPCA8104(T2LPAV,Q)	202004	202104	202110	3	TOSHIBA	TJ50S06M3L	2	
X33	TPCA8104(T2LPHC,Q)	202004	202104	202110	3	TOSHIBA	TJ50S06M3L	2	
X33	TPCA8104(TE12L,Q)	202004	202104	202110	3	TOSHIBA	TJ50S06M3L	2	Y
X33	TPCA8104(TE12L,Q,M	202004	202104	202110	3	TOSHIBA	TJ50S06M3L	2	Y
X33	TPCA8105(T2LPAIO,Q	202004	202104	202110	3	TOSHIBA	SSM6J511NU	2	
X33	TPCA8106(T2LNKOD,Q	202004	202104	202110	1	TOSHIBA	TPCA8120	2	
X33	TPCA8106(T2LTYG,X)	202004	202104	202110	1	TOSHIBA	TPCA8120	2	
X33	TPCA8106(TE12L,Q)	202004	202104	202110	1	TOSHIBA	TPCA8120	2	Y
X33	TPCA8106(TE12L,Q,M	202004	202104	202110	1	TOSHIBA	TPCA8120	2	Y
X33	TPCA8107-H(2LPAS,Q	202004	202104	202110	3	TOSHIBA	TJ20S04M3L	2	
X33	TPCA8107-H(TE12L,Q	202004	202104	202110	3	TOSHIBA	TPC8132	2	
X33	TPCA8107-H(TE12LQM	202004	202104	202110	3	TOSHIBA	TPC8132	2	Y
X33	TPCA8108(T2LASAW,X	202004	202104	202110	3	TOSHIBA	TJ40S04M3L	2	
X33	TPCA8108(T2LASN,X)	202004	202104	202110	3	TOSHIBA	TJ40S04M3L	2	
X33	TPCA8108(T2LFDKK,Q	202004	202104	202110	3	TOSHIBA	TJ40S04M3L	2	

X33	TPCA8108(T2LHIJ,Q)	202004	202104	202110	3	TOSHIBA	TJ40S04M3L	2	
X33	TPCA8108(TE12L,Q)	202004	202104	202110	3	TOSHIBA	TJ40S04M3L	2	Y
X33	TPCA8108(TE12L,Q,M	202004	202104	202110	3	TOSHIBA	TJ40S04M3L	2	
X33	TPCA8108(TE12L,V,M	202004	202104	202110	3	TOSHIBA	TJ40S04M3L	2	
X33	TPCA8109(T2L,A,Q)	202004	202104	202110	1	TOSHIBA	TPCA8109(T2L1,A,V)	3	
X33	TPCA8109(TE12L,QM)	202004	202104	202110	1	TOSHIBA	TPCA8109(TE12L1,VM	3	
X33	TPCA8109(TE12L,V,M	202004	202104	202110	1	TOSHIBA	TPCA8109(TE12L1,VM	3	
X33	TPCA8120,LQ(CM	202004	202104	202110	1	TOSHIBA	TPCA8120,L1Q(CM	3	
X33	TPCA8120,LQ(J	202004	202104	202110	1	TOSHIBA	TPCA8120,L1Q(CJ	3	Y
X33	TPCA8120,LQ(M	202004	202104	202110	1	TOSHIBA	TPCA8120,L1Q(CM	3	
X33	TPCA8120,LSANX(J	202004	202104	202110	1	TOSHIBA	TPCA8120,L1SANX(CJ	3	
X33	TPCA8120,LSANX(M	202004	202104	202110	1	TOSHIBA	TPCA8120,L1SANX(CM	3	
X33	TPCA8128,LQ(CM	202004	202104	202110	1	TOSHIBA	TPCA8128,L1Q(CM	3	
X33	TPCA8128,LQ(J	202004	202104	202110	1	TOSHIBA	TPCA8128,L1Q(CJ	3	
X33	TPCA8128,LQ(M	202004	202104	202110	1	TOSHIBA	TPCA8128,L1Q(CM	3	Y
X33	TPCA8201-H,LF(S	202004	202104	202110	1	infineon	BSC0923NDI	2	
X33	TPCA8A02-H(2L1SOVM	202004	202104	202110	1	TOSHIBA	TPH4R803PL	2	
X33	TPCA8A02-H(TE12L,Q	202004	202104	202110	1	TOSHIBA	TPH4R803PL	2	
X33	TPCA8A02-H,L1SQ(CM	202004	202104	202110	1	TOSHIBA	TPH4R803PL	2	
X33	TPCA8A04-H(T2L1,AV	202004	202104	202110	1	TOSHIBA	TPH2R903PL	2	
X33	TPCA8A05-H(T2L,A,Q	202004	202104	202110	1	TOSHIBA	TPH11003NL	2	
X33	TPCA8A09-H,L1Q(M	202004	202104	202110	1	TOSHIBA	TPH2R003PL	2	
X33	TPCA8A09-H,L1SQ(M	202004	202104	202110	1	TOSHIBA	TPH2R003PL	2	
X33	TPCA8A09-H,LQ(J	202004	202104	202110	1	TOSHIBA	TPH2R003PL	2	
X33	TPCA8A09-H,LQ(M	202004	202104	202110	1	TOSHIBA	TPH2R003PL	2	
X33	TPCA8A10-H,L1Q(M	202004	202104	202110	2	TOSHIBA	TPH2R903PL	2	
X33	TPCA8A10-H,LQ(J	202004	202104	202110	2	TOSHIBA	TPH2R903PL	2	
X33	TPCA8A10-H,LQ(M	202004	202104	202110	2	TOSHIBA	TPH2R903PL	2	
X33	TPCA8A11-H,L1Q(M	202004	202104	202110	2	TOSHIBA	TPH3R203NL	2	
X33	TPCA8A11-H,L1SQ(M	202004	202104	202110	2	TOSHIBA	TPH3R203NL	2	
X33	TPCA8A11-H,LQ(J	202004	202104	202110	2	TOSHIBA	TPH3R203NL	2	
X33	TPCA8A11-H,LQ(M	202004	202104	202110	2	TOSHIBA	TPH3R203NL	2	
X33	TPCA8A21-H,L1Q(M	202004	202104	202110	1	TOSHIBA	TPH2R104PL	2	
X33	TPCC8001-H(T2LSO,Q	202004	202104	202110	1	TOSHIBA	TPN6R303NC	2	
X33	TPCC8001-H(TE12L,Q	202004	202104	202110	1	TOSHIBA	TPN6R303NC	2	
X33	TPCC8003-H(TE12L,Q	202004	202104	202110	1	TOSHIBA	TPN11003NL	3	

X33	TPCC8006-H(TE12L,Q	202004	202104	202110	3	TOSHIBA	TPN6R303NC	3	
X33	TPCC8007(T2L1PC,V)	202004	202104	202110	3	infineon	BSC046N02KS G	3	
X33	TPCC8007(T2L1PC,VM	202004	202104	202110	3	infineon	BSC046N02KS G	3	
X33	TPCC8007(T2LPC,Q)	202004	202104	202110	3	infineon	BSC046N02KS G	3	
X33	TPCC8007(T2LPC,QM)	202004	202104	202110	3	infineon	BSC046N02KS G	3	
X33	TPCC8007(TE12L,Q)	202004	202104	202110	3	infineon	BSC046N02KS G	3	
X33	TPCC8007(TE12L,QM)	202004	202104	202110	3	infineon	BSC046N02KS G	3	
X33	TPCC8007(TE12L,VM)	202004	202104	202110	3	infineon	BSC046N02KS G	3	
X33	TPCC8007(TE12L1,V)	202004	202104	202110	3	infineon	BSC046N02KS G	3	
X33	TPCC8007(TE12L1,VM	202004	202104	202110	3	infineon	BSC046N02KS G	3	
X33	TPCC8007,L1Q(CJ	202004	202104	202110	3	infineon	BSC046N02KS G	3	
X33	TPCC8007,L1Q(CM	202004	202104	202110	3	infineon	BSC046N02KS G	3	
X33	TPCC8008(TE12L,Q)	202004	202104	202110	1	TOSHIBA	TPN6R303NC	3	
X33	TPCC8008(TE12L,QM)	202004	202104	202110	1	TOSHIBA	TPN6R303NC	3	
X33	TPCC8009,L1SA2X(CM	202004	202104	202110	1	TOSHIBA	TPN6R303NC	3	
X33	TPCC8009,LSAN2X(J	202004	202104	202110	1	TOSHIBA	TPN6R303NC	3	
X33	TPCC8009,LSAN2X(M	202004	202104	202110	1	TOSHIBA	TPN6R303NC	3	
X33	TPCC8061-H,LQ(O	202004	202104	202110	1	TOSHIBA	TPN11003NL	3	
X33	TPCC8061-H,LQ(S	202004	202104	202110	1	TOSHIBA	TPN11003NL	3	
X33	TPCC8062-H,L1MQ(CM	202004	202104	202110	1	TOSHIBA	TPN5R203PL	2	
X33	TPCC8062-H,L1Q(CJ	202004	202104	202110	1	TOSHIBA	TPN5R203PL	2	
X33	TPCC8062-H,L1Q(CM	202004	202104	202110	1	TOSHIBA	TPN5R203PL	2	
X33	TPCC8062-H,LMU1Q(J	202004	202104	202110	1	TOSHIBA	TPN5R203PL	2	
X33	TPCC8062-H,LMU1Q(M	202004	202104	202110	1	TOSHIBA	TPN5R203PL	2	
X33	TPCC8062-H,LQ(M	202004	202104	202110	1	TOSHIBA	TPN5R203PL	2	
X33	TPCC8062-H,LQ(O	202004	202104	202110	1	TOSHIBA	TPN5R203PL	2	
X33	TPCC8064-H,L1Q(CJ	202004	202104	202110	1	TOSHIBA	TPN6R303NC	2	
X33	TPCC8064-H,L1Q(CM	202004	202104	202110	1	TOSHIBA	TPN6R303NC	2	
X33	TPCC8064-H,L1SQ(CJ	202004	202104	202110	1	TOSHIBA	TPN6R303NC	2	
X33	TPCC8064-H,L1SQ(CM	202004	202104	202110	1	TOSHIBA	TPN6R303NC	2	
X33	TPCC8064-H,LQ(M	202004	202104	202110	1	TOSHIBA	TPN6R303NC	2	
X33	TPCC8064-H,LQ(O	202004	202104	202110	1	TOSHIBA	TPN6R303NC	2	
X33	TPCC8064-H,LSOQ(CJ	202004	202104	202110	1	TOSHIBA	TPN6R303NC	2	
X33	TPCC8064-H,LSOYQ(J	202004	202104	202110	1	TOSHIBA	TPN6R303NC	2	Y
X33	TPCC8064-H,LSOYQ(M	202004	202104	202110	1	TOSHIBA	TPN6R303NC	2	Y
X33	TPCC8064-H,LSOYQ(O	202004	202104	202110	1	TOSHIBA	TPN6R303NC	2	

X33	TPCC8065-H,LQ(S	202004	202104	202110	1	TOSHIBA	TPN8R903NL	2	
X33	TPCC8066-H,LQ(S	202004	202104	202110	1	TOSHIBA	TPN11003NL	2	
X33	TPCC8067-H,LQ(S	202004	202104	202110	1	TOSHIBA	TPN11003NL	2	
X33	TPCC8068-H,LQ(S	202004	202104	202110	1	TOSHIBA	TPN11003NL	2	
X33	TPCC8073,L1Q(CJ	202004	202104	202110	1	TOSHIBA	TPN4R203NC	2	
X33	TPCC8073,L1Q(CM	202004	202104	202110	1	TOSHIBA	TPN4R203NC	2	Y
X33	TPCC8073,L1SONQ(CJ	202004	202104	202110	1	TOSHIBA	TPN4R203NC	2	
X33	TPCC8073,L1SONQ(CM	202004	202104	202110	1	TOSHIBA	TPN4R203NC	2	
X33	TPCC8073,L1SONQ(CO	202004	202104	202110	1	TOSHIBA	TPN4R203NC	2	
X33	TPCC8073,L1SQ(CM	202004	202104	202110	1	TOSHIBA	TPN4R203NC	2	
X33	TPCC8073,LQ(M	202004	202104	202110	1	TOSHIBA	TPN4R203NC	2	
X33	TPCC8073,LQ(O	202004	202104	202110	1	TOSHIBA	TPN4R203NC	2	
X33	TPCC8073,LSONYQ(CJ	202004	202104	202110	1	TOSHIBA	TPN4R203NC	2	
X33	TPCC8073,LSONYQ(CM	202004	202104	202110	1	TOSHIBA	TPN4R203NC	2	
X33	TPCC8073,LSONYQ(J	202004	202104	202110	1	TOSHIBA	TPN4R203NC	2	
X33	TPCC8073,LSONYQ(M	202004	202104	202110	1	TOSHIBA	TPN4R203NC	2	
X33	TPCC8073,LSONYQ(O	202004	202104	202110	1	TOSHIBA	TPN4R203NC	2	
X33	TPCC8074,L1Q(CJ	202004	202104	202110	1	TOSHIBA	TPN6R303NC	2	
X33	TPCC8074,L1Q(CM	202004	202104	202110	1	TOSHIBA	TPN6R303NC	2	
X33	TPCC8074,LQ(M	202004	202104	202110	1	TOSHIBA	TPN6R303NC	2	
X33	TPCC8074,LQ(O	202004	202104	202110	1	TOSHIBA	TPN6R303NC	2	
X33	TPCC8076,L1NKOQ(CJ	202004	202104	202110	1	TOSHIBA	TPN3R704PL	2	
X33	TPCC8076,L1Q(CJ	202004	202104	202110	1	TOSHIBA	TPN3R704PL	2	
X33	TPCC8076,L1Q(CM	202004	202104	202110	1	TOSHIBA	TPN3R704PL	2	Y
X33	TPCC8076,L1SA2X(CJ	202004	202104	202110	1	TOSHIBA	TPN3R704PL	2	
X33	TPCC8076,L1SA2X(CM	202004	202104	202110	1	TOSHIBA	TPN3R704PL	2	
X33	TPCC8076,LQ(M	202004	202104	202110	1	TOSHIBA	TPN3R704PL	2	
X33	TPCC8076,LQ(O	202004	202104	202110	1	TOSHIBA	TPN3R704PL	2	
X33	TPCC8076,LSAN2X(J	202004	202104	202110	1	TOSHIBA	TPN3R704PL	2	
X33	TPCC8076,LSAN2X(M	202004	202104	202110	1	TOSHIBA	TPN3R704PL	2	
X33	TPCC8076,LSAN2X(O	202004	202104	202110	1	TOSHIBA	TPN3R704PL	2	
X33	TPCC8084,L1PHCQ(CM	202004	202104	202110	1	TOSHIBA	TPN3R704PL	2	
X33	TPCC8084,L1Q(CJ	202004	202104	202110	1	TOSHIBA	TPN3R704PL	2	
X33	TPCC8084,L1Q(CM	202004	202104	202110	1	TOSHIBA	TPN3R704PL	2	Y
X33	TPCC8084,L1SA2X(CJ	202004	202104	202110	1	TOSHIBA	TPN3R704PL	2	
X33	TPCC8084,L1SA2X(CM	202004	202104	202110	1	TOSHIBA	TPN3R704PL	2	

X33	TPCC8084,LQ(M	202004	202104	202110	1	TOSHIBA	TPN3R704PL	2	
X33	TPCC8084,LQ(O	202004	202104	202110	1	TOSHIBA	TPN3R704PL	2	
X33	TPCC8084,LSAN2X(J	202004	202104	202110	1	TOSHIBA	TPN3R704PL	2	
X33	TPCC8084,LSAN2X(M	202004	202104	202110	1	TOSHIBA	TPN3R704PL	2	
X33	TPCC8093,L1Q(M	202004	202104	202110	3	infineon	BSC046N02KS G	2	
X33	TPCC8093,L1SONYQ(M	202004	202104	202110	3	infineon	BSC046N02KS G	2	
X33	TPCC8093,L1TDSQ(M	202004	202104	202110	3	infineon	BSC046N02KS G	2	
X33	TPCC8093,LQ(J	202004	202104	202110	3	infineon	BSC046N02KS G	2	
X33	TPCC8093,LQ(M	202004	202104	202110	3	infineon	BSC046N02KS G	2	
X33	TPCC8102(TE12L,Q)	202004	202104	202110	1	TOSHIBA	TPCC8131	2	
X33	TPCC8102(TE12L,Q,M	202004	202104	202110	1	TOSHIBA	TPCC8131	2	
X33	TPCC8103(TE12L,Q)	202004	202104	202110	1	TOSHIBA	TPCC8104	2	
X33	TPCC8103(TE12L,QM)	202004	202104	202110	1	TOSHIBA	TPCC8104	2	
X33	TPCC8103(TE12L,VM)	202004	202104	202110	1	TOSHIBA	TPCC8104	2	
X33	TPCC8103(TE12L1,VM	202004	202104	202110	1	TOSHIBA	TPCC8104	2	
X33	TPCC8104,LQ(J	202004	202104	202110	1	TOSHIBA	TPCC8104,L1Q(CJ	3	
X33	TPCC8104,LQ(M	202004	202104	202110	1	TOSHIBA	TPCC8104,L1Q(CM	3	
X33	TPCC8104,LQ(O	202004	202104	202110	1	TOSHIBA	TPCC8104,L1Q(CM	3	
X33	TPCC8105,LQ(M	202004	202104	202110	1	TOSHIBA	TPCC8105,L1Q(CM	3	
X33	TPCC8105,LQ(O	202004	202104	202110	1	TOSHIBA	TPCC8105,L1Q(CM	3	
X33	TPCC8105,LSONYQ(CJ	202004	202104	202110	1	TOSHIBA	TPCC8105,L1SONQ(CJ	3	
X33	TPCC8105,LSONYQ(O	202004	202104	202110	1	TOSHIBA	TPCC8105,L1SONQ(CJ	3	
X33	TPCC8A01-H(TE12L,Q	202004	202104	202110	1	TOSHIBA	TPN8R903NL	2	
X33	TPCF8002,LF(CJ	202004	202104	202110	3	TOSHIBA	SSM6K504NU	4	
X33	TPCF8002,LF(CM	202004	202104	202110	3	TOSHIBA	SSM6K504NU	4	
X33	TPCF8003(TE85L,F,M	202004	202104	202110	3	TOSHIBA	SSM3K123TU	4	
X33	TPCF8003,LF(CJ	202004	202104	202110	3	TOSHIBA	SSM3K123TU	4	
X33	TPCF8003,LF(CM	202004	202104	202110	3	TOSHIBA	SSM3K123TU	4	
X33	TPCF8004,LF(CJ	202004	202104	202110	3	TOSHIBA	SSM6K504NU	4	
X33	TPCF8004,LF(CM	202004	202104	202110	3	TOSHIBA	SSM6K504NU	4	
X33	TPCF8004,LF(J	202004	202104	202110	3	TOSHIBA	SSM6K504NU	4	
X33	TPCF8004,LF(M	202004	202104	202110	3	TOSHIBA	SSM6K504NU	4	
X33	TPCF8101(T5LAP,F,M	202004	202104	202110	3	TOSHIBA	SSM3J140TU	4	Y
X33	TPCF8101(TE85L,F,M	202004	202104	202110	3	TOSHIBA	SSM3J338R	4	Y
X33	TPCF8101,LAPNF(J	202004	202104	202110	3	TOSHIBA	SSM3J140TU	4	
X33	TPCF8101,LAPNF(M	202004	202104	202110	3	TOSHIBA	SSM3J140TU	4	

X33	TPCF8101,LF(J	202004	202104	202110	3	TOSHIBA	SSM3J338R	4
X33	TPCF8104(T5LCAN,AF	202004	202104	202110	3	TOSHIBA	SSM3J378R	4
X33	TPCF8104(T5LCAN,FM	202004	202104	202110	3	TOSHIBA	SSM3J378R	4
X33	TPCF8104(T5LLNV2FM	202004	202104	202110	3	TOSHIBA	SSM3J378R	4
X33	TPCF8104(T5LPP,A,F	202004	202104	202110	3	TOSHIBA	SSM3J378R	4
X33	TPCF8104(T5LPP,F,M	202004	202104	202110	3	TOSHIBA	SSM3J378R	4
X33	TPCF8104(T5RSON,AF	202004	202104	202110	3	TOSHIBA	SSM3J378R	4
X33	TPCF8104(T5RSON,FM	202004	202104	202110	3	TOSHIBA	SSM3J378R	4
X33	TPCF8104(TE85L,F,M	202004	202104	202110	3	TOSHIBA	SSM3J378R	4
X33	TPCF8104,LF(J	202004	202104	202110	3	TOSHIBA	SSM3J378R	4
X33	TPCF8104,LF(M	202004	202104	202110	3	TOSHIBA	SSM3J378R	4
X33	TPCF8104,LKENWF(J	202004	202104	202110	3	TOSHIBA	SSM3J378R	4
X33	TPCF8104,LKENWF(M	202004	202104	202110	3	TOSHIBA	SSM3J378R	4
X33	TPCF8104,LLNV2F(J	202004	202104	202110	3	TOSHIBA	SSM3J378R	4
X33	TPCF8104,LPAIOF(J	202004	202104	202110	3	TOSHIBA	SSM3J378R	4
X33	TPCF8104,LPAIOF(M	202004	202104	202110	3	TOSHIBA	SSM3J378R	4
X33	TPCF8105(TE85L,F,M	202004	202104	202110	3	TOSHIBA	SSM3J378R	4
X33	TPCF8105,LCSF(J	202004	202104	202110	3	TOSHIBA	SSM3J378R	4
X33	TPCF8105,LF(CJ	202004	202104	202110	3	TOSHIBA	SSM3J378R	4
X33	TPCF8105,LF(CM	202004	202104	202110	3	TOSHIBA	SSM3J378R	4
X33	TPCF8105,LTYUF(CJ	202004	202104	202110	3	TOSHIBA	SSM3J378R	4
X33	TPCF8105,LTYUF(CM	202004	202104	202110	3	TOSHIBA	SSM3J378R	4
X33	TPCF8107(TE85L,F,M	202004	202104	202110	3	TOSHIBA	SSM6J507NU	4
X33	TPCF8107,LCSF(J	202004	202104	202110	3	TOSHIBA	SSM6J507NU	4
X33	TPCF8107,LF(CJ	202004	202104	202110	3	TOSHIBA	SSM6J507NU	4
X33	TPCF8107,LF(CM	202004	202104	202110	3	TOSHIBA	SSM6J507NU	4
X33	TPCF8107,LPAIOF(CJ	202004	202104	202110	3	TOSHIBA	SSM6J507NU	4
X33	TPCF8107,LPAIOF(CM	202004	202104	202110	3	TOSHIBA	SSM6J507NU	4
X33	TPCF8107,LPPF(CJ	202004	202104	202110	3	TOSHIBA	SSM6J507NU	4
X33	TPCF8107,LPPF(CM	202004	202104	202110	3	TOSHIBA	SSM6J507NU	4
X33	TPCF8108(TE85L,F,M	202004	202104	202110	3	TOSHIBA	SSM3J378R	4
X33	TPCF8108,LF(CJ	202004	202104	202110	3	TOSHIBA	SSM3J378R	4
X33	TPCF8108,LF(CM	202004	202104	202110	3	TOSHIBA	SSM3J378R	4
X33	TPCF8302(T5LCAN,AF	202004	202104	202110	3	TOSHIBA	SSM6P49NU	4
X33	TPCF8302(T5LCAN,FM	202004	202104	202110	3	TOSHIBA	SSM6P49NU	4
X33	TPCF8302(T5LSON,AF	202004	202104	202110	3	TOSHIBA	SSM6P49NU	4

X33	TPCF8302(T5LSON,FM	202004	202104	202110	3	TOSHIBA	SSM6P49NU	4
X33	TPCF8302(TE85L,F,M	202004	202104	202110	3	TOSHIBA	SSM6P49NU	4
X33	TPCF8302,LF(J	202004	202104	202110	3	TOSHIBA	SSM6P49NU	4
X33	TPCF8302,LSHRPF(J	202004	202104	202110	3	TOSHIBA	SSM6P49NU	4
X33	TPCF8305,LF(CJ	202004	202104	202110	3	TOSHIBA	SSM6P49NU	4
X33	TPCF8305,LF(CM	202004	202104	202110	3	TOSHIBA	SSM6P49NU	4
X33	TPCF8305,LF(J	202004	202104	202110	3	TOSHIBA	SSM6P49NU	4
X33	TPCF8305,LF(M	202004	202104	202110	3	TOSHIBA	SSM6P49NU	4
X33	TPCF8305,LSONYF(CJ	202004	202104	202110	3	TOSHIBA	SSM6P49NU	4
X33	TPCF8305,LSONYF(CM	202004	202104	202110	3	TOSHIBA	SSM6P49NU	4
X33	TPCF8305,LSONYF(J	202004	202104	202110	3	TOSHIBA	SSM6P49NU	4
X33	TPCF8305,LSONYF(M	202004	202104	202110	3	TOSHIBA	SSM6P49NU	4
X33	TPCF8306,LF(CJ	202004	202104	202110	3	infineon	IRF7316	4
X33	TPCF8306,LF(CM	202004	202104	202110	3	infineon	IRF7316	4
X33	TPCF8306,LF(J	202004	202104	202110	3	infineon	IRF7316	4
X33	TPCF8306,LF(M	202004	202104	202110	3	infineon	IRF7316	4
X33	TPCP8003-H(T5LPP,E	202004	202104	202110	3	TOSHIBA	TPN1200APL	3
X33	TPCP8003-H(T5LPP,F	202004	202104	202110	3	TOSHIBA	TPN1200APL	3
X33	TPCP8005-H(TE85LFM	202004	202104	202110	3	TOSHIBA	TPN11003NL	3
X33	TPCP8005-H,LF(CM	202004	202104	202110	3	TOSHIBA	TPN11003NL	3
X33	TPCP8005-H,RPCF(CM	202004	202104	202110	3	TOSHIBA	TPN11003NL	3
X33	TPCP8006(BRA,F)	202004	202104	202110	3	infineon	BSC046N02KS G	3
X33	TPCP8006(T5LDN,F)	202004	202104	202110	3	infineon	BSC046N02KS G	3
X33	TPCP8006(T5LPAV,F)	202004	202104	202110	3	infineon	BSC046N02KS G	3
X33	TPCP8006(T5LPAV,FM	202004	202104	202110	3	infineon	BSC046N02KS G	3
X33	TPCP8006(T5RSONY,F	202004	202104	202110	3	infineon	BSC046N02KS G	3
X33	TPCP8006(TE85L,C)	202004	202104	202110	3	infineon	BSC046N02KS G	3
X33	TPCP8006(TE85L,F)	202004	202104	202110	3	infineon	BSC046N02KS G	3
X33	TPCP8006(TE85L,F,M	202004	202104	202110	3	infineon	BSC046N02KS G	3
X33	TPCP8006(TE85R,F,M	202004	202104	202110	3	infineon	BSC046N02KS G	3
X33	TPCP8006,LDNF(CJ	202004	202104	202110	3	infineon	BSC046N02KS G	3
X33	TPCP8006,LF(CJ	202004	202104	202110	3	infineon	BSC046N02KS G	3
X33	TPCP8006,LF(CM	202004	202104	202110	3	infineon	BSC046N02KS G	3
X33	TPCP8006,LPAVF(CJ	202004	202104	202110	3	infineon	BSC046N02KS G	3
X33	TPCP8006,LPAVF(CM	202004	202104	202110	3	infineon	BSC046N02KS G	3
X33	TPCP8006,RSONYF(CJ	202004	202104	202110	3	infineon	BSC046N02KS G	3

X33	TPCP8006,RSONYF(CM	202004	202104	202110	3	infineon	BSC046N02KS G	3	
X33	TPCP8007-H,LF(CJ	202004	202104	202110	3	TOSHIBA	TPN22006NH	4	
X33	TPCP8007-H,LF(CM	202004	202104	202110	3	TOSHIBA	TPN22006NH	4	
X33	TPCP8008-H(5LSMI,F	202004	202104	202110	3	TOSHIBA	TPN11003NL	3	
X33	TPCP8008-H,LF(CM	202004	202104	202110	3	TOSHIBA	TPN11003NL	3	
X33	TPCP8102(T5LAP,E,M	202004	202104	202110	3	TOSHIBA	TPCC8136	3	
X33	TPCP8102(TE85L,F)	202004	202104	202110	3	TOSHIBA	TPCC8136	3	
X33	TPCP8102(TE85L,F,M	202004	202104	202110	3	TOSHIBA	TPCC8136	3	
X33	TPCP8103-H(5LMU3,F	202004	202104	202110	1	TOSHIBA	TPCP8107	3	
X33	TPCP8103-H(T5LFJ,F	202004	202104	202110	1	TOSHIBA	TPCP8107	3	Y
X33	TPCP8103-H(T5LKE,F	202004	202104	202110	1	TOSHIBA	TPCP8107	3	Y
X33	TPCP8103-H(TE85LFM	202004	202104	202110	1	TOSHIBA	TPCP8107	3	
X33	TPCP8105,LAWF(CM	202004	202104	202110	3	TOSHIBA	TPCC8136	4	
X33	TPCP8105,LF(CJ	202004	202104	202110	3	TOSHIBA	TPCC8136	4	
X33	TPCP8105,LF(CM	202004	202104	202110	3	TOSHIBA	TPCC8136	4	
X33	TPCP8105,LF(J	202004	202104	202110	3	TOSHIBA	TPCC8136	3	
X33	TPCP8105,LF(M	202004	202104	202110	3	TOSHIBA	TPCC8136	3	
X33	TPCP8105,LPAVF(CM	202004	202104	202110	3	TOSHIBA	TPCC8136	4	
X33	TPCP8106,LCANOF(CJ	202004	202104	202110	3	TOSHIBA	TPCC8131	4	
X33	TPCP8106,LCANOF(CM	202004	202104	202110	3	TOSHIBA	TPCC8131	4	
X33	TPCP8106,LCANOF(J	202004	202104	202110	3	TOSHIBA	TPCC8131	3	
X33	TPCP8106,LCANOF(M	202004	202104	202110	3	TOSHIBA	TPCC8131	3	
X33	TPCP8106,LF(CJ	202004	202104	202110	3	TOSHIBA	TPCC8131	4	
X33	TPCP8106,LF(CM	202004	202104	202110	3	TOSHIBA	TPCC8131	4	Y
X33	TPCP8106,LF(J	202004	202104	202110	3	TOSHIBA	TPCC8131	3	
X33	TPCP8106,LF(M	202004	202104	202110	3	TOSHIBA	TPCC8131	3	
X33	TPCP8106,LSONYF(CM	202004	202104	202110	3	TOSHIBA	TPCC8131	4	
X33	TPCP8106,LXGF(CM	202004	202104	202110	3	TOSHIBA	TPCC8131	4	
X33	TPCP8204(T5LCAN,CM	202004	202104	202110	1	TOSHIBA	TPCP8207	4	
X33	TPCP8204,LCANOF(CJ	202004	202104	202110	1	TOSHIBA	TPCP8207	4	
X33	TPCP8204,LF(CJ	202004	202104	202110	1	TOSHIBA	TPCP8207	4	
X33	TPCP8204,LF(CM	202004	202104	202110	1	TOSHIBA	TPCP8207	4	
X33	TPCP8205-H(5LPAS,F	202004	202104	202110	1	TOSHIBA	TPCP8207	3	
X33	TPCP8205-H(TE85LFM	202004	202104	202110	1	TOSHIBA	TPCP8207	3	
X33	TPCP8205-H,LF(CJ	202004	202104	202110	1	TOSHIBA	TPCP8207	4	
X33	TPCP8205-H,LF(CM	202004	202104	202110	1	TOSHIBA	TPCP8207	4	Y

X33	TPCP8205-H,LF(J	202004	202104	202110	1	TOSHIBA	TPCP8207	3	
X33	TPCP8205-H,LF(M	202004	202104	202110	1	TOSHIBA	TPCP8207	3	
X33	TPCP8205-H,LPAF(CJ	202004	202104	202110	1	TOSHIBA	TPCP8207	4	
X33	TPCP8206,LF(CJ	202004	202104	202110	3	TOSHIBA	SSM6N61NU	4	
X33	TPCP8206,LF(CM	202004	202104	202110	3	TOSHIBA	SSM6N61NU	4	Y
X33	TPCP8206,LF(J	202004	202104	202110	3	TOSHIBA	SSM6N61NU	4	
X33	TPCP8206,LF(M	202004	202104	202110	3	TOSHIBA	SSM6N61NU	4	
X33	TPCP8206,LOLYF(CJ	202004	202104	202110	3	TOSHIBA	SSM6N61NU	4	
X33	TPCP8206,LOLYF(CM	202004	202104	202110	3	TOSHIBA	SSM6N61NU	4	
X33	TPCP8206,LOLYF(J	202004	202104	202110	3	TOSHIBA	SSM6N61NU	4	
X33	TPCP8206,LOLYF(M	202004	202104	202110	3	TOSHIBA	SSM6N61NU	4	
X33	TPCP8206,LPAPF(CM	202004	202104	202110	3	TOSHIBA	SSM6N61NU	4	
X33	TPCP8303(T5L,A,F)	202004	202104	202110	3	TOSHIBA	SSM6P49NU	3	
X33	TPCP8303(TE85L,F,M	202004	202104	202110	3	TOSHIBA	SSM6P49NU	3	
X33	TPCP8303,LF(CJ	202004	202104	202110	3	TOSHIBA	SSM6P49NU	3	
X33	TPCP8303,LF(CM	202004	202104	202110	3	TOSHIBA	SSM6P49NU	3	Y
X33	TPCP8305,LF(CJ	202004	202104	202110	3	TOSHIBA	SSM6P49NU	4	
X33	TPCP8305,LF(CM	202004	202104	202110	3	TOSHIBA	SSM6P49NU	4	Y
X33	TPCP8305,LF(J	202004	202104	202110	3	TOSHIBA	SSM6P49NU	4	
X33	TPCP8305,LF(M	202004	202104	202110	3	TOSHIBA	SSM6P49NU	4	
X33	TPCP8305,LPAPF(CM	202004	202104	202110	3	TOSHIBA	SSM6P49NU	4	
X33	TPCP8305,LSONYF(CJ	202004	202104	202110	3	TOSHIBA	SSM6P49NU	4	
X33	TPCP8305,LSONYF(CM	202004	202104	202110	3	TOSHIBA	SSM6P49NU	4	
X33	TPCP8305,LSONYF(J	202004	202104	202110	3	TOSHIBA	SSM6P49NU	4	
X33	TPCP8305,LSONYF(M	202004	202104	202110	3	TOSHIBA	SSM6P49NU	4	
X33	TPCP8305,LTYUF(CJ	202004	202104	202110	3	TOSHIBA	SSM6P49NU	4	
X33	TPCP8305,LTYUF(CM	202004	202104	202110	3	TOSHIBA	SSM6P49NU	4	
X33	TPCP8305,LTYUF(M	202004	202104	202110	3	TOSHIBA	SSM6P49NU	4	
X33	TPCP8306,LF(CJ	202004	202104	202110	3	TOSHIBA	SSM6P49NU	4	
X33	TPCP8306,LF(CM	202004	202104	202110	3	TOSHIBA	SSM6P49NU	4	
X33	TPCP8306,LF(J	202004	202104	202110	3	TOSHIBA	SSM6P49NU	4	
X33	TPCP8306,LF(M	202004	202104	202110	3	TOSHIBA	SSM6P49NU	4	
X33	TPCP8403(TE85L,F,M	202004	202104	202110	1	TOSHIBA	TPCP8407	3	
X33	TPCP8404(T5L,A,F)	202004	202104	202110	1	TOSHIBA	TPCP8407	3	
X33	TPCP8404(T5R,A,F)	202004	202104	202110	1	TOSHIBA	TPCP8407	3	
X33	TPCP8404(TE85L,C,M	202004	202104	202110	1	TOSHIBA	TPCP8407	3	

X33	TPCP8404(TE85L,F,M	202004	202104	202110	1	TOSHIBA	TPCP8407	3	
X33	TPCP8404(TE85R,F,M	202004	202104	202110	1	TOSHIBA	TPCP8407	3	
X33	TPCP8404,LF(CJ	202004	202104	202110	1	TOSHIBA	TPCP8407	3	
X33	TPCP8404,LF(CM	202004	202104	202110	1	TOSHIBA	TPCP8407	3	Y
X33	TPCP8404,RF(CJ	202004	202104	202110	1	TOSHIBA	TPCP8407	3	
X33	TPCP8404,RF(CM	202004	202104	202110	1	TOSHIBA	TPCP8407	3	
X33	TPCP8405(T5LPAS,F)	202004	202104	202110	3	TOSHIBA	TPC8408	3	
X33	TPCP8405(TE85L,F,M	202004	202104	202110	3	TOSHIBA	TPC8408	3	
X33	TPCP8405,LADF(CJ	202004	202104	202110	3	TOSHIBA	TPC8408	3	
X33	TPCP8405,LALPHF(CJ	202004	202104	202110	3	TOSHIBA	TPC8408	3	
X33	TPCP8405,LF(CJ	202004	202104	202110	3	TOSHIBA	TPC8408	3	
X33	TPCP8405,LF(CM	202004	202104	202110	3	TOSHIBA	TPC8408	3	Y
X33	TPCP8405,LF(J	202004	202104	202110	3	TOSHIBA	TPC8408	3	
X33	TPCP8405,LF(M	202004	202104	202110	3	TOSHIBA	TPC8408	3	
X33	TPCP8405,LPASF(CJ	202004	202104	202110	3	TOSHIBA	TPC8408	3	
X33	TPCP8405,LYKOF(CJ	202004	202104	202110	3	TOSHIBA	TPC8408	3	
X33	TPCP8406(TE85L,F,M	202004	202104	202110	3	TOSHIBA	TPC8408	3	
X33	TPCP8406,LF(CJ	202004	202104	202110	3	TOSHIBA	TPC8408	3	
X33	TPCP8406,LF(CM	202004	202104	202110	3	TOSHIBA	TPC8408	3	Y
X33	TPCP8406,LF(J	202004	202104	202110	3	TOSHIBA	TPC8408	3	Y
X33	TPCP8406,LF(M	202004	202104	202110	3	TOSHIBA	TPC8408	3	
X33	TPCP8406,LNMBF(CJ	202004	202104	202110	3	TOSHIBA	TPC8408	3	
X33	TPCP8406,LNMBF(CM	202004	202104	202110	3	TOSHIBA	TPC8408	3	
X33	TPCP8406,LNMBF(J	202004	202104	202110	3	TOSHIBA	TPC8408	3	
X35	TPCP8504(TE85L,F,M	202004	202104	202110	1	TOSHIBA	TPCP8505	9	
X35	TPCP8505(TE85L,A,F	202004	202104	202110	1	TOSHIBA	TPCP8505(TE85L,F)	9	
X35	TPCP8505(TE85L,F,M	202004	202104	202110	1	TOSHIBA	TPCP8505(TE85L,F)	9	
X35	TPCP8507(TE85L,F,M	202004	202104	202110	1	TOSHIBA	TPCP8507(TE85L,F)	9	
X35	TPCP8601(TE85L,F,M	202004	202104	202110	1	TOSHIBA	TPCP8601(TE85L,F)	9	
X35	TPCP8602(TE85L,A,F	202004	202104	202110	1	TOSHIBA	TPCP8602(TE85L,F)	9	
X35	TPCP8602(TE85L,F,M	202004	202104	202110	1	TOSHIBA	TPCP8602(TE85L,F)	9	
X35	TPCP8701(TE85L,F,M	202004	202104	202110	1	TOSHIBA	TPCP8701(TE85L,F)	9	
X35	TPCP8901(TE85L,F,M	202004	202104	202110	1	TOSHIBA	TPCP8901(TE85L,F)	9	
X35	TPCP8902(TE85L,F,M	202004	202104	202110	1	TOSHIBA	TPCP8902(TE85L,F)	9	
X33	TPCP8A05-H(T5L,C,E	202004	202104	202110	3	TOSHIBA	TPN5R203PL	3	
X33	TPCP8A05-H,LF(CM	202004	202104	202110	3	TOSHIBA	TPN5R203PL	3	

X33	TPCP8J01(T5LCANO,F	202004	202104	202110	0			3	
X33	TPCP8J01(T5LCANOFM	202004	202104	202110	0			3	
X33	TPCP8J01(T5LSONY,F	202004	202104	202110	0			3	
X33	TPCP8J01(TE85L,F)	202004	202104	202110	0			3	
X33	TPCP8J01(TE85L,F,M	202004	202104	202110	0			3	
X35	TPCP8L01(TE85L,F,M	202004	202104	202110	1	TOSHIBA	TPCP8L01(TE85L,F)	9	
X35	TPCP8L01,LSEPF(M	202004	202104	202110	1	TOSHIBA	TPCP8L01,LSEPF(O	9	
X35	TPD1018F(EL,F)	202004	202104	202110	3	TOSHIBA	TPD1052F	3	Y
X35	TPD1018F(EL1AISINF	202004	202104	202110	3	TOSHIBA	TPD1052F	3	
X35	TPD1018F(ELALPSA,F	202004	202104	202110	3	TOSHIBA	TPD1052F	3	
X35	TPD1018F(ELAPN,F)	202004	202104	202110	3	TOSHIBA	TPD1052F	3	
X35	TPD1018F(ELASTI,F)	202004	202104	202110	3	TOSHIBA	TPD1052F	3	
X35	TPD1018F(ELDAIHA,F	202004	202104	202110	3	TOSHIBA	TPD1052F	3	
X35	TPD1018F(ELDNSO,F)	202004	202104	202110	3	TOSHIBA	TPD1052F	3	
X35	TPD1018F(ELFJTN,F)	202004	202104	202110	3	TOSHIBA	TPD1052F	3	
X35	TPD1018F(ELHILX,F)	202004	202104	202110	3	TOSHIBA	TPD1052F	3	
X35	TPD1018F(ELMA,F)	202004	202104	202110	3	TOSHIBA	TPD1052F	3	
X35	TPD1018F(ELMITSU,F	202004	202104	202110	3	TOSHIBA	TPD1052F	3	
X35	TPD1018F(ELNILES,F	202004	202104	202110	3	TOSHIBA	TPD1052F	3	
X35	TPD1018F(ELPAS,F)	202004	202104	202110	3	TOSHIBA	TPD1052F	3	Y
X35	TPD1018F(ELSANYU,F	202004	202104	202110	3	TOSHIBA	TPD1052F	3	
X35	TPD1018F(ELSMI,F)	202004	202104	202110	3	TOSHIBA	TPD1052F	3	
X35	TPD1018F(ELTKR,F)	202004	202104	202110	3	TOSHIBA	TPD1052F	3	
X35	TPD1018F(ELWMATU,F	202004	202104	202110	3	TOSHIBA	TPD1052F	3	
X35	TPD1018F(ERALPSA,F	202004	202104	202110	3	TOSHIBA	TPD1052F	3	Y
X35	TPD1018F(ERPAIO1,F	202004	202104	202110	3	TOSHIBA	TPD1052F	3	
X35	TPD1018F(ERPAIO-KF	202004	202104	202110	3	TOSHIBA	TPD1052F	3	Y
X35	TPD1033F(2LDAIHA,Q	202004	202104	202110	3	TOSHIBA	TPD1055FA	3	
X35	TPD1033F(2LTOYOG,Q	202004	202104	202110	3	TOSHIBA	TPD1055FA	3	
X35	TPD1033F(T2LAISINQ	202004	202104	202110	3	TOSHIBA	TPD1055FA	3	
X35	TPD1033F(T2LDNSO,Q	202004	202104	202110	3	TOSHIBA	TPD1055FA	3	
X35	TPD1033F(T2LFJTN,Q	202004	202104	202110	3	TOSHIBA	TPD1055FA	3	
X35	TPD1033F(T2LMATUTQ	202004	202104	202110	3	TOSHIBA	TPD1055FA	3	
X35	TPD1033F(T2LSANW,Q	202004	202104	202110	3	TOSHIBA	TPD1055FA	3	
X35	TPD1033F(T2LSMI,Q)	202004	202104	202110	3	TOSHIBA	TPD1055FA	3	
X35	TPD1033F(T2LSTANRQ	202004	202104	202110	3	TOSHIBA	TPD1055FA	3	

X35	TPD1033F(T2LTOJS,Q	202004	202104	202110	3	TOSHIBA	TPD1055FA	3	
X35	TPD1033F(T2LZEC,Q)	202004	202104	202110	3	TOSHIBA	TPD1055FA	3	
X35	TPD1033F(TE12L,Q)	202004	202104	202110	3	TOSHIBA	TPD1055FA	3	
X35	TPD1034F(T2LDNS1,Q	202004	202104	202110	3	TOSHIBA	TPD1055FA	3	
X35	TPD1034F(T2LDNSO,Q	202004	202104	202110	3	TOSHIBA	TPD1055FA	3	
X35	TPD1034F(T2LKEHINQ	202004	202104	202110	3	TOSHIBA	TPD1055FA	3	Y
X35	TPD1034F(T2LOKI,Q)	202004	202104	202110	3	TOSHIBA	TPD1055FA	3	
X35	TPD1034F(T2LPAS,Q)	202004	202104	202110	3	TOSHIBA	TPD1055FA	3	
X35	TPD1034F(T2LTOJS,Q	202004	202104	202110	3	TOSHIBA	TPD1055FA	3	
X35	TPD1034F(T2LTOYOGQ	202004	202104	202110	3	TOSHIBA	TPD1055FA	3	
X35	TPD1034F(TE12L,Q)	202004	202104	202110	3	TOSHIBA	TPD1055FA	3	Y
X35	TPD1034F(TE12LCK,Q	202004	202104	202110	3	TOSHIBA	TPD1055FA	3	
X35	TPD1038AF(T2LHIJ,Q	202004	202104	202110	1	TOSHIBA	TPD1055FA	3	
X35	TPD1038F(2LDAIHA,Q	202004	202104	202110	3	TOSHIBA	TPD1055FA	3	
X35	TPD1038F(2LDNSO1,X	202004	202104	202110	3	TOSHIBA	TPD1055FA	3	
X35	TPD1038F(T2LALPI,Q	202004	202104	202110	3	TOSHIBA	TPD1055FA	3	
X35	TPD1038F(T2LASAW,X	202004	202104	202110	3	TOSHIBA	TPD1055FA	3	
X35	TPD1038F(T2LDNSO,Q	202004	202104	202110	3	TOSHIBA	TPD1055FA	3	
X35	TPD1038F(T2LFJTN,Q	202004	202104	202110	3	TOSHIBA	TPD1055FA	3	
X35	TPD1038F(T2LHIT-JQ	202004	202104	202110	3	TOSHIBA	TPD1055FA	3	Y
X35	TPD1038F(T2LKEHINQ	202004	202104	202110	3	TOSHIBA	TPD1055FA	3	Y
X35	TPD1038F(T2LOMI,Q)	202004	202104	202110	3	TOSHIBA	TPD1055FA	3	
X35	TPD1038F(T2LPAE,Q)	202004	202104	202110	3	TOSHIBA	TPD1055FA	3	
X35	TPD1038F(T2LSTAN,Q	202004	202104	202110	3	TOSHIBA	TPD1055FA	3	
X35	TPD1038F(TE12L,Q)	202004	202104	202110	3	TOSHIBA	TPD1055FA	3	Y
X35	TPD1038F(TE12LOMII	202004	202104	202110	3	TOSHIBA	TPD1055FA	3	
X35	TPD1042F(T2LDNSO,Q	202004	202104	202110	3	TOSHIBA	TPD1055FA	3	
X35	TPD1042F(T2LFJJ,Q)	202004	202104	202110	3	TOSHIBA	TPD1055FA	3	
X35	TPD1042F(T2LKEHINQ	202004	202104	202110	3	TOSHIBA	TPD1055FA	3	
X35	TPD1042F(TE12L,Q)	202004	202104	202110	3	TOSHIBA	TPD1055FA	3	Y
X35	TPD1045F(T2LCLAR,Q	202004	202104	202110	3	TOSHIBA	TPD1058FA	3	
X35	TPD1045F(T2LFJTN,Q	202004	202104	202110	3	TOSHIBA	TPD1058FA	3	
X35	TPD1045F(T2LKUBO,Q	202004	202104	202110	3	TOSHIBA	TPD1058FA	3	
X35	TPD1045F(T2LPPH,X)	202004	202104	202110	3	TOSHIBA	TPD1058FA	3	
X35	TPD1045F(T2LSMI,Q)	202004	202104	202110	3	TOSHIBA	TPD1058FA	3	
X35	TPD1045F(TE12L,Q)	202004	202104	202110	3	TOSHIBA	TPD1058FA	3	Y

X35	TPD1045F(TE12LPP,Q	202004	202104	202110	3	TOSHIBA	TPD1055FA	3	
X35	TPD1047F(T2LDNSO,Q	202004	202104	202110	1	TOSHIBA	TPD1055FA	3	
X35	TPD4004F(ELND,F)	202004	202104	202110	0			5	
X35	TPD4123AK(C,A,Q)	202004	202104	202110	3	TOSHIBA	TPD4204F/4163K[UD]	4	
X35	TPD4123AK(C,Q,M)	202004	202104	202110	3	TOSHIBA	TPD4204F/4163K[UD]	4	Y
X35	TPD4123K(C,A,Q)	202004	202104	202110	3	TOSHIBA	TPD4204F/4163K[UD]	4	
X35	TPD4123K(C,Q,M)	202004	202104	202110	3	TOSHIBA	TPD4204F/4163K[UD]	4	Y
X35	TPD4131K(A,Q)	202004	202104	202110	3	TOSHIBA	TPD4162F	4	
X35	TPD4131K(Q)	202004	202104	202110	3	TOSHIBA	TPD4162F	4	
X35	TPD4131K(Q,M)	202004	202104	202110	3	TOSHIBA	TPD4162F	4	
X35	TPD4131K,WMQ(M	202004	202104	202110	3	TOSHIBA	TPD4162F	4	
X35	TPD4132K(A,Q)	202004	202104	202110	3	TOSHIBA	TPD4162F	4	
X35	TPD4132K(HID,Q)	202004	202104	202110	3	TOSHIBA	TPD4162F	4	
X35	TPD4132K(HID,Q,M)	202004	202104	202110	3	TOSHIBA	TPD4162F	4	Y
X35	TPD4132K(Q)	202004	202104	202110	3	TOSHIBA	TPD4162F	4	
X35	TPD4132K(Q,M)	202004	202104	202110	3	TOSHIBA	TPD4162F	4	
X35	TPD4132K,WMQ(M	202004	202104	202110	3	TOSHIBA	TPD4162F	4	
X35	TPD4134AK(A,Q)	202004	202104	202110	3	TOSHIBA	TPD4204F/4164K[UD]	4	
X35	TPD4134AK(CHO,F,Q)	202004	202104	202110	3	TOSHIBA	TPD4204F/4164K[UD]	4	
X35	TPD4134AK(Q)	202004	202104	202110	3	TOSHIBA	TPD4204F/4164K[UD]	4	Y
X35	TPD4134AK(Q,M)	202004	202104	202110	3	TOSHIBA	TPD4204F/4164K[UD]	4	
X35	TPD4134AK(SWEM,A,Q	202004	202104	202110	3	TOSHIBA	TPD4204F/4164K[UD]	4	
X35	TPD4134AK,WNLQ(M	202004	202104	202110	3	TOSHIBA	TPD4204F/4164K[UD]	4	
X35	TPD4134K(A,Q)	202004	202104	202110	3	TOSHIBA	TPD4204F/4164K[UD]	4	
X35	TPD4134K(Q)	202004	202104	202110	3	TOSHIBA	TPD4204F/4164K[UD]	4	Y
X35	TPD4134K(Q,M)	202004	202104	202110	3	TOSHIBA	TPD4204F/4164K[UD]	4	Y
X35	TPD4135AK(A,Q)	202004	202104	202110	3	TOSHIBA	TPD4204F/4165K[UD]	4	
X35	TPD4135AK(Q,M)	202004	202104	202110	3	TOSHIBA	TPD4204F/4165K[UD]	4	Y
X35	TPD4135K(A,Q)	202004	202104	202110	3	TOSHIBA	TPD4204F/4165K[UD]	4	
X35	TPD4135K(HID,Q,M)	202004	202104	202110	3	TOSHIBA	TPD4204F/4165K[UD]	4	Y
X35	TPD4135K(Q,M)	202004	202104	202110	3	TOSHIBA	TPD4204F/4165K[UD]	4	Y
X35	TPD4142K,Q(J	202004	202104	202110	3	TOSHIBA	TPD4162F	4	
X35	TPD4142K,Q(M	202004	202104	202110	3	TOSHIBA	TPD4162F	4	Y
X35	TPD4142K,WMQ(M	202004	202104	202110	3	TOSHIBA	TPD4162F	4	
X35	TPD4144AK,Q(J	202004	202104	202110	3	TOSHIBA	TPD4204F/4164K[UD]	4	
X35	TPD4144AK,Q(M	202004	202104	202110	3	TOSHIBA	TPD4204F/4164K[UD]	4	Y

X35	TPD4144K,Q(J	202004	202104	202110	3	TOSHIBA	TPD4204F/4164K[UD]	4	
X35	TPD4144K,Q(M	202004	202104	202110	3	TOSHIBA	TPD4204F/4164K[UD]	4	Y
X35	TPD4146K,Q(J	202004	202104	202110	3	TOSHIBA	TPD4162F	4	
X35	TPD4146K,Q(M	202004	202104	202110	3	TOSHIBA	TPD4162F	4	
X35	TPD4146K,WMQ(M	202004	202104	202110	3	TOSHIBA	TPD4162F	4	
X35	TPD4151AK,Q(M	202004	202104	202110	3	TOSHIBA	TPD4162F	4	
X35	TPD4151K,Q(M	202004	202104	202110	3	TOSHIBA	TPD4162F	4	
X35	TPD4151K,WMQ(M	202004	202104	202110	3	TOSHIBA	TPD4162F	4	
X35	TPD7100F(EL1KEHINF	202004	202104	202110	3	TOSHIBA	TPD7106F/07F/04AF	3	
X35	TPD7100F(ELMC,F)	202004	202104	202110	3	TOSHIBA	TPD7106F/07F/04AF	3	
X35	TPD7100F(ELTOYOG,F	202004	202104	202110	3	TOSHIBA	TPD7106F/07F/04AF	3	
X35	TPD7203F(EL1AISINF	202004	202104	202110	3	TOSHIBA	TPD7212F/TPD7212FN	3	
X35	TPD7203F(EL1FJTN,F	202004	202104	202110	3	TOSHIBA	TPD7212F/TPD7212FN	3	
X35	TPD7203F(EL1HITJ,F	202004	202104	202110	3	TOSHIBA	TPD7212F/TPD7212FN	3	
X35	TPD7203F(EL1KEHINF	202004	202104	202110	3	TOSHIBA	TPD7212F/TPD7212FN	3	
X35	TPD7203F(EL1NEC-CF	202004	202104	202110	3	TOSHIBA	TPD7212F/TPD7212FN	3	
X35	TPD7203F(EL1NEST,F	202004	202104	202110	3	TOSHIBA	TPD7212F/TPD7212FN	3	
X35	TPD7203F(EL1OMII,F	202004	202104	202110	3	TOSHIBA	TPD7212F/TPD7212FN	3	Y
X35	TPD7203F(EL1TOYK,F	202004	202104	202110	3	TOSHIBA	TPD7212F/TPD7212FN	3	
X35	TPD7203F(ELAISINF)	202004	202104	202110	3	TOSHIBA	TPD7212F/TPD7212FN	3	
X35	TPD7203F(ELDNSO,F)	202004	202104	202110	3	TOSHIBA	TPD7212F/TPD7212FN	3	
X35	TPD7203F(ELHITJ,F)	202004	202104	202110	3	TOSHIBA	TPD7212F/TPD7212FN	3	
X35	TPD7203F(ELMBSH,F)	202004	202104	202110	3	TOSHIBA	TPD7212F/TPD7212FN	3	
X35	TPD7203F(ELMC,F)	202004	202104	202110	3	TOSHIBA	TPD7212F/TPD7212FN	3	
X35	TPD7203F(ELOMII,F)	202004	202104	202110	3	TOSHIBA	TPD7212F/TPD7212FN	3	
X35	TPD7203F(ELTOYOG,F	202004	202104	202110	3	TOSHIBA	TPD7212F/TPD7212FN	3	
X33	TPN2R503NC,L1Q(J	202004	202104	202110	1	TOSHIBA	TPN2R203NC	3	
X33	TPN2R503NC,L1Q(M	202004	202104	202110	1	TOSHIBA	TPN2R203NC	3	
X33	TPN2R503NC,L1SYQ(M	202004	202104	202110	1	TOSHIBA	TPN2R203NC	3	
X33	TTK2698(S1V,E,S)	202004	202104	202110	1	TOSHIBA	TTK2698(STA1,E,S)	3	
X33	TTK2837(S1V,E,S)	202004	202104	202110	1	TOSHIBA	TTK2837(STA1,E,S)	3	

Substitution level:

0 No replacement

1 Package and characteristics are mostly same or better, not necessary to change other circuit to replace.

2 Package and characteristics are mostly same or better, but some modification of the other circuit is necessary.

3 Characteristics are same or better, but package/pin arrangement are different, so the other circuit modification is necessary.

Reason:

1 Version Up

2 Chip Shrink

3 Integration of products

4 Discontinuation of Assembly Machine

5 No Order Forecast

9 Others

Discontinuation schedule:

1) Official announcement to Customer Date: April 2020

2) Last date of order entry to Toshiba's local Sales Office in April 2021

3) Last date of delivery to customer in October 2021

Date 22.04.2020

generated by M. Piela - Engineering Manager

Toshiba local Sales Office

.....

(document transmitted by E-Mail, valid without signature)