

October, 2006

Attn.: _____

HIROSE ELECTRIC CO., LTD.

5-23, OSAKI 5-CHOME, SHINAGAWA-KU, TOKYO, JAPAN

Notice of Change to the HR10A Series Connection Sleeve

Hirose Electric will modify the connection sleeve of the HR10A Series for the reason mentioned below.

Thank you in advance for your cooperation.


1. Affected Products

HR10A Series of plug connectors (See the Supplementary table.)


2. Details of the Change

The form of the connection sleeve crimp portion modified as illustrated in the photographs below.

[Existing Product]



[Modified Product]



3. Reason for the Change

This change has been made to improve productivity.

4. Differences Accompanying the Change

The change will not affect the mechanical or electrical performance of the connector.

5. Schedule for the Change

The change will be phased in starting with in December, 2006.

Please note that during the changeover period (of approximately 3 months) there may be a partial mixing of new and old production lots.

If you would like clarification concerning any of the points, please contact your Hirose Electric account representative.

Supplementary Sheet

No.	Product Number	CL	No.	Product Number	CL
1	HR10A-7P-4P(73)	110-0301-2 73	31	HR10A-13PD-20P(74)	110-0440-9 74
2	HR10A-7P-4P(74)	110-0301-2 74	32	HR10A-10PD-12P(73)	110-0448-0 73
3	HR10A-7P-4P(77)	110-0301-2 77	33	HR10A-10PD-12P(74)	110-0448-0 74
4	HR10A-7P-4S(73)	110-0302-5 73	34	HR10A-10PD-12S(73)	110-0449-3 73
5	HR10A-7P-4S(74)	110-0302-5 74	35	HR10A-10PD-12S(74)	110-0449-3 74
6	HR10A-7P-6P(73)	110-0303-8 73	36	HR10A-7P-4PC(73)	110-0501-1 73
7	HR10A-7P-6P(74)	110-0303-8 74	37	HR10A-7P-4SC(73)	110-0502-4 73
8	HR10A-7P-6P(77)	110-0303-8 77	38	HR10A-7P-6PC(73)	110-0503-7 73
9	HR10A-7P-6S(73)	110-0304-0 73	39	HR10A-7P-6SC(73)	110-0504-0 73
10	HR10A-7P-6S(74)	110-0304-0 74	40	HR10A-10P-10PC(73)	110-0601-6 73
11	HR10A-7P-5P(73)	110-0318-5 73	41	HR10A-10P-10SC(73)	110-0602-9 73
12	HR10A-7P-5P(74)	110-0318-5 74	42	HR10A-10P-12PC(73)	110-0603-1 73
13	HR10A-7P-5S(73)	110-0319-8 73	43	HR10A-10P-12SC(73)	110-0604-4 73
14	HR10A-7PH-4P(74)	110-0332-6 74	44	HR10A-10PA-12PC(73)	110-0615-0 73
15	HR10A-10P-12P(73)	110-0401-7 73	45	HR10A-10PA-12SC(73)	110-0616-3 73
16	HR10A-10P-12P(74)	110-0401-7 74	46	HR10A-10PG-12PC(73)	110-0630-4 73
17	HR10A-10P-12P(77)	110-0401-7 77	47	HR10A-10PI-12PC(73)	110-0631-7 73
18	HR10A-10P-12S(73)	110-0402-0 73	48	HR10A-13P-20PC(73)	110-0701-0 73
19	HR10A-10P-12S(74)	110-0402-0 74	49	HR10A-13P-20SC(73)	110-0702-3 73
20	HR10A-10P-12S(77)	110-0402-0 77	50	HR10A-13PB-20PC(73)	110-0710-1 73
21	HR10A-10P-10P(73)	110-0407-3 73	51	HR10A-13PB-20SC(73)	110-0712-7 73
22	HR10A-10P-10P(74)	110-0407-3 74	52	HR10A-13P-20P(73)	110-0713-0 73
23	HR10A-10P-10S(73)	110-0408-6 73	53	HR10A-13P-20P(74)	110-0713-0 74
24	HR10A-10P-10S(74)	110-0408-6 74	54	HR10A-13P-20S(73)	110-0716-8 73
25	HR10A-10PA-10P(74)	110-0419-2 74	55	HR10A-13P-20S(74)	110-0716-8 74
26	HR10A-10PA-10S(74)	110-0421-4 74	56	HR10B-10P-10PC(73)	110-0901-0 73
27	HR10A-10PB-10P(73)	110-0422-7 73	57	HR10B-10PA-10PC(73)	110-0906-3 73
28	HR10A-10PA-12P(74)	110-0426-8 74			
29	HR10A-10PA-12S(74)	110-0427-0 74			
30	HR10A-13PA-20P(74)	110-0430-5 74			

Acknowledgment

October, 2006

(Customer→Hirose Electric business representative)

**Notice of Change to the
HR10A Series Connection Sleeve**

We acknowledge the aforementioned matter.

•Customer's name: _____

•Acknowledgment stamp (or signature): _____

(Cut on this line)

Document Receipt

October, 2006

(Customer→Hirose Electric business representative)

**Notice of Change to the
HR10A Series Connection Sleeve**

We have received the aforementioned document.

•Customer's name: _____

•Received stamp (or signature): _____