

Product Code Change

Issue Date
August 27, 2014

No. PP-L-1408002

Tactile switches


The modifications of manufacturing country and product code change for B3FS series.

[Effective Date]

Effective as of February 01, 2015

[Changes]

Models	Old Product Code	New Product Code
B3FS-1012P-S(L)	B3FS1028F	B3FS1109F
B3FS-1015P	B3FS0007H	B3FS1110M
B3FS-1005P	B3FS0009D	B3FS1111H
B3FS-1002P-SUS	B3FS1103G	B3FS1113D
B3FS-1000P	B3FS1000F	B3FS1114B



[Other Changes]

Before the change	After the change
<p>The country of origin. MADE IN JAPAN</p> <p>The display of a packing label on reel. Production factory abbreviation change Lot No □□□□R□</p> <p>Display of the country of origin. MADE IN JAPAN</p> <p>□□□□R□ MADE IN JAPAN</p>	<p>The country of origin. MADE IN CHINA</p> <p>The display of a packing label on reel. Production factory abbreviation change Lot No □□□□C□</p> <p>Display of the country of origin. MADE IN CHINA</p> <p>□□□□C□ MADE IN CHINA</p>

Specifications in this product news are as of the issue date and are subject to change without notice. Only main changes in specifications are described in this document. Please be sure to read the relevant catalogs, datasheets, product specifications, instructions, and manuals for precautions and necessary information when using products.