

10th December 2010

Dear Customer

We have been advised by Taicom that the following D-Sub connector parts will have a plating material change to improve durability.

Currently the front and rear outer shell are Tin plated this will be replaced with a Nickel plating process; the change will come into effect for all manufacturing batches after November 2010.

Part numbers affected.

TT09MB	TT09FB	TD09FB	TD09MB	THD15FB	THD15MB
TT15MB	TT15FB	TD15FB	TD15MB	THD26FB	THD26MB
TT25MB	TT25FB	TD25FB	TD25MB	THD44FB	THD44MB
TT37MB	TT37FB	TD37FB	TD37MB		
TT50MB	TT50FB	TD50FB	TD50MB		

There is no change to the form, fit and function of the parts.

Anglia operates a strict FIFO system in our warehouse facility therefore it may take some time for this change to filter through to customer deliveries of the above part numbers. Please make the relevant person(s) in your organisation aware of this change.

Yours Sincerely

Anglia