


Friday 23<sup>rd</sup> April, 2021

Dear Customer,

**Re: Product Change Notification for Harwin packaging.**

Please be advised that the pick and place cap used on male Datamate connectors (M80 Series) has been changed from a plastic cap to a metal stamped cap. This reverses a previous PCN dated 8<sup>th</sup> January 2020, following further investigation and improvement of the previous metal cap design.

The visual difference is as follows:



*Left = Previous plastic cap, Right = New metal cap*

As you can see from the profiles, a small amount of height has been reduced, and changes to the settings on your pick and place machines may be required.

This change affects the following ranges:

- M80-5S1xxxxMEP
- M80-501xxxxP
- M80-502xxxxP
- M80-512xxxxP
- M80-513xxxxP
- M80-522xxxxP
- M80-826xxxxP
- M80-828xxxxP

The connector design itself is unchanged. Please note that we are no longer prepared to supply the plastic cap once stock of the existing packaging is exhausted.

If you have any further questions regarding this letter, please do not hesitate to contact us.

Yours faithfully,

The Product Change Team

[technical@harwin.com](mailto:technical@harwin.com)

# Product Change Notification from Harwin

Part number affected
M80-5020405P
M80-5020422P
M80-5020442P
M80-5020605P
M80-5020622P
M80-5020642P
M80-5020805P
M80-5020822P
M80-5020842P
M80-5021005P
M80-5021022P
M80-5021042P
M80-5021205P
M80-5021222P
M80-5021242P
M80-5021405P
M80-5021422P
M80-5021442P
M80-5021605P
M80-5021622P
M80-5021642P
M80-5021805P
M80-5021822P
M80-5021842P
M80-5022005P
M80-5022022P
M80-5022042P
M80-5022205P
M80-5022222P
M80-5022242P
M80-5022405P
M80-5022422P
M80-5022442P
M80-5022605P
M80-5022622P
M80-5022642P
M80-5022805P
M80-5022822P
M80-5022842P
M80-5023005P
M80-5023022P
M80-5023042P
M80-5023205P
M80-5023222P
M80-5023242P
M80-5023405P
M80-5023422P
M80-5023442P
M80-5023605P
M80-5023622P
M80-5023642P
M80-5023805P
M80-5023822P
M80-5023842P
M80-5024005P
M80-5024022P
M80-5024042P
M80-5024205P
M80-5024222P
M80-5024242P
M80-5024405P
M80-5024422P
M80-5024442P
M80-5024605P
M80-5024622P
M80-5024642P
M80-5024805P
M80-5024822P

# Product Change Notification from Harwin

Part number affected
M80-5024842P
M80-5025005P
M80-5025022P
M80-5025042P
M80-5120405P
M80-5120422P
M80-5120442P
M80-5120605P
M80-5120622P
M80-5120642P
M80-5120805P
M80-5120822P
M80-5120842P
M80-5121005P
M80-5121042P
M80-5121205P
M80-5121222P
M80-5121242P
M80-5121405P
M80-5121422P
M80-5121442P
M80-5121605P
M80-5121622P
M80-5121642P
M80-5121805P
M80-5121822P
M80-5121842P
M80-5122005P
M80-5122042P
M80-5122205P
M80-5122222P
M80-5122242P
M80-5122405P
M80-5122422P
M80-5122442P
M80-5122605P
M80-5122622P
M80-5122642P
M80-5122805P
M80-5122822P
M80-5122842P
M80-5123005P
M80-5123022P
M80-5123042P
M80-5123205P
M80-5123222P
M80-5123242P
M80-5123405P
M80-5123422P
M80-5123442P
M80-5123605P
M80-5123622P
M80-5123642P
M80-5123805P
M80-5123822P
M80-5123842P
M80-5124005P
M80-5124022P
M80-5124042P
M80-5124205P
M80-5124222P
M80-5124242P
M80-5124405P
M80-5124422P
M80-5124442P
M80-5124605P
M80-5124622P
M80-5124642P

# Product Change Notification from Harwin

Part number affected
M80-5124805P
M80-5124822P
M80-5124842P
M80-5125005P
M80-5125022P
M80-5125042P
M80-5130405P
M80-5130422P
M80-5130442P
M80-5130605P
M80-5130622P
M80-5130642P
M80-5130805P
M80-5130822P
M80-5130842P
M80-5131005P
M80-5131022P
M80-5131042P
M80-5131205P
M80-5131222P
M80-5131242P
M80-5131405P
M80-5131422P
M80-5131442P
M80-5131605P
M80-5131622P
M80-5131642P
M80-5131805P
M80-5131822P
M80-5131842P
M80-5132005P
M80-5132022P
M80-5132042P
M80-5132205P
M80-5132222P
M80-5132242P
M80-5132405P
M80-5132422P
M80-5132442P
M80-5132605P
M80-5132622P
M80-5132642P
M80-5132805P
M80-5132822P
M80-5132842P
M80-5133005P
M80-5133022P
M80-5133042P
M80-5133205P
M80-5133222P
M80-5133242P
M80-5133405P
M80-5133422P
M80-5133442P
M80-5133605P
M80-5133622P
M80-5133642P
M80-5133805P
M80-5133822P
M80-5133842P
M80-5134005P
M80-5134022P
M80-5134042P
M80-5134205P
M80-5134222P
M80-5134242P
M80-5134405P
M80-5134422P

# Product Change Notification from Harwin

Part number affected
M80-5134442P
M80-5134605P
M80-5134622P
M80-5134642P
M80-5134805P
M80-5134822P
M80-5134842P
M80-5135005P
M80-5135022P
M80-5135042P
M80-5220405P
M80-5220422P
M80-5220442P
M80-5220605P
M80-5220622P
M80-5220642P
M80-5220805P
M80-5220822P
M80-5220842P
M80-5221005P
M80-5221022P
M80-5221042P
M80-5221205P
M80-5221222P
M80-5221242P
M80-5221405P
M80-5221422P
M80-5221442P
M80-5221605P
M80-5221622P
M80-5221642P
M80-5221805P
M80-5221822P
M80-5221842P
M80-5222005P
M80-5222022P
M80-5222042P
M80-522205P
M80-522222P
M80-522242P
M80-5222405P
M80-5222422P
M80-5222442P
M80-5222605P
M80-5222622P
M80-5222642P
M80-5222805P
M80-5222822P
M80-5222842P
M80-5223005P
M80-5223022P
M80-5223042P
M80-5223205P
M80-5223222P
M80-5223242P
M80-5223405P
M80-5223422P
M80-5223442P
M80-5223605P
M80-5223622P
M80-5223642P
M80-5223805P
M80-5223822P
M80-5223842P
M80-5224005P
M80-5224022P
M80-5224042P
M80-5224205P

# Product Change Notification from Harwin

Part number affected
M80-5224222P
M80-5224242P
M80-5224405P
M80-5224422P
M80-5224442P
M80-5224605P
M80-5224622P
M80-5224642P
M80-5224805P
M80-5224822P
M80-5224842P
M80-5225005P
M80-5225022P
M80-5225042P
M80-5S10405MEP
M80-5S10422MEP
M80-5S10442MEP
M80-5S10605MEP
M80-5S10622MEP
M80-5S10642MEP
M80-5S10805MEP
M80-5S10822MEP
M80-5S10842MEP
M80-5S11005MEP
M80-5S11022MEP
M80-5S11042MEP
M80-5S11205MEP
M80-5S11222MEP
M80-5S11242MEP
M80-5S11405MEP
M80-5S11422MEP
M80-5S11442MEP
M80-5S11605MEP
M80-5S11622MEP
M80-5S11642MEP
M80-5S11805MEP
M80-5S11822MEP
M80-5S11842MEP
M80-5S12005MEP
M80-5S12022MEP
M80-5S12042MEP
M80-5S12205MEP
M80-5S12222MEP
M80-5S12242MEP
M80-5S12405MEP
M80-5S12422MEP
M80-5S12442MEP
M80-5S12605MEP
M80-5S12622MEP
M80-5S12642MEP
M80-5S12805MEP
M80-5S12822MEP
M80-5S12842MEP
M80-5S13005MEP
M80-5S13022MEP
M80-5S13042MEP
M80-5S13205MEP
M80-5S13222MEP
M80-5S13242MEP
M80-5S13405MEP
M80-5S13422MEP
M80-5S13442MEP
M80-5S13605MEP
M80-5S13622MEP
M80-5S13642MEP
M80-5S13805MEP
M80-5S13822MEP
M80-5S13842MEP

# Product Change Notification from Harwin

<b>Part number affected</b>
M80-5S14005MEP
M80-5S14022MEP
M80-5S14042MEP
M80-5S14205MEP
M80-5S14222MEP
M80-5S14242MEP
M80-5S14405MEP
M80-5S14422MEP
M80-5S14442MEP
M80-5S14605MEP
M80-5S14622MEP
M80-5S14642MEP
M80-5S14805MEP
M80-5S14822MEP
M80-5S14842MEP
M80-5S15005MEP
M80-5S15022MEP
M80-5S15042MEP
M80-8260422P
M80-8260442P
M80-8260445P
M80-8260622P
M80-8260642P
M80-8260645P
M80-8260822P
M80-8260842P
M80-8260845P
M80-8261022P
M80-8261042P
M80-8261045P
M80-8261222P
M80-8261242P
M80-8261245P
M80-8261422P
M80-8261442P
M80-8261445P
M80-8261622P
M80-8261642P
M80-8261645P
M80-8261822P
M80-8261842P
M80-8261845P
M80-8262022P
M80-8262042P
M80-8262045P
M80-8262622P
M80-8262642P
M80-8262645P
M80-8263422P
M80-8263442P
M80-8263445P
M80-8280422P
M80-8280442P
M80-8280445P
M80-8280622P
M80-8280642P
M80-8280645P
M80-8280822P
M80-8280842P
M80-8280845P
M80-8281022P
M80-8281042P
M80-8281045P
M80-8281222P
M80-8281242P
M80-8281245P
M80-8281422P
M80-8281442P

# Product Change Notification from Harwin

<b>Part number affected</b>
M80-8281445P
M80-8281622P
M80-8281642P
M80-8281645P
M80-8281822P
M80-8281842P
M80-8281845P
M80-8282022P
M80-8282042P
M80-8282045P
M80-8282622P
M80-8282642P
M80-8282645P
M80-8283422P
M80-8283442P
M80-8283445P