


17 November 2011

Dear Customer

We have been advised by Taicom that the tooling for the following ZIF sockets has reached the end of its useful life. A new tool has been commissioned which includes some design improvements; the new tooling changes the physical appearance of the product but retains the same PCB layout as before.

Please see below to view pictures and outline drawings of the new design.



Anglia Part Numbers Affected

TFPC042RL1SM	TFPC102RL2SM	TFPC172RL2SM	TFPC252RL1SM
TFPC042RL2SM	TFPC112RL1SM	TFPC182RL1SM	TFPC252RL2SM
TFPC052RL1SM	TFPC112RL2SM	TFPC182RL2SM	TFPC262RL1SM
TFPC052RL2SM	TFPC122RL1SM	TFPC182RL2SM-TR	TFPC262RL2SM
TFPC062RL1SM	TFPC122RL2SM	TFPC192RL1SM	TFPC272RL1SM
TFPC062RL2SM	TFPC132RL1SM	TFPC192RL2SM	TFPC272RL2SM
TFPC062RL2SM-TR	TFPC132RL2SM	TFPC202RL1SM	TFPC282RL1SM
TFPC072RL1SM	TFPC142RL1SM	TFPC202RL2SM	TFPC282RL2SM
TFPC072RL2SM	TFPC142RL1SM-TR	TFPC212RL1SM	TFPC292RL1SM
TFPC082RL1SM	TFPC142RL2SM	TFPC212RL2SM	TFPC292RL2SM
TFPC082RL2SM	TFPC142RL2SM-TR	TFPC222RL1SM	TFPC302RL1SM
TFPC082RL2SM-TR	TFPC152RL1SM	TFPC222RL2SM	TFPC302RL1SM-TR
TFPC092RL1SM	TFPC152RL2SM	TFPC232RL1SM	TFPC302RL2SM
TFPC092RL2SM	TFPC162RL1SM	TFPC232RL2SM	TFPC302RL2SM-TR
TFPC102RL1SM	TFPC162RL2SM	TFPC242RL1SM	
TFPC102RL1SM-TR	TFPC172RL1SM	TFPC242RL2SM	

This change does not affect the fit and function of the parts. Parts manufactured using the new tooling will begin shipping from the Taicom factory to Anglia's Distribution Centre during November 2011. Anglia operates a strict FIFO system in our Distribution Centre therefore it may take some time for this change to filter through to customer deliveries of the above part numbers.

Please make the relevant person(s) in your organisation aware of this change.

Yours Sincerely

Anglia