

ID No. 00636	Product/Process Change Notification	Date 30.1.2019
Product	Ordering Code	
ELS61T_E2 LAN Rel2	L30960-N2751-A200	
PLS62T_W LAN	L30960-N2771-A100	
Ordering No. changes:	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
New Ordering Code:		

Reason of Change:

- | | |
|--|--|
| <input type="checkbox"/> Technical requirement
<input type="checkbox"/> Customer requirement
<input checked="" type="checkbox"/> Quality improvement | <input type="checkbox"/> Change of production process/logistical changes
<input type="checkbox"/> Location of production moved
<input type="checkbox"/> Other: |
|--|--|

Description of change:	<p>To increase security of the OpenWRT based LAN interface, a different random password for root login has been assigned to each terminal. This password can be found on the label of each individual terminal box, and should be changed to a customer specific password as soon as possible.</p> <p>Also, the OpenWRT / Linux kernel inside the LAN interface module has been updated to OpenWrt 18.06.1 / Linux version 4.9.120.</p> <p>There are no changes to the normal terminal operation.</p> <p>For more details, please refer to the latest HID/RN.</p>
Scheduled date of introduction (cw/year):	09/2019
Timing note:	If Gemalto M2M GmbH does not receive a notification to the contrary within a period of 6 weeks, Gemalto M2M GmbH assumes that the customer agrees to the change.

Quality assurance measurements:	The new version fulfills all internal test requirements according to our Quality Management process and philosophy, and has obtained full type approval.
--	--

30.01.2019

2019/2/1

X Dr. Boris Siepert

 Dr. Boris Siepert
 PLM
 Signed by: Boris Siepert 10015128

X Gu Yifeng

 Gu Yi Feng
 QM
 Signed by: Yi Feng Gu 10015168

Attachments:

-