

List of products applicable to additional production location

No.	CL Code	Product Name	Production Location		Start Date for Additional	Supervising Factory
			Current	Added		
1	570-0300-6 71	FX10B-200P/20-SV1(71)	Malaysia	Indonesia	Jan-2016	Malaysia
2	570-0301-9 71	FX10B-200S/20-SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
3	573-0548-0 21	FX11A-80P-SV(21)	Malaysia	Indonesia	Jan-2016	Malaysia
4	573-0004-2 71	FX11LA-100P/10-SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
5	573-0004-2 91	FX11LA-100P/10-SV(91)	Malaysia	Indonesia	Jan-2016	Malaysia
6	573-0004-2 92	FX11LA-100P/10-SV(92)	Malaysia	Indonesia	Jan-2016	Malaysia
7	573-0104-7 71	FX11LA-100S/10-SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
8	573-0104-7 91	FX11LA-100S/10-SV(91)	Malaysia	Indonesia	Jan-2016	Malaysia
9	573-0104-7 92	FX11LA-100S/10-SV(92)	Malaysia	Indonesia	Jan-2016	Malaysia
10	573-0044-7 00	FX11LA-116P-SV	Malaysia	Indonesia	Jan-2016	Malaysia
11	573-0044-7 21	FX11LA-116P-SV(21)	Malaysia	Indonesia	Jan-2016	Malaysia
12	573-0044-7 22	FX11LA-116P-SV(22)	Malaysia	Indonesia	Jan-2016	Malaysia
13	573-0144-1 00	FX11LA-116S-SV	Malaysia	Indonesia	Jan-2016	Malaysia
14	573-0144-1 21	FX11LA-116S-SV(21)	Malaysia	Indonesia	Jan-2016	Malaysia
15	573-0144-1 22	FX11LA-116S-SV(22)	Malaysia	Indonesia	Jan-2016	Malaysia
16	573-0005-5 71	FX11LA-120P/12-SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
17	573-0005-5 91	FX11LA-120P/12-SV(91)	Malaysia	Indonesia	Jan-2016	Malaysia
18	573-0005-5 92	FX11LA-120P/12-SV(92)	Malaysia	Indonesia	Jan-2016	Malaysia
19	573-0105-0 71	FX11LA-120S/12-SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
20	573-0105-0 91	FX11LA-120S/12-SV(91)	Malaysia	Indonesia	Jan-2016	Malaysia
21	573-0105-0 92	FX11LA-120S/12-SV(92)	Malaysia	Indonesia	Jan-2016	Malaysia
22	573-0045-0 00	FX11LA-140P-SV	Malaysia	Indonesia	Jan-2016	Malaysia
23	573-0045-0 21	FX11LA-140P-SV(21)	Malaysia	Indonesia	Jan-2016	Malaysia
24	573-0045-0 22	FX11LA-140P-SV(22)	Malaysia	Indonesia	Jan-2016	Malaysia
25	573-0145-4 00	FX11LA-140S-SV	Malaysia	Indonesia	Jan-2016	Malaysia
26	573-0145-4 21	FX11LA-140S-SV(21)	Malaysia	Indonesia	Jan-2016	Malaysia
27	573-0145-4 22	FX11LA-140S-SV(22)	Malaysia	Indonesia	Jan-2016	Malaysia
28	573-0102-1 71	FX11LA-60S/6-SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
29	573-0102-1 91	FX11LA-60S/6-SV(91)	Malaysia	Indonesia	Jan-2016	Malaysia
30	573-0102-1 92	FX11LA-60S/6-SV(92)	Malaysia	Indonesia	Jan-2016	Malaysia
31	573-0102-1 98	FX11LA-60S/6-SV(98)	Malaysia	Indonesia	Jan-2016	Malaysia
32	573-0042-1 00	FX11LA-68P-SV	Malaysia	Indonesia	Jan-2016	Malaysia
33	573-0042-1 21	FX11LA-68P-SV(21)	Malaysia	Indonesia	Jan-2016	Malaysia
34	573-0042-1 22	FX11LA-68P-SV(22)	Malaysia	Indonesia	Jan-2016	Malaysia
35	573-0142-6 00	FX11LA-68S-SV	Malaysia	Indonesia	Jan-2016	Malaysia
36	573-0142-6 21	FX11LA-68S-SV(21)	Malaysia	Indonesia	Jan-2016	Malaysia
37	573-0142-6 22	FX11LA-68S-SV(22)	Malaysia	Indonesia	Jan-2016	Malaysia
38	573-0003-0 71	FX11LA-80P/8-SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
39	573-0003-0 91	FX11LA-80P/8-SV(91)	Malaysia	Indonesia	Jan-2016	Malaysia
40	573-0003-0 92	FX11LA-80P/8-SV(92)	Malaysia	Indonesia	Jan-2016	Malaysia
41	573-0103-4 71	FX11LA-80S/8-SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
42	573-0103-4 91	FX11LA-80S/8-SV(91)	Malaysia	Indonesia	Jan-2016	Malaysia
43	573-0103-4 92	FX11LA-80S/8-SV(92)	Malaysia	Indonesia	Jan-2016	Malaysia
44	573-0043-4 00	FX11LA-92P-SV	Malaysia	Indonesia	Jan-2016	Malaysia
45	573-0043-4 21	FX11LA-92P-SV(21)	Malaysia	Indonesia	Jan-2016	Malaysia
46	573-0043-4 22	FX11LA-92P-SV(22)	Malaysia	Indonesia	Jan-2016	Malaysia
47	573-0143-9 00	FX11LA-92S-SV	Malaysia	Indonesia	Jan-2016	Malaysia
48	573-0143-9 21	FX11LA-92S-SV(21)	Malaysia	Indonesia	Jan-2016	Malaysia
49	573-0143-9 22	FX11LA-92S-SV(22)	Malaysia	Indonesia	Jan-2016	Malaysia
50	573-0014-6 71	FX11LB-100P/10-SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
51	573-0014-6 91	FX11LB-100P/10-SV(91)	Malaysia	Indonesia	Jan-2016	Malaysia
52	573-0014-6 92	FX11LB-100P/10-SV(92)	Malaysia	Indonesia	Jan-2016	Malaysia
53	573-0114-0 71	FX11LB-100S/10-SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
54	573-0114-0 91	FX11LB-100S/10-SV(91)	Malaysia	Indonesia	Jan-2016	Malaysia
55	573-0114-0 92	FX11LB-100S/10-SV(92)	Malaysia	Indonesia	Jan-2016	Malaysia
56	573-0054-0 00	FX11LB-116P-SV	Malaysia	Indonesia	Jan-2016	Malaysia
57	573-0054-0 21	FX11LB-116P-SV(21)	Malaysia	Indonesia	Jan-2016	Malaysia
58	573-0054-0 22	FX11LB-116P-SV(22)	Malaysia	Indonesia	Jan-2016	Malaysia
59	573-0154-5 00	FX11LB-116S-SV	Malaysia	Indonesia	Jan-2016	Malaysia
60	573-0154-5 21	FX11LB-116S-SV(21)	Malaysia	Indonesia	Jan-2016	Malaysia
61	573-0154-5 22	FX11LB-116S-SV(22)	Malaysia	Indonesia	Jan-2016	Malaysia
62	573-0015-9 71	FX11LB-120P/12-SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
63	573-0015-9 91	FX11LB-120P/12-SV(91)	Malaysia	Indonesia	Jan-2016	Malaysia
64	573-0015-9 92	FX11LB-120P/12-SV(92)	Malaysia	Indonesia	Jan-2016	Malaysia

No.	CL Code	Product Name	Production Location		Start Date for Additional	Supervising Factory
			Current	Added		
65	573-0115-3 71	FX11LB-120S/12-SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
66	573-0115-3 91	FX11LB-120S/12-SV(91)	Malaysia	Indonesia	Jan-2016	Malaysia
67	573-0115-3 92	FX11LB-120S/12-SV(92)	Malaysia	Indonesia	Jan-2016	Malaysia
68	573-0055-3 00	FX11LB-140P-SV	Malaysia	Indonesia	Jan-2016	Malaysia
69	573-0055-3 21	FX11LB-140P-SV(21)	Malaysia	Indonesia	Jan-2016	Malaysia
70	573-0055-3 22	FX11LB-140P-SV(22)	Malaysia	Indonesia	Jan-2016	Malaysia
71	573-0155-8 00	FX11LB-140S-SV	Malaysia	Indonesia	Jan-2016	Malaysia
72	573-0155-8 21	FX11LB-140S-SV(21)	Malaysia	Indonesia	Jan-2016	Malaysia
73	573-0155-8 22	FX11LB-140S-SV(22)	Malaysia	Indonesia	Jan-2016	Malaysia
74	573-0112-5 71	FX11LB-60S/6-SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
75	573-0112-5 91	FX11LB-60S/6-SV(91)	Malaysia	Indonesia	Jan-2016	Malaysia
76	573-0112-5 92	FX11LB-60S/6-SV(92)	Malaysia	Indonesia	Jan-2016	Malaysia
77	573-0112-5 97	FX11LB-60S/6-SV(97)	Malaysia	Indonesia	Jan-2016	Malaysia
78	573-0052-5 00	FX11LB-68P-SV	Malaysia	Indonesia	Jan-2016	Malaysia
79	573-0052-5 21	FX11LB-68P-SV(21)	Malaysia	Indonesia	Jan-2016	Malaysia
80	573-0052-5 22	FX11LB-68P-SV(22)	Malaysia	Indonesia	Jan-2016	Malaysia
81	573-0152-0 00	FX11LB-68S-SV	Malaysia	Indonesia	Jan-2016	Malaysia
82	573-0152-0 21	FX11LB-68S-SV(21)	Malaysia	Indonesia	Jan-2016	Malaysia
83	573-0152-0 22	FX11LB-68S-SV(22)	Malaysia	Indonesia	Jan-2016	Malaysia
84	573-0056-6 91	FX11LB-72P/6-SV(91)	Malaysia	Indonesia	Jan-2016	Malaysia
85	573-0157-3 91	FX11LB-72S/6-SV(91)	Malaysia	Indonesia	Jan-2016	Malaysia
86	573-0013-3 71	FX11LB-80P/8-SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
87	573-0013-3 91	FX11LB-80P/8-SV(91)	Malaysia	Indonesia	Jan-2016	Malaysia
88	573-0013-3 92	FX11LB-80P/8-SV(92)	Malaysia	Indonesia	Jan-2016	Malaysia
89	573-0113-8 71	FX11LB-80S/8-SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
90	573-0113-8 91	FX11LB-80S/8-SV(91)	Malaysia	Indonesia	Jan-2016	Malaysia
91	573-0113-8 92	FX11LB-80S/8-SV(92)	Malaysia	Indonesia	Jan-2016	Malaysia
92	573-0053-8 00	FX11LB-92P-SV	Malaysia	Indonesia	Jan-2016	Malaysia
93	573-0053-8 21	FX11LB-92P-SV(21)	Malaysia	Indonesia	Jan-2016	Malaysia
94	573-0053-8 22	FX11LB-92P-SV(22)	Malaysia	Indonesia	Jan-2016	Malaysia
95	573-0153-2 00	FX11LB-92S-SV	Malaysia	Indonesia	Jan-2016	Malaysia
96	573-0153-2 21	FX11LB-92S-SV(21)	Malaysia	Indonesia	Jan-2016	Malaysia
97	573-0153-2 22	FX11LB-92S-SV(22)	Malaysia	Indonesia	Jan-2016	Malaysia
98	576-0008-2 71	FX6-100P-0.8SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
99	576-0008-2 91	FX6-100P-0.8SV(91)	Malaysia	Indonesia	Jan-2016	Malaysia
100	576-0028-0 71	FX6-100P-0.8SV1(71)	Malaysia	Indonesia	Jan-2016	Malaysia
101	576-0028-0 91	FX6-100P-0.8SV1(91)	Malaysia	Indonesia	Jan-2016	Malaysia
102	576-0028-0 92	FX6-100P-0.8SV1(92)	Malaysia	Indonesia	Jan-2016	Malaysia
103	576-0048-7 71	FX6-100P-0.8SV2(71)	Malaysia	Indonesia	Jan-2016	Malaysia
104	576-0048-7 91	FX6-100P-0.8SV2(91)	Malaysia	Indonesia	Jan-2016	Malaysia
105	576-0048-7 93	FX6-100P-0.8SV2(93)	Malaysia	Indonesia	Jan-2016	Malaysia
106	576-0108-7 71	FX6-100S-0.8SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
107	576-0108-7 91	FX6-100S-0.8SV(91)	Malaysia	Indonesia	Jan-2016	Malaysia
108	576-0108-7 93	FX6-100S-0.8SV(93)	Malaysia	Indonesia	Jan-2016	Malaysia
109	576-0128-4 71	FX6-100S-0.8SV2(71)	Malaysia	Indonesia	Jan-2016	Malaysia
110	576-0128-4 91	FX6-100S-0.8SV2(91)	Malaysia	Indonesia	Jan-2016	Malaysia
111	576-0128-4 92	FX6-100S-0.8SV2(92)	Malaysia	Indonesia	Jan-2016	Malaysia
112	576-0128-4 93	FX6-100S-0.8SV2(93)	Malaysia	Indonesia	Jan-2016	Malaysia
113	576-0049-0 92	FX6-12P-0.8SV2(92)	Malaysia	Indonesia	Jan-2016	Malaysia
114	576-0001-3 71	FX6-20P-0.8SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
115	576-0001-3 92	FX6-20P-0.8SV(92)	Malaysia	Indonesia	Jan-2016	Malaysia
116	576-0001-3 93	FX6-20P-0.8SV(93)	Malaysia	Indonesia	Jan-2016	Malaysia
117	576-0021-0 71	FX6-20P-0.8SV1(71)	Malaysia	Indonesia	Jan-2016	Malaysia
118	576-0021-0 92	FX6-20P-0.8SV1(92)	Malaysia	Indonesia	Jan-2016	Malaysia
119	576-0021-0 93	FX6-20P-0.8SV1(93)	Malaysia	Indonesia	Jan-2016	Malaysia
120	576-0041-8 71	FX6-20P-0.8SV2(71)	Malaysia	Indonesia	Jan-2016	Malaysia
121	576-0041-8 92	FX6-20P-0.8SV2(92)	Malaysia	Indonesia	Jan-2016	Malaysia
122	576-0041-8 93	FX6-20P-0.8SV2(93)	Malaysia	Indonesia	Jan-2016	Malaysia
123	576-0101-8 71	FX6-20S-0.8SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
124	576-0101-8 91	FX6-20S-0.8SV(91)	Malaysia	Indonesia	Jan-2016	Malaysia
125	576-0101-8 92	FX6-20S-0.8SV(92)	Malaysia	Indonesia	Jan-2016	Malaysia
126	576-0101-8 93	FX6-20S-0.8SV(93)	Malaysia	Indonesia	Jan-2016	Malaysia
127	576-0121-5 71	FX6-20S-0.8SV2(71)	Malaysia	Indonesia	Jan-2016	Malaysia
128	576-0121-5 93	FX6-20S-0.8SV2(93)	Malaysia	Indonesia	Jan-2016	Malaysia
129	576-0003-9 71	FX6-40P-0.8SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
130	576-0003-9 92	FX6-40P-0.8SV(92)	Malaysia	Indonesia	Jan-2016	Malaysia

No.	CL Code	Product Name	Production Location		Start Date for Additional	Supervising Factory
			Current	Added		
131	576-0023-6 71	FX6-40P-0.8SV1(71)	Malaysia	Indonesia	Jan-2016	Malaysia
132	576-0023-6 92	FX6-40P-0.8SV1(92)	Malaysia	Indonesia	Jan-2016	Malaysia
133	576-0023-6 93	FX6-40P-0.8SV1(93)	Malaysia	Indonesia	Jan-2016	Malaysia
134	576-0043-3 71	FX6-40P-0.8SV2(71)	Malaysia	Indonesia	Jan-2016	Malaysia
135	576-0043-3 91	FX6-40P-0.8SV2(91)	Malaysia	Indonesia	Jan-2016	Malaysia
136	576-0043-3 92	FX6-40P-0.8SV2(92)	Malaysia	Indonesia	Jan-2016	Malaysia
137	576-0043-3 93	FX6-40P-0.8SV2(93)	Malaysia	Indonesia	Jan-2016	Malaysia
138	576-0103-3 71	FX6-40S-0.8SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
139	576-0103-3 93	FX6-40S-0.8SV(93)	Malaysia	Indonesia	Jan-2016	Malaysia
140	576-0103-3 97	FX6-40S-0.8SV(97)	Malaysia	Indonesia	Jan-2016	Malaysia
141	576-0123-0 71	FX6-40S-0.8SV2(71)	Malaysia	Indonesia	Jan-2016	Malaysia
142	576-0123-0 91	FX6-40S-0.8SV2(91)	Malaysia	Indonesia	Jan-2016	Malaysia
143	576-0123-0 93	FX6-40S-0.8SV2(93)	Malaysia	Indonesia	Jan-2016	Malaysia
144	576-0004-1 71	FX6-50P-0.8SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
145	576-0004-1 92	FX6-50P-0.8SV(92)	Malaysia	Indonesia	Jan-2016	Malaysia
146	576-0004-1 93	FX6-50P-0.8SV(93)	Malaysia	Indonesia	Jan-2016	Malaysia
147	576-0024-9 71	FX6-50P-0.8SV1(71)	Malaysia	Indonesia	Jan-2016	Malaysia
148	576-0024-9 92	FX6-50P-0.8SV1(92)	Malaysia	Indonesia	Jan-2016	Malaysia
149	576-0044-6 71	FX6-50P-0.8SV2(71)	Malaysia	Indonesia	Jan-2016	Malaysia
150	576-0044-6 92	FX6-50P-0.8SV2(92)	Malaysia	Indonesia	Jan-2016	Malaysia
151	576-0044-6 93	FX6-50P-0.8SV2(93)	Malaysia	Indonesia	Jan-2016	Malaysia
152	576-0104-6 71	FX6-50S-0.8SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
153	576-0104-6 91	FX6-50S-0.8SV(91)	Malaysia	Indonesia	Jan-2016	Malaysia
154	576-0104-6 93	FX6-50S-0.8SV(93)	Malaysia	Indonesia	Jan-2016	Malaysia
155	576-0124-3 71	FX6-50S-0.8SV2(71)	Malaysia	Indonesia	Jan-2016	Malaysia
156	576-0124-3 93	FX6-50S-0.8SV2(93)	Malaysia	Indonesia	Jan-2016	Malaysia
157	576-0005-4 71	FX6-60P-0.8SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
158	576-0005-4 92	FX6-60P-0.8SV(92)	Malaysia	Indonesia	Jan-2016	Malaysia
159	576-0005-4 93	FX6-60P-0.8SV(93)	Malaysia	Indonesia	Jan-2016	Malaysia
160	576-0025-1 71	FX6-60P-0.8SV1(71)	Malaysia	Indonesia	Jan-2016	Malaysia
161	576-0025-1 92	FX6-60P-0.8SV1(92)	Malaysia	Indonesia	Jan-2016	Malaysia
162	576-0025-1 93	FX6-60P-0.8SV1(93)	Malaysia	Indonesia	Jan-2016	Malaysia
163	576-0045-9 71	FX6-60P-0.8SV2(71)	Malaysia	Indonesia	Jan-2016	Malaysia
164	576-0045-9 92	FX6-60P-0.8SV2(92)	Malaysia	Indonesia	Jan-2016	Malaysia
165	576-0105-9 71	FX6-60S-0.8SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
166	576-0105-9 93	FX6-60S-0.8SV(93)	Malaysia	Indonesia	Jan-2016	Malaysia
167	576-0125-6 71	FX6-60S-0.8SV2(71)	Malaysia	Indonesia	Jan-2016	Malaysia
168	576-0125-6 91	FX6-60S-0.8SV2(91)	Malaysia	Indonesia	Jan-2016	Malaysia
169	576-0125-6 93	FX6-60S-0.8SV2(93)	Malaysia	Indonesia	Jan-2016	Malaysia
170	576-0007-0 71	FX6-80P-0.8SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
171	576-0007-0 93	FX6-80P-0.8SV(93)	Malaysia	Indonesia	Jan-2016	Malaysia
172	576-0027-7 71	FX6-80P-0.8SV1(71)	Malaysia	Indonesia	Jan-2016	Malaysia
173	576-0027-7 92	FX6-80P-0.8SV1(92)	Malaysia	Indonesia	Jan-2016	Malaysia
174	576-0027-7 93	FX6-80P-0.8SV1(93)	Malaysia	Indonesia	Jan-2016	Malaysia
175	576-0047-4 71	FX6-80P-0.8SV2(71)	Malaysia	Indonesia	Jan-2016	Malaysia
176	576-0047-4 92	FX6-80P-0.8SV2(92)	Malaysia	Indonesia	Jan-2016	Malaysia
177	576-0047-4 93	FX6-80P-0.8SV2(93)	Malaysia	Indonesia	Jan-2016	Malaysia
178	576-0107-4 71	FX6-80S-0.8SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
179	576-0107-4 91	FX6-80S-0.8SV(91)	Malaysia	Indonesia	Jan-2016	Malaysia
180	576-0107-4 93	FX6-80S-0.8SV(93)	Malaysia	Indonesia	Jan-2016	Malaysia
181	576-0127-1 71	FX6-80S-0.8SV2(71)	Malaysia	Indonesia	Jan-2016	Malaysia
182	576-0127-1 91	FX6-80S-0.8SV2(91)	Malaysia	Indonesia	Jan-2016	Malaysia
183	576-0127-1 93	FX6-80S-0.8SV2(93)	Malaysia	Indonesia	Jan-2016	Malaysia
184	576-0208-1 71	FX6A-100P-0.8SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
185	576-0228-9 71	FX6A-100P-0.8SV1(71)	Malaysia	Indonesia	Jan-2016	Malaysia
186	576-0248-6 71	FX6A-100P-0.8SV2(71)	Malaysia	Indonesia	Jan-2016	Malaysia
187	576-0308-6 71	FX6A-100S-0.8SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
188	576-0308-6 91	FX6A-100S-0.8SV(91)	Malaysia	Indonesia	Jan-2016	Malaysia
189	576-0328-3 71	FX6A-100S-0.8SV2(71)	Malaysia	Indonesia	Jan-2016	Malaysia
190	576-0328-3 91	FX6A-100S-0.8SV2(91)	Malaysia	Indonesia	Jan-2016	Malaysia
191	576-0201-2 71	FX6A-20P-0.8SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
192	576-0201-2 92	FX6A-20P-0.8SV(92)	Malaysia	Indonesia	Jan-2016	Malaysia
193	576-0201-2 93	FX6A-20P-0.8SV(93)	Malaysia	Indonesia	Jan-2016	Malaysia
194	576-0221-0 71	FX6A-20P-0.8SV1(71)	Malaysia	Indonesia	Jan-2016	Malaysia
195	576-0221-0 92	FX6A-20P-0.8SV1(92)	Malaysia	Indonesia	Jan-2016	Malaysia
196	576-0221-0 93	FX6A-20P-0.8SV1(93)	Malaysia	Indonesia	Jan-2016	Malaysia

No.	CL Code	Product Name	Production Location		Start Date for Additional	Supervising Factory
			Current	Added		
197	576-0241-7 71	FX6A-20P-0.8SV2(71)	Malaysia	Indonesia	Jan-2016	Malaysia
198	576-0241-7 92	FX6A-20P-0.8SV2(92)	Malaysia	Indonesia	Jan-2016	Malaysia
199	576-0241-7 93	FX6A-20P-0.8SV2(93)	Malaysia	Indonesia	Jan-2016	Malaysia
200	576-0301-7 71	FX6A-20S-0.8SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
201	576-0301-7 93	FX6A-20S-0.8SV(93)	Malaysia	Indonesia	Jan-2016	Malaysia
202	576-0321-4 71	FX6A-20S-0.8SV2(71)	Malaysia	Indonesia	Jan-2016	Malaysia
203	576-0321-4 93	FX6A-20S-0.8SV2(93)	Malaysia	Indonesia	Jan-2016	Malaysia
204	576-0242-0 93	FX6A-30P-0.8SV2(93)	Malaysia	Indonesia	Jan-2016	Malaysia
205	576-0322-7 93	FX6A-30S-0.8SV2(93)	Malaysia	Indonesia	Jan-2016	Malaysia
206	576-0203-8 71	FX6A-40P-0.8SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
207	576-0203-8 92	FX6A-40P-0.8SV(92)	Malaysia	Indonesia	Jan-2016	Malaysia
208	576-0223-5 71	FX6A-40P-0.8SV1(71)	Malaysia	Indonesia	Jan-2016	Malaysia
209	576-0223-5 92	FX6A-40P-0.8SV1(92)	Malaysia	Indonesia	Jan-2016	Malaysia
210	576-0223-5 93	FX6A-40P-0.8SV1(93)	Malaysia	Indonesia	Jan-2016	Malaysia
211	576-0243-2 71	FX6A-40P-0.8SV2(71)	Malaysia	Indonesia	Jan-2016	Malaysia
212	576-0243-2 92	FX6A-40P-0.8SV2(92)	Malaysia	Indonesia	Jan-2016	Malaysia
213	576-0243-2 93	FX6A-40P-0.8SV2(93)	Malaysia	Indonesia	Jan-2016	Malaysia
214	576-0303-2 71	FX6A-40S-0.8SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
215	576-0303-2 91	FX6A-40S-0.8SV(91)	Malaysia	Indonesia	Jan-2016	Malaysia
216	576-0303-2 93	FX6A-40S-0.8SV(93)	Malaysia	Indonesia	Jan-2016	Malaysia
217	576-0323-0 71	FX6A-40S-0.8SV2(71)	Malaysia	Indonesia	Jan-2016	Malaysia
218	576-0323-0 93	FX6A-40S-0.8SV2(93)	Malaysia	Indonesia	Jan-2016	Malaysia
219	576-0204-0 71	FX6A-50P-0.8SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
220	576-0204-0 92	FX6A-50P-0.8SV(92)	Malaysia	Indonesia	Jan-2016	Malaysia
221	576-0204-0 93	FX6A-50P-0.8SV(93)	Malaysia	Indonesia	Jan-2016	Malaysia
222	576-0224-8 71	FX6A-50P-0.8SV1(71)	Malaysia	Indonesia	Jan-2016	Malaysia
223	576-0224-8 92	FX6A-50P-0.8SV1(92)	Malaysia	Indonesia	Jan-2016	Malaysia
224	576-0224-8 93	FX6A-50P-0.8SV1(93)	Malaysia	Indonesia	Jan-2016	Malaysia
225	576-0244-5 71	FX6A-50P-0.8SV2(71)	Malaysia	Indonesia	Jan-2016	Malaysia
226	576-0244-5 92	FX6A-50P-0.8SV2(92)	Malaysia	Indonesia	Jan-2016	Malaysia
227	576-0304-5 71	FX6A-50S-0.8SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
228	576-0304-5 93	FX6A-50S-0.8SV(93)	Malaysia	Indonesia	Jan-2016	Malaysia
229	576-0324-2 71	FX6A-50S-0.8SV2(71)	Malaysia	Indonesia	Jan-2016	Malaysia
230	576-0324-2 91	FX6A-50S-0.8SV2(91)	Malaysia	Indonesia	Jan-2016	Malaysia
231	576-0324-2 93	FX6A-50S-0.8SV2(93)	Malaysia	Indonesia	Jan-2016	Malaysia
232	576-0205-3 71	FX6A-60P-0.8SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
233	576-0205-3 92	FX6A-60P-0.8SV(92)	Malaysia	Indonesia	Jan-2016	Malaysia
234	576-0225-0 71	FX6A-60P-0.8SV1(71)	Malaysia	Indonesia	Jan-2016	Malaysia
235	576-0225-0 92	FX6A-60P-0.8SV1(92)	Malaysia	Indonesia	Jan-2016	Malaysia
236	576-0225-0 93	FX6A-60P-0.8SV1(93)	Malaysia	Indonesia	Jan-2016	Malaysia
237	576-0245-8 71	FX6A-60P-0.8SV2(71)	Malaysia	Indonesia	Jan-2016	Malaysia
238	576-0245-8 92	FX6A-60P-0.8SV2(92)	Malaysia	Indonesia	Jan-2016	Malaysia
239	576-0245-8 93	FX6A-60P-0.8SV2(93)	Malaysia	Indonesia	Jan-2016	Malaysia
240	576-0305-8 71	FX6A-60S-0.8SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
241	576-0305-8 93	FX6A-60S-0.8SV(93)	Malaysia	Indonesia	Jan-2016	Malaysia
242	576-0325-5 71	FX6A-60S-0.8SV2(71)	Malaysia	Indonesia	Jan-2016	Malaysia
243	576-0325-5 93	FX6A-60S-0.8SV2(93)	Malaysia	Indonesia	Jan-2016	Malaysia
244	576-0207-9 71	FX6A-80P-0.8SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
245	576-0207-9 92	FX6A-80P-0.8SV(92)	Malaysia	Indonesia	Jan-2016	Malaysia
246	576-0207-9 93	FX6A-80P-0.8SV(93)	Malaysia	Indonesia	Jan-2016	Malaysia
247	576-0227-6 71	FX6A-80P-0.8SV1(71)	Malaysia	Indonesia	Jan-2016	Malaysia
248	576-0227-6 92	FX6A-80P-0.8SV1(92)	Malaysia	Indonesia	Jan-2016	Malaysia
249	576-0247-3 71	FX6A-80P-0.8SV2(71)	Malaysia	Indonesia	Jan-2016	Malaysia
250	576-0247-3 92	FX6A-80P-0.8SV2(92)	Malaysia	Indonesia	Jan-2016	Malaysia
251	576-0247-3 93	FX6A-80P-0.8SV2(93)	Malaysia	Indonesia	Jan-2016	Malaysia
252	576-0307-3 71	FX6A-80S-0.8SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
253	576-0307-3 91	FX6A-80S-0.8SV(91)	Malaysia	Indonesia	Jan-2016	Malaysia
254	576-0307-3 93	FX6A-80S-0.8SV(93)	Malaysia	Indonesia	Jan-2016	Malaysia
255	576-0327-0 71	FX6A-80S-0.8SV2(71)	Malaysia	Indonesia	Jan-2016	Malaysia
256	576-0327-0 91	FX6A-80S-0.8SV2(91)	Malaysia	Indonesia	Jan-2016	Malaysia
257	576-0327-0 93	FX6A-80S-0.8SV2(93)	Malaysia	Indonesia	Jan-2016	Malaysia
258	578-0205-6 00	FX8-100S-SV	Malaysia	Indonesia	Apr-2016	Malaysia
259	578-0205-6 21	FX8-100S-SV(21)	Malaysia	Indonesia	Apr-2016	Malaysia
260	578-0201-5 00	FX8-60S-SV	Malaysia	Indonesia	Apr-2016	Malaysia
261	578-0201-5 21	FX8-60S-SV(21)	Malaysia	Indonesia	Apr-2016	Malaysia
262	578-0201-5 22	FX8-60S-SV(22)	Malaysia	Indonesia	Apr-2016	Malaysia

No.	CL Code	Product Name	Production Location		Start Date for Additional	Supervising Factory
			Current	Added		
263	578-0203-0 00	FX8-80S-SV	Malaysia	Indonesia	Apr-2016	Malaysia
264	578-0203-0 21	FX8-80S-SV(21)	Malaysia	Indonesia	Apr-2016	Malaysia
265	578-0203-0 22	FX8-80S-SV(22)	Malaysia	Indonesia	Apr-2016	Malaysia
266	578-0203-0 88	FX8-80S-SV(88)	Malaysia	Indonesia	Apr-2016	Malaysia
267	578-0601-3 80	FX8C-60P-SV6(80)	Malaysia	Indonesia	Apr-2016	Malaysia
268	578-1003-7 00	FX8CS-140P-SV6	Malaysia	Indonesia	Apr-2016	Malaysia
269	578-1003-7 86	FX8CS-140P-SV6(86)	Malaysia	Indonesia	Apr-2016	Malaysia
270	578-1004-0 00	FX8CS-140S-SV5	Malaysia	Indonesia	Apr-2016	Malaysia
271	578-1004-0 84	FX8CS-140S-SV5(84)	Malaysia	Indonesia	Apr-2016	Malaysia
272	630-0011-8 00	HIF6-100D-1.27R	Malaysia	Indonesia	Apr-2016	Malaysia
273	630-0011-8 02	HIF6-100D-1.27R(02)	Malaysia	Indonesia	Apr-2016	Malaysia
274	630-0011-8 05	HIF6-100D-1.27R(05)	Malaysia	Indonesia	Apr-2016	Malaysia
275	630-0001-4 00	HIF6-20D-1.27R	Malaysia	Indonesia	Apr-2016	Malaysia
276	630-0002-7 00	HIF6-26D-1.27R	Malaysia	Indonesia	Apr-2016	Malaysia
277	630-0003-0 00	HIF6-32D-1.27R	Malaysia	Indonesia	Apr-2016	Malaysia
278	630-0004-2 00	HIF6-34D-1.27R	Malaysia	Indonesia	Apr-2016	Malaysia
279	630-0004-2 02	HIF6-34D-1.27R(02)	Malaysia	Indonesia	Apr-2016	Malaysia
280	630-0005-5 00	HIF6-40D-1.27R	Malaysia	Indonesia	Apr-2016	Malaysia
281	630-0006-8 00	HIF6-50D-1.27R	Malaysia	Indonesia	Apr-2016	Malaysia
282	630-0006-8 02	HIF6-50D-1.27R(02)	Malaysia	Indonesia	Apr-2016	Malaysia
283	630-0006-8 05	HIF6-50D-1.27R(05)	Malaysia	Indonesia	Apr-2016	Malaysia
284	630-0007-0 00	HIF6-52D-1.27R	Malaysia	Indonesia	Apr-2016	Malaysia
285	630-0008-3 00	HIF6-60D-1.27R	Malaysia	Indonesia	Apr-2016	Malaysia
286	630-0008-3 05	HIF6-60D-1.27R(05)	Malaysia	Indonesia	Apr-2016	Malaysia
287	630-0009-6 00	HIF6-68D-1.27R	Malaysia	Indonesia	Apr-2016	Malaysia
288	630-0009-6 02	HIF6-68D-1.27R(02)	Malaysia	Indonesia	Apr-2016	Malaysia
289	630-0010-5 00	HIF6-80D-1.27R	Malaysia	Indonesia	Apr-2016	Malaysia
290	630-0010-5 02	HIF6-80D-1.27R(02)	Malaysia	Indonesia	Apr-2016	Malaysia
291	630-0010-5 05	HIF6-80D-1.27R(05)	Malaysia	Indonesia	Apr-2016	Malaysia
292	222-2850-0 50	TM11R-5C-62(50)	Malaysia	Indonesia	May-2016	Malaysia
293	222-2148-6 50	TM11R-5C-66(50)	Malaysia	Indonesia	May-2016	Malaysia
294	222-1378-0 50	TM11R-5C-88(50)	Malaysia	Indonesia	May-2016	Malaysia
295	222-5133-5 50	TM11RX-5C-88(50)	Malaysia	Indonesia	May-2016	Malaysia
296	222-2981-8 00	TM24P-HR1-88(4)P1-TL	Malaysia	Indonesia	May-2016	Malaysia
297	222-2971-4 00	TM24P-HR1-88(4)P-TL	Malaysia	Indonesia	May-2016	Malaysia
298	222-2959-9 00	TM24P-HR1-88P-TL	Malaysia	Indonesia	May-2016	Malaysia
299	299-8006-0 00	TM24P-HR1-88P-TL-1	Malaysia	Indonesia	May-2016	Malaysia
300	222-2960-8 00	TM24P-HR2-88P-TL	Malaysia	Indonesia	May-2016	Malaysia
301	222-2972-7 00	TM24P-HR3-88(4)P-TL	Malaysia	Indonesia	May-2016	Malaysia
302	222-2961-0 00	TM24P-HR3-88P-TL	Malaysia	Indonesia	May-2016	Malaysia
303	222-2962-3 00	TM24P-HR-SHE1	Malaysia	Indonesia	May-2016	Malaysia
304	222-2963-6 00	TM24P-HR-SHE2	Malaysia	Indonesia	May-2016	Malaysia
305	222-1286-4 50	TM2RE-0602(50)	Malaysia	Indonesia	May-2016	Malaysia
306	222-1391-9 50	TM2RE-0604(50)	Malaysia	Indonesia	May-2016	Malaysia
307	222-1422-0 50	TM2RE-0606(50)	Malaysia	Indonesia	May-2016	Malaysia
308	222-0592-5 50	TM2RE-1204(50)	Malaysia	Indonesia	May-2016	Malaysia
309	222-0756-0 50	TM2RE-1208(50)	Malaysia	Indonesia	May-2016	Malaysia
310	222-0757-3 50	TM2RE-1212(50)	Malaysia	Indonesia	May-2016	Malaysia
311	222-0591-2 50	TM2RE-1806(50)	Malaysia	Indonesia	May-2016	Malaysia
312	222-0753-2 50	TM2RE-1812(50)	Malaysia	Indonesia	May-2016	Malaysia
313	222-0796-5 50	TM2RE-1818(50)	Malaysia	Indonesia	May-2016	Malaysia
314	222-0797-8 50	TM2RE-2408(50)	Malaysia	Indonesia	May-2016	Malaysia
315	222-0590-0 50	TM2RE-2416(50)	Malaysia	Indonesia	May-2016	Malaysia
316	222-0751-7 50	TM2RE-2424(50)	Malaysia	Indonesia	May-2016	Malaysia
317	222-1277-3 50	TM2REA-0602(50)	Malaysia	Indonesia	May-2016	Malaysia
318	222-1466-6 50	TM2REA-0604(50)	Malaysia	Indonesia	May-2016	Malaysia
319	222-1467-9 50	TM2REA-0606(50)	Malaysia	Indonesia	May-2016	Malaysia
320	222-0802-6 50	TM2REA-1204(50)	Malaysia	Indonesia	May-2016	Malaysia
321	222-0799-3 50	TM2REA-1208(50)	Malaysia	Indonesia	May-2016	Malaysia
322	222-3821-7 50	TM2REA-1210-64(50)	Malaysia	Indonesia	May-2016	Malaysia
323	222-0681-3 50	TM2REA-1212(50)	Malaysia	Indonesia	May-2016	Malaysia
324	222-0801-3 50	TM2REA-1806(50)	Malaysia	Indonesia	May-2016	Malaysia
325	222-0798-0 50	TM2REA-1812(50)	Malaysia	Indonesia	May-2016	Malaysia
326	222-0737-6 50	TM2REA-1818(50)	Malaysia	Indonesia	May-2016	Malaysia
327	222-0800-0 50	TM2REA-2408(50)	Malaysia	Indonesia	May-2016	Malaysia
328	222-0749-5 50	TM2REA-2416(50)	Malaysia	Indonesia	May-2016	Malaysia

No.	CL Code	Product Name	Production Location		Start Date for Additional	Supervising Factory
			Current	Added		
329	222-0750-4 50	TM2REA-2424(50)	Malaysia	Indonesia	May-2016	Malaysia
330	222-5018-7 50	TM2REAX-1204(50)	Malaysia	Indonesia	May-2016	Malaysia
331	222-5024-0 50	TM2REAX-2408(50)	Malaysia	Indonesia	May-2016	Malaysia
332	222-5025-2 65	TM2REAX-2416(65)	Malaysia	Indonesia	May-2016	Malaysia
333	222-1012-9 50	TM3RA-88(50)	Malaysia	Indonesia	May-2016	Malaysia
334	222-1012-9 55	TM3RA-88(55)	Malaysia	Indonesia	May-2016	Malaysia
335	222-1012-9 58	TM3RA-88(58)	Malaysia	Indonesia	May-2016	Malaysia
336	222-5034-3 50	TM3RAX-88(50)	Malaysia	Indonesia	May-2016	Malaysia
337	222-5047-5 50	TM5RBX-66-2.5DS(50)	Malaysia	Indonesia	May-2016	Malaysia
338	222-1513-4 50	TM5RC-1212(50)	Malaysia	Indonesia	May-2016	Malaysia
339	222-1513-4 51	TM5RC-1212(51)	Malaysia	Indonesia	May-2016	Malaysia
340	222-2578-5 50	TM5RC-1212-1.2(50)	Malaysia	Indonesia	May-2016	Malaysia
341	222-0270-9 50	TM5RC-44(50)	Malaysia	Indonesia	May-2016	Malaysia
342	222-0338-0 50	TM5RC-64(50)	Malaysia	Indonesia	May-2016	Malaysia
343	222-0337-8 50	TM5RC-66(50)	Malaysia	Indonesia	May-2016	Malaysia
344	222-0339-3 50	TM5RC-88(50)	Malaysia	Indonesia	May-2016	Malaysia
345	222-5136-3 20	TM5RE3VX-1212(20)	Malaysia	Indonesia	May-2016	Malaysia
346	222-1242-9 71	TM5RF1-44(71)	Malaysia	Indonesia	May-2016	Malaysia
347	222-5002-7 50	TM5RFX-44(50)	Malaysia	Indonesia	May-2016	Malaysia
348	222-1459-0 50	TM5RJ2-44(50)	Malaysia	Indonesia	May-2016	Malaysia
349	222-1486-3 50	TM5RJ2-62(50)	Malaysia	Indonesia	May-2016	Malaysia
350	222-1486-3 90	TM5RJ2-62(90)	Malaysia	Indonesia	May-2016	Malaysia
351	222-1460-0 50	TM5RJ2-64(50)	Malaysia	Indonesia	May-2016	Malaysia
352	222-1460-0 52	TM5RJ2-64(52)	Malaysia	Indonesia	May-2016	Malaysia
353	222-1461-2 50	TM5RJ2-66(50)	Malaysia	Indonesia	May-2016	Malaysia
354	222-1461-2 52	TM5RJ2-66(52)	Malaysia	Indonesia	May-2016	Malaysia
355	222-1461-2 53	TM5RJ2-66(53)	Malaysia	Indonesia	May-2016	Malaysia
356	222-1462-5 50	TM5RJ2-88(50)	Malaysia	Indonesia	May-2016	Malaysia
357	222-5081-3 50	TM5RJ2X-66(50)	Malaysia	Indonesia	May-2016	Malaysia
358	222-5081-3 53	TM5RJ2X-66(53)	Malaysia	Indonesia	May-2016	Malaysia
359	222-5082-6 50	TM5RJ2X-88(50)	Malaysia	Indonesia	May-2016	Malaysia
360	222-1363-3 50	TM5RJ3-44(50)	Malaysia	Indonesia	May-2016	Malaysia
361	222-1487-6 50	TM5RJ3-62(50)	Malaysia	Indonesia	May-2016	Malaysia
362	222-1463-8 50	TM5RJ3-64(50)	Malaysia	Indonesia	May-2016	Malaysia
363	222-1464-0 50	TM5RJ3-66(50)	Malaysia	Indonesia	May-2016	Malaysia
364	222-1464-0 51	TM5RJ3-66(51)	Malaysia	Indonesia	May-2016	Malaysia
365	222-1465-3 50	TM5RJ3-88(50)	Malaysia	Indonesia	May-2016	Malaysia
366	222-1465-3 51	TM5RJ3-88(51)	Malaysia	Indonesia	May-2016	Malaysia
367	222-1465-3 52	TM5RJ3-88(52)	Malaysia	Indonesia	May-2016	Malaysia
368	222-5085-4 50	TM5RJ3X-64(50)	Malaysia	Indonesia	May-2016	Malaysia
369	222-5087-0 50	TM5RJ3X-88(50)	Malaysia	Indonesia	May-2016	Malaysia