

1 Products affected

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PGU	Type				
01	002	012	0000000529	0031.3571	Circuit protection	Fuse holder FAU	
				0031.3572			
				0031.3573			
				0031.3577			
				0031.3581			
				0031.3584			



*SBU (2-digit) / PG (3-digit) / PGU (3-digit) / Type (10-digit)

2 Type of change

The inscription at the socket of the fuse holder changes. SEV and SEMKO symbol are no longer on the socket.

3 Detailed description of change

The inscription changes as follows:

Old inscription	New inscription
	

4 Reason of change

Because of the harmonizing of the European fuse holder standards, SEMKO and SEV symbols are removed from the fuse holder socket. The fuse holder FAU is approved acc. to IEC 60127-6 at VDE.

5 Release date

The change comes into effect on ww 16/2015 (date code 1516 or higher on packaging label).

6 Impact of change and recommended action

Form:	Yes (inscription approval symbols)
Fit:	No
Function:	No
Production Site:	No
Product Label:	No

7 Reference Documents / Attachments

Kind of document	Remarks
Data sheet FAU	Web link data sheet FAU
VDE approval acc. to IEC	Web link approval FAU

FAU					0118.2255	
creation date	created by	release date	released by	notification no.	revision	page
2015-01-13	dislercy	2015-01-16	dislercy			1 of 1