

1 Products affected

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PUG	Type				
01	002	002	0000000501	See list below	Fuseholder complete	FPG2	n.a.

*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

List of part numbers affected

FPG2 complete

3101.0020	3101.0120	3101.0025	3101.0125	3101.0220
3101.0320	3101.0225	3101.0325		

FPG2 socket

3101.2511.1	3101.2513.1			
-------------	-------------	--	--	--



FPG2 carrier

3101.7011	3101.7021	3101.7511	3101.7521	
-----------	-----------	-----------	-----------	--

2 Type of change

- Change of markings

3 Detailed description of change

Old product appearance	New product appearance
	

4 Reason of change

- Newly approved nominal voltage according to IEC 60127-6

5 Release date

The change will be rolled-out starting ww 09/2017 (Date code 1709 or higher on label) and lasts approx. 6 months depending on the variant.

6 Impact of change and recommended action

Form	Yes	Modified marking on product
Fit	No	No change for dimension
Function	No	No change in function
Manufacturing	No	No change for manufacturing site
Label	No	No change on label
Packaging	No	No change in packaging

7 Reference Documents / Attachments

Kind of document	Remarks
Data Sheet	

Product Change Notification					FPG2 change of the marks		
owner	creation date	release date	released by	change order no	rev	page	
zbindeja	2016-11-16	2017-01-30	nowakfr	2011481	A	1 of 1	D10-010-915