

# knitter-switch

## Product Discontinuation Notice

Products affected: DBS 3001, DBS 3002, DBS 3003, DBS 3004  
DBS 3005, DBS 3006, DBS 3007, DBS 3008  
DBS 3009, DBS 3010, DBS 3012

DBS 3101, DBS 3102, DBS 3103, DBS 3104  
DBS 3105, DBS 3106, DBS 3107, DBS 3108  
DBS 3109, DBS 3110, DBS 3112

DBS 3001-B, DBS 3002-B, DBS 3003-B, DBS 3004-B  
DBS 3005-B, DBS 3006-B, DBS 3007-B, DBS 3008-B  
DBS 3009-B, DBS 3010-B, DBS 3012-B

DBS 3101-B, DBS 3102-B, DBS 3103-B, DBS 3104-B  
DBS 3105-B, DBS 3106-B, DBS 3107-B, DBS 3108-B  
DBS 3109-B, DBS 3110-B, DBS 3112-B

DBS 3001-VM, DBS 3002-VM, DBS 3003-VM, DBS 3004-VM  
DBS 3005-VM, DBS 3006-VM, DBS 3007-VM, DBS 3008-VM  
DBS 3009-VM, DBS 3010-VM, DBS 3012-VM

DBS 3101-VM, DBS 3102-VM, DBS 3103-VM, DBS 3104-VM  
DBS 3105-VM, DBS 3106-VM, DBS 3107-VM, DBS 3108-VM  
DBS 3109-VM, DBS 3110-VM, DBS 3112-VM

Effective date: After current stock is sold out

### Details:

For standardization reasons, these parts are removed from our range of products.

The following is our recommendation for replacement:

series	replaced by
DBS 30xx	DBS 60xx
DBS 31xx	DBS 61xx
DBS 30xx-B	DBS 60xx
DBS 31xx-B	DBS 61xx
DBS 30xx-VM	DBS 21xx-VM
DBS 31xx-VM	DBS 21xx-VM

In case of questions, our sales staff is at your disposal.

knitter-switch, December 2013



Oliver Kluj  
Technical Director