

Attn.: _____

HIROSE ELECTRIC CO., LTD.
2-6-3 Nakagawa Chuoh, Tsuzuki-ku, Yokohama, JAPAN

Product Change Notification

We are writing today to inform you that we will make some product changes for the reasons described below.

We will announce them in advance.

| | | |
|---|---|--|
| 1 | Products affected | Please refer to attachments for the affected product names. |
| 2 | Substitute products | We have no plan to sell substitute products. We're sorry to cause any inconvenience to you. |
| 3 | Classification of change | For discontinued sales. |
| 4 | Reason for change | Due to scarce demand and aging of the production facilities. |
| 5 | Date of final reception of orders for the current product | November 30, 2024 |
| 6 | Date of final shipment of the current product | November 30, 2025 |
| 7 | Date of your acknowledgement | By November 30, 2023 |

We kindly request that you let a Hirose business representative know you acknowledge this matter by the aforementioned date of your acknowledgement.

In the absence of a response by the acknowledgement date, please be advised that your products for delivery will be changed as described above.

If you should have any questions, please feel free to contact a Hirose business representative.

Your understanding and cooperation are highly appreciated.

■Product List PCN2022-17_FY2022 Discontinued Sales of Connector

*We have no plan to sell substitute products. We're sorry to cause any inconvenience to you.

| No. | Current product | | Remarks |
|-----|-----------------|-----------------------|---------|
| | Product code | Product name | |
| 1 | 757-0008-0-00 | GT7-16DS-HU | |
| 2 | 757-0010-2-00 | GT7-16R | |
| 3 | 757-0015-6-00 | GT7-22DS-HU | |
| 4 | 757-0016-9-00 | GT7-22R | |
| 5 | 758-0116-0-00 | GT8E-4(2)P-2H | |
| 6 | 758-0235-9-00 | GT8EB-2S-HU | |
| 7 | 758-1043-3-00 | GT8EUL-2022SCF | |
| 8 | 758-1044-6-00 | GT8BUL-2428SCF | |
| 9 | 765-0003-1-70 | GT15-2024SCF(70) | |
| 10 | 772-0003-0-31 | GT22-8S-2.54SF(31) | |
| 11 | 775-0018-0-00 | GT25N-24DPP-HU | |
| 12 | 775-0019-0-00 | GT25-24DP-R | |
| 13 | 775-0049-0-00 | GT25H-32DP-2.2H | |
| 14 | 775-0052-4-00 | GT25H-24DP-2.2V | |
| 15 | 775-0056-5-00 | GT25H-2024PCF | |
| 16 | 778-0002-5-20 | GT28-2S-HU(20) | |
| 17 | 778-0002-5-21 | GT28-2S-HU(21) | |
| 18 | 778-0002-5-22 | GT28-2S-HU(22) | |
| 19 | 778-0010-3-00 | GT28-4.2CF | |
| 20 | 778-0011-6-00 | GT28-1214PCF | |
| 21 | 781-0821-9-00 | WTWGT15HD-0821 | |
| 22 | 766-0016-0-00 | GT16-/0.7-1.5PC | |
| 23 | 767-0262-2-00 | GT17HNT1-4DP-2V(A) | |
| 24 | 781-0593-0-00 | WGT21HRM-0593 | |
| 25 | 781-0598-0-00 | WGT21HRM-0598 | |
| 26 | 781-0980-2-00 | W5GT21NUFL-0980 | |
| 27 | 580-1300-9-99 | FH33-28S-0.5SH(99) | |
| 28 | 580-1301-1-99 | FH33-6S-0.5SH(99) | |
| 29 | 580-1303-7-99 | FH33-9S-0.5SH(99) | |
| 30 | 580-1306-5-99 | FH33-26S-0.5SH(99) | |
| 31 | 580-1307-8-99 | FH33-19S-0.5SH(99) | |
| 32 | 580-1310-2-10 | FH33-32S-0.5SH(10) | |
| 33 | 580-1310-2-99 | FH33-32S-0.5SH(99) | |
| 34 | 580-1311-5-99 | FH33-36S-0.5SH(99) | |
| 35 | 580-1319-7-99 | FH33M-16S-0.4SH(99) | |
| 36 | 580-1323-4-10 | FH33-12(6)SB-1SH(10) | |
| 37 | 580-1323-4-99 | FH33-12(6)SB-1SH(99) | |
| 38 | 580-1325-0-99 | FH33MHJ-65S-0.4SH(99) | |
| 39 | 580-2311-0-10 | FH42-39S-0.3SHW(10) | |
| 40 | 580-4502-0-00 | FH52T-32S-0.5SH | |
| 41 | 586-1800-0-98 | FH28-55S-0.5SH(98) | |
| 42 | 586-1818-5-05 | FH28-60(30)SB-1SH(05) | |
| 43 | 586-1822-2-11 | FH28E-20S-0.5SH(11) | |
| 44 | 586-0521-0-54 | FH12-24S-0.5SH(54) | |
| 45 | 580-3806-9-99 | FH58-31S-0.2SHW(99) | |
| 46 | 580-4500-0-99 | FH52T-24S-0.5SH(99) | |
| 47 | 580-4501-7-99 | FH52T-50S-0.5SH(99) | |
| 48 | 580-4502-0-99 | FH52T-32S-0.5SH(99) | |
| 49 | 580-4503-0-99 | FH52T-10S-0.5SH(99) | |
| 50 | 684-9021-2-53 | BM20JC-10DS-0.4V(53) | |
| 51 | 684-9022-5-53 | BM20JC-20DS-0.4V(53) | |
| 52 | 684-9023-8-53 | BM20JC-24DS-0.4V(53) | |
| 53 | 684-9024-0-53 | BM20JC-30DS-0.4V(53) | |
| 54 | 684-9025-3-53 | BM20JC-34DS-0.4V(53) | |
| 55 | 684-9026-6-53 | BM20JC-40DS-0.4V(53) | |
| 56 | 684-1086-4-82 | DF30CJ-24DS-0.4V(82) | |
| 57 | 684-3041-7-53 | DF37CJ-10DP-0.4V(53) | |
| 58 | 684-3043-2-53 | DF37CJ-20DP-0.4V(53) | |
| 59 | 684-3044-5-53 | DF37CJ-20DS-0.4V(53) | |
| 60 | 684-3047-3-53 | DF37CJ-30DP-0.4V(53) | |
| 61 | 684-3049-9-53 | DF37CJ-40DP-0.4V(53) | |
| 62 | 684-3053-6-53 | DF37CJ-60DP-0.4V(53) | |
| 63 | 684-3054-9-53 | DF37CJ-60DS-0.4V(53) | |
| 64 | 684-3068-3-53 | DF37CJ-16DP-0.4V(53) | |
| 65 | 684-3069-6-53 | DF37CJ-16DS-0.4V(53) | |
| 66 | 684-3086-5-53 | DF37CJ-34DS-0.4V(53) | |
| 67 | 684-3091-5-53 | DF37CJ-44DP-0.4V(53) | |
| 68 | 684-3045-8-53 | DF37CJ-24DP-0.4V(53) | |

■Product List PCN2022-17_FY2022 Discontinued Sales of Connector

*We have no plan to sell substitute products. We're sorry to cause any inconvenience to you.

| No. | Current product | | Remarks |
|-----|-----------------|---------------------|---------|
| | Product code | Product name | |
| 69 | 218-0012-4-01 | HNC2-2.5P-2DS(01) | |
| 70 | 218-0019-3-01 | HNC2-2.5P-10DSL(01) | |
| 71 | 218-0044-0-01 | HNC2-2.5P-6DSL(01) | |
| 72 | 218-0044-0-55 | HNC2-2.5P-6DSL(55) | |
| 73 | 536-0051-2-75 | DF13B-2P-1.25V(75) | |
| 74 | 536-0052-5-75 | DF13B-3P-1.25V(75) | |
| 75 | 536-0052-5-76 | DF13B-3P-1.25V(76) | |
| 76 | 536-0053-8-75 | DF13B-4P-1.25V(75) | |
| 77 | 536-0054-0-75 | DF13B-5P-1.25V(75) | |
| 78 | 536-0055-3-75 | DF13B-6P-1.25V(75) | |
| 79 | 536-0055-3-76 | DF13B-6P-1.25V(76) | |
| 80 | 536-0059-4-75 | DF13B-10P-1.25V(75) | |
| 81 | 536-0061-6-51 | DF13B-12P-1.25V(51) | |
| 82 | 536-0061-6-76 | DF13B-12P-1.25V(76) | |
| 83 | 536-0063-1-75 | DF13B-14P-1.25V(75) | |
| 84 | 536-0064-4-75 | DF13B-15P-1.25V(75) | |
| 85 | 536-0064-4-76 | DF13B-15P-1.25V(76) | |
| 86 | 536-0202-6-75 | DF13-3P-1.25V(75) | |
| 87 | 536-0202-6-76 | DF13-3P-1.25V(76) | |
| 88 | 536-0204-1-75 | DF13-5P-1.25V(75) | |
| 89 | 536-0205-4-75 | DF13-6P-1.25V(75) | |
| 90 | 536-0206-7-75 | DF13-7P-1.25V(75) | |
| 91 | 536-0207-0-75 | DF13-8P-1.25V(75) | |
| 92 | 536-0208-2-76 | DF13-9P-1.25V(76) | |
| 93 | 536-0209-5-75 | DF13-10P-1.25V(75) | |
| 94 | 536-0210-4-75 | DF13-11P-1.25V(75) | |
| 95 | 536-0211-7-75 | DF13-12P-1.25V(75) | |
| 96 | 536-0211-7-76 | DF13-12P-1.25V(76) | |
| 97 | 536-0213-2-75 | DF13-14P-1.25V(75) | |
| 98 | 536-0213-2-76 | DF13-14P-1.25V(76) | |
| 99 | 536-0214-5-75 | DF13-15P-1.25V(75) | |
| 100 | 536-0214-5-76 | DF13-15P-1.25V(76) | |
| 101 | 536-0251-1-75 | DF13-2P-1.25H(75) | |
| 102 | 536-0251-1-76 | DF13-2P-1.25H(76) | |
| 103 | 536-0252-4-75 | DF13-3P-1.25H(75) | |
| 104 | 536-0253-7-75 | DF13-4P-1.25H(75) | |
| 105 | 536-0254-0-75 | DF13-5P-1.25H(75) | |
| 106 | 536-0255-2-75 | DF13-6P-1.25H(75) | |
| 107 | 536-0256-5-75 | DF13-7P-1.25H(75) | |
| 108 | 536-0256-5-76 | DF13-7P-1.25H(76) | |
| 109 | 536-0257-8-75 | DF13-8P-1.25H(75) | |
| 110 | 536-0258-0-75 | DF13-9P-1.25H(75) | |
| 111 | 536-0258-0-76 | DF13-9P-1.25H(76) | |
| 112 | 536-0259-3-75 | DF13-10P-1.25H(75) | |
| 113 | 536-0259-3-76 | DF13-10P-1.25H(76) | |
| 114 | 536-0261-5-75 | DF13-12P-1.25H(75) | |
| 115 | 536-0263-0-75 | DF13-14P-1.25H(75) | |
| 116 | 536-0263-0-76 | DF13-14P-1.25H(76) | |
| 117 | 536-0264-3-75 | DF13-15P-1.25H(75) | |
| 118 | 536-0264-3-76 | DF13-15P-1.25H(76) | |
| 119 | 536-0298-5-45 | DF13-2630SCFA(45) | |
| 120 | 536-0301-8-75 | DF13A-2P-1.25H(75) | |
| 121 | 536-0301-8-76 | DF13A-2P-1.25H(76) | |
| 122 | 536-0302-0-75 | DF13A-3P-1.25H(75) | |
| 123 | 536-0302-0-76 | DF13A-3P-1.25H(76) | |
| 124 | 536-0303-3-75 | DF13A-4P-1.25H(75) | |
| 125 | 536-0303-3-76 | DF13A-4P-1.25H(76) | |
| 126 | 536-0304-6-75 | DF13A-5P-1.25H(75) | |
| 127 | 536-0304-6-76 | DF13A-5P-1.25H(76) | |
| 128 | 536-0304-6-79 | DF13A-5P-1.25H(79) | |
| 129 | 536-0305-9-75 | DF13A-6P-1.25H(75) | |
| 130 | 536-0305-9-76 | DF13A-6P-1.25H(76) | |
| 131 | 536-0306-1-76 | DF13A-7P-1.25H(76) | |
| 132 | 536-0307-4-75 | DF13A-8P-1.25H(75) | |
| 133 | 536-0307-4-76 | DF13A-8P-1.25H(76) | |
| 134 | 536-0309-0-75 | DF13A-10P-1.25H(75) | |
| 135 | 536-0309-0-77 | DF13A-10P-1.25H(77) | |
| 136 | 536-0311-1-75 | DF13A-12P-1.25H(75) | |
| 137 | 536-0311-1-76 | DF13A-12P-1.25H(76) | |
| 138 | 536-0313-7-75 | DF13A-14P-1.25H(75) | |
| 139 | 536-0313-7-76 | DF13A-14P-1.25H(76) | |
| 140 | 536-0314-0-75 | DF13A-15P-1.25H(75) | |
| 141 | 536-0314-0-76 | DF13A-15P-1.25H(76) | |
| 142 | 536-0401-2-75 | DF13C-2P-1.25V(75) | |
| 143 | 536-0401-2-76 | DF13C-2P-1.25V(76) | |
| 144 | 536-0403-8-75 | DF13C-4P-1.25V(75) | |
| 145 | 536-0403-8-76 | DF13C-4P-1.25V(76) | |
| 146 | 536-0404-0-75 | DF13C-5P-1.25V(75) | |

■Product List PCN2022-17_FY2022 Discontinued Sales of Connector

*We have no plan to sell substitute products. We're sorry to cause any inconvenience to you.

| No. | Current product | | Remarks |
|-----|-----------------|--------------------------|---------|
| | Product code | Product name | |
| 147 | 536-0404-0-76 | DF13C-5P-1.25V(76) | |
| 148 | 536-0405-3-75 | DF13C-6P-1.25V(75) | |
| 149 | 536-0405-3-76 | DF13C-6P-1.25V(76) | |
| 150 | 536-0405-3-79 | DF13C-6P-1.25V(79) | |
| 151 | 536-0406-6-76 | DF13C-7P-1.25V(76) | |
| 152 | 536-0407-9-75 | DF13C-8P-1.25V(75) | |
| 153 | 536-0408-1-93 | DF13C-9P-1.25V(93) | |
| 154 | 536-0409-4-75 | DF13C-10P-1.25V(75) | |
| 155 | 536-0409-4-76 | DF13C-10P-1.25V(76) | |
| 156 | 536-0411-6-75 | DF13C-12P-1.25V(75) | |
| 157 | 536-0413-1-75 | DF13C-14P-1.25V(75) | |
| 158 | 536-0414-4-76 | DF13C-15P-1.25V(76) | |
| 159 | 536-9001-0-05 | DF13-2630S1-26A9-300(05) | |
| 160 | 538-9001-0-05 | DF14-2628S1-26A9-300(05) | |
| 161 | 541-0141-9-00 | DF1-7S-2.5C | |
| 162 | 541-0143-4-00 | DF1-9S-2.5C | |
| 163 | 541-0144-7-00 | DF1-10S-2.5C | |
| 164 | 541-0145-0-00 | DF1-11S-2.5C | |
| 165 | 541-0146-2-00 | DF1-12S-2.5C | |
| 166 | 541-0148-8-00 | DF1-14S-2.5C | |
| 167 | 541-0149-0-00 | DF1-15S-2.5C | |
| 168 | 541-0150-0-00 | DF1-16S-2.5C | |
| 169 | 541-0152-5-00 | DF1-18S-2.5C | |
| 170 | 541-0154-0-00 | DF1-20S-2.5C | |
| 171 | 541-0709-3-00 | DF1BA-11EP-2.5RC | |
| 172 | 541-0711-5-00 | DF1BA-13EP-2.5RC | |
| 173 | 541-0713-0-00 | DF1BA-15EP-2.5RC | |
| 174 | 543-0315-0-24 | DF3EA-2P-2V(24) | |
| 175 | 543-0315-0-54 | DF3EA-2P-2V(54) | |
| 176 | 543-0315-0-96 | DF3EA-2P-2V(96) | |
| 177 | 543-0316-0-54 | DF3EA-3P-2V(54) | |
| 178 | 543-0316-0-96 | DF3EA-3P-2V(96) | |
| 179 | 543-0317-0-24 | DF3EA-4P-2V(24) | |
| 180 | 543-0317-0-96 | DF3EA-4P-2V(96) | |
| 181 | 543-0318-0-96 | DF3EA-5P-2V(96) | |
| 182 | 543-0319-0-24 | DF3EA-6P-2V(24) | |
| 183 | 543-0319-0-54 | DF3EA-6P-2V(54) | |
| 184 | 543-0319-0-96 | DF3EA-6P-2V(96) | |
| 185 | 543-0320-0-24 | DF3EA-7P-2V(24) | |
| 186 | 543-0320-0-96 | DF3EA-7P-2V(96) | |
| 187 | 543-0321-0-96 | DF3EA-8P-2V(96) | |
| 188 | 543-0324-0-96 | DF3EA-11P-2V(96) | |
| 189 | 543-0325-0-96 | DF3EA-12P-2V(96) | |
| 190 | 543-0326-0-96 | DF3EA-13P-2V(96) | |
| 191 | 543-0329-0-24 | DF3EA-2P-2H(24) | |
| 192 | 543-0329-0-26 | DF3EA-2P-2H(26) | |
| 193 | 543-0329-0-96 | DF3EA-2P-2H(96) | |
| 194 | 543-0330-0-24 | DF3EA-3P-2H(24) | |
| 195 | 543-0330-0-59 | DF3EA-3P-2H(59) | |
| 196 | 543-0330-0-96 | DF3EA-3P-2H(96) | |
| 197 | 543-0331-0-24 | DF3EA-4P-2H(24) | |
| 198 | 543-0331-0-54 | DF3EA-4P-2H(54) | |
| 199 | 543-0331-0-96 | DF3EA-4P-2H(96) | |
| 200 | 543-0332-0-96 | DF3EA-5P-2H(96) | |
| 201 | 543-0333-0-96 | DF3EA-6P-2H(96) | |
| 202 | 543-0335-0-54 | DF3EA-8P-2H(54) | |
| 203 | 543-0338-0-96 | DF3EA-11P-2H(96) | |
| 204 | 543-0339-0-96 | DF3EA-12P-2H(96) | |
| 205 | 543-0340-0-54 | DF3EA-13P-2H(54) | |
| 206 | 543-0342-0-54 | DF3EA-15P-2H(54) | |
| 207 | 543-0342-0-96 | DF3EA-15P-2H(96) | |
| 208 | 543-0343-0-54 | DF3E-2P-2H(54) | |
| 209 | 543-0344-0-24 | DF3E-3P-2H(24) | |
| 210 | 543-0345-0-24 | DF3E-4P-2H(24) | |
| 211 | 543-0345-0-54 | DF3E-4P-2H(54) | |
| 212 | 543-0346-0-24 | DF3E-5P-2H(24) | |
| 213 | 543-0346-0-54 | DF3E-5P-2H(54) | |
| 214 | 543-0347-0-24 | DF3E-6P-2H(24) | |
| 215 | 543-0347-0-54 | DF3E-6P-2H(54) | |
| 216 | 543-0348-0-21 | DF3E-7P-2H(21) | |
| 217 | 543-0348-0-24 | DF3E-7P-2H(24) | |
| 218 | 543-0348-0-51 | DF3E-7P-2H(51) | |
| 219 | 543-0349-0-21 | DF3E-8P-2H(21) | |
| 220 | 543-0349-0-54 | DF3E-8P-2H(54) | |
| 221 | 543-0351-0-24 | DF3E-10P-2H(24) | |
| 222 | 543-0351-0-54 | DF3E-10P-2H(54) | |
| 223 | 543-0355-0-24 | DF3E-14P-2H(24) | |
| 224 | 543-0355-0-54 | DF3E-14P-2H(54) | |

■Product List PCN2022-17_FY2022 Discontinued Sales of Connector

*We have no plan to sell substitute products. We're sorry to cause any inconvenience to you.

| No. | Current product | | Remarks |
|-----|-----------------|--------------------------|---|
| | Product code | Product name | |
| 225 | 543-0356-0-51 | DF3E-15P-2H(51) | |
| 226 | 543-0357-0-54 | DF3E-2P-2V(54) | |
| 227 | 543-0358-0-24 | DF3E-3P-2V(24) | |
| 228 | 543-0358-0-54 | DF3E-3P-2V(54) | |
| 229 | 543-0359-0-24 | DF3E-4P-2V(24) | |
| 230 | 543-0359-0-54 | DF3E-4P-2V(54) | |
| 231 | 543-0359-0-72 | DF3E-4P-2V(72) | |
| 232 | 543-0359-0-96 | DF3E-4P-2V(96) | |
| 233 | 543-0360-0-51 | DF3E-5P-2V(51) | |
| 234 | 543-0360-0-54 | DF3E-5P-2V(54) | |
| 235 | 543-0360-0-72 | DF3E-5P-2V(72) | |
| 236 | 543-0361-0-24 | DF3E-6P-2V(24) | |
| 237 | 543-0361-0-51 | DF3E-6P-2V(51) | |
| 238 | 543-0361-0-54 | DF3E-6P-2V(54) | |
| 239 | 543-0362-0-24 | DF3E-7P-2V(24) | |
| 240 | 543-0362-0-54 | DF3E-7P-2V(54) | |
| 241 | 543-0363-0-24 | DF3E-8P-2V(24) | |
| 242 | 543-0363-0-54 | DF3E-8P-2V(54) | |
| 243 | 543-0364-0-24 | DF3E-9P-2V(24) | |
| 244 | 543-0365-0-21 | DF3E-10P-2V(21) | |
| 245 | 543-0365-0-24 | DF3E-10P-2V(24) | |
| 246 | 543-0365-0-51 | DF3E-10P-2V(51) | |
| 247 | 543-0365-0-54 | DF3E-10P-2V(54) | |
| 248 | 543-0366-0-21 | DF3E-11P-2V(21) | |
| 249 | 543-0367-0-24 | DF3E-12P-2V(24) | |
| 250 | 543-0367-0-54 | DF3E-12P-2V(54) | |
| 251 | 543-0370-0-54 | DF3E-15P-2V(54) | |
| 252 | 543-0683-4-70 | DF11C-6DP-2V(70) | |
| 253 | 543-2018-6-21 | DF11Z-6DP-2V(21) | |
| 254 | 543-9001-0-05 | DF3-2428S2-24A9-300(05) | |
| 255 | 543-9500-0-05 | DF11-2428S2-24A9-300(05) | |
| 256 | 544-1009-6-10 | DF62W-6EP-2.2C(10) | |
| 257 | 546-0013-0-05 | DF6A-1822PCF(05) | |
| 258 | 546-0014-3-05 | DF6A-1822PC(05) | |
| 259 | 665-0001-8-61 | DF50-30DP-1V(61) | |
| 260 | 665-0001-8-62 | DF50-30DP-1V(62) | |
| 261 | 665-0002-0-04 | DF50-2830SCFA(04) | |
| 262 | 665-0002-0-79 | DF50-2830SCFA(79) | |
| 263 | 665-0005-9-61 | DF50-40DP-1V(61) | |
| 264 | 665-0005-9-62 | DF50-40DP-1V(62) | |
| 265 | 665-0005-9-77 | DF50-40DP-1V(77) | |
| 266 | 665-0011-1-61 | DF50-50DP-1V(61) | |
| 267 | 665-0011-1-62 | DF50-50DP-1V(62) | |
| 268 | 665-0016-5-77 | DF50-20DP-1H(77) | |
| 269 | 665-0019-3-61 | DF50-20DP-1V(61) | |
| 270 | 665-0019-3-62 | DF50-20DP-1V(62) | |
| 271 | 665-0023-0-76 | DF50-26SCFA(76) | |
| 272 | 665-1033-0-77 | DF50A-4P-1H(77) | |
| 273 | 667-0024-6-24 | DF59S-1S-V(24) | |
| 274 | 668-0006-0-51 | DF52-6S-0.8H(51) | |
| 275 | 668-0007-3-51 | DF52-8S-0.8H(51) | |
| 276 | 668-0022-7-51 | DF52-3S-0.8H(51) | |
| 277 | 668-0023-0-51 | DF52-5S-0.8H(51) | |
| 278 | 680-0506-7-01 | DF63-5P-3.96DSA(01) | |
| 279 | 680-0515-8-00 | DF63R-3P-3.96DSA | |
| 280 | 680-0515-8-01 | DF63R-3P-3.96DSA(01) | |
| 281 | 680-0517-3-00 | DF63R-1P-3.96DSA | |
| 282 | 680-0518-6-00 | DF63R-2P-3.96DSA | |
| 283 | 680-0519-9-00 | DF63R-4P-3.96DSA | |
| 284 | 680-0522-3-00 | DF63R-1S-3.96C | |
| 285 | 680-0523-6-00 | DF63R-2S-3.96C | |
| 286 | 680-0530-1-00 | DF63A-2P-3.96DSA | |
| 287 | 680-0546-0-01 | DF63-5P-3.96DS(01) | |
| 288 | 680-0550-0-00 | DF63R-2P-7.92DSA | |
| 289 | 680-0562-0-01 | DF63R-3P-7.92DSA(01) | |
| 290 | 680-3020-1-26 | DF60-6P-10.16DS(26) | |
| 291 | 680-3038-7-26 | DF60R-3P-10.16DSA(26) | |
| 292 | 539-0384-4-00 | WAT-00262 | |
| 293 | 562-0499-3-00 | HIF-ヒキヌキ77(34) | |
| 294 | 562-0500-0-00 | HIF-ヒキヌキ77(40) | |
| 295 | 563-0064-7-00 | HIF4RA-16D-3.18R | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 296 | 571-0304-3-71 | FX1-192P-1.27DSA(71) | |
| 297 | 571-0305-6-71 | FX1-216P-1.27DSA(71) | |
| 298 | 572-2773-1-88 | FX2A-40P-0.635SH(88) | |
| 299 | 578-0603-9-88 | FX8C-80P-SV6(88) | |
| 300 | 578-0656-5-71 | FX8C-120/120P11-SVJ(71) | |
| 301 | 578-0737-5-71 | FX8C-140/140P11-SV4J(71) | |

■Product List PCN2022-17_FY2022 Discontinued Sales of Connector

*We have no plan to sell substitute products. We're sorry to cause any inconvenience to you.

| No. | Current product | | Remarks |
|-----|-----------------|---------------------------|---|
| | Product code | Product name | |
| 302 | 588-5103-0-00 | MA50B-3PA-7.62SP | |
| 303 | 588-5104-3-00 | MA50A-4PA-5.08SP | |
| 304 | 619-0005-8-74 | A1-16PA-2.54DS(74) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 305 | 619-0031-8-72 | A1-34PA-2.54DSA(72) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 306 | 621-0184-5-02 | A3-SP(B)(02) | |
| 307 | 621-1146-1-95 | A3A-16DA-2SV(95) | |
| 308 | 640-0035-3-52 | IC1F-68RD-1.27SF(52) | |
| 309 | 640-0040-3-52 | IC1F-68RD-1.27SFA(52) | |
| 310 | 681-0012-0-00 | WO-00318 | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 311 | 681-0013-0-00 | HIF3BA-34D-AA-35.0TA | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 312 | 681-0021-0-00 | WO-00317 | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 313 | 681-0026-0-00 | HIF6H-80D-AB-9.0JJ(A) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 314 | 681-0088-0-00 | HIF6H-50D-AA-34.0JJ(A) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 315 | 681-0089-0-00 | HIF6H-50D-AA-38.0JJ(A) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 316 | 681-6444-0-40 | WT-00026(40) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 317 | 681-6541-7-40 | WT-00066(40) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 318 | 681-6792-7-40 | HIF6H-40D-AA-40.0JJ(40) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 319 | 681-6799-6-40 | HIF6H-80D-AA-10.0JJ(40) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 320 | 681-6838-6-40 | HIF6H-100D-AA-5.0JJ(40) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 321 | 681-6838-6-41 | HIF6H-100D-AA-5.0JJ(41) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 322 | 681-6839-9-40 | HIF6H-60D-AB-10.0JJ(40) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 323 | 681-6843-6-40 | HIF6H-100D-AB-10.0JJ(40) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 324 | 681-6844-9-40 | HIF6H-100D-AB-25.0JJ(40) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 325 | 681-6855-5-40 | HIF6H-34D-AA-10.0JJ(40) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 326 | 681-6856-8-40 | HIF6H-60D-AA-9.0JJ(40) | |
| 327 | 681-6858-3-40 | HIF6H-100D-AA-15.0JJ(40) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 328 | 681-6862-0-10 | HIF3BA-26D-AC-5.0HA(10) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 329 | 681-6892-1-40 | HIF6H-100D-AA-10.0JJ(40) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 330 | 681-6911-4-40 | HIF6H-50D-AA-12.0JJ(40) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 331 | 681-7140-1-40 | HIF6H-100D-AB-20.0JJ(40) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 332 | 681-7141-4-40 | HIF6H-60D-AB-20.0JJ(40) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 333 | 681-7177-1-40 | HIF6H-80D-AA-20.0JJ(40) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 334 | 681-7207-0-40 | WT-00165(40) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 335 | 681-7292-0-40 | W3-00106(40) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 336 | 681-7379-6-40 | HIF6H-40D-AB-17.0JJ(40) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 337 | 681-7381-8-10 | HIF3BA-10D-AC-100.0HA(10) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 338 | 681-7396-5-40 | WT-00196(40) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 339 | 681-7426-4-10 | HIF3BA-10D-A0-25.0HA(10) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 340 | 681-7434-2-10 | HIF3BA-50D-AC-210.0HA(10) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 341 | 681-7460-2-40 | WO-00305(40) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 342 | 681-7461-5-40 | WT-00239(40) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 343 | 681-7464-3-40 | WO-00306(40) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |

■Product List PCN2022-17_FY2022 Discontinued Sales of Connector

*We have no plan to sell substitute products. We're sorry to cause any inconvenience to you.

| No. | Current product | | Remarks |
|-----|-----------------|--------------------------|---|
| | Product code | Product name | |
| 344 | 681-7497-2-40 | HIF6H-80D-AA-70.0JJ(40) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 345 | 681-7500-5-00 | WO-00310HW | |
| 346 | 681-7518-0-40 | HIF6H-34D-AB-150.0JJ(40) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 347 | 681-7524-3-00 | HIF3BA-14D-A0-29.0KA | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 348 | 681-7525-6-00 | HIF3BA-34D-A0-86.0KA | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 349 | 681-7530-6-40 | HIF6H-60D-AB-15.0JJ(40) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 350 | 681-7537-5-00 | WO-00324 | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 351 | 681-7538-8-00 | WO-00325 | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 352 | 681-7540-0-00 | HIF3BA-16D-AC-5.0TA | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 353 | 681-7543-8-40 | HIF6H-50D-AA-7.0JJ(40) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 354 | 681-7546-6-40 | W2-00101(40) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 355 | 681-7549-4-00 | HIF3BA-10D-AA-60.0TA | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 356 | 522-0023-4-70 | CR22-30D-2.54DSA(70) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 357 | 522-0027-5-70 | CR22-50D-2.54DSA(70) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 358 | 522-0034-0-70 | CR22A-30D-2.54DSA(70) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 359 | 522-0055-0-70 | CR22D-120D-2.54DSA(70) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 360 | 575-0009-9-97 | FX5-80P-SH(97) | |
| 361 | 575-0101-1-91 | FX5-20S2A-DSA(91) | |
| 362 | 575-1006-6-71 | FX5-80S3C-DSAL(71) | |
| 363 | 578-0541-3-89 | FX8C-60P-SV2(89) | |
| 364 | 578-0601-3-89 | FX8C-60P-SV6(89) | |
| 365 | 620-0052-8-74 | A2-2PA-2.54DSA(74) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 366 | 620-0053-0-74 | A2-3PA-2.54DSA(74) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 367 | 620-0056-9-81 | A2-6PA-2.54DSA(81) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 368 | 620-0074-0-82 | A2-25PA-2.54DSA(82) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 369 | 206-0775-6-61 | MQ153-JR-2R(61) | |
| 370 | 211-0001-3-50 | HDA-15P(50) | |
| 371 | 211-0012-0-50 | HDE-9P(50) | |
| 372 | 211-0162-2-00 | DB-25S-DC | |
| 373 | 211-0172-6-03 | HD-LNA(03) | |
| 374 | 211-0172-6-10 | HD-LNA(10) | |
| 375 | 211-0172-6-11 | HD-LNA(11) | |
| 376 | 211-0276-1-19 | HDE-CTH(19) | |
| 377 | 211-0293-0-55 | RDBD-25SE-LN(55) | |
| 378 | 211-0316-4-55 | RDAD-15S-LN(55) | |
| 379 | 211-0410-2-55 | RDAD-15SA-LNA(55) | |
| 380 | 211-0411-5-55 | RDAD-37SA-LNA(55) | |
| 381 | 211-0416-9-55 | RDAD-37SA-LN(55) | |
| 382 | 211-0421-9-55 | RDAD-15SE-LN(55) | |
| 383 | 211-0423-4-55 | RDAD-37SE-LN(55) | |
| 384 | 211-0638-0-73 | SDBB-25S-LN(73) | |
| 385 | 211-0772-3-55 | SDAG-15PF(55) | |
| 386 | 211-0773-6-55 | SDCG-37PF(55) | |
| 387 | 211-5184-2-02 | RDG-LNA(4-40)-W1(02) | |
| 388 | 211-5212-6-50 | RDAG-15SE1-LNA-W2(50) | |
| 389 | 211-5277-1-50 | SDEB-MI-9P-LNK(4-40)(50) | |
| 390 | 216-0055-4-09 | S-1608G(09) | |
| 391 | 216-0056-7-09 | S-1612G(09) | |
| 392 | 216-0060-4-09 | S-1628G(09) | |
| 393 | 216-0061-7-09 | S-1634G(09) | |
| 394 | 216-0062-0-09 | S-1645G(09) | |
| 395 | 216-0063-2-09 | S-1660G(09) | |
| 396 | 216-0114-1-50 | S-1634A-STA(50) | |
| 397 | 216-0114-1-51 | S-1634A-STA(51) | |
| 398 | 216-0116-7-50 | S-1660A-STA(50) | |
| 399 | 216-0116-7-51 | S-1660A-STA(51) | |
| 400 | 216-0139-2-50 | S-1620A-J(50) | |
| 401 | 216-0140-1-50 | S-1624A-J(50) | |
| 402 | 216-0142-7-50 | S-1634A-J(50) | |

■Product List PCN2022-17_FY2022 Discontinued Sales of Connector

*We have no plan to sell substitute products. We're sorry to cause any inconvenience to you.

| No. | Current product | | Remarks |
|-----|-----------------|---------------------|---------|
| | Product code | Product name | |
| 403 | 216-0180-6-09 | P-1608BG(09) | |
| 404 | 216-0181-9-09 | P-1612BG(09) | |
| 405 | 216-0182-1-09 | P-1616BG(09) | |
| 406 | 216-0183-4-09 | P-1620BG(09) | |
| 407 | 216-0185-0-09 | P-1628BG(09) | |
| 408 | 216-0189-0-09 | SW-1608A(09) | |
| 409 | 216-0190-0-09 | SW-1612A(09) | |
| 410 | 216-0191-2-09 | SW-1616A(09) | |
| 411 | 216-0192-5-09 | SW-1620A(09) | |
| 412 | 216-0194-0-09 | SW-1628A(09) | |
| 413 | 216-0195-3-09 | SW-1634A(09) | |
| 414 | 216-0196-6-09 | SW-1645A(09) | |
| 415 | 216-0198-1-09 | PW-1608BA(09) | |
| 416 | 216-0199-4-09 | PW-1612BA(09) | |
| 417 | 216-0200-1-09 | PW-1616BA(09) | |
| 418 | 216-0201-4-09 | PW-1620BA(09) | |
| 419 | 216-0203-0-09 | PW-1628BA(09) | |
| 420 | 216-0204-2-09 | PW-1634BA(09) | |
| 421 | 216-0205-5-09 | PW-1645BA(09) | |
| 422 | 216-0206-8-09 | PW-1660BA(09) | |
| 423 | 216-0207-0-09 | SW-1608G(09) | |
| 424 | 216-0208-3-09 | SW-1612G(09) | |
| 425 | 216-0209-6-09 | SW-1616G(09) | |
| 426 | 216-0210-5-09 | SW-1620G(09) | |
| 427 | 216-0211-8-09 | SW-1624G(09) | |
| 428 | 216-0212-0-09 | SW-1628G(09) | |
| 429 | 216-0213-3-09 | SW-1634G(09) | |
| 430 | 216-0214-6-09 | SW-1645G(09) | |
| 431 | 216-0215-9-09 | SW-1660G(09) | |
| 432 | 216-0217-4-09 | PW-1612BG(09) | |
| 433 | 216-0218-7-09 | PW-1616BG(09) | |
| 434 | 216-0219-0-09 | PW-1620BG(09) | |
| 435 | 216-0220-9-09 | PW-1624BG(09) | |
| 436 | 216-0221-1-09 | PW-1628BG(09) | |
| 437 | 216-0222-4-09 | PW-1634BG(09) | |
| 438 | 216-0223-7-09 | PW-1645BG(09) | |
| 439 | 216-0225-2-50 | S-1645A-J(50) | |
| 440 | 216-0226-5-50 | S-1660A-J(50) | |
| 441 | 216-0250-0-50 | P-1634BA-CA(50) | |
| 442 | 216-0299-9-50 | SW-1634A-STA(50) | |
| 443 | 216-0301-9-51 | SW-1660A-STA(51) | |
| 444 | 216-0302-1-05 | 1600-STB(05) | |
| 445 | 216-0321-6-00 | 1620STA-DC | |
| 446 | 216-0322-9-00 | 1624STA-DC | |
| 447 | 216-0323-1-00 | 1628STA-DC | |
| 448 | 216-0324-4-00 | 1634STA-DC | |
| 449 | 216-0325-7-00 | 1645STA-DC | |
| 450 | 216-0326-0-00 | 1660STA-DC | |
| 451 | 216-0365-1-09 | SC-1600-211(09) | |
| 452 | 216-0386-1-09 | SD-1645A(09) | |
| 453 | 216-0395-2-09 | PD-1645BA(09) | |
| 454 | 216-0397-8-09 | SD-1608G(09) | |
| 455 | 216-0398-0-09 | SD-1612G(09) | |
| 456 | 216-0399-3-09 | SD-1616G(09) | |
| 457 | 216-0400-0-09 | SD-1620G(09) | |
| 458 | 216-0401-3-09 | SD-1624G(09) | |
| 459 | 216-0402-6-09 | SD-1628G(09) | |
| 460 | 216-0404-1-09 | SD-1645G(09) | |
| 461 | 216-0406-7-09 | PD-1608BG(09) | |
| 462 | 216-0408-2-09 | PD-1616BG(09) | |
| 463 | 216-0409-5-09 | PD-1620BG(09) | |
| 464 | 216-0410-4-09 | PD-1624BG(09) | |
| 465 | 216-0411-7-09 | PD-1628BG(09) | |
| 466 | 216-0412-0-09 | PD-1634BG(09) | |
| 467 | 216-0416-0-50 | 1608-CBA(50) | |
| 468 | 216-0417-3-51 | 1612-CBA(51) | |
| 469 | 216-0418-6-50 | 1616-CBA(50) | |
| 470 | 221-0107-1-15 | QR/P1-PC2A-211(15) | |
| 471 | 221-0118-8-15 | QR/P1-PC1B-221(15) | |
| 472 | 221-0120-0-15 | QR/P1-SC1B-221(15) | |
| 473 | 221-0173-6-15 | QR/P8-SC-211(15) | |
| 474 | 221-0174-9-15 | QR/P8-SC-221(15) | |
| 475 | 221-0175-1-15 | QR/P8-PC-211(15) | |
| 476 | 221-0176-4-15 | QR/P8-PC-221(15) | |
| 477 | 221-0181-4-00 | QR/P4-SCREW | |
| 478 | 221-0215-4-59 | QR/P11-8P-DS(59) | |
| 479 | 221-0216-7-09 | QR/P11-8S-C(09) | |
| 480 | 221-0228-6-15 | QR/P1-PCA2A-211(15) | |

■Product List PCN2022-17_FY2022 Discontinued Sales of Connector

*We have no plan to sell substitute products. We're sorry to cause any inconvenience to you.

| No. | Current product | | Remarks |
|-----|-----------------|---------------------------|---|
| | Product code | Product name | |
| 481 | 221-0229-9-15 | QR/P1-PCA1A-211(15) | |
| 482 | 222-0004-0-00 | TM1RV-647AF88-C-400K | |
| 483 | 222-0028-3-50 | TM1P-66PP-KC330(50) | |
| 484 | 222-0071-2-50 | TM3R-64(50) | |
| 485 | 222-1165-0-52 | TM5RJ-62(52) | |
| 486 | 222-1366-1-50 | TM5RJ1-4848(50) | |
| 487 | 222-1643-0-55 | TM11PA-88P(55) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 488 | 222-2715-4-00 | TM40P-1212P | |
| 489 | 222-2716-7-00 | TM40PA-1212P | |
| 490 | 222-2770-2-00 | TM10P1-88P | |
| 491 | 222-2784-7-50 | TM15RB-64(50) | |
| 492 | 222-2844-7-50 | TM10RV-66PR6666(50) | |
| 493 | 222-2862-9-33 | TM21P-88P(33) | |
| 494 | 222-2862-9-34 | TM21P-88P(34) | |
| 495 | 222-2888-2-50 | TM5RU1-62(50) | |
| 496 | 222-2914-0-50 | TM22R-3C-88(50) | |
| 497 | 222-2917-9-00 | TM23P-8-BT | |
| 498 | 222-2917-9-01 | TM23P-8-BT(01) | |
| 499 | 222-2917-9-02 | TM23P-8-BT(02) | |
| 500 | 222-2917-9-04 | TM23P-8-BT(04) | |
| 501 | 222-2917-9-05 | TM23P-8-BT(05) | |
| 502 | 222-2917-9-06 | TM23P-8-BT(06) | |
| 503 | 222-2917-9-07 | TM23P-8-BT(07) | |
| 504 | 222-2955-8-00 | TM21R-5B-3232D | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 505 | 222-2980-5-00 | TM41W-R | |
| 506 | 222-3283-7-50 | TM12RV-66-D(50) | |
| 507 | 222-4052-0-00 | TM1R-616W44-4S-250M | |
| 508 | 222-4053-0-00 | TM1R-616M44-35S-150M | |
| 509 | 222-4235-0-50 | TM5RN-88(50) | |
| 510 | 222-4425-5-00 | TM1RV-623P64-35S-150M | |
| 511 | 222-4433-3-00 | TM2RD-44-3S-100M | |
| 512 | 222-4434-6-30 | TM2RCV-M88-5S-450M(30) | |
| 513 | 222-4434-6-31 | TM2RCV-M88-5S-450M(31) | |
| 514 | 222-4436-1-30 | TM1R616PE44-35S50.5UM(30) | |
| 515 | 222-4438-7-00 | TM2RD-F44-C-100M | |
| 516 | 222-4448-0-00 | TM1R-647A88-01M | |
| 517 | 222-4450-2-30 | TM1R-616M44-DF1B-130K(30) | |
| 518 | 222-4455-6-00 | TM2RGV-L62-4S-150M | |
| 519 | 222-4457-1-00 | TM2RM-E1212-C-1500K | |
| 520 | 222-4462-1-00 | TM2RGV-L66-4S-150M | |
| 521 | 222-4470-0-00 | TM1RV-623K62-4S-150M | |
| 522 | 222-4471-2-00 | TM1RV-623P66-35S-150M | |
| 523 | 222-4472-5-00 | TM7RV-A66-35S-150M | |
| 524 | 222-4506-5-30 | TM2RGV-E62-4S-150M(30) | |
| 525 | 222-4509-3-00 | TM1R-616P44-35S-400M | |
| 526 | 222-4521-9-00 | TM2RFV-E62-4S-74M | |
| 527 | 222-4522-1-00 | TM2RFV-E64-4S-74M | |
| 528 | 222-4531-2-00 | TM1RV-623K64-4S-300M | |
| 529 | 222-4534-0-00 | TM2RM-E1212-C-210K | |
| 530 | 222-4535-3-00 | TM1RV-623K64-35S-150M | |
| 531 | 222-4540-3-30 | TM2RGV-E66-4S-200M(30) | |
| 532 | 222-4555-0-00 | TM1RV-623K66-4S-350M | |
| 533 | 222-4560-0-30 | TM1R-616M44-DF1B-110K(30) | |
| 534 | 222-4563-9-00 | TM2RDAY-F44-C-100M | |
| 535 | 222-4574-5-00 | TM2RDA-F44-4S-300M | |
| 536 | 222-4592-7-30 | TM1RV-623K66-4S-150UM(30) | |
| 537 | 222-4594-2-00 | TM1R-616W44-5S-190K | |
| 538 | 222-4595-5-00 | TM2RDAY-F42-ZC-60M | |
| 539 | 222-4601-6-30 | TM1RY-623P62-ZC-60M(30) | |
| 540 | 222-4612-2-00 | TM2RD-F44-4S-190M | |
| 541 | 222-4616-3-30 | TM1RV-647A88-35S-150M(30) | |
| 542 | 222-4624-1-30 | TM11R-88-6S-63M(30) | |
| 543 | 222-4639-9-00 | TM2RGV-L62-4S-500M | |
| 544 | 222-4642-3-00 | TM1RV-623P66-4S-50M | |
| 545 | 222-4654-2-00 | TM1R-616P44-25S-1200K | |
| 546 | 222-4659-6-00 | TM1RV-623K64-5H-80K | |
| 547 | 222-4662-0-00 | TM2RGV-L64-4S-300K | |
| 548 | 222-4668-7-00 | TM4P1212P01OKSFNP1000RS | |
| 549 | 222-4670-9-00 | TM40P1212P01OKSFNP2160 | |
| 550 | 222-4671-1-00 | TM2RD-F44-4S-170M | |
| 551 | 222-4672-4-00 | TM2RM-E1212-4P-OKSFNP300 | |
| 552 | 222-4681-5-00 | TM40P1212P01OKSFNP1550 | |
| 553 | 222-4682-8-00 | TM1R-616M44-35S-150K | |
| 554 | 222-4683-0-00 | TM1R-616B44-35S-150AM | |
| 555 | 222-4684-3-00 | TM4P-1212PP-OKSFNP400RS | |
| 556 | 222-4687-1-00 | TM4P-1212PP-OKSFNP2000RS | |

■Product List PCN2022-17_FY2022 Discontinued Sales of Connector

*We have no plan to sell substitute products. We're sorry to cause any inconvenience to you.

| No. | Current product | | Remarks |
|-----|-----------------|----------------------------|---|
| | Product code | Product name | |
| 557 | 222-4689-7-00 | TM1RV-623P66-35S-500M | |
| 558 | 222-4691-9-00 | TM2RD-F44-4S-190AM | |
| 559 | 222-4693-4-00 | TM2RD-F44-3S-175K | |
| 560 | 222-6089-0-30 | TM1RVX-623P62-C-110T(30) | |
| 561 | 222-6090-0-30 | TM1RVX-623P62-C-170T(30) | |
| 562 | 222-6091-2-30 | TM1RVX-623P62-C-300T(30) | |
| 563 | 222-6092-5-31 | TM1RVX-623P64-C-300T(31) | |
| 564 | 222-6094-0-30 | TM2RCVX-M84-C-140T(30) | |
| 565 | 222-6096-6-00 | TM2RGVX-L62-4S-500M | |
| 566 | 222-6101-4-30 | TM2RGVX-E64-C-150K(30) | |
| 567 | 222-6104-2-30 | TM1RVX-623P62-C-330K(30) | |
| 568 | 222-6114-6-30 | TM1RVX-623K66-5S-150M(30) | |
| 569 | 222-6116-1-30 | TM1RVX647AF88-35S-500M(30) | |
| 570 | 222-6118-7-30 | TM1RVX-647AF88-C-700K(30) | |
| 571 | 225-0004-4-00 | DN50-26P | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 572 | 225-0014-8-02 | DN-50-CV(02) | |
| 573 | 225-0016-3-00 | DN50-20P | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 574 | 225-0024-1-00 | DN-26-CV1 | |
| 575 | 225-0029-5-50 | DN30-26P(50) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 576 | 225-0030-4-50 | DN30-20P(50) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 577 | 230-0237-8-00 | DX-68-CV3 | |
| 578 | 230-5022-9-57 | DX20BM-100S(57) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 579 | 230-5052-0-11 | DX30M-20-CV(11) | |
| 580 | 230-5055-8-13 | DX30M-50-CV(13) | |
| 581 | 230-5056-0-00 | DX30M-68-CV | |
| 582 | 230-5084-6-00 | DX30M-68-CV3 | |
| 583 | 230-5093-7-00 | DX30M-100-CV1 | |
| 584 | 230-5153-7-00 | DX30M-50-CV4 | |
| 585 | 230-5213-7-51 | DX10G1M-36SE(51) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 586 | 230-5243-8-50 | DX10HM-20SE(50) | |
| 587 | 235-0004-1-57 | 3540-16P-CV(57) | |
| 588 | 235-0018-6-50 | 3540-10P-CV1(50) | |
| 589 | 235-0024-9-57 | 3530A-24P-CV(57) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 590 | 241-0036-0-30 | ST60-36PR(30) | |
| 591 | 242-0009-3-30 | ZX64-B-5S-UNIT(30) | |
| 592 | 242-0013-0-00 | ZX64-B-SLDA | |
| 593 | 242-0049-8-00 | ZX64-SLDB | |
| 594 | 247-0001-3-30 | GX60-18P(30) | |
| 595 | 247-0002-6-30 | GX40-18S(30) | |
| 596 | 206-2001-9-31 | MQ172X-4SA-CV(31) | |
| 597 | 206-2098-0-30 | MQ172-3SAC-CV(30) | |
| 598 | 211-0990-4-50 | HDBW-25-CV(50) | |
| 599 | 216-0202-7-09 | PW-1624BA(09) | |
| 600 | 216-0403-9-09 | SD-1634G(09) | |
| 601 | 216-0407-0-09 | PD-1612BG(09) | |
| 602 | 222-0072-5-50 | TM5RA-44(50) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 603 | 222-0091-0-50 | TM5RA-66(50) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 604 | 222-0104-0-50 | TM5RA-64(50) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 605 | 222-1464-0-51 | TM5RJ3-66(51) | |
| 606 | 222-1737-1-50 | TM13R-1006(50) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 607 | 222-1804-7-50 | TM13RA-1006(50) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 608 | 222-1953-7-50 | TM14R-E44(50) | |
| 609 | 222-2850-0-50 | TM11R-5C-62(50) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 610 | 222-4632-0-00 | TM2RGV-L64-5S-1800M | |
| 611 | 222-5114-0-20 | TM5RE2X-64(20) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 612 | 235-0002-6-30 | 3560-16SR(30) | |
| 613 | 240-2003-5-01 | UX40-MB-5PA-1000-2003(01) | |
| 614 | 216-0196-6-10 | SW-1645A(10) | |
| 615 | 216-0197-9-10 | SW-1660A(10) | |
| 616 | 221-0264-0-70 | QR/P17-SCA-111(70) | |
| 617 | 221-0265-2-70 | QR/P17-PCA-111(70) | |
| 618 | 222-4632-0-01 | TM2RGV-L64-5S-1800M(01) | |
| 619 | 230-5128-0-16 | DXM-26S-DC2(16) | |

■Product List PCN2022-17_FY2022 Discontinued Sales of Connector

*We have no plan to sell substitute products. We're sorry to cause any inconvenience to you.

| No. | Current product | | Remarks |
|-----|-----------------|---------------------|---|
| | Product code | Product name | |
| 620 | 108-0113-6-00 | HR08-2PA60 | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 621 | 108-0114-9-00 | HR08-2PA40 | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 622 | 109-0481-6-81 | RM24TP-31S(81) | |
| 623 | 109-1145-4-31 | RM12WBP-6S(31) | |
| 624 | 110-0015-3-31 | KMC9BRD-4S(31) | |
| 625 | 112-2002-5-74 | HR212-10R-8SD(74) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 626 | 112-2003-8-73 | HR212-10R-8SDL(73) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 627 | 113-0265-0-00 | RP19-SC-212 | |
| 628 | 113-5151-8-01 | RP34L-SC1-212(01) | |
| 629 | 113-5179-7-01 | RP34L-SC1-112(01) | |
| 630 | 114-0060-0-00 | JR-S1 | |
| 631 | 114-0257-8-71 | JRC16BR-14P(71) | |
| 632 | 114-0301-0-00 | JRC16BP-10SA | |
| 633 | 114-0507-3-71 | JR25PK-16P(71) | |
| 634 | 114-0517-7-00 | JR13RK-3P | |
| 635 | 114-0525-5-00 | JR13RK-3S | |
| 636 | 114-0533-3-00 | JR13JK-3P | |
| 637 | 114-0534-6-00 | JR13JK-5P | |
| 638 | 114-0535-9-00 | JR16JK-7P | |
| 639 | 114-0537-4-00 | JR21JK-10P | |
| 640 | 114-0538-7-00 | JR21JK-16P | |
| 641 | 114-0539-0-00 | JR25JK-16P | |
| 642 | 114-0540-9-00 | JR25JK-24P | |
| 643 | 114-0542-4-00 | JR13JK-5S | |
| 644 | 114-0545-2-00 | JR21JK-10S | |
| 645 | 114-0546-5-00 | JR21JK-16S | |
| 646 | 114-0548-0-00 | JR25JK-24S | |
| 647 | 114-1032-3-31 | JRC25WRG-16P(31) | |
| 648 | 114-1033-6-31 | JRC25WRG-24P(31) | |
| 649 | 114-1043-0-31 | JRC25WRG-16S(31) | |
| 650 | 114-1044-2-31 | JRC25WRG-24S(31) | |
| 651 | 114-2005-6-31 | JR21WP-10P(31) | |
| 652 | 114-2006-9-31 | JR21WP-16P(31) | |
| 653 | 114-2010-6-31 | JR25WP-16P(31) | |
| 654 | 114-2016-2-31 | JR21WP-10S(31) | |
| 655 | 114-2017-5-31 | JR21WP-16S(31) | |
| 656 | 114-2021-2-31 | JR25WP-16S(31) | |
| 657 | 114-2026-6-31 | JR16WR-10P(31) | |
| 658 | 114-2027-9-31 | JR21WR-10P(31) | |
| 659 | 114-2028-1-31 | JR21WR-16P(31) | |
| 660 | 114-2032-9-31 | JR25WR-16P(31) | |
| 661 | 114-2038-5-31 | JR21WR-10S(31) | |
| 662 | 114-2039-8-31 | JR21WR-16S(31) | |
| 663 | 114-2043-5-31 | JR25WR-16S(31) | |
| 664 | 114-2096-1-31 | JR16WRA-10P(31) | |
| 665 | 114-2145-5-31 | JR16WRA-10S(31) | |
| 666 | 121-0048-6-75 | HR21-26TR-10S(75) | |
| 667 | 125-0413-5-72 | HR25-9TJ-12SC(72) | |
| 668 | 125-0414-8-72 | HR25-9TJ-12PC(72) | |
| 669 | 125-0416-3-72 | HR25-9TJ-16PC(72) | |
| 670 | 127-0201-0-71 | MXR-8RC(71) | |
| 671 | 134-0016-6-20 | HR34B-12WRA-10P(20) | |
| 672 | 139-0002-3-00 | EV1-62R-3SB | |
| 673 | 141-0208-5-00 | HR41A-17WP-C2 | |
| 674 | 141-0209-8-00 | HR41A-17WR-C2 | |
| 675 | 150-0013-7-00 | RM215TP-T01 | |
| 676 | 150-0014-0-00 | RM215TJ-T02 | |
| 677 | 150-0072-6-00 | RP34-SC-TP | |
| 678 | 150-0078-2-00 | KMC9BP-T | |
| 679 | 150-0083-2-00 | HR25-7TP-T02 | |
| 680 | 150-0087-3-00 | HR25-7P-T02 | |
| 681 | 150-0088-6-00 | HR25-9P-T02 | |
| 682 | 150-0092-3-00 | MXR-8P-T01 | |
| 683 | 150-0093-6-00 | HR25-7TJ-T02 | |
| 684 | 150-0251-5-00 | EV1-PC-TP | |
| 685 | 109-1601-1-71 | RM15WTPZA-3S(71) | |
| 686 | 109-1601-1-72 | RM15WTPZA-3S(72) | |
| 687 | 109-1602-4-72 | RM15WTPZA-3P(72) | |
| 688 | 109-1621-9-72 | RM15WTPZ-3S(72) | |
| 689 | 109-1622-1-72 | RM15WTPZ-3P(72) | |
| 690 | 109-1632-5-71 | RM15WTRZ-3P(71) | |
| 691 | 109-1632-5-72 | RM15WTRZ-3P(72) | |
| 692 | 109-1638-1-71 | RM15WTRZ-3S(71) | |
| 693 | 109-1638-1-72 | RM15WTRZ-3S(72) | |

■Product List PCN2022-17_FY2022 Discontinued Sales of Connector

*We have no plan to sell substitute products. We're sorry to cause any inconvenience to you.

| No. | Current product | | Remarks |
|-----|-----------------|-------------------------|---|
| | Product code | Product name | |
| 694 | 109-1652-2-71 | RM15WTRZA-3P(71) | |
| 695 | 109-1652-2-72 | RM15WTRZA-3P(72) | |
| 696 | 109-1658-9-71 | RM15WTRZA-3S(71) | |
| 697 | 109-1658-9-72 | RM15WTRZA-3S(72) | |
| 698 | 109-1672-0-71 | RM15WTRZB-3P(71) | |
| 699 | 109-1672-0-72 | RM15WTRZB-3P(72) | |
| 700 | 109-1678-6-71 | RM15WTRZB-3S(71) | |
| 701 | 109-1678-6-72 | RM15WTRZB-3S(72) | |
| 702 | 109-1905-6-81 | RM15WTJZA-4S(81) | |
| 703 | 109-5004-4-71 | RM515ER-10SC(71) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 704 | 110-1608-0-74 | HR10G-10R-10P(74) | |
| 705 | 110-1805-1-74 | HR10G-7R-6SB(74) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 706 | 113-0207-3-71 | RP13A-12RA-15PC(71) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 707 | 113-0219-2-71 | RP13A-12PK-15SC(71) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 708 | 113-1002-6-71 | RP13A-12RA-15PA(71) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 709 | 113-5100-7-00 | RP34-SC-222 | |
| 710 | 113-5102-2-00 | RP34-SC-122 | |
| 711 | 114-0304-0-00 | JRC16BR-10SA | |
| 712 | 114-0571-2-71 | JR21PK-10SC(71) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 713 | 114-0572-5-71 | JR21PK-16PC(71) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 714 | 114-0573-8-71 | JR21PK-16SC(71) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 715 | 114-0575-3-71 | JR25PK-24SC(71) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 716 | 114-0579-4-00 | JR21RK-16SC | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 717 | 114-2023-8-31 | JR13WR-3P(31) | |
| 718 | 114-2034-4-31 | JR13WR-3S(31) | |
| 719 | 134-0024-4-00 | HR34B-12WRB-4P-X | |
| 720 | 139-0003-6-00 | EV1-62RA-3SB | |
| 721 | 139-0004-9-00 | EV1-PC-112 | |
| 722 | 112-4001-3-42 | HR212-10P-8P(42) | |
| 723 | 112-4001-3-44 | HR212-10P-8P(44) | |
| 724 | 112-4002-6-44 | HR212-10LP-8P(44) | |
| 725 | 113-5178-4-74 | RP34L-5PA-3SC(74) | |
| 726 | 636-0504-3-57 | IT3M-100P-15BGA(57) | |
| 727 | 636-1702-2-03 | IT5E-300P-25H(03) | |
| 728 | 636-1703-5-03 | IT5E-200P-25H(03) | |
| 729 | 641-0002-0-34 | IT1-168S-SV(34) | |
| 730 | 624-0002-5-00 | XG1-260S-SV | |
| 731 | 624-0200-9-00 | XG1-130P/30-20H-SV | |
| 732 | 701-0001-7-33 | HRFC-P1-H(33) | |
| 733 | 701-0071-2-52 | HRFC-PA11-G1(52) | |
| 734 | 701-1097-0-00 | HRFC-SPA2-F3M-0.1M | |
| 735 | 701-1098-0-00 | HRFC-SPA2-F3M-0.2M | |
| 736 | 701-1099-0-00 | HRFC-SPA2-F3M-0.6M | |
| 737 | 704-0217-5-02 | HSC-A3-D1(02) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 738 | 704-1190-0-00 | HSC-SPV2-F3M-A-0.3M | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 739 | 704-2008-6-51 | HSCF-2A(P)(51) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 740 | 704-2008-6-52 | HSCF-2A(P)(52) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 741 | 704-2062-1-02 | HSCH-2A-D(P)(02) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 742 | 704-2117-1-05 | HSCH-2A1-D(P)(05) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 743 | 709-0200-0-00 | MF25S-WP16.5S20-0203 | |
| 744 | 709-0212-3-31 | MF10S-WP22C50-0200(31) | |
| 745 | 709-0214-9-31 | MF10S-WPN7C50-0200(31) | |
| 746 | 709-0215-1-31 | MF10S-WP6C52-0200(31) | |
| 747 | 709-0216-0-31 | MF10S-WP7C52-0200(31) | |
| 748 | 709-1032-7-31 | MF10B-WRFCH01-0200(31) | |
| 749 | 709-1033-0-31 | MF10B-WRBCH01-0200(31) | |
| 750 | 709-1049-0-00 | MF10B-C1 | |
| 751 | 709-1544-0-31 | MF10BWRFCH01-U-0.7M(31) | |
| 752 | 715-1004-0-00 | HRLC-ASP72-F3Q27-A-0.4M | |
| 753 | 717-7010-1-00 | SW23-RC-B1 | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 754 | 701-0074-0-60 | HRFC-P8-H3(60) | |

■Product List PCN2022-17_FY2022 Discontinued Sales of Connector

*We have no plan to sell substitute products. We're sorry to cause any inconvenience to you.

| No. | Current product | | Remarks |
|-----|-----------------|---------------------------|---|
| | Product code | Product name | |
| 755 | 701-0074-0-61 | HRFC-P8-H3(61) | |
| 756 | 701-0074-0-62 | HRFC-P8-H3(62) | |
| 757 | 701-0078-1-61 | HRFC-P8-L3(61) | |
| 758 | 701-0111-5-62 | HRFC-P8-W2(62) | |
| 759 | 704-0480-0-93 | HSC-PH2-E2-A(93) | |
| 760 | 710-1003-0-00 | HMUA-ASP2-F3M-0.2M | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 761 | 301-0006-0-00 | N-WR-2D-4 | |
| 762 | 301-0007-0-40 | N-LP-5DW(40) | |
| 763 | 301-0162-3-42 | N-P-141(42) | |
| 764 | 301-0206-7-31 | N-P-10DFB(31) | |
| 765 | 301-0706-0-00 | N-WBPJ-088H-1 | |
| 766 | 302-0005-0-00 | BNC-P-1.5DV | |
| 767 | 302-0017-0-43 | UG-625/U(43) | |
| 768 | 302-0108-4-41 | BNC-PJ-58(41) | |
| 769 | 302-0167-3-45 | BNC-UPA(45) | |
| 770 | 302-0178-0-42 | UG-1094/U(42) | |
| 771 | 302-0218-2-42 | BNC-P-5DV-SA(42) | |
| 772 | 302-0219-5-40 | BNC-P-3DV-SA(40) | |
| 773 | 302-0219-5-41 | BNC-P-3DV-SA(41) | |
| 774 | 302-0219-5-42 | BNC-P-3DV-SA(42) | |
| 775 | 302-0219-5-43 | BNC-P-3DV-SA(43) | |
| 776 | 302-0224-5-40 | UG-625/U-3(40) | |
| 777 | 302-0253-3-41 | UG-625/U-10(41) | |
| 778 | 302-0274-3-41 | UG-625/U-11A(41) | |
| 779 | 302-0297-9-41 | BNC-J-1.5WCR(41) | |
| 780 | 302-0299-4-41 | BNC-P-1.5W(41) | |
| 781 | 302-0356-6-40 | BNC-PJ-85(40) | |
| 782 | 302-0371-0-41 | BNC(75)-PJ-1.5CV-2P(41) | |
| 783 | 302-0391-7-40 | BNC-PJ-196CR(40) | |
| 784 | 302-0399-9-40 | BNC(75)-BPJ-1.5CV-5(40) | |
| 785 | 302-0411-2-00 | BNC-BPJ-1.5DW(B) | |
| 786 | 303-0025-5-42 | M-PA-JJ(42) | |
| 787 | 305-0077-1-31 | S-3DWPL(31) | |
| 788 | 311-0003-7-40 | UG-273/U(40) | |
| 789 | 311-0009-3-40 | BNCJ-MP(40) | |
| 790 | 311-0011-5-40 | NJ-MJ(40) | |
| 791 | 311-0016-0-00 | HRMP-U.FLJ-5 | |
| 792 | 311-0050-7-40 | NP-BNCP(40) | |
| 793 | 311-0091-4-40 | HRM-507(40) | |
| 794 | 311-0092-7-31 | HRM-508(31) | |
| 795 | 311-0129-5-00 | HRM-518-1S | |
| 796 | 311-0143-6-40 | HRM-511S(40) | |
| 797 | 311-0167-4-40 | BNCJ-PO6J(40) | |
| 798 | 311-0225-9-40 | N.J-TNC.P(40) | |
| 799 | 311-0470-2-00 | PL76J-H.FLJ-BPA | |
| 800 | 312-0214-9-40 | PO(ST)-R-3(16.6)(40) | |
| 801 | 312-0227-0-40 | PO(ST)-R-6(16.6)(40) | |
| 802 | 313-0321-5-00 | 7/8-PA-JJ | |
| 803 | 313-1003-5-40 | MRF03-6PR-SMT(40) | |
| 804 | 318-0007-2-40 | UM-SJ-1.5(40) | |
| 805 | 318-0213-4-40 | UM-QR-1-4A(40) | |
| 806 | 321-0009-0-04 | E.FL-2LP-066N1-A-(550) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 807 | 321-0009-0-05 | E.FL-2LP-066N1-A-(70)A | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 808 | 321-0030-0-28 | U.FL-2LPHF6-04N1TV-A-115 | |
| 809 | 321-0030-0-30 | U.FL-2LPHF6-04N1TV-A-220 | |
| 810 | 321-0030-0-31 | U.FL-2LPHF6-04N1TV-A-107 | |
| 811 | 321-0030-0-33 | U.FL-2LPHF6-04N1TV-A-460 | |
| 812 | 321-0031-0-34 | U.FL-2LPHF6-04N2TV-A-230 | |
| 813 | 321-0051-0-05 | H.FL75-LPG-084N4-A-80 | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 814 | 321-0065-0-01 | HRMJ-X.FL(I)-068N1T-A-75 | |
| 815 | 321-0098-0-02 | WFL2-2HFNM-032N6TS-200 | |
| 816 | 321-0098-0-03 | WFL2-2HFNM-032N6TS-400 | |
| 817 | 321-0098-0-04 | WFL2-2HFNM-032N6TS-445 | |
| 818 | 321-0098-0-05 | WFL2-2HFNM-032N6TS-600 | |
| 819 | 321-0098-0-06 | WFL2-2HFNM-032N6TS-800 | |
| 820 | 321-0101-0-03 | H.FL-2LP(A)-066N1-A-(210) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 821 | 321-0101-0-05 | H.FL-2LP(A)-066N1-A-145A | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 822 | 321-0158-0-06 | U.FL-LPHF6-066N1-A-(310) | |
| 823 | 321-0160-0-01 | B(CR)-2P-1.5DHV-A-2000RS | |
| 824 | 321-0176-0-01 | HRM-J-1.5DHV-170ARS | |
| 825 | 321-0176-0-02 | HRM-J-1.5DHV-164RS | |
| 826 | 321-0188-0-01 | MMCX(AR)-2P-AF2-200 | |

■Product List PCN2022-17_FY2022 Discontinued Sales of Connector

*We have no plan to sell substitute products. We're sorry to cause any inconvenience to you.

| No. | Current product | | Remarks |
|-----|-----------------|---------------------------|---|
| | Product code | Product name | |
| 827 | 321-0234-0-11 | UFL-2LPVHF6-04N2TV-A-130 | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 828 | 321-0238-0-02 | PL71P-PL75LP-1.5CW-A306RS | |
| 829 | 321-0248-0-01 | EFL-MMCXLP-066N1-A-200RS | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 830 | 321-0261-0-01 | H.FL-LP(A)-066N1-A-(100) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 831 | 321-0262-0-01 | POST-LPP-FCCAF1-A-100RS | |
| 832 | 321-0300-0-01 | BPJ-UMLP6-1.5W-AAE-160ARS | |
| 833 | 321-0307-0-26 | H.FL75-2LPG-084N1-AC-125 | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 834 | 321-0330-0-01 | HRMG-2P-068K5TS-A-200RS | |
| 835 | 321-0331-0-01 | HRMG-2BPJ-068K5TS-A-200RS | |
| 836 | 321-0345-0-01 | HRM-J-04N1-A-39-185RS | |
| 837 | 321-0346-0-01 | MMCX(AR)-2P-AF1-200 | |
| 838 | 321-0354-0-01 | MMCX(AR)-2LP-AF1-200 | |
| 839 | 321-0365-0-01 | MMCX(AR)-2LP-AF2-200 | |
| 840 | 321-0366-0-01 | MMCX-2PJ-AF1-200 | |
| 841 | 321-0376-0-01 | E.FL-2LP-066N1-AC-(40) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 842 | 321-0382-0-01 | MCX-2P-FCCAF1-A-500RS | |
| 843 | 321-0425-0-01 | HRMJ-WFL2(I)-068N1T-A-130 | |
| 844 | 321-0425-0-02 | HRMJ-WFL2(I)-068N1T-A-300 | |
| 845 | 321-0454-0-02 | HRM-2P-FCCAF1-A-600RS | |
| 846 | 321-0454-0-03 | HRM-2P-FCCAF1-A-800RS | |
| 847 | 321-0482-0-01 | HRMM-P-1.5DHV-A-351.2ARS | |
| 848 | 321-0509-0-01 | HRM-P.LP-066N1-A-300RS | |
| 849 | 321-0510-0-01 | HRM-P.LP-04N1T-A-300RS | |
| 850 | 321-0533-0-01 | HRMS-P.LP-TFMMF1-A-480RS | |
| 851 | 321-0533-0-02 | HRMS-P.LP-TFMMF1-A-2000RS | |
| 852 | 321-0533-0-03 | HRMS-P.LP-TFMMF1-A-2500RS | |
| 853 | 321-0533-0-04 | HRMS-P.LP-TFMMF1-A-3000RS | |
| 854 | 321-0558-0-01 | HRMS-2P-TFMMF1-A-2000RS | |
| 855 | 321-0558-0-02 | HRMS-2P-TFMMF1-A-2500RS | |
| 856 | 321-0558-0-03 | HRMS-2P-TFMMF1-A-3000RS | |
| 857 | 321-0559-0-01 | HRMJ-UFLHF-066N1-A-80RS | |
| 858 | 321-0650-0-01 | MMCX-2P-068N1T-A-400RS | |
| 859 | 321-0676-0-28 | U.FL-LPHF6-066N2-A-29 | |
| 860 | 321-0677-0-29 | U.FL-LPHF6-088N2T-A-1500 | |
| 861 | 321-0686-0-01 | MMCX-2P-178B/U-A-1000RS | |
| 862 | 321-0829-0-01 | UFLHF6-MMCXLP-088N2T-A185 | |
| 863 | 321-0845-0-02 | H.FLA-UFLHF6-066N1-A-297B | |
| 864 | 321-0855-0-01 | TBPJA-UFLHF6-068N1T-AT370 | |
| 865 | 321-0855-0-02 | TBPJA-UFLHF6-068N1T-AT400 | |
| 866 | 321-0862-0-01 | HRMP-UFLHF6-066N2-A220RS | |
| 867 | 321-0917-0-01 | UFLHF6-MMCXLP-066N2-AC73A | |
| 868 | 321-0917-0-02 | UFLHF6-MMCXLP-066N2-AC99A | |
| 869 | 321-0935-0-01 | UFLHF6-MMCXP-088N2T-A-450 | |
| 870 | 321-0962-0-01 | SMA(R)-P-J-088N2T-A-240RS | |
| 871 | 321-0969-0-01 | HPJ2-UFLHF6-04N2TV-A275RS | |
| 872 | 321-0988-0-01 | FL-2LP-1.5CW-AA-170RS | |
| 873 | 321-1001-0-01 | FL-LP-1.5CW-AA-600RS | |
| 874 | 321-1025-0-00 | POSTLPP75-HRMP-AF1-A-100A | |
| 875 | 321-1039-0-28 | UFL-2LPHF6-04N2TV-AC-30D | |
| 876 | 321-1231-0-28 | U.FL-2LPHF6-088N3T-A-320 | |
| 877 | 321-1554-3-16 | E.FL-2LP-04-A-(80) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 878 | 321-1819-6-01 | E.FL-2LP-066H-A-(120) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 879 | 321-1890-0-03 | H.FL-2LP(A)-FHSA-A-(35) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 880 | 321-1890-0-04 | H.FL-2LP(A)-FHSA-A-(40) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 881 | 321-1890-0-07 | H.FL-2LP(A)-FHSA-A-(70) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 882 | 321-1890-0-08 | H.FL-2LP(A)-FHSA-A-(80) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 883 | 321-1890-0-18 | H.FL-2LP(A)-FHSA-A-(180) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 884 | 321-1890-0-26 | H.FL-2LP(A)-FHSA-A-(260) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 885 | 321-1890-0-28 | H.FL-2LP(A)-FHSA-A-(280) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 886 | 321-1890-0-45 | H.FL-2LP(A)-FHSA-A-(500) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 887 | 321-1890-0-57 | H.FL-2LP(A)-FHSA-A-(1600) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |

■Product List PCN2022-17_FY2022 Discontinued Sales of Connector

*We have no plan to sell substitute products. We're sorry to cause any inconvenience to you.

| No. | Current product | | Remarks |
|-----|-----------------|---------------------------|---|
| | Product code | Product name | |
| 888 | 321-1890-0-59 | H.FL-2LP(A)-FHSB-A-(1500) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 889 | 321-1908-4-15 | H.FL-LP(A)-FHSB-A-(150) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 890 | 321-2148-8-12 | H.FL75-LP-084N-A-150 | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 891 | 321-2148-8-17 | H.FL75-LP-084N-A-200 | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 892 | 321-2149-0-02 | H.FL75-2LP-084N-A-50 | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 893 | 321-2149-0-04 | H.FL75-2LP-084N-A-70 | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 894 | 321-2149-0-09 | H.FL75-2LP-084N-A-120 | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 895 | 321-2149-0-13 | H.FL75-2LP-084N-A-160 | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 896 | 321-2149-0-14 | H.FL75-2LP-084N-A-170 | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 897 | 321-2149-0-21 | H.FL75-2LP-084N-A-600 | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 898 | 321-2149-0-25 | H.FL75-2LP-084N-A-1000 | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 899 | 321-2180-0-20 | H.FL75-2LP-WMF-A-TO-320 | |
| 900 | 321-2181-3-18 | H.FL75-2LP-WMF-A-TB-320 | |
| 901 | 321-2182-6-17 | H.FL75-2LP-WMF-A-TG-320 | |
| 902 | 321-2613-6-07 | E.FL-LP-0733-A-310 | |
| 903 | 321-2638-7-11 | H.FL-2LP(A)-111-A-(110) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 904 | 321-2638-7-24 | H.FL-2LP(A)-111-A-(255) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 905 | 321-3464-3-15 | H.FL-LP(A)-111-A-(220) | |
| 906 | 321-3771-2-40 | BPJ-PL71LP-1.5CE-200A-RS | |
| 907 | 321-3780-3-01 | BPJ(P)-PL71AP-1.5CE-150RS | |
| 908 | 321-3821-9-02 | PL71-2LP-1.5CE-3500SRS | |
| 909 | 321-3862-6-01 | MMCX-2P-178B/U-(200)RS | |
| 910 | 321-3901-6-01 | UM-2P-1.5DHW-AA-150RS | |
| 911 | 321-3901-6-03 | UM-2P-1.5DHW-AA-250RS | |
| 912 | 321-3958-3-03 | BBPJ5-PO6LP-1.5CV-160RS | |
| 913 | 321-3958-3-05 | BBPJ5-PO6LP-1.5CV-200RS | |
| 914 | 321-3958-3-07 | BBPJ5-PO6LP-1.5CV-240RS | |
| 915 | 321-3999-0-01 | BBPJ-H.FL-111-A-(120)RS | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 916 | 321-4003-6-03 | UM-P.LP-1.5DHW-A-237RS | |
| 917 | 321-4116-2-02 | BNC-2P-58C/U-A-1000RS | |
| 918 | 321-4116-2-03 | BNC-2P-58C/U-A-3000RS | |
| 919 | 321-4116-2-04 | BNC-2P-58C/U-A-5000RS | |
| 920 | 321-4116-2-05 | BNC-2P-58C/U-A-4022RS | |
| 921 | 321-4116-2-06 | BNC-2P-58C/U-A-6022RS | |
| 922 | 321-4116-2-07 | BNC-2P-58C/U-A-500RS | |
| 923 | 321-4116-2-08 | BNC-2P-58C/U-A-2000RS | |
| 924 | 321-4189-6-02 | UM-2LP6-1.5CW-400RS | |
| 925 | 321-4202-2-01 | FL-2LP-1.5CW-300RS | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 926 | 321-4202-2-02 | FL-2LP-1.5CW-180RS | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 927 | 321-4202-2-07 | FL-2LP-1.5CW-110RS | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 928 | 321-4202-2-09 | FL-2LP-1.5CW-100RS | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 929 | 321-4202-2-10 | FL-2LP-1.5CW-150RS | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 930 | 321-4202-2-13 | FL-2LP-1.5CW-250RS | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 931 | 321-4202-2-14 | FL-2LP-1.5CW-320RS | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 932 | 321-4202-2-15 | FL-2LP-1.5CW-270RS | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 933 | 321-4202-2-16 | FL-2LP-1.5CW-140RS | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 934 | 321-4223-2-05 | FL-2LP-1.5DW-A-550RS | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 935 | 321-4223-2-06 | FL-2LP-1.5DW-A-340RS | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 936 | 321-4244-2-01 | HRMPJ-S.FL2-111-AA-125ARS | |
| 937 | 321-4303-0-01 | PODBPJ-E.FL-066H-260RS | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 938 | 321-4304-2-01 | PODBPJ41-E.FL-066H-150ARS | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |

■Product List PCN2022-17_FY2022 Discontinued Sales of Connector

*We have no plan to sell substitute products. We're sorry to cause any inconvenience to you.

| No. | Current product | | Remarks |
|-----|-----------------|--------------------------|---|
| | Product code | Product name | |
| 939 | 321-4325-2-11 | UM-2LP6-1.5DHW-AA-160RS | |
| 940 | 321-4325-2-12 | UM-2LP6-1.5DHW-AA-350RS | |
| 941 | 321-4325-2-13 | UM-2LP6-1.5DHW-AA-270RS | |
| 942 | 321-4325-2-16 | UM-2LP6-1.5DHW-AA-70RS | |
| 943 | 321-4325-2-17 | UM-2LP6-1.5DHW-AA-200RS | |
| 944 | 321-4325-2-18 | UM-2LP6-1.5DHW-AA-80RS | |
| 945 | 321-4325-2-19 | UM-2LP6-1.5DHW-AA-250RS | |
| 946 | 321-4703-8-01 | BBPJ-PL75-1.5CE-W160RS | |
| 947 | 321-4704-0-01 | BBPJ-PL75-1.5CE-BE160RS | |
| 948 | 321-4763-0-02 | MMCX-2LP-066J1-AC-200RS | |
| 949 | 321-4792-8-05 | W.FL-2LPGHF-062N2D-A-70 | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 950 | 321-4792-8-08 | W.FL-2LPGHF-062N2D-A-100 | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 951 | 321-4888-5-01 | W.FL-2LPGHF-062N1D-A-35 | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 952 | 321-4888-5-02 | W.FL-2LPGHF-062N1D-A-40 | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 953 | 321-4888-5-04 | W.FL-2LPGHF-062N1D-A-60 | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 954 | 321-4888-5-05 | W.FL-2LPGHF-062N1D-A-70 | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 955 | 321-4888-5-09 | W.FL-2LPGHF-062N1D-A-110 | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 956 | 321-4888-5-10 | W.FL-2LPGHF-062N1D-A-120 | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 957 | 321-4888-5-11 | W.FL-2LPGHF-062N1D-A-130 | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 958 | 321-4888-5-12 | W.FL-2LPGHF-062N1D-A-140 | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 959 | 321-4888-5-13 | W.FL-2LPGHF-062N1D-A-150 | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 960 | 321-4888-5-14 | W.FL-2LPGHF-062N1D-A-160 | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 961 | 321-4888-5-15 | W.FL-2LPGHF-062N1D-A-170 | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 962 | 321-4888-5-16 | W.FL-2LPGHF-062N1D-A-180 | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 963 | 321-4888-5-17 | W.FL-2LPGHF-062N1D-A-190 | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 964 | 321-4888-5-18 | W.FL-2LPGHF-062N1D-A-200 | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 965 | 321-4888-5-19 | W.FL-2LPGHF-062N1D-A-250 | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 966 | 321-4888-5-20 | W.FL-2LPGHF-062N1D-A-300 | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 967 | 321-4888-5-21 | W.FL-2LPGHF-062N1D-A-400 | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 968 | 321-4888-5-22 | W.FL-2LPGHF-062N1D-A-500 | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 969 | 321-4888-5-23 | W.FL-2LPGHF-062N1D-A-600 | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 970 | 321-4888-5-24 | W.FL-2LPGHF-062N1D-A-700 | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 971 | 321-4888-5-25 | W.FL-2LPGHF-062N1D-A-800 | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 972 | 321-4888-5-26 | W.FL-2LPGHF-062N1D-A-900 | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 973 | 321-4899-1-01 | W.FL-2LPGHF-062N3D-A-35 | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 974 | 321-4899-1-02 | W.FL-2LPGHF-062N3D-A-40 | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 975 | 321-4899-1-03 | W.FL-2LPGHF-062N3D-A-50 | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 976 | 321-4899-1-04 | W.FL-2LPGHF-062N3D-A-60 | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 977 | 321-4899-1-05 | W.FL-2LPGHF-062N3D-A-70 | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 978 | 321-4899-1-06 | W.FL-2LPGHF-062N3D-A-80 | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 979 | 321-4899-1-07 | W.FL-2LPGHF-062N3D-A-90 | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 980 | 321-4899-1-08 | W.FL-2LPGHF-062N3D-A-100 | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 981 | 321-4899-1-09 | W.FL-2LPGHF-062N3D-A-110 | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 982 | 321-4899-1-10 | W.FL-2LPGHF-062N3D-A-120 | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |

■Product List PCN2022-17_FY2022 Discontinued Sales of Connector

*We have no plan to sell substitute products. We're sorry to cause any inconvenience to you.

| No. | Current product | | Remarks |
|------|-----------------|---------------------------|---|
| | Product code | Product name | |
| 1022 | 321-4909-3-23 | W.FL-2LPHF-04N2T-A-(600) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1023 | 321-4909-3-24 | W.FL-2LPHF-04N2T-A-(700) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1024 | 321-4909-3-25 | W.FL-2LPHF-04N2T-A-(800) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1025 | 321-4909-3-26 | W.FL-2LPHF-04N2T-A-(900) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1026 | 321-4909-3-27 | W.FL-2LPHF-04N2T-A-(1000) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1027 | 321-5112-7-26 | H.FL75-2LPG-084N2-A-1040 | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1028 | 321-5112-7-28 | H.FL75-2LPG-084N2-A-593A | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1029 | 321-5363-7-03 | WFL-2LPHF6-04N1TV-A-50 | |
| 1030 | 321-5363-7-08 | WFL-2LPHF6-04N1TV-A-100 | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1031 | 321-5363-7-10 | WFL-2LPHF6-04N1TV-A-120 | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1032 | 321-5363-7-11 | WFL-2LPHF6-04N1TV-A-130 | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1033 | 321-5363-7-13 | WFL-2LPHF6-04N1TV-A-150 | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1034 | 321-5363-7-20 | WFL-2LPHF6-04N1TV-A-300 | |
| 1035 | 321-5363-7-21 | WFL-2LPHF6-04N1TV-A-400 | |
| 1036 | 321-5404-2-09 | WFL-2LPHF6-04N2TV-A-110 | |
| 1037 | 321-5922-7-01 | UM-2LP6-1.5DHW-A-174RS | |
| 1038 | 321-5922-7-02 | UM-2LP6-1.5DHW-A-60ARS | |
| 1039 | 321-6065-4-01 | H.FL75-2LPG-084N1-300 | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1040 | 321-6097-0-11 | MMCX(AR)-2LP-178B/U-550 | |
| 1041 | 321-6113-5-01 | HRMMP-ML51LP-DTR178-350RS | |
| 1042 | 321-6120-0-02 | MMCX-2LP-111-AC-200RS | |
| 1043 | 321-6189-7-01 | HRMJ-PO51MJ-1.5W-A-100RS | |
| 1044 | 321-6192-1-01 | NWPJH-MMCXARLP-111-A-500 | |
| 1045 | 321-6208-0-03 | U.FL-2LPHF6-066N1-AA-73 | |
| 1046 | 321-6208-0-04 | U.FL-2LPHF6-066N1-AA-77 | |
| 1047 | 321-6576-3-80 | N-2P-1.5DHW-A-1000RS | |
| 1048 | 321-6626-0-01 | HRMSLP-NUMP-1.5W-A-400RS | |
| 1049 | 323-0016-9-09 | HRM-304(09) | |
| 1050 | 323-0041-6-40 | HRM-202B(40) | |
| 1051 | 323-0061-3-00 | HRM-304S | |
| 1052 | 323-0129-5-00 | HRM-300-65 | |
| 1053 | 323-0321-2-02 | HRM-JCAP(02) | |
| 1054 | 323-0361-7-00 | HRM-103-1 | |
| 1055 | 323-0370-8-00 | HRM-200-3-C | |
| 1056 | 325-0001-4-40 | MP2.5CP(40) | |
| 1057 | 325-0005-5-40 | MP2.5CPJ(40) | |
| 1058 | 327-0002-0-40 | POD-J-85(40) | |
| 1059 | 331-0332-3-01 | N.FL-R-SMT-1(01) | |
| 1060 | 331-0567-7-00 | W.FL-R-2B | |
| 1061 | 331-0713-7-40 | X.FL-PR-SMT1-2(40) | |
| 1062 | 336-0031-9-41 | N.UM-R-PC-4(41) | |
| 1063 | 350-0027-8-00 | NF-T-11 | |
| 1064 | 358-0003-0-00 | MS-180S | |
| 1065 | 362-0006-0-01 | MS156CLP-LP068N5T119.4A18 | |
| 1066 | 362-0012-0-11 | MS156CLP-SMARJ-068N1T550 | |
| 1067 | 362-0013-0-02 | MS156CLP-HWBPJ068N1T100A | |
| 1068 | 362-0156-0-00 | MS156LH2-HRMJ-088V130 | |
| 1069 | 362-0159-9-00 | MS156LH2-HRMP-088V330 | |
| 1070 | 362-0183-3-00 | MS156LH2-HRMJ-088V131 | |
| 1071 | 362-0184-6-00 | MS156LH1-HRMJ-088V140 | |
| 1072 | 362-0216-0-00 | MS156L2-HRMJ-15W55 | |
| 1073 | 362-0222-3-05 | MS156LH1-HRMJ-088V500 | |
| 1074 | 362-0222-3-06 | MS156LH1-HRMJ-088V600 | |
| 1075 | 362-0222-3-07 | MS156LH1-HRMJ-088V175 | |
| 1076 | 362-0223-6-04 | MS180LH1-HRMJ-088V400 | |
| 1077 | 362-0223-6-06 | MS180LH1-HRMJ-088V600 | |
| 1078 | 362-0224-9-05 | MS180LH3-HRMJ-040V500 | |
| 1079 | 362-0224-9-06 | MS180LH3-HRMJ-040V600 | |
| 1080 | 362-0248-7-01 | MS180LH3-040V100 | |
| 1081 | 362-0248-7-02 | MS180LH3-040V200 | |
| 1082 | 362-0248-7-03 | MS180LH3-040V300 | |
| 1083 | 362-0248-7-04 | MS180LH3-040V400 | |
| 1084 | 362-0248-7-05 | MS180LH3-040V500 | |
| 1085 | 362-0248-7-06 | MS180LH3-040V600 | |
| 1086 | 362-0907-1-03 | MS156CLP-HRMBPJ-068N1T300 | |
| 1087 | 362-0907-1-04 | MS156CLP-HRMBPJ-068N1T400 | |

■Product List PCN2022-17_FY2022 Discontinued Sales of Connector

*We have no plan to sell substitute products. We're sorry to cause any inconvenience to you.

| No. | Current product | | Remarks |
|------|-----------------|---------------------------|---|
| | Product code | Product name | |
| 1088 | 362-0907-1-06 | MS156CLP-HRMBPJ-068N1T600 | |
| 1089 | 362-0907-1-09 | MS156CLP-HRMBPJ-068N1T105 | |
| 1090 | 362-0907-1-12 | MS156CLP-HRMBPJ068N1T1000 | |
| 1091 | 362-0907-1-13 | MS156CLP-HRMBPJ-068N1T50 | |
| 1092 | 362-0909-7-04 | MS156CLP-LP-068N1T400 | |
| 1093 | 362-0909-7-05 | MS156CLP-LP-068N1T500 | |
| 1094 | 362-0909-7-08 | MS156CLP-LP-068N1T255 | |
| 1095 | 362-0911-9-01 | MS156CLP-LP-068N1T80-13 | |
| 1096 | 362-0912-1-08 | MS156CLP-2LP-068N1T800 | |
| 1097 | 362-0912-1-12 | MS156CLP-2LP-068N1T1200 | |
| 1098 | 362-0912-1-14 | MS156CLP-2LP-068N1T1400 | |
| 1099 | 362-0913-4-02 | MS156CLP-HRMP-068N1T200 | |
| 1100 | 362-0913-4-04 | MS156CLP-HRMP-068N1T400 | |
| 1101 | 362-0913-4-05 | MS156CLP-HRMP-068N1T500 | |
| 1102 | 362-0913-4-06 | MS156CLP-HRMP-068N1T600 | |
| 1103 | 362-0913-4-08 | MS156CLP-HRMP-068N1T65 | |
| 1104 | 362-0913-4-10 | MS156CLP-HRMP-068N1T80 | |
| 1105 | 362-0914-7-05 | MS156CLP-HRMJ-068N1T500 | |
| 1106 | 362-0918-8-07 | MS156LH1-HRMP-088V1700 | |
| 1107 | 362-0919-0-05 | MS180LH1-HRMP-088V500 | |
| 1108 | 321-0202-0-29 | U.FL-LPHF6-068N1T-A-390 | |
| 1109 | 321-0234-0-13 | UFL-2LPVHF6-04N2TV-A-150 | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1110 | 321-0674-0-01 | HBPJ-UFLHF6-068N1T-A70RS | |
| 1111 | 321-0760-0-02 | HWBPJ-UFLHF6-088N2T-A265A | |
| 1112 | 321-0837-0-03 | UFLHF6-MMCXLP066N1-A35RS | |
| 1113 | 321-0855-0-03 | TBPJA-UFLHF6-068N1T-AT240 | |
| 1114 | 321-1181-0-01 | HRMWPJ-UFLHF6-066N2-A190 | |
| 1115 | 321-5363-7-18 | WFL-2LPHF6-04N1TV-A-200 | |
| 1116 | 321-5404-2-08 | WFL-2LPHF6-04N2TV-A-100 | |
| 1117 | 321-5404-2-22 | WFL-2LPHF6-04N2TV-A-500 | |
| 1118 | 321-5442-1-28 | W.FL2-2LPHF6-04N2TV-A-72 | |
| 1119 | 331-0332-3-80 | N.FL-R-SMT-1(80) | |
| 1120 | 331-0472-2-75 | U.FL-SMTGP | |
| 1121 | 339-0017-7-40 | MMCX-R-PC-1(40) | |
| 1122 | 321-2812-0-01 | CETCA-HRM-P.LP-088N2TA150 | |
| 1123 | 321-2815-0-01 | CETCA-HLP-MMCXLP088N2TA85 | |
| 1124 | 321-2816-0-01 | CETCA-MMCX-2LP-088N2TA115 | |
| 1125 | 338-0003-0-21 | HK-R-SR2-1(21) | |
| 1126 | 338-0003-0-22 | HK-R-SR2-1(22) | |
| 1127 | 815-5627-6-00 | RS1D-CA11 | |
| 1128 | 815-6302-7-00 | DH2C-B2PA | |
| 1129 | 815-5606-6-00 | RS1A-BA11 | |
| 1130 | 815-5620-7-00 | RS1A-EB11 | |
| 1131 | 815-5684-0-00 | RS1A-BB11 | |
| 1132 | 815-1622-0-00 | DG13-B3LA | |
| 1133 | 815-1653-4-00 | DG23-B3RA | |
| 1134 | 815-1668-1-00 | DG23-C2AA | |
| 1135 | 815-1673-1-00 | DG23-C3LA | |
| 1136 | 815-4613-6-00 | HA69-40A | |
| 1137 | 815-4620-1-00 | HA78-30L | |
| 1138 | 331-0472-2-75 | U.FL-SMTGP | |
| 1139 | 331-0482-6-60 | W.FL-R-SMT-1(60) | |
| 1140 | 765-0011-0-22 | GT15A-3S(22) | |
| 1141 | 701-0114-3-62 | HRFC-P15-H(62) | |
| 1142 | 701-0115-6-62 | HRFC-P15-L(62) | |
| 1143 | 701-2004-6-61 | HRFC-P15-G(61) | |
| 1144 | 704-0339-2-26 | HSC-PH0.9-E1(26) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1145 | 704-0354-6-02 | HSC-PH0.9-E2(02) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1146 | 704-0354-6-51 | HSC-PH0.9-E2(51) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1147 | 704-0354-6-51 | HSC-PH0.9-E2(51) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1148 | 710-0047-9-61 | HMUA-P2-H1(61) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1149 | 710-0121-0-10 | HMUA-F3-A1255(10) | |
| 1150 | 710-0158-0-60 | HMUA-P0.9-H1(60) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1151 | 710-0159-2-60 | HMUA-P0.9-H2(60) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1152 | 701-0075-3-63 | HRFC-P8-H2(63) | |
| 1153 | 701-0077-9-61 | HRFC-P8-L2(61) | |
| 1154 | 701-2001-8-62 | HRFC-P8-G2(62) | |
| 1155 | 704-0327-3-64 | HSC-PH2-E1(64) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |

■Product List PCN2022-17_FY2022 Discontinued Sales of Connector

*We have no plan to sell substitute products. We're sorry to cause any inconvenience to you.

| No. | Current product | | Remarks |
|------|-----------------|--------------------------|---|
| | Product code | Product name | |
| 1156 | 704-0328-6-75 | HSC-PH2-E2(75) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1157 | 704-0480-0-63 | HSC-PH2-E2-A(63) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1158 | 580-2601-0-00 | FH19SD-10S-0.5SH | |
| 1159 | 580-2603-6-00 | FH19SDJ-10S-0.5SH | |
| 1160 | 580-2803-5-10 | FH43B-35S-0.2SHW(10) | |
| 1161 | 580-2804-8-10 | FH43B-25S-0.2SHW(10) | |
| 1162 | 580-2805-0-10 | FH43B-61S-0.2SHW(10) | |
| 1163 | 580-2807-6-42 | FH43B-71S-0.2SHW(42) | |
| 1164 | 580-2809-1-10 | FH43B-41S-0.2SHW(10) | |
| 1165 | 586-0529-2-54 | FH12-50S-0.5SH(54) | |
| 1166 | 586-0530-1-54 | FH12-18S-0.5SH(54) | |
| 1167 | 580-1607-1-50 | FH36-19S-0.3SHW(50) | |
| 1168 | 543-2054-0-21 | DF11CZ-18DP-2V(21) | |
| 1169 | 640-0013-0-52 | IC1F-68RD-1.27SH(52) | |
| 1170 | 640-0021-9-72 | IC1GA-68PD-1.27DS-EJ(72) | |
| 1171 | 640-0031-2-72 | IC1G-68PD-1.27DS(72) | |
| 1172 | 640-0046-0-71 | IC1K-68RD-1.27SF(71) | |
| 1173 | 640-0047-2-71 | IC1K-68RD-1.27SFA(71) | |
| 1174 | 640-0047-2-91 | IC1K-68RD-1.27SFA(91) | |
| 1175 | 640-0048-5-71 | IC1K-68RD-1.27SFB(71) | |
| 1176 | 572-2804-3-00 | FX2D-52S-1.27DSAL | |
| 1177 | 206-2097-8-30 | MQ172-3PAC(30) | |
| 1178 | 211-0122-8-50 | DA-L(50) | |
| 1179 | 211-0123-0-50 | DA-LP(50) | |
| 1180 | 211-0130-6-00 | HDE-9S-DC | |
| 1181 | 211-0140-0-05 | HD-LN(05) | |
| 1182 | 211-0171-3-05 | HD-LN(4-40)(05) | |
| 1183 | 211-0171-3-07 | HD-LN(4-40)(07) | |
| 1184 | 211-0171-3-08 | HD-LN(4-40)(08) | |
| 1185 | 211-0172-6-05 | HD-LNA(05) | |
| 1186 | 211-0196-4-05 | HD-LNA(4-40)(05) | |
| 1187 | 211-0227-6-05 | RDCB-37P-LN(05) | |
| 1188 | 211-0295-6-55 | RDBD-25S-LN(55) | |
| 1189 | 211-0299-7-55 | RDBD-25SA-LNA(55) | |
| 1190 | 211-0305-8-55 | RDBD-25SA-LNA(4-40)(55) | |
| 1191 | 211-0313-6-55 | RDED-9S-LN(55) | |
| 1192 | 211-0319-2-55 | RDCD-37S-LN(55) | |
| 1193 | 211-0324-2-55 | SDBG-25S(55) | |
| 1194 | 211-0368-8-55 | RDBD-25P-LN(55) | |
| 1195 | 211-0373-8-55 | RDBD-25PA(55) | |
| 1196 | 211-0401-1-55 | RDED-9S-LN(4-40)(55) | |
| 1197 | 211-0409-3-55 | RDED-9SA-LNA(55) | |
| 1198 | 211-0417-1-55 | RDED-9SA-LNA(4-40)(55) | |
| 1199 | 211-0420-6-55 | RDED-9SE-LN(55) | |
| 1200 | 211-0449-8-10 | FDBD-25S(10) | |
| 1201 | 211-0464-1-55 | SDEG-9S(55) | |
| 1202 | 211-0476-0-55 | RDED-9P-LN(55) | |
| 1203 | 211-0479-9-55 | RDED-9P-LN(4-40)(55) | |
| 1204 | 211-0486-4-55 | RDED-9PA-LNA(55) | |
| 1205 | 211-0489-2-55 | RDED-9PA-LNA(4-40)(55) | |
| 1206 | 211-0491-4-55 | RDED-9PE-LN(55) | |
| 1207 | 211-0509-8-55 | RDAD-15PE-LN(55) | |
| 1208 | 211-0550-1-55 | SDAG-15S(55) | |
| 1209 | 211-0551-4-10 | HDA-CTH(M3)(10) | |
| 1210 | 211-0606-4-10 | FDBD-25PF(10) | |
| 1211 | 211-0632-4-55 | SDDG-50S(55) | |
| 1212 | 211-0689-1-55 | SDEG-9PF(55) | |
| 1213 | 211-0690-0-55 | SDBG-25PF(55) | |
| 1214 | 211-0771-0-55 | SDCG-37S(55) | |
| 1215 | 211-5180-1-00 | RDG-LNA | |
| 1216 | 211-5181-4-00 | RDG-LNA-W1 | |
| 1217 | 211-5182-7-00 | RDG-LNA-W2 | |
| 1218 | 211-5183-0-00 | RDG-LNA(4-40) | |
| 1219 | 211-5184-2-00 | RDG-LNA(4-40)-W1 | |
| 1220 | 211-5185-5-00 | RDG-LNA(4-40)-W2 | |
| 1221 | 216-0008-4-09 | S-1645A(09) | |
| 1222 | 216-0009-7-09 | S-1660A(09) | |
| 1223 | 216-0057-0-09 | S-1616G(09) | |
| 1224 | 216-0058-2-09 | S-1620G(09) | |
| 1225 | 216-0059-5-09 | S-1624G(09) | |
| 1226 | 216-0178-4-09 | P-1645BA(09) | |
| 1227 | 216-0179-7-09 | P-1660BA(09) | |
| 1228 | 216-0184-7-09 | P-1624BG(09) | |
| 1229 | 216-0186-2-09 | P-1634BG(09) | |
| 1230 | 216-0187-5-09 | P-1645BG(09) | |
| 1231 | 216-0188-8-09 | P-1660BG(09) | |

■Product List PCN2022-17_FY2022 Discontinued Sales of Connector

*We have no plan to sell substitute products. We're sorry to cause any inconvenience to you.

| No. | Current product | | Remarks |
|------|-----------------|----------------------------|---|
| | Product code | Product name | |
| 1232 | 216-0197-9-09 | SW-1660A(09) | |
| 1233 | 216-0224-0-09 | PW-1660BG(09) | |
| 1234 | 216-0387-4-09 | SD-1660A(09) | |
| 1235 | 216-0396-5-09 | PD-1660BA(09) | |
| 1236 | 216-0405-4-09 | SD-1660G(09) | |
| 1237 | 216-0413-2-09 | PD-1645BG(09) | |
| 1238 | 216-0414-5-09 | PD-1660BG(09) | |
| 1239 | 221-0108-4-15 | QR/P1-SC1A-211(15) | |
| 1240 | 221-0109-7-15 | QR/P1-SC2A-211(15) | |
| 1241 | 222-0005-0-00 | TM1R-616W44-4S-200M | |
| 1242 | 222-0094-0-00 | TM1R-616P44-35S-500M | |
| 1243 | 222-0095-0-00 | TM1R-616M44-35S-400M | |
| 1244 | 222-0114-3-50 | TM3R-66(50) | |
| 1245 | 222-0135-3-00 | TM-6-DC | |
| 1246 | 222-0276-5-00 | TM-8-DC | |
| 1247 | 222-1310-7-00 | TM4P-1212P | |
| 1248 | 222-1817-9-00 | TM8P-88P | |
| 1249 | 222-2643-5-50 | TM2RD-F44-38CJ-160(50) | |
| 1250 | 222-2684-2-00 | TM30P-66P | |
| 1251 | 222-2685-5-00 | TM30P-88P | |
| 1252 | 222-2809-6-50 | TM5RU1-66(50) | |
| 1253 | 222-2911-2-51 | TM22R-3C-88A(51) | |
| 1254 | 222-2916-6-00 | TM23P-88P | |
| 1255 | 222-2917-9-03 | TM23P-8-BT(03) | |
| 1256 | 222-2918-1-50 | TM23R-5A-88(50) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1257 | 222-2929-8-50 | TM22R-5C-88(50) | |
| 1258 | 222-2931-0-50 | TM5RU1-64(50) | |
| 1259 | 222-3347-8-50 | TM12RV-64-C(50) | |
| 1260 | 222-3910-5-30 | TM1RV-647A84-8P-470(30) | |
| 1261 | 222-4307-9-00 | TM1RV-623K66-4S-150M | |
| 1262 | 222-4431-8-00 | TM2RD-F44-3S-140M | |
| 1263 | 222-4441-1-00 | TM1R-616W44-4S-150M | |
| 1264 | 222-4447-8-00 | TM2RG-L66-5S-150M | |
| 1265 | 222-4449-3-30 | TM11R-88-35S-300M(30) | |
| 1266 | 222-4451-5-00 | TM1R-616M44-35S-70M | |
| 1267 | 222-4453-0-00 | TM2RG-L64-5S-150M | |
| 1268 | 222-4454-3-00 | TM1RV647AF88-35S-150M | |
| 1269 | 222-4456-9-00 | TM2RGV-L64-4S-150M | |
| 1270 | 222-4463-4-00 | TM1RV-623KD64-3S-153K | |
| 1271 | 222-4465-0-00 | TM1R-616B44-35S-150M | |
| 1272 | 222-4466-2-00 | TM1R-616P44-35S-150M | |
| 1273 | 222-4467-5-00 | TM2RD-F44-4S-150M | |
| 1274 | 222-4473-8-00 | TM1RV-623K64-4S-150M | |
| 1275 | 222-4483-1-00 | TM2RG-L62-5S-150M | |
| 1276 | 222-4484-4-30 | TM1RVX-647AF88-4S-230M(30) | |
| 1277 | 222-4487-2-00 | TM1R-616M44-35S-150AM | |
| 1278 | 222-4488-5-00 | TM1RV-623K66-35S-150M | |
| 1279 | 222-4494-8-00 | TM1R-647AF88-4S-90M | |
| 1280 | 222-4496-3-00 | TM2RGV-L66-4S-300M | |
| 1281 | 222-4497-6-00 | TM1R-616M44-35S-205M | |
| 1282 | 222-4498-9-00 | TM2RGV-L66-5S-500M | |
| 1283 | 222-4525-0-30 | TM11R-88-35S-720M(30) | |
| 1284 | 222-4558-9-00 | TM1RV-647AF88-35S-200M | |
| 1285 | 222-4599-0-00 | TM2RD-F44-C-52H | |
| 1286 | 222-4602-9-00 | TM1RV-623P66-35S-110M | |
| 1287 | 222-4655-5-00 | TM1RV-623K66-C-150K | |
| 1288 | 222-4680-2-00 | TM2RD-F44-4S-170AM | |
| 1289 | 222-4686-9-00 | TM2RD-F44-3S-160M | |
| 1290 | 222-4692-1-00 | TM1RV-623P66-DF1B-450M | |
| 1291 | 222-6115-9-30 | TM1RVX-647AF88-4S-530M(30) | |
| 1292 | 225-0005-7-00 | DN50-36P | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1293 | 225-0006-0-00 | DN50-50P | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1294 | 225-0007-2-00 | DN50-2628PC1 | |
| 1295 | 225-0008-5-00 | DN50-2628PC2 | |
| 1296 | 225-0021-3-00 | DN-36-CVE1 | |
| 1297 | 225-0025-4-00 | DN-36-CV1 | |
| 1298 | 225-0027-0-50 | DN30-36P(50) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1299 | 225-0027-0-51 | DN30-36P(51) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1300 | 225-0031-7-00 | DN-20-CV1 | |
| 1301 | 230-0064-1-50 | DX20J-26S-CR3(50) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1302 | 230-0069-5-50 | DX10-50SW(50) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |

■Product List PCN2022-17_FY2022 Discontinued Sales of Connector

*We have no plan to sell substitute products. We're sorry to cause any inconvenience to you.

| No. | Current product | | Remarks |
|------|-----------------|------------------------|---|
| | Product code | Product name | |
| 1303 | 230-0274-4-50 | DX10-20SE(50) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1304 | 230-5051-7-00 | DX30M-14-CV | |
| 1305 | 230-5052-0-00 | DX30M-20-CV | |
| 1306 | 230-5052-0-13 | DX30M-20-CV(13) | |
| 1307 | 230-5053-2-00 | DX30M-26-CV | |
| 1308 | 230-5054-5-00 | DX30M-36-CV | |
| 1309 | 230-5054-5-13 | DX30M-36-CV(13) | |
| 1310 | 230-5055-8-00 | DX30M-50-CV | |
| 1311 | 230-5076-8-50 | DX10BM-100SE(50) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1312 | 230-5095-2-50 | DX33AM-36S(50) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1313 | 230-5134-2-50 | DX10GM-68SE(50) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1314 | 230-5181-2-50 | DX10GM-68S(50) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1315 | 232-0047-5-59 | 3260-10S3(59) | |
| 1316 | 242-0009-3-31 | ZX64-B-5S-UNIT(31) | |
| 1317 | 242-0018-4-00 | ZX64-B-SLDC | |
| 1318 | 216-0193-8-09 | SW-1624A(09) | |
| 1319 | 222-0270-9-50 | TM5RC-44(50) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1320 | 222-1223-4-20 | TM5RE2-64(20) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1321 | 222-1224-7-20 | TM5RE2-62(20) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1322 | 222-1225-0-20 | TM5RE2-66(20) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1323 | 222-1465-3-52 | TM5RJ3-88(52) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1324 | 222-1534-4-50 | TM5RF1-66(50) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1325 | 222-2034-7-50 | TM13R-44(50) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1326 | 222-2578-5-50 | TM5RC-1212-1.2(50) | |
| 1327 | 222-2949-5-00 | TM21RE-5C-88 | |
| 1328 | 222-2969-2-00 | TM22AR-5B-3232D | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1329 | 230-5130-1-50 | DX10GM-20SE(50) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1330 | 231-3002-7-50 | 3130-8P-C(50) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1331 | 231-3014-6-50 | 3130-6P-C(50) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1332 | 231-3017-4-50 | 3110-6SB(50) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1333 | 240-2003-5-00 | UX40-MB-5PA-1000-2003 | |
| 1334 | 216-0205-5-10 | PW-1645BA(10) | |
| 1335 | 216-0206-8-10 | PW-1660BA(10) | |
| 1336 | 222-0011-0-00 | TM2RGV-L62-4S-800M | |
| 1337 | 222-0096-0-00 | TM1RV-647A85-35S-150MA | |
| 1338 | 109-0484-4-81 | RM24TR-31S(81) | |
| 1339 | 110-0013-8-31 | KMC9BPD-4P(31) | |
| 1340 | 110-0015-3-75 | KMC9BRD-4S(75) | |
| 1341 | 110-0017-9-75 | KMC9BRD-6S(75) | |
| 1342 | 110-0018-1-31 | KMC9BPD-6P(31) | |
| 1343 | 110-0062-3-71 | KMC9BPF-4P(71) | |
| 1344 | 111-0002-8-73 | HR11-9BR-6S(73) | |
| 1345 | 112-2003-8-72 | HR212-10R-8SDL(72) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1346 | 113-1005-4-71 | RP13A-12JD-15PC(71) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1347 | 113-5097-4-71 | RP34-8SP-4SC(71) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1348 | 114-0252-4-72 | JRC16BP-10P(72) | |
| 1349 | 114-0254-0-71 | JRC16BP-14S(71) | |
| 1350 | 114-0260-2-71 | JRC16BR-14S(71) | |
| 1351 | 114-0267-1-31 | JRC21BP-26S(31) | |
| 1352 | 114-0300-0-00 | JRC16BP-10PA | |
| 1353 | 114-0302-0-00 | JRC16BP-7PA | |
| 1354 | 114-0303-0-00 | JRC16BP-7SA | |
| 1355 | 114-0502-0-71 | JR13PK-5P(71) | |
| 1356 | 114-0503-2-71 | JR16PK-7P(71) | |
| 1357 | 114-0504-5-71 | JR16PK-10P(71) | |
| 1358 | 114-0505-8-71 | JR21PK-10P(71) | |
| 1359 | 114-0506-0-71 | JR21PK-16P(71) | |
| 1360 | 114-0508-6-71 | JR25PK-24P(71) | |

■Product List PCN2022-17_FY2022 Discontinued Sales of Connector

*We have no plan to sell substitute products. We're sorry to cause any inconvenience to you.

| No. | Current product | | Remarks |
|------|-----------------|--------------------------|---|
| | Product code | Product name | |
| 1361 | 114-0511-0-71 | JR16PK-7S(71) | |
| 1362 | 114-0512-3-71 | JR16PK-10S(71) | |
| 1363 | 114-0513-6-71 | JR21PK-10S(71) | |
| 1364 | 114-0514-9-71 | JR21PK-16S(71) | |
| 1365 | 114-0515-1-71 | JR25PK-16S(71) | |
| 1366 | 114-0516-4-71 | JR25PK-24S(71) | |
| 1367 | 114-0518-0-00 | JR13RK-5P | |
| 1368 | 114-0519-2-00 | JR16RK-7P | |
| 1369 | 114-0520-1-00 | JR16RK-10P | |
| 1370 | 114-0521-4-00 | JR21RK-10P | |
| 1371 | 114-0522-7-00 | JR21RK-16P | |
| 1372 | 114-0523-0-00 | JR25RK-16P | |
| 1373 | 114-0524-2-00 | JR25RK-24P | |
| 1374 | 114-0526-8-00 | JR13RK-5S | |
| 1375 | 114-0527-0-00 | JR16RK-7S | |
| 1376 | 114-0528-3-00 | JR16RK-10S | |
| 1377 | 114-0529-6-00 | JR21RK-10S | |
| 1378 | 114-0530-5-00 | JR21RK-16S | |
| 1379 | 114-0531-8-00 | JR25RK-16S | |
| 1380 | 114-0532-0-00 | JR25RK-24S | |
| 1381 | 114-0536-1-00 | JR16JK-10P | |
| 1382 | 114-0541-1-00 | JR13JK-3S | |
| 1383 | 114-0543-7-00 | JR16JK-7S | |
| 1384 | 114-0544-0-00 | JR16JK-10S | |
| 1385 | 114-2004-3-31 | JR16WP-10P(31) | |
| 1386 | 114-2015-0-31 | JR16WP-10S(31) | |
| 1387 | 114-2037-2-31 | JR16WR-10S(31) | |
| 1388 | 114-2051-3-74 | JR13WCC-10(74) | |
| 1389 | 121-0016-0-75 | HR21-26TR-8P(75) | |
| 1390 | 121-0158-4-75 | HR21-26TPE-10P(75) | |
| 1391 | 139-0001-0-00 | EV1-62P-3PC | |
| 1392 | 150-0015-2-00 | RM215-T03 | |
| 1393 | 150-0016-5-00 | RM215A-T04 | |
| 1394 | 150-0040-0-00 | RP6-SC-TC | |
| 1395 | 150-0048-1-00 | RP19-TC-11 | |
| 1396 | 150-0055-7-00 | HR10D-TC-02 | |
| 1397 | 150-0079-5-00 | KMC-TP | |
| 1398 | 150-0094-9-00 | RM15WTPQ-12S-T01 | |
| 1399 | 150-0095-1-00 | HR24-9DJ-4S-T01 | |
| 1400 | 150-0202-0-00 | RP34-1/CR-HT | |
| 1401 | 150-0206-0-00 | H/MS/CC-HT | |
| 1402 | 150-0252-8-00 | EV1-62P/CV-MD | |
| 1403 | 109-1621-9-71 | RM15WTPZ-3S(71) | |
| 1404 | 109-1622-1-71 | RM15WTPZ-3P(71) | |
| 1405 | 112-2004-0-71 | HR212-10RA-8SDL(71) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1406 | 112-2004-0-72 | HR212-10RA-8SDL(72) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1407 | 112-4051-1-72 | HR212-10P-8PC(72) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1408 | 113-0206-0-71 | RP13A-12PD-15SC(71) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1409 | 113-0218-0-71 | RP13A-12JK-15PC(71) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1410 | 113-1010-4-71 | RP13A-12PP-15SC(71) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1411 | 113-5041-0-71 | RP34-8P-3SC(71) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1412 | 113-5042-2-00 | RP34-8R-3PDL | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1413 | 113-5043-5-00 | RP34-SC-212 | |
| 1414 | 113-5049-1-71 | RP34-8SP-3SC(71) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1415 | 113-5076-4-00 | RP34-SC-112 | |
| 1416 | 113-5098-7-00 | RP34-8R-4PDL | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1417 | 113-5153-3-71 | RP34L-5PA-2SC(1857)(71) | |
| 1418 | 113-5154-6-71 | RP34L-5R-2PD(71) | |
| 1419 | 113-5157-4-71 | RP34L-5R-3PD(71) | |
| 1420 | 113-5161-1-71 | RP34L-5LP-3SC(71) | |
| 1421 | 113-5165-2-71 | RP34L-5PA-2SC(1800)B(71) | |
| 1422 | 113-5178-4-71 | RP34L-5PA-3SC(71) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1423 | 114-0268-4-31 | JRC21BPA-26P(31) | |
| 1424 | 114-0269-7-71 | JRC21BR-26P(71) | |
| 1425 | 114-0270-6-00 | JRC21BRA-26S | |
| 1426 | 114-0501-7-71 | JR13PK-3P(71) | |
| 1427 | 114-0509-9-71 | JR13PK-3S(71) | |

■Product List PCN2022-17_FY2022 Discontinued Sales of Connector

*We have no plan to sell substitute products. We're sorry to cause any inconvenience to you.

| No. | Current product | | Remarks |
|------|-----------------|------------------------|---|
| | Product code | Product name | |
| 1428 | 114-0510-8-71 | JR13PK-5S(71) | |
| 1429 | 114-0570-0-71 | JR21PK-10PC(71) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1430 | 114-0574-0-71 | JR25PK-24PC(71) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1431 | 114-0577-9-00 | JR21RK-10SC | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1432 | 114-0578-1-00 | JR21RK-16PC | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1433 | 114-0581-6-00 | JR25RK-24SC | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1434 | 114-2001-5-31 | JR13WP-3P(31) | |
| 1435 | 114-2012-1-31 | JR13WP-3S(31) | |
| 1436 | 121-0046-0-76 | HR21-26TR-10P(76) | |
| 1437 | 121-0272-0-75 | HR21-26TPE-8S(75) | |
| 1438 | 139-0005-1-00 | EV1-PC1-112 | |
| 1439 | 701-0014-9-52 | HRFC-PA1-G1(52) | |
| 1440 | 701-0014-9-53 | HRFC-PA1-G1(53) | |
| 1441 | 701-0106-5-40 | HRFC-PA11-D1(40) | |
| 1442 | 704-0206-9-43 | HSCJ-HRFCJ-C(43) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1443 | 704-0258-2-01 | HSC-A2-D1(01) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1444 | 704-0339-2-60 | HSC-PH0.9-E1(60) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1445 | 704-0363-7-00 | HSC-C5 | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1446 | 704-0555-8-20 | HSC-PH0.9-E1-HOOD(20) | |
| 1447 | 704-0571-4-11 | HSC-F3E2-A1255(11) | |
| 1448 | 704-0593-7-00 | HSC-AFL1-S1-D1 | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1449 | 704-2040-9-06 | HSCF-2A-D(P)(06) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1450 | 706-0084-0-00 | CA04AJ153-SPW-A-1M | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1451 | 709-0564-0-31 | MF10S-WDRFC02-0200(31) | |
| 1452 | 710-0001-8-60 | HMUA-P2-H2(60) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1453 | 710-0021-5-40 | HMUB-SH-1(40) | |
| 1454 | 704-0223-8-68 | HSC-PH3-B2(68) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1455 | 704-0327-3-69 | HSC-PH2-E1(69) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1456 | 704-0328-6-74 | HSC-PH2-E2(74) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1457 | 704-2036-1-65 | HSCF-2PH3-B2(P)(65) | *This item is subject to material manufacturer change 430-18025_SABIC. Therefore, the material manufacturer may change by the final order date. |
| 1458 | 709-0209-9-16 | MF25S-WP14S02-0203(16) | |
| 1459 | 311-0004-0-40 | UG-349/U(40) | |
| 1460 | 318-0159-0-40 | UM-LR-PC-4-1(40) | |
| 1461 | 323-0136-0-49 | HRM-300-3H(49) | |
| 1462 | 323-0384-2-40 | HRM-400-64S(40) | |
| 1463 | 303-0061-9-40 | M-R-1(40) | |
| 1464 | 353-0137-5-50 | N-TMP-1-1(50) | |
| 1465 | 331-0004-0-10 | W.FL2-R-SMT-1-NM(10) | |
| 1466 | 331-0315-4-60 | W.FL2-R-SMT-1(60) | |
| 1467 | 331-0482-6-10 | W.FL-R-SMT-1(10) | |
| 1468 | 331-0482-6-40 | W.FL-R-SMT-1(40) | |
| 1469 | 331-0482-6-80 | W.FL-R-SMT-1(80) | |
| 1470 | 480-0266-0-51 | BM30B-48DP-0.35V(51) | |
| 1471 | 480-0268-0-51 | BM30B-54DP-0.35V(51) | |
| 1472 | 480-0430-0-00 | KN14(0.7)-2P/2-V(800) | |
| 1473 | 480-0431-0-00 | KN14(0.7)-2S/2-V(800) | |
| 1474 | 480-0626-0-00 | KP15TC-SF(800) | |
| 1475 | 480-0169-2-00 | TF31-10(4)SA-1SH(800) | |

Acknowledgement

(Customer → Hirose Electric business representative)

Product Change Notification
Request for Your Acknowledgement

We acknowledge the changes and schedule of this notification.

Customer's name: _____

Acknowledgement stamp (or signature): _____

HIROSE ELECTRIC CO., LTD.

(Cut on this line)

Document Receipt

(Customer → Hirose Electric business representative)

Product Change Notification
Request for Your Acknowledgement

We received the document concerning the above.

Customer's name: _____

Acknowledgment stamp (or signature): _____

HIROSE ELECTRIC CO., LTD.