

Document Receipt Acknowledgement

Date:
Section:
Name:



Document Number: MPS00001269

Date: Sep. 22, 2016

Attention:

ANGLIA COMPONENTS LTD

Product Withdrawal Notice

BWR*, CHE*, D1U3CS*, D1U4*, D1U54P*, D1U*, DDR*, HPQ*, HPR*, HS*, LSN*, LSS*, NBE*, OKLP*, PRW*, QCX*, RBQ*, RH*, TWR*, UCH*, UCP*, UCQ*, UHE*, ULQ*, ULS*, ULT*, USM*, UVQ*, UWR*, VR* Series

Dear. Valued Customer

Thank you very much for your great and continued support for business with Murata.

This is the official notification that some of our products will be discontinued as detailed below.

Please review this, and place Last Time Buy Order by the Last Time Order Due Date as needed.

Your understanding and support are highly appreciated.

1. Product Type, Customer/Murata/Alternative Part Numbers:

BWR*, CHE*, D1U3CS*, D1U4*, D1U54P*, D1U*, DDR*, HPQ*, HPR*, HS*, LSN*,
Product Type: LSS*, NBE*, OKLP*, PRW*, QCX*, RBQ*, RH*, TWR*, UCH*, UCP*, UCQ*, UHE*,
ULQ*, ULS*, ULT*, USM*, UVQ*, UWR*, VR* Series

Not all part numbers in each series will be discontinued.

Please refer to the attached documents for detailed Part Numbers' information.

2. Reasons/Background:

Due to the declining sales volume and for improving manufacturing efficiency.

3. Product Withdrawal Schedule:

Last Time Order Due (*): Apr. 30, 2017

Last Production Date: Sep. 30, 2017

Last Shipment Date: Sep. 30, 2017

* : Last Time Order is the subject to Minimum Order Quantity and Package Quantity.

Order Cancel and Product Return can be accepted only in the case of quality issue.

4. Contact Window:

Should you have any questions or concerns,

please contact Murata Sales, Representative, or Distributor in your area.

Truly Yours. Thank you.

Murata Manufacturing, Co., Ltd.

Muata Power Solution / Product Marketing

DC/DC & Panel Meters Product Manager: Bill Smith

AC/DC Product Manager: Roya Movahedi

Discontinued Part Numbers List (133 Part Numbers)

#	Murata Part Number	Recommended Replacement
1	BWR-15/575-D12A-C	BPM15-150-Q12-C
2	BWR-5/3-3.3/4.25-D24A-C	None
3	CHE-12/2100-D48PHL2-C-HW	None
4	D1U3CS-D-850-12-HC4C	None
5	D1U4-W-1200-12-HA2C	None
6	D1U4-W-1200-12-HC2C	None
7	D1U4-W-1600-12-HA2C	None
8	D1U4-W-1600-12-HC2C	None
9	D1U54P-12-CONC(HxxC)	None
10	D1U54P-12-CONC(HxxPC)	None
11	D1U-W-1200-12-HA2C	None
12	D1U-W-1200-12-HC2C	None
13	D1U-W-1600-12-HA2C	None
14	D1U-W-1600-12-HC2C	None
15	DDR-9-W3H-C-CIS	None
16	HPQ-8.3/22-D48NB-C	None
17	HPQ-8.3/22-D48NBX-C	None
18	HPQ-8.3/22-D48N-C	None
19	HPQ-8.3/22-D48PB-C	None
20	HPQ-8.3/22-D48P-C	None
21	HPR102C	MER1S0515SC
22	HPR103C	MEA1D0505SC
23	HPR104C	MEA1D0512SC
24	HPR106C	MER1S1205SC
25	HPR110C	MEA1D1212SC
26	HPR117VC	MEA1D1515DC
27	HPR120C	MER1S2415SC
28	HPR403C	NMV0505SC
29	HS-23-C	None
30	HS-24-C	None
31	HS-32-C	None
32	HS-40-C	None
33	LSN-3.3/10-D12J-C-CIS	None
34	LSN-T/10-D12J-Y-CIS	None
35	LSS-T/10-W12-C	OKR-T/10-W12-C
36	NBE-18/15-L24N-C	None
37	OKLP-X/25-W12-C	None
38	OKLP-X/35-W12-C	None
39	PWR1305AC	None
40	PWR1306AC	None
41	PWR1309AC	None
42	QCX-31153-C	None
43	RBQ-12/33-D48NB-C	DVQ0135V2NBC
44	RBQ-12/33-D48NBL2-C	None

Discontinued Part Numbers List (133 Part Numbers)

#	Murata Part Number	Recommended Replacement
45	RBQ-12/33-D48NBS-C	DVQ0135V2NBSC
46	RBQ-31250-C	None
47	RBQ-31250-CIS	None
48	RBQ-31250-CIS2	None
49	RBQ-31251-C	None
50	RBQ-31251-CIS	None
51	RBQ-31251-CIS2	None
52	RBQ-8.2/45-L48NBL2-CIS2	None
53	RBQ-8.2/45-L48NL2-CIS2	None
54	RBQ-8.5/45-L48NBL2-C	None
55	RBQ-8.5/45-L48NBL2-CIS	None
56	RBQ-8.5/45-L48NL2-C	None
57	RBQ-8.5/45-L48NL2-CIS	None
58	RBQ-9.6/50-L48NBL2-C	None
59	RBQ-9.6/50-L48NBL2-CIS	None
60	RBQ-9.6/50-L48NBL2-CIS2	None
61	RBQ-9.6/65-L48NL2-C	None
62	RBQ-9.6/65-L48NL4-C	None
63	RBQ-9.6/65-L48NL4-CIS	None
64	RBQ-9.8/50-L54NBL2-CIS2	None
65	RBQ-9.8/50-L54NBL2R-CIS2	None
66	RH1410Y-B	None
67	RH1448Y	None
68	RH1448YFRU	None
69	RH1492Y	None
70	RH1492YFRU	None
71	RH1627	None
72	RH1654	None
73	UCH-12/12.5-D48NB-C	None
74	UCH-12/12.5-D48N-C	None
75	UCH-12/4.2-D48NB-C	None
76	UCH-12/4.2-D48N-C	None
77	UCP-15/4-D48-C	None
78	UCQ-12/8.3-D48NB-C	UEE-12/12.5-D48NB-C
79	UCQ-12/8.3-D48N-C	UEE-12/12.5-D48N-C
80	UCQ-3.3/30-D48NB-C	UEE-3.3/30-D48NB-C
81	UCQ-3.3/30-D48NBHL2-C-HW	None
82	UCQ-5/20-D48NHL2-C-HW	None
83	UCQ-5/25-D48N-C	UEE-5/30-D48N-C
84	UCQ-75/0.7-D48-31166-C	None
85	UHE-15/2000-D12-C	UHE-15/2000-Q12-C
86	ULQ-12/8-D24N-C	UVQ-12/8-D24N-C
87	ULQ-12/8-D24NL1-C	None
88	ULQ-12/8-D24NL2-C	None

Discontinued Part Numbers List (133 Part Numbers)

#	Murata Part Number	Recommended Replacement
89	ULQ-12/8-D24P-C	UVQ-12/8-D24P-C
90	ULQ-12/8-D24PL1-C	None
91	ULQ-3.3/15-D48N-C	UEE-3.3/15-D48N-C
92	ULQ-3.3/15-D48P-C	UEE-3.3/15-D48P-C
93	ULQ-3.3/15-D48PL1-C	None
94	ULQ-5/15-D48N-C	UEE-5/30-D48N-C
95	ULQ-5/15-D48P-C	UEE-5/30-D48P-C
96	ULQ-5/15-D48PL2-C	None
97	ULS-12/2.5-D48N-C	ULS-12/5-D48N-C
98	ULS-12/2.5-D48NL2-C	ULS-12/5-D48NL2-C
99	ULS-12/2.5-D48NM-C	ULS-12/5-D48NM-C
100	ULS-12/2.5-D48P-C	ULS-12/8.3-D48P-C
101	ULS-12/5-D48P-C	ULS-12/8.3-D48P-C
102	ULS-12/5-D48PH-C	ULS-12/8.3-D48PH-C
103	ULS-15/2-D48P-C	None
104	ULS-15/2-D48PM-C	None
105	ULS-3.3/20-D48P-C	None
106	ULS-3.3/20-D48PH-C	None
107	ULS-3.3/8-D48NHL1-C	None
108	ULS-3.3/8-D48NM-C	None
109	ULS-3.3/8-D48P-C	None
110	ULS-5/12-D48P-C	ULS-5/20-D48P-C
111	ULS-5/12-D48PH-C	ULS-5/20-D48PH-C
112	ULT-12/2.5-D48NHL2-C-HW	None
113	USM-31110	None
114	UVQ-12/10-D48NB-C	UEE-12/12.5-D48NB-C
115	UVQ-12/10-D48N-C	UEE-12/12.5-D48N-C
116	UVQ-12/10-D48P-C	UEE-12/12.5-D48P-C
117	UVQ-15/7-D48NB-C	None
118	UVQ-15/7-D48N-C	None
119	UVQ-15/7-D48PB-C	None
120	UVQ-15/7-D48P-C	None
121	UVQ-18/6-D48N-C	None
122	UVQ-18/6-D48PB-C	None
123	UVQ-5/20-D24NB-C	None
124	UVQ-5/20-D24N-C	None
125	UVQ-5/20-D48NB-C	UEE-5/30-D48NB-C
126	UWR-1.5/6000-D48AHL2-Y	None
127	UWR-5/3000-D24AT-C	None
128	UWR-96/100-D48A-C	None
129	VR111B080CE-6C	None
130	VR111B080CU-5C	None
131	VR111B150CU-9C	None
132	VR111B150CU-C	None



For Document Number:
MPS00001269

Discontinued Part Numbers List (133 Part Numbers)

#	Murata Part Number	Recommended Replacement
133	VR11FB080CE-C	None