

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
24502BVA	10/06/2015	10/12/2015	10/06/2016	HM1-6514B
50838B	10/06/2015	10/12/2015	10/06/2016	None
5962-0620701Q3A	10/06/2015	10/12/2015	10/06/2016	None
5962-0620702Q3A	10/06/2015	10/12/2015	10/06/2016	None
5962-0620703Q2A	10/06/2015	10/12/2015	10/06/2016	None
5962-0620704Q2A	10/06/2015	10/12/2015	10/06/2016	None
5962-0620705Q3A	10/06/2015	10/12/2015	10/06/2016	None
5962-0620706Q3A	10/06/2015	10/12/2015	10/06/2016	None
5962-0620707Q2A	10/06/2015	10/12/2015	10/06/2016	None
5962-0620708Q2A	10/06/2015	10/12/2015	10/06/2016	None
5962-0623501QPC	10/06/2015	10/12/2015	10/06/2016	None
5962-0623502QPC	10/06/2015	10/12/2015	10/06/2016	None
5962-0623601QPC	10/06/2015	10/12/2015	10/06/2016	None
5962-0623602QPC	10/06/2015	10/12/2015	10/06/2016	None
5962-0625501QXC	10/06/2015	10/12/2015	10/06/2016	None
5962-8778301EA	10/06/2015	10/12/2015	10/06/2016	None
5962-8869002JA	10/06/2015	10/12/2015	10/06/2016	HM1-6642B
5962-8950201GC	10/06/2015	10/12/2015	10/06/2016	None
5962-8954801GC	10/06/2015	10/12/2015	10/06/2016	None
5962-8954801GCS2035	10/06/2015	10/12/2015	10/06/2016	None
5962-89620012A	10/06/2015	10/12/2015	10/06/2016	None
5962-9051801MEA	10/06/2015	10/12/2015	10/06/2016	None
5962-9054901MQA	10/06/2015	10/12/2015	10/06/2016	None
5962-9467701M2A	10/06/2015	10/12/2015	10/06/2016	None
5962M95A0501QXA	10/06/2015	10/12/2015	10/06/2016	None
5962M95A0501QYA	10/06/2015	10/12/2015	10/06/2016	None
7800302GC	10/06/2015	10/12/2015	10/06/2016	HA2-2640-2
7800302PA	10/06/2015	10/12/2015	10/06/2016	HA7-2640-2
81006122A	10/06/2015	10/12/2015	10/06/2016	None
81006222A	10/06/2015	10/12/2015	10/06/2016	HI4-5051
ACTS373DMSR-02	10/06/2015	10/12/2015	10/06/2016	None
ACTS373KMSR-02	10/06/2015	10/12/2015	10/06/2016	None
CD4071BDMSR	10/06/2015	10/12/2015	10/06/2016	None
CD4071BHSR	10/06/2015	10/12/2015	10/06/2016	None
CD4071BKMSR	10/06/2015	10/12/2015	10/06/2016	None
CD4073BDNSR	10/06/2015	10/12/2015	10/06/2016	None
CD4073BHNSR	10/06/2015	10/12/2015	10/06/2016	None
CD4073BKNSR	10/06/2015	10/12/2015	10/06/2016	None
CD4098BDNSR	10/06/2015	10/12/2015	10/06/2016	None
CD4098BHNSR	10/06/2015	10/12/2015	10/06/2016	None
CD4098BKNSR	10/06/2015	10/12/2015	10/06/2016	None
CD4503BKNSR	10/06/2015	10/12/2015	10/06/2016	None
CDP68HC68T1E	10/06/2015	10/12/2015	10/06/2016	CDP68HC68T1EZ
CDP68HC68T1M	10/06/2015	10/12/2015	10/06/2016	CDP68HC68T1MZ
CDP68HC68T1M2	10/06/2015	10/12/2015	10/06/2016	CDP68HC68T1M2Z
CDP68HC68T1M296	10/06/2015	10/12/2015	10/06/2016	CDP68HC68T1M2Z96
CDP68HC68T1M96	10/06/2015	10/12/2015	10/06/2016	CDP68HC68T1MZ96
CDP68HC68T1W	10/06/2015	10/12/2015	10/06/2016	None
CP80C86-2	10/06/2015	10/12/2015	10/06/2016	None
CP82C37A-5	10/06/2015	10/12/2015	10/06/2016	IS82C37A
CP82C50A-5	10/06/2015	10/12/2015	10/06/2016	CS82C50A-5Z
CP82C50A-5Z	10/06/2015	10/12/2015	10/06/2016	CS82C50A-5Z
CP82C52	10/06/2015	10/12/2015	10/06/2016	CP82C52Z
CP82C54-10	10/06/2015	10/12/2015	10/06/2016	CP82C54-10Z
CP82C54-12	10/06/2015	10/12/2015	10/06/2016	CP82C54-12Z
CP82C55A-5	10/06/2015	10/12/2015	10/06/2016	CP82C55A-5Z
CP82C59A-12	10/06/2015	10/12/2015	10/06/2016	CP82C59A-12Z
CP82C88	10/06/2015	10/12/2015	10/06/2016	None
CP82C88Z	10/06/2015	10/12/2015	10/06/2016	None

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
CP82C89	10/06/2015	10/12/2015	10/06/2016	None
CP82C89Z	10/06/2015	10/12/2015	10/06/2016	None
CS82C37A	10/06/2015	10/12/2015	10/06/2016	IS82C37A
CS82C37A-1296	10/06/2015	10/12/2015	10/06/2016	IS82C37A
CS82C37AZ	10/06/2015	10/12/2015	10/06/2016	IS82C37A
CS82C54-1096	10/06/2015	10/12/2015	10/06/2016	CS82C54-10, CS82C54-10Z96
CS82C54-12	10/06/2015	10/12/2015	10/06/2016	CS82C54-12Z
CS82C5496	10/06/2015	10/12/2015	10/06/2016	CS82C54, CS82C54Z96
CS82C54R2499	10/06/2015	10/12/2015	10/06/2016	CS82C54, CS82C54Z
CS82C55A-5	10/06/2015	10/12/2015	10/06/2016	CS82C55A-5Z
CS82C55A-596	10/06/2015	10/12/2015	10/06/2016	CS82C55A-5Z96
CS82C55A96	10/06/2015	10/12/2015	10/06/2016	CS82C55A, CS82C55AZ96
CS82C55AR2499	10/06/2015	10/12/2015	10/06/2016	CS82C55A, CS82C55AZ
CS82C59A	10/06/2015	10/12/2015	10/06/2016	CS82C59AZ
CS82C59A-12	10/06/2015	10/12/2015	10/06/2016	CS82C59A-12Z
CS82C59A96	10/06/2015	10/12/2015	10/06/2016	CS82C59AZ96
CS82C84A	10/06/2015	10/12/2015	10/06/2016	CP82C84A, CP82C84AZ
CS82C84AZ	10/06/2015	10/12/2015	10/06/2016	CP82C84A, CP82C84AZ
CS82C84AZ96	10/06/2015	10/12/2015	10/06/2016	CP82C84A, CP82C84AZ
D2-81434-LR	10/06/2015	10/12/2015	10/06/2016	D2-81433-LR
DG403DYZ-TS2457	10/06/2015	10/06/2016	10/12/2016	DG403DYZ-T
DG407DYZ-TS2705	10/06/2015	10/03/2016	10/03/2017	DG407DYZ-T
DG408DVZ-TS2568	10/06/2015	10/12/2015	10/06/2016	DG408DVZ-T
EL1516AIYZ-T13	10/06/2015	10/12/2015	10/06/2016	None
EL1516AIYZ-T7	10/06/2015	10/12/2015	10/06/2016	None
EL1516ISZ-T13	10/06/2015	10/12/2015	10/06/2016	None
EL1516ISZ-T7	10/06/2015	10/12/2015	10/06/2016	None
EL1516IYZ-T13	10/06/2015	10/12/2015	10/06/2016	None
EL1516IYZ-T7	10/06/2015	10/12/2015	10/06/2016	None
EL2045CSZ	10/06/2015	10/12/2015	10/06/2016	None
EL2045CSZ-T13	10/06/2015	10/12/2015	10/06/2016	None
EL2045CSZ-T7	10/06/2015	10/12/2015	10/06/2016	None
EL2227CSZ	10/06/2015	10/12/2015	10/06/2016	None
EL2227CSZ-T13	10/06/2015	10/12/2015	10/06/2016	None
EL2227CSZ-T7	10/06/2015	10/12/2015	10/06/2016	None
EL2227CYZ	10/06/2015	10/12/2015	10/06/2016	None
EL2227CYZ-T13	10/06/2015	10/12/2015	10/06/2016	None
EL2227CYZ-T7	10/06/2015	10/12/2015	10/06/2016	None
EL2250CSZ	10/06/2015	10/12/2015	10/06/2016	None
EL2250CSZ-T13	10/06/2015	10/12/2015	10/06/2016	None
EL2250CSZ-T7	10/06/2015	10/12/2015	10/06/2016	None
EL2276CSZ	10/06/2015	10/12/2015	10/06/2016	None
EL2276CSZ-T13	10/06/2015	10/12/2015	10/06/2016	None
EL2276CSZ-T7	10/06/2015	10/12/2015	10/06/2016	None
EL4544IGZS2729	10/06/2015	10/12/2015	10/06/2016	EL4544IGZ
EL5001IREZ	10/06/2015	10/12/2015	10/06/2016	None
EL5001IREZ-T13	10/06/2015	10/12/2015	10/06/2016	None
EL5001IREZ-T7	10/06/2015	10/12/2015	10/06/2016	None
EL5106ISZ	10/06/2015	10/12/2015	10/06/2016	None
EL5106ISZ-T13	10/06/2015	10/12/2015	10/06/2016	None
EL5106ISZ-T7	10/06/2015	10/12/2015	10/06/2016	None
EL5108ISZ	10/06/2015	10/12/2015	10/06/2016	None
EL5108ISZ-T13	10/06/2015	10/12/2015	10/06/2016	None
EL5108ISZ-T7	10/06/2015	10/12/2015	10/06/2016	None
EL5108IWZ-T7	10/06/2015	10/12/2015	10/06/2016	None
EL5111IYEZ	10/06/2015	10/12/2015	10/06/2016	None
EL5111IYEZ-T13	10/06/2015	10/12/2015	10/06/2016	None
EL5111IYEZ-T7	10/06/2015	10/12/2015	10/06/2016	None
EL5120TIWZ-T7	10/06/2015	10/12/2015	10/06/2016	None

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
EL5123CYZ	10/06/2015	10/12/2015	10/06/2016	None
EL5123CYZ-T13	10/06/2015	10/12/2015	10/06/2016	None
EL5123CYZ-T7	10/06/2015	10/12/2015	10/06/2016	None
EL5127CYZ	10/06/2015	10/12/2015	10/06/2016	None
EL5127CYZ-T13	10/06/2015	10/12/2015	10/06/2016	None
EL5127CYZ-T7	10/06/2015	10/12/2015	10/06/2016	None
EL5162IWZ-T7	10/06/2015	10/12/2015	10/06/2016	EL5163IWZ-T7
EL5162IWZ-T7A	10/06/2015	10/12/2015	10/06/2016	EL5163IWZ-T7A
EL5163ICZ-T7	10/06/2015	10/12/2015	10/06/2016	EL5163IWZ-T7
EL5163ICZ-T7A	10/06/2015	10/12/2015	10/06/2016	EL5163IWZ-T7A
EL5173IYZ	10/06/2015	10/12/2015	10/06/2016	EL5173ISZ
EL5173IYZ-T13	10/06/2015	10/12/2015	10/06/2016	EL5173ISZ-T13
EL5173IYZ-T7	10/06/2015	10/12/2015	10/06/2016	EL5173ISZ-T7
EL5176IYZ	10/06/2015	10/12/2015	10/06/2016	EL5171ISZ
EL5176IYZ-T13	10/06/2015	10/12/2015	10/06/2016	EL5171ISZ-T13
EL5176IYZ-T7	10/06/2015	10/12/2015	10/06/2016	EL5171ISZ-T7
EL5178ISZ	10/06/2015	10/12/2015	10/06/2016	EL5174ISZ
EL5178ISZ-T13	10/06/2015	10/12/2015	10/06/2016	EL5174ISZ-T13
EL5178ISZ-T7	10/06/2015	10/12/2015	10/06/2016	EL5174ISZ-T7
EL5178IYZ	10/06/2015	10/12/2015	10/06/2016	EL5174ISZ
EL5178IYZ-T13	10/06/2015	10/12/2015	10/06/2016	EL5174ISZ-T13
EL5178IYZ-T7	10/06/2015	10/12/2015	10/06/2016	EL5174ISZ-T7
EL5205IYZ	10/06/2015	10/12/2015	10/06/2016	None
EL5205IYZ-T13	10/06/2015	10/12/2015	10/06/2016	None
EL5205IYZ-T7	10/06/2015	10/12/2015	10/06/2016	None
EL5211IYEZ	10/06/2015	10/12/2015	10/06/2016	None
EL5211IYEZ-T13	10/06/2015	10/12/2015	10/06/2016	None
EL5211IYEZ-T7	10/06/2015	10/12/2015	10/06/2016	None
EL5211TILZ-T13	10/06/2015	10/12/2015	10/06/2016	None
EL5211TIYEZ	10/06/2015	10/12/2015	10/06/2016	None
EL5211TIYEZ-T13	10/06/2015	10/12/2015	10/06/2016	None
EL5211TIYEZ-T7	10/06/2015	10/12/2015	10/06/2016	None
EL5225IRZ	10/06/2015	10/12/2015	10/06/2016	None
EL5225IRZ-T13	10/06/2015	10/12/2015	10/06/2016	None
EL5225IRZ-T7	10/06/2015	10/12/2015	10/06/2016	None
EL5227CLZ	10/06/2015	10/12/2015	10/06/2016	None
EL5227CLZ-T13	10/06/2015	10/12/2015	10/06/2016	None
EL5227CLZ-T7	10/06/2015	10/12/2015	10/06/2016	None
EL5227CRZ	10/06/2015	10/12/2015	10/06/2016	None
EL5227CRZ-T13	10/06/2015	10/12/2015	10/06/2016	None
EL5227CRZ-T7	10/06/2015	10/12/2015	10/06/2016	None
EL5236ISZ	10/06/2015	10/12/2015	10/06/2016	None
EL5236ISZ-T13	10/06/2015	10/12/2015	10/06/2016	None
EL5236ISZ-T7	10/06/2015	10/12/2015	10/06/2016	None
EL5236IYZ	10/06/2015	10/12/2015	10/06/2016	None
EL5236IYZ-T13	10/06/2015	10/12/2015	10/06/2016	None
EL5236IYZ-T7	10/06/2015	10/12/2015	10/06/2016	None
EL5237IYZ	10/06/2015	10/12/2015	10/06/2016	None
EL5237IYZ-T13	10/06/2015	10/12/2015	10/06/2016	None
EL5237IYZ-T7	10/06/2015	10/12/2015	10/06/2016	None
EL5260IYZ	10/06/2015	10/12/2015	10/06/2016	None
EL5260IYZ-T13	10/06/2015	10/12/2015	10/06/2016	None
EL5260IYZ-T7	10/06/2015	10/12/2015	10/06/2016	None
EL5261ISZ	10/06/2015	10/12/2015	10/06/2016	None
EL5261ISZ-T13	10/06/2015	10/12/2015	10/06/2016	None
EL5261ISZ-T7	10/06/2015	10/12/2015	10/06/2016	None
EL5304IUZ	10/06/2015	10/12/2015	10/06/2016	None
EL5304IUZ-T13	10/06/2015	10/12/2015	10/06/2016	None
EL5304IUZ-T7	10/06/2015	10/12/2015	10/06/2016	None

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
EL5306ISZ	10/06/2015	10/12/2015	10/06/2016	EL5306IUZ
EL5306ISZ-T13	10/06/2015	10/12/2015	10/06/2016	EL5306IUZ-T13
EL5306ISZ-T7	10/06/2015	10/12/2015	10/06/2016	EL5306IUZ-T7
EL5306IUZ-T7S2490	10/06/2015	10/12/2015	10/06/2016	EL5306IUZ-T7
EL5325AIREZ	10/06/2015	10/12/2015	10/06/2016	None
EL5325AIREZ-T13	10/06/2015	10/12/2015	10/06/2016	None
EL5325AIREZ-T7	10/06/2015	10/12/2015	10/06/2016	None
EL5327CLZ	10/06/2015	10/12/2015	10/06/2016	None
EL5327CLZ-T13	10/06/2015	10/12/2015	10/06/2016	None
EL5327CLZ-T7	10/06/2015	10/12/2015	10/06/2016	None
EL5327CRZ	10/06/2015	10/12/2015	10/06/2016	None
EL5327CRZ-T13	10/06/2015	10/12/2015	10/06/2016	None
EL5327CRZ-T7	10/06/2015	10/12/2015	10/06/2016	None
EL5360ISZ	10/06/2015	10/12/2015	10/06/2016	None
EL5360ISZ-T13	10/06/2015	10/12/2015	10/06/2016	None
EL5360ISZ-T7	10/06/2015	10/12/2015	10/06/2016	None
EL5360IUZ	10/06/2015	10/12/2015	10/06/2016	None
EL5360IUZ-T13	10/06/2015	10/12/2015	10/06/2016	None
EL5360IUZ-T7	10/06/2015	10/12/2015	10/06/2016	None
EL5370IUZ	10/06/2015	10/12/2015	10/06/2016	None
EL5370IUZ-T13	10/06/2015	10/12/2015	10/06/2016	None
EL5370IUZ-T7	10/06/2015	10/12/2015	10/06/2016	None
EL5371IUZ	10/06/2015	10/12/2015	10/06/2016	EL5373IUZ
EL5371IUZ-T13	10/06/2015	10/12/2015	10/06/2016	EL5373IUZ-T13
EL5371IUZ-T7	10/06/2015	10/12/2015	10/06/2016	EL5373IUZ-T7
EL5372IUZ	10/06/2015	10/12/2015	10/06/2016	EL5375IUZ
EL5372IUZ-T13	10/06/2015	10/12/2015	10/06/2016	EL5375IUZ-T13
EL5372IUZ-T7	10/06/2015	10/12/2015	10/06/2016	EL5375IUZ-T7
EL5374IUZ	10/06/2015	10/12/2015	10/06/2016	EL5373IUZ
EL5374IUZ-T13	10/06/2015	10/12/2015	10/06/2016	EL5373IUZ-T13
EL5374IUZ-T7	10/06/2015	10/12/2015	10/06/2016	EL5373IUZ-T7
EL5411IREZ	10/06/2015	10/12/2015	10/06/2016	None
EL5411IREZ-T13	10/06/2015	10/12/2015	10/06/2016	None
EL5411IREZ-T13R5379	10/06/2015	10/12/2015	10/06/2016	None
EL5411IREZ-T7	10/06/2015	10/12/2015	10/06/2016	None
EL5411IREZ-T7R5379	10/06/2015	10/12/2015	10/06/2016	None
EL5411IRZ	10/06/2015	10/12/2015	10/06/2016	None
EL5411IRZ-T13	10/06/2015	10/12/2015	10/06/2016	None
EL5411IRZ-T7	10/06/2015	10/12/2015	10/06/2016	None
EL5411TILZ	10/06/2015	10/12/2015	10/06/2016	None
EL5411TILZ-T13	10/06/2015	10/12/2015	10/06/2016	None
EL5411TILZ-T7	10/06/2015	10/12/2015	10/06/2016	None
EL5411TIREZ	10/06/2015	10/12/2015	10/06/2016	None
EL5411TIREZ-T13	10/06/2015	10/12/2015	10/06/2016	None
EL5411TIREZ-T7	10/06/2015	10/12/2015	10/06/2016	None
EL5420CLZ	10/06/2015	10/12/2015	10/06/2016	None
EL5420CLZ-T13	10/06/2015	10/12/2015	10/06/2016	None
EL5420CLZ-T7	10/06/2015	10/12/2015	10/06/2016	None
EL5420TILZ	10/06/2015	10/12/2015	10/06/2016	None
EL5420TILZ-T13	10/06/2015	10/12/2015	10/06/2016	None
EL5420TILZ-T7	10/06/2015	10/12/2015	10/06/2016	None
EL5420TISZ	10/06/2015	10/12/2015	10/06/2016	None
EL5420TISZ-T13	10/06/2015	10/12/2015	10/06/2016	None
EL5420TISZ-T7	10/06/2015	10/12/2015	10/06/2016	None
EL5421CYZ	10/06/2015	10/12/2015	10/06/2016	None
EL5421CYZ-T13	10/06/2015	10/12/2015	10/06/2016	None
EL5421CYZ-T7	10/06/2015	10/12/2015	10/06/2016	None
EL5625ILZ	10/06/2015	10/12/2015	10/06/2016	None
EL5625ILZ-T13	10/06/2015	10/12/2015	10/06/2016	None

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
EL7104W	10/06/2015	10/12/2015	10/06/2016	None
EL7154CNZ	10/06/2015	10/12/2015	10/06/2016	EL7154CSZ
EL7156CNZ	10/06/2015	10/12/2015	10/06/2016	EL7156CSZ
EL7158W	10/06/2015	10/12/2015	10/06/2016	None
EL7182CN	10/06/2015	10/12/2015	10/06/2016	None
EL7182CSZ	10/06/2015	10/12/2015	10/06/2016	None
EL7182CSZ-T13	10/06/2015	10/12/2015	10/06/2016	None
EL7182CSZ-T7	10/06/2015	10/12/2015	10/06/2016	None
EL7222CSZE9044	10/06/2015	10/12/2015	10/06/2016	EL7222CSZ
EL7222CSZE9044-T7	10/06/2015	10/12/2015	10/06/2016	EL7222CSZ
EL7222CW	10/06/2015	10/12/2015	10/06/2016	None
EL7232CN	10/06/2015	10/12/2015	10/06/2016	EL7232CNZ
EL7252CN	10/06/2015	10/12/2015	10/06/2016	EL7252CSZ
EL7457CD	10/06/2015	10/12/2015	10/06/2016	None
EL7515IY-T7	10/06/2015	10/12/2015	10/06/2016	None
EL7515IYZ	10/06/2015	10/12/2015	10/06/2016	None
EL7515IYZS2695	10/06/2015	10/12/2015	10/06/2016	None
EL7515IYZ-T13	10/06/2015	10/12/2015	10/06/2016	None
EL7515IYZ-T13S2695	10/06/2015	10/12/2015	10/06/2016	None
EL7515IYZ-T7	10/06/2015	10/12/2015	10/06/2016	None
EL7515IYZ-T7S2695	10/06/2015	10/12/2015	10/06/2016	None
EL7531IY	10/06/2015	10/12/2015	10/06/2016	None
EL7531IY-T13	10/06/2015	10/12/2015	10/06/2016	None
EL7531IYZ	10/06/2015	10/12/2015	10/06/2016	None
EL7531IYZ-T13	10/06/2015	10/12/2015	10/06/2016	None
EL7531IYZ-T7	10/06/2015	10/12/2015	10/06/2016	None
EL7532IY-T13	10/06/2015	10/12/2015	10/06/2016	EL7532IYZ-T13
EL7535IY-T13	10/06/2015	10/12/2015	10/06/2016	EL7535IYZ-T13
EL7535IY-T7	10/06/2015	10/12/2015	10/06/2016	EL7535IYZ-T7
EL7536IYZS2695	10/06/2015	10/12/2015	10/06/2016	None
EL7536IYZ-T13S2695	10/06/2015	10/12/2015	10/06/2016	None
EL7536IYZ-T7S2695	10/06/2015	10/12/2015	10/06/2016	None
EL7563CREZ	10/06/2015	10/12/2015	10/06/2016	EL7554IREZ
EL7563CREZ-T13	10/06/2015	10/12/2015	10/06/2016	EL7554IREZ-T13
EL7563CREZ-T13S2705	10/06/2015	10/03/2016	10/03/2017	EL7554IREZ-T13
EL7563CREZ-T7	10/06/2015	10/12/2015	10/06/2016	EL7554IREZ-T7
EL7564CREZ	10/06/2015	10/12/2015	10/06/2016	ISL8024IRTAJZ-T
EL7564CREZ-T13	10/06/2015	10/12/2015	10/06/2016	ISL8024IRTAJZ-T
EL7564CREZ-T7	10/06/2015	10/12/2015	10/06/2016	ISL8024IRTAJZ-T
EL7581IREZ	10/06/2015	10/12/2015	10/06/2016	None
EL7581IREZ-T13	10/06/2015	10/12/2015	10/06/2016	None
EL7581IREZ-T7	10/06/2015	10/12/2015	10/06/2016	None
EL7630IWTZ-T7	10/06/2015	10/12/2015	10/06/2016	None
EL7630IWTZ-T7A	10/06/2015	10/12/2015	10/06/2016	None
EL7640AILTZ	10/06/2015	10/12/2015	10/06/2016	None
EL7640AILTZ-T13	10/06/2015	10/12/2015	10/06/2016	None
EL7640AILTZ-T7	10/06/2015	10/12/2015	10/06/2016	None
EL7641AILTZ	10/06/2015	10/12/2015	10/06/2016	None
EL7641AILTZ-T13	10/06/2015	10/12/2015	10/06/2016	None
EL7641AILTZ-T7	10/06/2015	10/12/2015	10/06/2016	None
EL7642AILTZ	10/06/2015	10/12/2015	10/06/2016	None
EL7642AILTZ-T13	10/06/2015	10/12/2015	10/06/2016	None
EL7642AILTZ-T7	10/06/2015	10/12/2015	10/06/2016	None
EL8108ILZ	10/06/2015	10/12/2015	10/06/2016	None
EL8108ILZ-T13	10/06/2015	10/12/2015	10/06/2016	None
EL8108ILZ-T7	10/06/2015	10/12/2015	10/06/2016	None
EL8108ISZ	10/06/2015	10/12/2015	10/06/2016	None
EL8108ISZ-T13	10/06/2015	10/12/2015	10/06/2016	None
EL8108ISZ-T7	10/06/2015	10/12/2015	10/06/2016	None

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
EL8171FSZ	10/06/2015	10/12/2015	10/06/2016	EL8170FSZ-T7
EL8171FSZ-T7	10/06/2015	10/12/2015	10/06/2016	EL8170FSZ-T7
EL8173FSZ	10/06/2015	10/12/2015	10/06/2016	EL8170FSZ-T7
EL8173FSZ-T7	10/06/2015	10/12/2015	10/06/2016	EL8170FSZ-T7
EL8200IYZ	10/06/2015	10/12/2015	10/06/2016	EL8201ISZ
EL8200IYZ-T13	10/06/2015	10/12/2015	10/06/2016	EL8201ISZ-T13
EL8200IYZ-T7	10/06/2015	10/12/2015	10/06/2016	EL8201ISZ-T7
EL8202IYZ	10/06/2015	10/12/2015	10/06/2016	None
EL8202IYZ-T13	10/06/2015	10/12/2015	10/06/2016	None
EL8202IYZ-T7	10/06/2015	10/12/2015	10/06/2016	None
EL8203ISZ	10/06/2015	10/12/2015	10/06/2016	None
EL8203ISZ-T13	10/06/2015	10/12/2015	10/06/2016	None
EL8203ISZ-T7	10/06/2015	10/12/2015	10/06/2016	None
EL8401ISZ	10/06/2015	10/12/2015	10/06/2016	None
EL8401ISZ-T13	10/06/2015	10/12/2015	10/06/2016	None
EL8401ISZ-T7	10/06/2015	10/12/2015	10/06/2016	None
EL8401IUZ	10/06/2015	10/12/2015	10/06/2016	None
EL8401IUZ-T13	10/06/2015	10/12/2015	10/06/2016	None
EL8401IUZ-T7	10/06/2015	10/12/2015	10/06/2016	None
EL8403ISZ	10/06/2015	10/12/2015	10/06/2016	None
EL8403ISZ-T13	10/06/2015	10/12/2015	10/06/2016	None
EL8403ISZ-T7	10/06/2015	10/12/2015	10/06/2016	None
EL8403IUZ	10/06/2015	10/12/2015	10/06/2016	None
EL8403IUZ-T13	10/06/2015	10/12/2015	10/06/2016	None
EL8403IUZ-T7	10/06/2015	10/12/2015	10/06/2016	None
HA0-2539B5454-6	10/06/2015	10/12/2015	10/06/2016	None
HA0-2625B5454-6	10/06/2015	10/12/2015	10/06/2016	None
HA0-5162B5454-6	10/06/2015	10/12/2015	10/06/2016	None
HA1-2400/883	10/06/2015	10/12/2015	10/06/2016	None
HA1-2420-2	10/06/2015	10/12/2015	10/06/2016	None
HA1-5320-5	10/06/2015	10/12/2015	10/06/2016	HA1-5320-2
HA1-5330-5	10/06/2015	10/12/2015	10/06/2016	None
HA2-5033-2	10/06/2015	10/12/2015	10/06/2016	None
HA2-5127/883	10/06/2015	10/12/2015	10/06/2016	None
HA3-5020-5Z	10/06/2015	10/12/2015	10/06/2016	HA9P5020-5Z, HA9P5020-5ZX96
HA4344BCBZ	10/06/2015	10/12/2015	10/06/2016	None
HA4344BCBZ96	10/06/2015	10/12/2015	10/06/2016	None
HA4600CPZ	10/06/2015	10/12/2015	10/06/2016	HA4600CBZ, HA4600CHZ96
HA5023IPZ	10/06/2015	10/12/2015	10/06/2016	HA5023IBZ
HA5024IBZ	10/06/2015	10/12/2015	10/06/2016	HA5023IBZ
HA5024IBZ96	10/06/2015	10/12/2015	10/06/2016	HA5023IBZ96
HA5024IPZ	10/06/2015	10/12/2015	10/06/2016	HA5023IBZ
HA7-2510/883	10/06/2015	10/12/2015	10/06/2016	None
HA7-2510/883S2035	10/06/2015	10/12/2015	10/06/2016	None
HA7-5033R5389	10/06/2015	10/12/2015	10/06/2016	None
HAA0-50782R3562	10/06/2015	10/12/2015	10/06/2016	None
HAA0-51043R4192	10/06/2015	10/12/2015	10/06/2016	None
HAA0-51044R4193	10/06/2015	10/12/2015	10/06/2016	None
HAA0-51045R4194	10/06/2015	10/12/2015	10/06/2016	None
HAA0-51150S2677	10/06/2015	10/12/2015	10/06/2016	None
HAA0-52038R4488	10/06/2015	10/12/2015	10/06/2016	None
HAA4-50690R5131	10/06/2015	10/12/2015	10/06/2016	None
HAA-50945R4507	10/06/2015	10/12/2015	10/06/2016	None
HAA-50946R4508	10/06/2015	10/12/2015	10/06/2016	None
HAA-50947R4033	10/06/2015	10/12/2015	10/06/2016	None
HAA-51540AS2571	10/06/2015	10/12/2015	10/06/2016	None
HAA-51541S2571	10/06/2015	10/12/2015	10/06/2016	None
HAA-51543S2571	10/06/2015	10/12/2015	10/06/2016	None
HAA-52471R4911	10/06/2015	10/12/2015	10/06/2016	None

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
HAA-52643S2571	10/06/2015	10/12/2015	10/06/2016	None
HAA-52666S2571	10/06/2015	10/12/2015	10/06/2016	None
HAA-52741S2571	10/06/2015	10/12/2015	10/06/2016	None
HAA-52742S2571	10/06/2015	10/12/2015	10/06/2016	None
HAA-52760S2571	10/06/2015	10/12/2015	10/06/2016	None
HAA-52900S2571	10/06/2015	10/12/2015	10/06/2016	None
HAA-53103R5187	10/06/2015	10/12/2015	10/06/2016	None
HAA-53108S2571	10/06/2015	10/12/2015	10/06/2016	None
HAA-53411BS2571	10/06/2015	10/12/2015	10/06/2016	None
HAA9-51150R4551	10/06/2015	10/12/2015	10/06/2016	None
HAA9-51150R4551/RAD	10/06/2015	10/12/2015	10/06/2016	None
HAA9-51150S2677	10/06/2015	10/12/2015	10/06/2016	None
HAA9-51150S2677/DPA	10/06/2015	10/12/2015	10/06/2016	None
HAA9Q-53721ZR5141	10/06/2015	10/12/2015	10/06/2016	None
HAA9Q-53721ZR5141-T	10/06/2015	10/12/2015	10/06/2016	None
HC4P5504BZR4741-104	10/06/2015	10/12/2015	10/06/2016	None
HC5503CBZ	10/06/2015	10/12/2015	10/06/2016	HC5503PRCBZ
HC5503CBZ96	10/06/2015	10/12/2015	10/06/2016	HC5503PRCBZ96
HC5503PRIBZ	10/06/2015	10/12/2015	10/06/2016	HC5503PRCBZ
HC5503PRIBZ96	10/06/2015	10/12/2015	10/06/2016	HC5503PRCBZ96
HC5503TCBZ	10/06/2015	10/12/2015	10/06/2016	HC5503PRCBZ
HC5503TCBZ96	10/06/2015	10/12/2015	10/06/2016	HC5503PRCBZ96
HC55120CMZ	10/06/2015	10/12/2015	10/06/2016	None
HC55121IMZ	10/06/2015	10/12/2015	10/06/2016	None
HC55130IMZ	10/06/2015	10/12/2015	10/06/2016	None
HC55140IMZ	10/06/2015	10/12/2015	10/06/2016	None
HC55142IMZ	10/06/2015	10/12/2015	10/06/2016	None
HC55142IMZ96	10/06/2015	10/12/2015	10/06/2016	None
HC55150CMZ	10/06/2015	10/12/2015	10/06/2016	None
HC5515CMZ	10/06/2015	10/12/2015	10/06/2016	None
HD0-6402RB6092-6	10/06/2015	10/12/2015	10/06/2016	None
HD0-82C54B6092-6	10/06/2015	10/12/2015	10/06/2016	None
HD1-4702/883	10/06/2015	10/12/2015	10/06/2016	None
HD3-4702-9	10/06/2015	10/12/2015	10/06/2016	None
HD3-4702-9Z	10/06/2015	10/12/2015	10/06/2016	None
HD3-6402R-9	10/06/2015	10/12/2015	10/06/2016	None
HD3-6402R-9Z	10/06/2015	10/12/2015	10/06/2016	None
HD3-6408-9	10/06/2015	10/12/2015	10/06/2016	HD3-6408-9Z
HD9P6409-9	10/06/2015	10/12/2015	10/06/2016	None
HFA1110IBZ	10/06/2015	10/12/2015	10/06/2016	HFA1112IBZ
HFA1112IPZ	10/06/2015	10/12/2015	10/06/2016	HFA1112IBZ
HFA1113IBZ	10/06/2015	10/12/2015	10/06/2016	None
HFA1113IBZ96	10/06/2015	10/12/2015	10/06/2016	None
HFA1130W	10/06/2015	10/12/2015	10/06/2016	None
HFA1145IBZ	10/06/2015	10/12/2015	10/06/2016	None
HFA1145IPZ	10/06/2015	10/12/2015	10/06/2016	None
HFA1412IBZ	10/06/2015	10/12/2015	10/06/2016	None
HFA1412IPZ	10/06/2015	10/12/2015	10/06/2016	None
HFA3046BZ96	10/06/2015	10/12/2015	10/06/2016	HFA3046BZ
HFA3096W	10/06/2015	10/12/2015	10/06/2016	None
HFA3101W	10/06/2015	10/12/2015	10/06/2016	None
HFA3127W	10/06/2015	10/12/2015	10/06/2016	None
HFA3128BZ	10/06/2015	10/12/2015	10/06/2016	None
HFA3128BZ96	10/06/2015	10/12/2015	10/06/2016	None
HFA3128RZ	10/06/2015	10/12/2015	10/06/2016	None
HFA3128RZ96	10/06/2015	10/12/2015	10/06/2016	None
HFA3128W	10/06/2015	10/12/2015	10/06/2016	None
HFA3135W	10/06/2015	10/12/2015	10/06/2016	None
HIO-0303B5454-6	10/06/2015	10/12/2015	10/06/2016	None

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
HI0-1818AB5454-6	10/06/2015	10/12/2015	10/06/2016	None
HI1-0390-2	10/06/2015	10/12/2015	10/06/2016	None
HI1-0507-2	10/06/2015	10/12/2015	10/06/2016	None
HI1-1818A-2	10/06/2015	10/12/2015	10/06/2016	None
HI1-5047-2	10/06/2015	10/12/2015	10/06/2016	None
HI1-565AJD-5	10/06/2015	10/12/2015	10/06/2016	None
HI2-0200/883	10/06/2015	10/12/2015	10/06/2016	None
HI3-0200-5Z	10/06/2015	10/12/2015	10/06/2016	None
HI4P0201-5Z	10/06/2015	10/12/2015	10/06/2016	None
HI4P0549-5Z	10/06/2015	10/12/2015	10/06/2016	None
HI5628/6INZ	10/06/2015	10/12/2015	10/06/2016	None
HI5628INZ	10/06/2015	10/12/2015	10/06/2016	None
HI5714/4CBZ	10/06/2015	10/12/2015	10/06/2016	None
HI5714/7CBZ-T	10/06/2015	10/12/2015	10/06/2016	None
HI5714/W	10/06/2015	10/12/2015	10/06/2016	None
HI5728/6INZ	10/06/2015	10/12/2015	10/06/2016	None
HI5728INZ	10/06/2015	10/12/2015	10/06/2016	None
HI5728INZ-T	10/06/2015	10/12/2015	10/06/2016	None
HI5731BIPZ	10/06/2015	10/12/2015	10/06/2016	HI5731BIBZ
HI5731W	10/06/2015	10/12/2015	10/06/2016	None
HI5735KCBZ	10/06/2015	10/12/2015	10/06/2016	None
HI5741BIBZ	10/06/2015	10/12/2015	10/06/2016	None
HI5741BIBZ-T	10/06/2015	10/12/2015	10/06/2016	None
HI5746KCAZ	10/06/2015	10/12/2015	10/06/2016	None
HI5746KCBZ	10/06/2015	10/12/2015	10/06/2016	None
HI5746KCBZ-T	10/06/2015	10/12/2015	10/06/2016	None
HI5762/6INZ	10/06/2015	10/12/2015	10/06/2016	None
HI5766KCAZ	10/06/2015	10/12/2015	10/06/2016	None
HI5766KCBZ	10/06/2015	10/12/2015	10/06/2016	None
HI5767/2CAZ	10/06/2015	10/12/2015	10/06/2016	None
HI5767/2CBZ	10/06/2015	10/12/2015	10/06/2016	None
HI5767/2IAZ	10/06/2015	10/12/2015	10/06/2016	None
HI5767/4CAZ	10/06/2015	10/12/2015	10/06/2016	None
HI5767/4CBZ	10/06/2015	10/12/2015	10/06/2016	None
HI5767/4CBZ-T	10/06/2015	10/12/2015	10/06/2016	None
HI5767/6CAZ	10/06/2015	10/12/2015	10/06/2016	None
HI5767/6CBZ	10/06/2015	10/12/2015	10/06/2016	None
HI5767/6CBZ-T	10/06/2015	10/12/2015	10/06/2016	None
HI5767/6IBZ	10/06/2015	10/12/2015	10/06/2016	None
HI5805BIBZ	10/06/2015	10/12/2015	10/06/2016	None
HI9P0509-5Z	10/06/2015	10/12/2015	10/06/2016	None
HIN207CAZ	10/06/2015	10/12/2015	10/06/2016	HIN207ECAZ
HIN207CAZ-T	10/06/2015	10/12/2015	10/06/2016	HIN207ECAZ-T
HIN208CBZ	10/06/2015	10/12/2015	10/06/2016	HIN208ECBZ
HIN208CBZ-T	10/06/2015	10/12/2015	10/06/2016	HIN208ECBZ-T
HIN232EIVZ	10/06/2015	10/12/2015	10/06/2016	HIN232ECAZ
HIN232EIVZ-T	10/06/2015	10/12/2015	10/06/2016	HIN232ECAZ-T
HIN236CBZ	10/06/2015	10/12/2015	10/06/2016	ICL3243ECBZ
HIN237CBZ	10/06/2015	10/12/2015	10/06/2016	ICL3243ECBZ
HIN237CBZ-T	10/06/2015	10/12/2015	10/06/2016	ICL3243ECBZ
HIN238CPZ	10/06/2015	10/12/2015	10/06/2016	HIN238CBZ
HIN240CNZ	10/06/2015	10/12/2015	10/06/2016	None
HIN240CNZ-T	10/06/2015	10/12/2015	10/06/2016	None
HIN241CAZ	10/06/2015	10/12/2015	10/06/2016	None
HIN241CBZ	10/06/2015	10/12/2015	10/06/2016	None
HIN241CBZ-T	10/06/2015	10/12/2015	10/06/2016	None
HIN241IBZ	10/06/2015	10/12/2015	10/06/2016	None
HIP1011ACBZA	10/06/2015	10/12/2015	10/06/2016	None
HIP1011ACBZA-T	10/06/2015	10/12/2015	10/06/2016	None

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
HIP1011BCBZA	10/06/2015	10/12/2015	10/06/2016	None
HIP1011BCBZA-T	10/06/2015	10/12/2015	10/06/2016	None
HIP1011CBZA	10/06/2015	10/12/2015	10/06/2016	None
HIP1011CBZA-T	10/06/2015	10/12/2015	10/06/2016	None
HIP1011CBZA-TS2490A	10/06/2015	10/12/2015	10/06/2016	None
HIP1011CBZA-TS2568	10/06/2015	10/12/2015	10/06/2016	None
HIP1011DCAZA	10/06/2015	10/12/2015	10/06/2016	None
HIP1011DCAZA-T	10/06/2015	10/12/2015	10/06/2016	None
HIP1011ECAZA	10/06/2015	10/12/2015	10/06/2016	None
HIP1011ECAZA-T	10/06/2015	10/12/2015	10/06/2016	None
HIP1012ACBZA	10/06/2015	10/12/2015	10/06/2016	None
HIP1012ACBZAS2695	10/06/2015	10/12/2015	10/06/2016	None
HIP1012ACBZA-T	10/06/2015	10/12/2015	10/06/2016	None
HIP1012ACBZA-TS2490A	10/06/2015	10/12/2015	10/06/2016	None
HIP1012ACBZA-TS2490S	10/06/2015	10/12/2015	10/06/2016	None
HIP1012ACBZA-TS2568	10/06/2015	10/12/2015	10/06/2016	None
HIP1012ACBZA-TS2695	10/06/2015	10/12/2015	10/06/2016	None
HIP1013CBZA	10/06/2015	10/12/2015	10/06/2016	None
HIP1013CBZA-T	10/06/2015	10/12/2015	10/06/2016	None
HIP2100IB	10/06/2015	10/12/2015	10/06/2016	HIP2100IBZ
HIP2100IBT	10/06/2015	10/12/2015	10/06/2016	HIP2100IBZT
HIP2100IBZTS2038	10/06/2015	10/12/2015	10/06/2016	HIP2100IBZT
HIP2100IR4Z	10/06/2015	10/12/2015	10/06/2016	HIP2100IRZ
HIP2100IR4ZT	10/06/2015	10/12/2015	10/06/2016	HIP2100IRZT
HIP2100IY	10/06/2015	10/12/2015	10/06/2016	None
HIP2101EIB	10/06/2015	10/12/2015	10/06/2016	HIP2101EIBZ
HIP2101IB	10/06/2015	10/12/2015	10/06/2016	HIP2101IBZ
HIP2101IW	10/06/2015	10/12/2015	10/06/2016	None
HIP2101IY	10/06/2015	10/12/2015	10/06/2016	None
HIP2120FRTAZ	10/06/2015	10/12/2015	10/06/2016	None
HIP2120FRTAZ-T	10/06/2015	10/12/2015	10/06/2016	None
HIP2121FRTAZ	10/06/2015	10/12/2015	10/06/2016	None
HIP2121FRTAZ-T	10/06/2015	10/12/2015	10/06/2016	None
HIP2122FRTAZ	10/06/2015	10/12/2015	10/06/2016	None
HIP2122FRTAZ-T	10/06/2015	10/12/2015	10/06/2016	None
HIP2123FRTAZ	10/06/2015	10/12/2015	10/06/2016	None
HIP2123FRTAZ-T	10/06/2015	10/12/2015	10/06/2016	None
HIP4020IB	10/06/2015	10/12/2015	10/06/2016	HIP4020IBZ
HIP4080AIW	10/06/2015	10/12/2015	10/06/2016	None
HIP4081AIBZR5525-2	10/06/2015	10/12/2015	10/06/2016	HIP4081AIBZ
HIP4081AIBZR5525-3	10/06/2015	10/12/2015	10/06/2016	HIP4081AIBZ
HIP4081AIBZR5525-4	10/06/2015	10/12/2015	10/06/2016	HIP4081AIBZ
HIP4081AIBZTR5525-2	10/06/2015	10/12/2015	10/06/2016	HIP4081AIBZT
HIP4081AIBZTR5525-3	10/06/2015	10/12/2015	10/06/2016	HIP4081AIBZT
HIP4081AIBZTR5525-4	10/06/2015	10/12/2015	10/06/2016	HIP4081AIBZT
HIP4081AIP	10/06/2015	10/12/2015	10/06/2016	HIP4081AIPZ
HIP4081AIW	10/06/2015	10/12/2015	10/06/2016	None
HIP4081AIY	10/06/2015	10/12/2015	10/06/2016	None
HIP4082IP	10/06/2015	10/12/2015	10/06/2016	HIP4082IPZ
HIP4083ABT	10/06/2015	10/12/2015	10/06/2016	HIP4083ABZT
HIP4083APZ	10/06/2015	10/12/2015	10/06/2016	HIP4083ABZ
HIP4086ABZATS2490S	10/06/2015	10/12/2015	10/06/2016	HIP4086ABZT
HIP4086AW	10/06/2015	10/12/2015	10/06/2016	None
HIP4086AY	10/06/2015	10/12/2015	10/06/2016	None
HIP6004BCBZ	10/06/2015	10/12/2015	10/06/2016	None
HIP6004BCBZA	10/06/2015	10/12/2015	10/06/2016	None
HIP6004BCBZA-T	10/06/2015	10/12/2015	10/06/2016	None
HIP6004BCBZ-T	10/06/2015	10/12/2015	10/06/2016	None
HIP6004BCRZ-TS2462	10/06/2015	10/12/2015	10/06/2016	None

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
HIP6004BCVZ	10/06/2015	10/12/2015	10/06/2016	None
HIP6004BCVZA	10/06/2015	10/12/2015	10/06/2016	None
HIP6004BCVZA-T	10/06/2015	10/12/2015	10/06/2016	None
HIP6004BCVZA-TS2568	10/06/2015	10/12/2015	10/06/2016	None
HIP6004BCVZ-T	10/06/2015	10/12/2015	10/06/2016	None
HIP6004CBZ-TS2462	10/06/2015	10/12/2015	10/06/2016	None
HIP6004DCBZ	10/06/2015	10/12/2015	10/06/2016	None
HIP6004DCBZ-T	10/06/2015	10/12/2015	10/06/2016	None
HIP6004DCBZ-TS2462	10/06/2015	10/12/2015	10/06/2016	None
HIP6004DCRZ-TS2462	10/06/2015	10/12/2015	10/06/2016	None
HIP6004ECBZA-TS2568	10/06/2015	10/12/2015	10/06/2016	HIP6004ECBZ-T
HIP6004ECVZ	10/06/2015	10/12/2015	10/06/2016	HIP6004ECBZ
HIP6004ECVZ-T	10/06/2015	10/12/2015	10/06/2016	HIP6004ECBZ-T
HIP6004ECVZ-TS2568	10/06/2015	10/12/2015	10/06/2016	HIP6004ECBZ-T
HIP6006CBZ-TS2604	10/06/2015	10/03/2016	10/03/2017	HIP6006CBZ-T
HIP6012CBZR5226	10/06/2015	10/12/2015	10/06/2016	HIP6012CBZ
HIP6012CBZ-TR5226	10/06/2015	10/12/2015	10/06/2016	HIP6012CBZ-T
HIP6013CBZ	10/06/2015	10/12/2015	10/06/2016	None
HIP6013CBZ-T	10/06/2015	10/12/2015	10/06/2016	None
HIP6018BCBZ	10/06/2015	10/12/2015	10/06/2016	None
HIP6018BCBZ-T	10/06/2015	10/12/2015	10/06/2016	None
HIP6019BCBZ	10/06/2015	10/12/2015	10/06/2016	None
HIP6019BCBZ-T	10/06/2015	10/12/2015	10/06/2016	None
HIP6021CBZ	10/06/2015	10/12/2015	10/06/2016	None
HIP6021CBZ-T	10/06/2015	10/12/2015	10/06/2016	None
HIP6301CBZ	10/06/2015	10/12/2015	10/06/2016	None
HIP6301CBZ-T	10/06/2015	10/12/2015	10/06/2016	None
HIP6301VCBZ	10/06/2015	10/12/2015	10/06/2016	None
HIP6301VCBZ-T	10/06/2015	10/12/2015	10/06/2016	None
HIP6302VCBZ	10/06/2015	10/12/2015	10/06/2016	None
HIP6302VCBZ-T	10/06/2015	10/12/2015	10/06/2016	None
HIP6311ACBZ	10/06/2015	10/12/2015	10/06/2016	None
HIP6311ACBZA	10/06/2015	10/12/2015	10/06/2016	None
HIP6311ACBZA-T	10/06/2015	10/12/2015	10/06/2016	None
HIP6311ACBZA-TS2568	10/06/2015	10/12/2015	10/06/2016	None
HIP6311ACBZ-T	10/06/2015	10/12/2015	10/06/2016	None
HIP6311CBZ	10/06/2015	10/12/2015	10/06/2016	None
HIP6311CBZA	10/06/2015	10/12/2015	10/06/2016	None
HIP6311CBZA-T	10/06/2015	10/12/2015	10/06/2016	None
HIP6311CBZ-T	10/06/2015	10/12/2015	10/06/2016	None
HIP6501ACBZ	10/06/2015	10/12/2015	10/06/2016	None
HIP6501ACBZ-T	10/06/2015	10/12/2015	10/06/2016	None
HIP6503CBZ	10/06/2015	10/12/2015	10/06/2016	None
HIP6503CBZ-T	10/06/2015	10/12/2015	10/06/2016	None
HIP6601BECBZ	10/06/2015	10/12/2015	10/06/2016	HIP6601BCBZ
HIP6601BECBZA	10/06/2015	10/12/2015	10/06/2016	HIP6601BCBZA
HIP6601BECBZA-T	10/06/2015	10/12/2015	10/06/2016	HIP6601BCBZA-T
HIP6601BECBZ-T	10/06/2015	10/12/2015	10/06/2016	HIP6601BCBZ-T
HIP6601BW	10/06/2015	10/12/2015	10/06/2016	None
HIP6602BCBZ	10/06/2015	10/12/2015	10/06/2016	None
HIP6602BCBZ-T	10/06/2015	10/12/2015	10/06/2016	None
HIP6602BCRZ	10/06/2015	10/12/2015	10/06/2016	None
HIP6602BCRZA	10/06/2015	10/12/2015	10/06/2016	None
HIP6602BCRZA-T	10/06/2015	10/12/2015	10/06/2016	None
HIP6602BCRZ-T	10/06/2015	10/12/2015	10/06/2016	None
HIP6603BECBZ	10/06/2015	10/12/2015	10/06/2016	HIP6603BCBZ
HIP6603BECBZ-T	10/06/2015	10/12/2015	10/06/2016	HIP6603BCBZ-T
HIP6603BW	10/06/2015	10/12/2015	10/06/2016	None
HIP6604BCRZ-TS2705	10/06/2015	10/03/2016	10/03/2017	HIP6603BCBZ-T

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
HIP9011ABZTS2668	10/06/2015	10/06/2016	10/12/2016	HIP9011ABZT
HMP8117CN	10/06/2015	10/12/2015	10/06/2016	None
HMP8117CNZ	10/06/2015	10/12/2015	10/06/2016	None
HMP8156ACN	10/06/2015	10/12/2015	10/06/2016	None
HMP8156ACNZ	10/06/2015	10/12/2015	10/06/2016	None
HS0-1100RH/SAMPLE	10/06/2015	10/12/2015	10/06/2016	None
HS0-1100RH-Q	10/06/2015	10/12/2015	10/06/2016	None
HS0-302EH-Q	10/06/2015	10/12/2015	10/06/2016	None
HS0-302RH/SAMPLE	10/06/2015	10/12/2015	10/06/2016	None
HS0-302RH-Q	10/06/2015	10/12/2015	10/06/2016	None
HS0-307RH-Q	10/06/2015	10/12/2015	10/06/2016	None
HS0-50416R4514	10/06/2015	10/12/2015	10/06/2016	None
HS0-50416R5152	10/06/2015	10/12/2015	10/06/2016	None
HS0-82C85RH/SAMPLE	10/06/2015	10/12/2015	10/06/2016	None
HS0-82C85RH-Q	10/06/2015	10/12/2015	10/06/2016	None
HS0-CMP05RH-QS2677	10/06/2015	10/12/2015	10/06/2016	None
HS0-REF05RH-QS2677	10/06/2015	10/12/2015	10/06/2016	None
HS1-246RH/PROTO	10/06/2015	10/12/2015	10/06/2016	None
HS1-246RH-8	10/06/2015	10/12/2015	10/06/2016	None
HS1-246RH-Q	10/06/2015	10/12/2015	10/06/2016	None
HS1-248RH/PROTO	10/06/2015	10/12/2015	10/06/2016	None
HS1-248RH-8	10/06/2015	10/12/2015	10/06/2016	None
HS1-248RH-Q	10/06/2015	10/12/2015	10/06/2016	None
HS1-302EH-Q	10/06/2015	10/12/2015	10/06/2016	None
HS1-302RH-8	10/06/2015	10/12/2015	10/06/2016	None
HS1-302RH-Q	10/06/2015	10/12/2015	10/06/2016	None
HS1-82C55ARH-8	10/06/2015	10/12/2015	10/06/2016	None
HS1-82C55ARH-Q	10/06/2015	10/12/2015	10/06/2016	None
HS1-82C85RH-8	10/06/2015	10/12/2015	10/06/2016	None
HS1-82C85RH-Q	10/06/2015	10/12/2015	10/06/2016	None
HS4P-3282R4648	10/06/2015	10/12/2015	10/06/2016	None
HS7B-1100RH/PROTO	10/06/2015	10/12/2015	10/06/2016	None
HS7B-1100RH-Q	10/06/2015	10/12/2015	10/06/2016	None
HS9-246RH/PROTO	10/06/2015	10/12/2015	10/06/2016	None
HS9-246RH-8	10/06/2015	10/12/2015	10/06/2016	None
HS9-246RH-Q	10/06/2015	10/12/2015	10/06/2016	None
HS9-248RH/PROTO	10/06/2015	10/12/2015	10/06/2016	None
HS9-248RH-8	10/06/2015	10/12/2015	10/06/2016	None
HS9-248RH-Q	10/06/2015	10/12/2015	10/06/2016	None
HS9-302EH-Q	10/06/2015	10/12/2015	10/06/2016	None
HS9-302RH/PROTO	10/06/2015	10/12/2015	10/06/2016	None
HS9-302RH-8	10/06/2015	10/12/2015	10/06/2016	None
HS9-302RH-Q	10/06/2015	10/12/2015	10/06/2016	None
HS9-50416R2559	10/06/2015	10/12/2015	10/06/2016	None
HS9-50509R1991	10/06/2015	10/12/2015	10/06/2016	None
HS9-50510R1992	10/06/2015	10/12/2015	10/06/2016	None
HS9-82C85RH-8	10/06/2015	10/12/2015	10/06/2016	None
HS9-82C85RH-Q	10/06/2015	10/12/2015	10/06/2016	None
HS9-CMP05RH-Q	10/06/2015	10/12/2015	10/06/2016	None
HS9-CMP05RH-Q/RAD	10/06/2015	10/12/2015	10/06/2016	None
HS9-CMP05RH-QS2677	10/06/2015	10/12/2015	10/06/2016	None
HS9-CMP05RHS2677/DPA	10/06/2015	10/12/2015	10/06/2016	None
HS9-REF05RH-Q	10/06/2015	10/12/2015	10/06/2016	None
HS9-REF05RH-Q/RAD	10/06/2015	10/12/2015	10/06/2016	None
HS9-REF05RH-QS2677	10/06/2015	10/12/2015	10/06/2016	None
HS9-REF05RHS2677/DPA	10/06/2015	10/12/2015	10/06/2016	None
HSP43124SC-45	10/06/2015	10/12/2015	10/06/2016	None
HSP43124SC-45Z	10/06/2015	10/12/2015	10/06/2016	None
HSP43168JC-33	10/06/2015	10/12/2015	10/06/2016	None

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
HSP43168JC-33Z	10/06/2015	10/12/2015	10/06/2016	None
HSP43216JC-52	10/06/2015	10/12/2015	10/06/2016	None
HSP43216JC-52Z	10/06/2015	10/12/2015	10/06/2016	None
HSP43216VC-52	10/06/2015	10/12/2015	10/06/2016	None
HSP43216VC-52Z	10/06/2015	10/12/2015	10/06/2016	None
HSP43220JC-25	10/06/2015	10/12/2015	10/06/2016	None
HSP43220JC-25Z	10/06/2015	10/12/2015	10/06/2016	None
HSP43220JC-33	10/06/2015	10/12/2015	10/06/2016	None
HSP43220JC-33Z	10/06/2015	10/12/2015	10/06/2016	None
HSP45106JC-25	10/06/2015	10/12/2015	10/06/2016	None
HSP45106JC-25Z	10/06/2015	10/12/2015	10/06/2016	None
HSP45106JC-33	10/06/2015	10/12/2015	10/06/2016	None
HSP45106JC-33Z	10/06/2015	10/12/2015	10/06/2016	None
HSP45116AVC-52	10/06/2015	10/12/2015	10/06/2016	None
HSP45116AVC-52Z	10/06/2015	10/12/2015	10/06/2016	None
HSP50210JC-52	10/06/2015	10/12/2015	10/06/2016	None
HSP50210JC-52Z	10/06/2015	10/12/2015	10/06/2016	None
HSP50210JI-52	10/06/2015	10/12/2015	10/06/2016	None
HSP50210JI-52Z	10/06/2015	10/12/2015	10/06/2016	None
HSP95011C-32	10/06/2015	10/12/2015	10/06/2016	None
HVS1535A3	10/06/2015	10/12/2015	10/06/2016	None
ICL3217CAZ	10/06/2015	10/12/2015	10/06/2016	ICL3238ECAZ
ICL3217CAZ-T	10/06/2015	10/12/2015	10/06/2016	ICL3238ECAZ
ICL3217CBZ	10/06/2015	10/12/2015	10/06/2016	ICL3238ECAZ
ICL3217CBZ-T	10/06/2015	10/12/2015	10/06/2016	ICL3238ECAZ
ICL3217ECAZ	10/06/2015	10/12/2015	10/06/2016	ICL3238ECAZ
ICL3217ECAZ-T	10/06/2015	10/12/2015	10/06/2016	ICL3238ECAZ
ICL3217ECBZ	10/06/2015	10/12/2015	10/06/2016	ICL3238ECAZ
ICL3217ECBZ-T	10/06/2015	10/12/2015	10/06/2016	ICL3238ECAZ
ICL3217EIAZ	10/06/2015	10/12/2015	10/06/2016	ICL3238ECAZ
ICL3217EIAZ-T	10/06/2015	10/12/2015	10/06/2016	ICL3238ECAZ
ICL3217EIBZ	10/06/2015	10/12/2015	10/06/2016	ICL3238ECAZ
ICL3217EIBZ-T	10/06/2015	10/12/2015	10/06/2016	ICL3238ECAZ
ICL3217IAZ	10/06/2015	10/12/2015	10/06/2016	ICL3238ECAZ
ICL3217IAZ-T	10/06/2015	10/12/2015	10/06/2016	ICL3238ECAZ
ICL3217IBZ	10/06/2015	10/12/2015	10/06/2016	ICL3238ECAZ
ICL3217IBZ-T	10/06/2015	10/12/2015	10/06/2016	ICL3238ECAZ
ICL3223CPZ	10/06/2015	10/12/2015	10/06/2016	ICL3223ECVZ
ICL3225CPZ	10/06/2015	10/12/2015	10/06/2016	ICL3225ECAZ
ICL3225ECPZ	10/06/2015	10/12/2015	10/06/2016	ICL3225ECAZ
ICL3237CAZ	10/06/2015	10/12/2015	10/06/2016	ICL3237ECAZ
ICL3237CAZ-T	10/06/2015	10/12/2015	10/06/2016	ICL3237ECAZ
ICL3237IAZ	10/06/2015	10/12/2015	10/06/2016	ICL3237EIAZ
ICL3237IAZ-T	10/06/2015	10/12/2015	10/06/2016	ICL3237EIAZ
ICL3241CBZ	10/06/2015	10/12/2015	10/06/2016	ICL3241EIVZ
ICL3241CBZ-T	10/06/2015	10/12/2015	10/06/2016	ICL3241EIVZ
ICL3241ECBZ	10/06/2015	10/12/2015	10/06/2016	ICL3241EIVZ
ICL3241ECBZ-T	10/06/2015	10/12/2015	10/06/2016	ICL3241EIVZ
ICL3241EIBZ	10/06/2015	10/12/2015	10/06/2016	ICL3241EIVZ
ICL3241EIBZ-T	10/06/2015	10/12/2015	10/06/2016	ICL3241EIVZ
ICL3241IBZ	10/06/2015	10/12/2015	10/06/2016	ICL3241EIVZ
ICL3241IBZ-T	10/06/2015	10/12/2015	10/06/2016	ICL3241EIVZ
ICL3245ECBZ	10/06/2015	10/12/2015	10/06/2016	ICL3245EIAZ
ICL3245ECBZ-T	10/06/2015	10/12/2015	10/06/2016	ICL3245EIAZ
ICL3245ECVZ	10/06/2015	10/12/2015	10/06/2016	ICL3245EIAZ
ICL3245ECVZ-T	10/06/2015	10/12/2015	10/06/2016	ICL3245EIAZ
ICL3245IVZ	10/06/2015	10/12/2015	10/06/2016	ICL3245EIAZ
ICL3245IVZ-T	10/06/2015	10/12/2015	10/06/2016	ICL3245EIAZ
ICL7107C/W	10/06/2015	10/12/2015	10/06/2016	None

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ICL7660W	10/06/2015	10/12/2015	10/06/2016	None
ICL7663SACBA	10/06/2015	10/12/2015	10/06/2016	ICL7663SACBAZA
ICL7663SACBA-T	10/06/2015	10/12/2015	10/06/2016	ICL7663SACBAZA-T
ICL7663SCBA	10/06/2015	10/12/2015	10/06/2016	ICL7663SCBAZA
ICL7663SCPA	10/06/2015	10/12/2015	10/06/2016	ICL7663SCPAZ
ICL7663SW	10/06/2015	10/12/2015	10/06/2016	None
ICL7665SACBA	10/06/2015	10/12/2015	10/06/2016	ICL7665SACBAZ
ICL7665SACBA-T	10/06/2015	10/12/2015	10/06/2016	ICL7665SACBAZ-T
ICL7665SACPA	10/06/2015	10/12/2015	10/06/2016	ICL7665SACPAZ
ICL7665SAIBA	10/06/2015	10/12/2015	10/06/2016	ICL7665SAIBAZA
ICL7665SAIPA	10/06/2015	10/12/2015	10/06/2016	ICL7665SAIPAZ
ICL7665SCBA	10/06/2015	10/12/2015	10/06/2016	ICL7665SCBAZ
ICL7665SCPA	10/06/2015	10/12/2015	10/06/2016	ICL7665SCPAZ
ICL7665SIBA-T	10/06/2015	10/12/2015	10/06/2016	ICL7665SIBAZ-T
ICL7667CBA	10/06/2015	10/12/2015	10/06/2016	ICL7667CBAZA
ICL7667CBA-T	10/06/2015	10/12/2015	10/06/2016	ICL7667CBAZA-T
ICL7673CBA	10/06/2015	10/12/2015	10/06/2016	ICL7673CBAZA-T
ICL7673CPA	10/06/2015	10/12/2015	10/06/2016	ICL7673CPAZ
ICM7211AMIPL	10/06/2015	10/12/2015	10/06/2016	ICM7211AMIPLZ
ICM7218B/W	10/06/2015	10/12/2015	10/06/2016	None
ICM7218DIJIR5254	10/06/2015	10/12/2015	10/06/2016	ICM7218DIJI
ICM7228AIBI	10/06/2015	10/12/2015	10/06/2016	ICM7228AIBIZ
ICM7228AIPi	10/06/2015	10/12/2015	10/06/2016	ICM7228AIPIZ
ICM7228BIBI	10/06/2015	10/12/2015	10/06/2016	ICM7228BIBIZ
ICM7228BIPI	10/06/2015	10/12/2015	10/06/2016	ICM7228BIPIZ
ICM7228CIBI	10/06/2015	10/12/2015	10/06/2016	ICM7228CIBIZ
ICM7228CIPI	10/06/2015	10/12/2015	10/06/2016	ICM7228CIPIZ
ICM7242CBAZ	10/06/2015	10/12/2015	10/06/2016	None
ICM7242CBAZ-T	10/06/2015	10/12/2015	10/06/2016	None
ICM7242IBAZ	10/06/2015	10/12/2015	10/06/2016	None
ICM7242IBAZ-T	10/06/2015	10/12/2015	10/06/2016	None
ICM7243AIM44Z	10/06/2015	10/12/2015	10/06/2016	ICM7244AIM44Z
ICM7243AIM44ZT	10/06/2015	10/12/2015	10/06/2016	ICM7244AIM44ZT
ICM7243AIPLZ	10/06/2015	10/12/2015	10/06/2016	None
ICM7243BIPL	10/06/2015	10/12/2015	10/06/2016	None
ID82C82	10/06/2015	10/12/2015	10/06/2016	None
ID82C86H	10/06/2015	10/12/2015	10/06/2016	None
IPM6220ACAZ	10/06/2015	10/12/2015	10/06/2016	None
IPM6220ACAZA-T	10/06/2015	10/12/2015	10/06/2016	None
IPM6220ACAZ-T	10/06/2015	10/12/2015	10/06/2016	None
IS80C286-20R5524	10/06/2015	10/12/2015	10/06/2016	IS80C286-20
IS82C37A-5	10/06/2015	10/12/2015	10/06/2016	IS82C37A
IS82C50A-5	10/06/2015	10/12/2015	10/06/2016	IS82C50A-5Z
IS82C55A96	10/06/2015	10/12/2015	10/06/2016	IS82C55A, IS82C55AZ96
IS82C59AX96	10/06/2015	10/12/2015	10/06/2016	IS82C59A, IS82C59AZX96
ISL12023IVZ	10/06/2015	10/12/2015	10/06/2016	None
ISL12023IVZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL12025IVZ	10/06/2015	10/12/2015	10/06/2016	None
ISL12025IVZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL12027AIB27Z	10/06/2015	10/12/2015	10/06/2016	None
ISL12027AIB27Z-T	10/06/2015	10/12/2015	10/06/2016	None
ISL12027AIV27Z	10/06/2015	10/12/2015	10/06/2016	None
ISL12027AIV27Z-T	10/06/2015	10/12/2015	10/06/2016	None
ISL12027IVAZ	10/06/2015	10/12/2015	10/06/2016	None
ISL12027IVAZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL12027IVZ	10/06/2015	10/12/2015	10/06/2016	None
ISL12027IVZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL12028AIB27Z	10/06/2015	10/12/2015	10/06/2016	None
ISL12028AIB27Z-T	10/06/2015	10/12/2015	10/06/2016	None

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL12028AIV27Z	10/06/2015	10/12/2015	10/06/2016	None
ISL12028AIV27Z-T	10/06/2015	10/12/2015	10/06/2016	None
ISL12028IB27AZ	10/06/2015	10/12/2015	10/06/2016	None
ISL12028IB27AZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL12028IB30AZ	10/06/2015	10/12/2015	10/06/2016	None
ISL12028IB30AZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL12028IBAZ	10/06/2015	10/12/2015	10/06/2016	None
ISL12028IBAZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL12028IV27AZ	10/06/2015	10/12/2015	10/06/2016	None
ISL12028IV27AZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL12028IV30AZ	10/06/2015	10/12/2015	10/06/2016	None
ISL12028IV30AZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL12028IVAZ	10/06/2015	10/12/2015	10/06/2016	None
ISL12028IVAZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL12029AIB27Z	10/06/2015	10/12/2015	10/06/2016	None
ISL12029AIB27Z-T	10/06/2015	10/12/2015	10/06/2016	None
ISL12029AIV27Z	10/06/2015	10/12/2015	10/06/2016	None
ISL12029AIV27Z-T	10/06/2015	10/12/2015	10/06/2016	None
ISL12029IB27AZ	10/06/2015	10/12/2015	10/06/2016	None
ISL12029IB27AZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL12029IB27Z	10/06/2015	10/12/2015	10/06/2016	None
ISL12029IB27Z-T	10/06/2015	10/12/2015	10/06/2016	None
ISL12029IB30AZ	10/06/2015	10/12/2015	10/06/2016	None
ISL12029IB30AZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL12029IBAZ	10/06/2015	10/12/2015	10/06/2016	None
ISL12029IBAZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL12029IBZ	10/06/2015	10/12/2015	10/06/2016	None
ISL12029IBZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL12029IV27AZ	10/06/2015	10/12/2015	10/06/2016	None
ISL12029IV27AZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL12029IV27Z	10/06/2015	10/12/2015	10/06/2016	None
ISL12029IV27Z-T	10/06/2015	10/12/2015	10/06/2016	None
ISL12029IV30AZ	10/06/2015	10/12/2015	10/06/2016	None
ISL12029IV30AZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL12029IVAZ	10/06/2015	10/12/2015	10/06/2016	None
ISL12029IVAZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL12029IVZ	10/06/2015	10/12/2015	10/06/2016	None
ISL12029IVZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL12030IBZ	10/06/2015	10/12/2015	10/06/2016	None
ISL12030IBZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL12032IVZ	10/06/2015	10/12/2015	10/06/2016	None
ISL12032IVZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL12057IRUZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL12058IRUZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL12059IBZ	10/06/2015	10/12/2015	10/06/2016	None
ISL12059IBZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL12082IUZ	10/06/2015	10/12/2015	10/06/2016	None
ISL12082IUZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL1208W	10/06/2015	10/12/2015	10/06/2016	None
ISL1220IUZ	10/06/2015	10/12/2015	10/06/2016	None
ISL1532AIRZ	10/06/2015	10/12/2015	10/06/2016	None
ISL1532AIRZ-T13	10/06/2015	10/12/2015	10/06/2016	None
ISL1532AIRZ-T7	10/06/2015	10/12/2015	10/06/2016	None
ISL1532AIVEZ	10/06/2015	10/12/2015	10/06/2016	None
ISL1532AIVEZ-T13	10/06/2015	10/12/2015	10/06/2016	None
ISL1532AIVEZ-T7	10/06/2015	10/12/2015	10/06/2016	None
ISL1532IRZ	10/06/2015	10/12/2015	10/06/2016	ISL1533IRZ
ISL1532IRZ-T13	10/06/2015	10/12/2015	10/06/2016	ISL1533IRZ-T13
ISL1532IRZ-T7	10/06/2015	10/12/2015	10/06/2016	ISL1533IRZ-T13

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL1532IVEZ	10/06/2015	10/12/2015	10/06/2016	None
ISL1532IVEZ-T13	10/06/2015	10/12/2015	10/06/2016	None
ISL1532IVEZ-T7	10/06/2015	10/12/2015	10/06/2016	None
ISL1533IVEZ	10/06/2015	10/12/2015	10/06/2016	None
ISL1533IVEZ-T13	10/06/2015	10/12/2015	10/06/2016	None
ISL1534IVEZ	10/06/2015	10/12/2015	10/06/2016	None
ISL1534IVEZ-T13	10/06/2015	10/12/2015	10/06/2016	None
ISL1535AIRZ	10/06/2015	10/12/2015	10/06/2016	None
ISL1535AIRZ-T13	10/06/2015	10/12/2015	10/06/2016	None
ISL1535IRZ	10/06/2015	10/12/2015	10/06/2016	None
ISL1535IRZ-T13	10/06/2015	10/12/2015	10/06/2016	None
ISL1535IVEZ	10/06/2015	10/12/2015	10/06/2016	None
ISL1535IVEZR5317	10/06/2015	10/12/2015	10/06/2016	None
ISL1535IVEZ-T13	10/06/2015	10/12/2015	10/06/2016	None
ISL1535IVEZ-T13R5317	10/06/2015	10/12/2015	10/06/2016	None
ISL1539IRZ	10/06/2015	10/12/2015	10/06/2016	None
ISL1539IRZ-T13	10/06/2015	10/12/2015	10/06/2016	None
ISL1539IRZ-T7	10/06/2015	10/12/2015	10/06/2016	None
ISL1557AIUEZ	10/06/2015	10/12/2015	10/06/2016	None
ISL1557AIUEZ-T7	10/06/2015	10/12/2015	10/06/2016	None
ISL21007CFB830Z	10/06/2015	10/12/2015	10/06/2016	ISL21007CFB825Z-TK
ISL21007CFB830Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL21007CFB825Z-TK
ISL21007DFB820Z	10/06/2015	10/12/2015	10/06/2016	ISL21007CFB825Z-TK
ISL21007DFB820Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL21007CFB825Z-TK
ISL21007DFB830Z	10/06/2015	10/12/2015	10/06/2016	ISL21007CFB825Z-TK
ISL21007DFB830Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL21007CFB825Z-TK
ISL21009DFB862Z	10/06/2015	10/12/2015	10/06/2016	ISL21009BFB850Z-TK
ISL21009DFB862Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL21009BFB850Z-TK
ISL2100AABZ	10/06/2015	10/12/2015	10/06/2016	HIP2100IBZ
ISL2100AABZ-T	10/06/2015	10/12/2015	10/06/2016	HIP2100IBZT
ISL2100AAR3Z	10/06/2015	10/12/2015	10/06/2016	None
ISL2100AAR3Z-T	10/06/2015	10/12/2015	10/06/2016	None
ISL21070DIH306Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL21070CIH325Z-TK
ISL22102IV20Z	10/06/2015	10/12/2015	10/06/2016	None
ISL22102IV20Z-TK	10/06/2015	10/12/2015	10/06/2016	None
ISL22316UFRT10Z	10/06/2015	10/12/2015	10/06/2016	ISL22316WFRT10Z-TK
ISL22316UFRT10Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL22316WFRT10Z-TK
ISL22316UFU10Z	10/06/2015	10/12/2015	10/06/2016	ISL22316WFRT10Z-TK
ISL22316UFU10Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL22316WFRT10Z-TK
ISL22317TFRTZ	10/06/2015	10/12/2015	10/06/2016	ISL22317WFRTZ-TK
ISL22317TFRTZ-TK	10/06/2015	10/12/2015	10/06/2016	ISL22317WFRTZ-TK
ISL22317UFRTZ	10/06/2015	10/12/2015	10/06/2016	ISL22317WFRTZ-TK
ISL22317UFRTZ-TK	10/06/2015	10/12/2015	10/06/2016	ISL22317WFRTZ-TK
ISL22317UFRTZTKS2568	10/06/2015	10/12/2015	10/06/2016	ISL22317WFRTZ-TK
ISL22323UFR16Z	10/06/2015	10/12/2015	10/06/2016	ISL22323TFV14Z-TK
ISL22323UFR16Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL22323TFV14Z-TK
ISL22323UFV14Z	10/06/2015	10/12/2015	10/06/2016	ISL22323TFV14Z-TK
ISL22323UFV14Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL22323TFV14Z-TK
ISL22323WFR16Z	10/06/2015	10/12/2015	10/06/2016	ISL22323TFV14Z-TK
ISL22323WFR16Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL22323TFV14Z-TK
ISL22323WFR16Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL22323TFV14Z-TK
ISL22323WFR16Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL22323TFV14Z-TK
ISL22323WFR16Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL22323TFV14Z-TK
ISL22323WFR16Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL22323TFV14Z-TK
ISL22326UFR16Z	10/06/2015	10/12/2015	10/06/2016	ISL22326WFR16Z-TK
ISL22326UFR16Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL22326WFR16Z-TK
ISL22326UFV14Z	10/06/2015	10/12/2015	10/06/2016	ISL22326WFR16Z-TK
ISL22326UFV14Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL22326WFR16Z-TK
ISL22343TFR20Z	10/06/2015	10/12/2015	10/06/2016	ISL22343WFR20Z-TK
ISL22343TFR20Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL22343WFR20Z-TK
ISL22343TFV20Z	10/06/2015	10/12/2015	10/06/2016	ISL22343WFR20Z-TK

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL22343TFV20Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL22343WFR20Z-TK
ISL22343UFR20Z	10/06/2015	10/12/2015	10/06/2016	ISL22343WFR20Z-TK
ISL22343UFR20Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL22343WFR20Z-TK
ISL22343UFV20Z	10/06/2015	10/12/2015	10/06/2016	ISL22343WFR20Z-TK
ISL22343UFV20Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL22343WFR20Z-TK
ISL22414UFU10Z	10/06/2015	10/12/2015	10/06/2016	ISL22414TFU10Z-TK
ISL22414UFU10Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL22414TFU10Z-TK
ISL22414WFU10Z	10/06/2015	10/12/2015	10/06/2016	ISL22414TFU10Z-TK
ISL22414WMU10Z	10/06/2015	10/12/2015	10/06/2016	ISL22414TFU10Z-TK
ISL22414WMU10Z-T7A	10/06/2015	10/12/2015	10/06/2016	ISL22414TFU10Z-TK
ISL22416UFRT10Z	10/06/2015	10/12/2015	10/06/2016	ISL22316WFRT10Z-TK
ISL22416UFRT10Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL22316WFRT10Z-TK
ISL22416UFU10Z	10/06/2015	10/12/2015	10/06/2016	ISL22316WFRT10Z-TK
ISL22416UFU10Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL22316WFRT10Z-TK
ISL22416WFRT10Z	10/06/2015	10/12/2015	10/06/2016	ISL22316WFRT10Z-TK
ISL22416WFRT10Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL22316WFRT10Z-TK
ISL22416WFU10Z	10/06/2015	10/12/2015	10/06/2016	ISL22316WFRT10Z-TK
ISL22416WFU10ZS2426	10/06/2015	10/12/2015	10/06/2016	ISL22316WFRT10Z-TK
ISL22416WFU10Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL22316WFRT10Z-TK
ISL22416WFU10ZTS2568	10/06/2015	10/12/2015	10/06/2016	ISL22316WFRT10Z-TK
ISL22424TFR16Z	10/06/2015	10/12/2015	10/06/2016	ISL22424WFR16Z-TK
ISL22424TFR16Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL22424WFR16Z-TK
ISL22424TFV14Z	10/06/2015	10/12/2015	10/06/2016	ISL22424WFR16Z-TK
ISL22424TFV14Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL22424WFR16Z-TK
ISL22424UFR16Z	10/06/2015	10/12/2015	10/06/2016	ISL22424WFR16Z-TK
ISL22424UFR16Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL22424WFR16Z-TK
ISL22424UFV14Z	10/06/2015	10/12/2015	10/06/2016	ISL22424WFR16Z-TK
ISL22424UFV14Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL22424WFR16Z-TK
ISL22426UFR16Z	10/06/2015	10/12/2015	10/06/2016	ISL22424WFR16Z-TK
ISL22426UFR16Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL22424WFR16Z-TK
ISL22426UFV14Z	10/06/2015	10/12/2015	10/06/2016	ISL22424WFR16Z-TK
ISL22426UFV14Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL22424WFR16Z-TK
ISL22426WFR16Z	10/06/2015	10/12/2015	10/06/2016	ISL22424WFR16Z-TK
ISL22426WFR16Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL22424WFR16Z-TK
ISL22426WV14Z	10/06/2015	10/12/2015	10/06/2016	ISL22424WFR16Z-TK
ISL22426WV14Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL22424WFR16Z-TK
ISL22444TFR20Z	10/06/2015	10/12/2015	10/06/2016	ISL22424WFR16Z-TK
ISL22444TFR20Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL22424WFR16Z-TK
ISL22444TFV20Z	10/06/2015	10/12/2015	10/06/2016	ISL22424WFR16Z-TK
ISL22444TFV20Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL22424WFR16Z-TK
ISL22444UFR20Z	10/06/2015	10/12/2015	10/06/2016	ISL22424WFR16Z-TK
ISL22444UFR20Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL22424WFR16Z-TK
ISL22444UFV20Z	10/06/2015	10/12/2015	10/06/2016	ISL22424WFR16Z-TK
ISL22444UFV20Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL22424WFR16Z-TK
ISL22444WFR20Z	10/06/2015	10/12/2015	10/06/2016	ISL22424WFR16Z-TK
ISL22444WFR20Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL22424WFR16Z-TK
ISL22444WV20Z	10/06/2015	10/12/2015	10/06/2016	ISL22424WFR16Z-TK
ISL22444WV20Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL22424WFR16Z-TK
ISL22446UFRT20Z	10/06/2015	10/12/2015	10/06/2016	ISL22424WFR16Z-TK
ISL22446UFRT20Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL22424WFR16Z-TK
ISL22446UFV20Z	10/06/2015	10/12/2015	10/06/2016	ISL22424WFR16Z-TK
ISL22446UFV20Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL22424WFR16Z-TK
ISL22446WFRT20Z	10/06/2015	10/12/2015	10/06/2016	ISL22424WFR16Z-TK
ISL22446WFRT20Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL22424WFR16Z-TK
ISL22446WV20Z	10/06/2015	10/12/2015	10/06/2016	ISL22424WFR16Z-TK
ISL22446WV20Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL22424WFR16Z-TK
ISL22511UFB8Z	10/06/2015	10/12/2015	10/06/2016	ISL22511WFRU10Z-TK
ISL22511UFB8Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL22511WFRU10Z-TK
ISL22511WFRU10Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL22511WFRU10Z-TK

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL22512WFRU10Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL22512WFB8Z-TK
ISL23315UFRUZ-T7A	10/06/2015	10/12/2015	10/06/2016	ISL23315TFUZ-TK
ISL23315UFRUZ-TK	10/06/2015	10/12/2015	10/06/2016	ISL23315TFUZ-TK
ISL23315UFUZ	10/06/2015	10/12/2015	10/06/2016	ISL23315TFUZ-TK
ISL23315UFUZ-T7A	10/06/2015	10/12/2015	10/06/2016	ISL23315TFUZ-TK
ISL23315UFUZ-TK	10/06/2015	10/12/2015	10/06/2016	ISL23315TFUZ-TK
ISL23315WFRUZ-T7A	10/06/2015	10/12/2015	10/06/2016	ISL23315TFUZ-TK
ISL23315WFRUZ-TK	10/06/2015	10/12/2015	10/06/2016	ISL23315TFUZ-TK
ISL23325UFRUZ-T7A	10/06/2015	10/12/2015	10/06/2016	ISL23325TFRUZ-TK
ISL23325UFRUZ-TK	10/06/2015	10/12/2015	10/06/2016	ISL23325TFRUZ-TK
ISL23325UFVZ	10/06/2015	10/12/2015	10/06/2016	ISL23325TFRUZ-TK
ISL23325UFVZ-T7A	10/06/2015	10/12/2015	10/06/2016	ISL23325TFRUZ-TK
ISL23325UFVZ-TK	10/06/2015	10/12/2015	10/06/2016	ISL23325TFRUZ-TK
ISL23328UFRUZ-T7A	10/06/2015	10/12/2015	10/06/2016	ISL23328TFRUZ-TK
ISL23328UFRUZ-TK	10/06/2015	10/12/2015	10/06/2016	ISL23328TFRUZ-TK
ISL23328UFVZ	10/06/2015	10/12/2015	10/06/2016	ISL23328TFRUZ-TK
ISL23328UFVZ-T7A	10/06/2015	10/12/2015	10/06/2016	ISL23328TFRUZ-TK
ISL23328UFVZ-TK	10/06/2015	10/12/2015	10/06/2016	ISL23328TFRUZ-TK
ISL23345TFRZ	10/06/2015	10/12/2015	10/06/2016	ISL23325TFRUZ-TK
ISL23345TFRZ-T7A	10/06/2015	10/12/2015	10/06/2016	ISL23325TFRUZ-TK
ISL23345TFRZ-TK	10/06/2015	10/12/2015	10/06/2016	ISL23325TFRUZ-TK
ISL23345TFVZ	10/06/2015	10/12/2015	10/06/2016	ISL23325TFRUZ-TK
ISL23345TFVZ-T7A	10/06/2015	10/12/2015	10/06/2016	ISL23325TFRUZ-TK
ISL23345TFVZ-TK	10/06/2015	10/12/2015	10/06/2016	ISL23325TFRUZ-TK
ISL23345UFRZ	10/06/2015	10/12/2015	10/06/2016	ISL23325TFRUZ-TK
ISL23345UFRZ-T7A	10/06/2015	10/12/2015	10/06/2016	ISL23325TFRUZ-TK
ISL23345UFRZ-TK	10/06/2015	10/12/2015	10/06/2016	ISL23325TFRUZ-TK
ISL23345UFVZ	10/06/2015	10/12/2015	10/06/2016	ISL23325TFRUZ-TK
ISL23345UFVZ-T7A	10/06/2015	10/12/2015	10/06/2016	ISL23325TFRUZ-TK
ISL23345UFVZ-TK	10/06/2015	10/12/2015	10/06/2016	ISL23325TFRUZ-TK
ISL23345WFRZ	10/06/2015	10/12/2015	10/06/2016	ISL23325TFRUZ-TK
ISL23345WFRZ-T7A	10/06/2015	10/12/2015	10/06/2016	ISL23325TFRUZ-TK
ISL23345WFRZ-TK	10/06/2015	10/12/2015	10/06/2016	ISL23325TFRUZ-TK
ISL23345WFVZ	10/06/2015	10/12/2015	10/06/2016	ISL23325TFRUZ-TK
ISL23345WFVZ-T7A	10/06/2015	10/12/2015	10/06/2016	ISL23325TFRUZ-TK
ISL23345WFVZ-TK	10/06/2015	10/12/2015	10/06/2016	ISL23325TFRUZ-TK
ISL23348TFRZ	10/06/2015	10/12/2015	10/06/2016	ISL23425TFVZ-TK
ISL23348TFRZ-T7A	10/06/2015	10/12/2015	10/06/2016	ISL23425TFVZ-TK
ISL23348TFRZ-TK	10/06/2015	10/12/2015	10/06/2016	ISL23425TFVZ-TK
ISL23348TFVZ	10/06/2015	10/12/2015	10/06/2016	ISL23425TFVZ-TK
ISL23348TFVZ-T7A	10/06/2015	10/12/2015	10/06/2016	ISL23425TFVZ-TK
ISL23348TFVZ-TK	10/06/2015	10/12/2015	10/06/2016	ISL23425TFVZ-TK
ISL23348UFRZ	10/06/2015	10/12/2015	10/06/2016	ISL23425TFVZ-TK
ISL23348UFRZ-T7A	10/06/2015	10/12/2015	10/06/2016	ISL23425TFVZ-TK
ISL23348UFRZ-TK	10/06/2015	10/12/2015	10/06/2016	ISL23425TFVZ-TK
ISL23348UFVZ	10/06/2015	10/12/2015	10/06/2016	ISL23425TFVZ-TK
ISL23348UFVZ-T7A	10/06/2015	10/12/2015	10/06/2016	ISL23425TFVZ-TK
ISL23348UFVZ-TK	10/06/2015	10/12/2015	10/06/2016	ISL23425TFVZ-TK
ISL23348WFRZ	10/06/2015	10/12/2015	10/06/2016	ISL23425TFVZ-TK
ISL23348WFRZ-T7A	10/06/2015	10/12/2015	10/06/2016	ISL23425TFVZ-TK
ISL23348WFRZ-TK	10/06/2015	10/12/2015	10/06/2016	ISL23425TFVZ-TK
ISL23348WFVZ	10/06/2015	10/12/2015	10/06/2016	ISL23425TFVZ-TK
ISL23348WFVZ-T7A	10/06/2015	10/12/2015	10/06/2016	ISL23425TFVZ-TK
ISL23348WFVZ-TK	10/06/2015	10/12/2015	10/06/2016	ISL23425TFVZ-TK
ISL23415UFRUZ-T7A	10/06/2015	10/12/2015	10/06/2016	ISL23415WFUZ-TK
ISL23415UFRUZ-TK	10/06/2015	10/12/2015	10/06/2016	ISL23415WFUZ-TK
ISL23415UFUZ	10/06/2015	10/12/2015	10/06/2016	ISL23415WFUZ-TK
ISL23415UFUZ-T7A	10/06/2015	10/12/2015	10/06/2016	ISL23415WFUZ-TK
ISL23415UFUZ-TK	10/06/2015	10/12/2015	10/06/2016	ISL23415WFUZ-TK

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL23415WFRUZ-T7A	10/06/2015	10/12/2015	10/06/2016	ISL23415WFRUZ-TK
ISL23415WFRUZ-TK	10/06/2015	10/12/2015	10/06/2016	ISL23415WFRUZ-TK
ISL23418UFRUZ-T7A	10/06/2015	10/12/2015	10/06/2016	ISL23418UFRUZ-TK
ISL23418UFRUZ-TK	10/06/2015	10/12/2015	10/06/2016	ISL23418UFRUZ-TK
ISL23418WFRUZ-T7A	10/06/2015	10/12/2015	10/06/2016	ISL23418WFRUZ-TK
ISL23418WFRUZ-TK	10/06/2015	10/12/2015	10/06/2016	ISL23418WFRUZ-TK
ISL23425UFRUZ-T7A	10/06/2015	10/12/2015	10/06/2016	ISL23425UFRUZ-TK
ISL23425UFRUZ-TK	10/06/2015	10/12/2015	10/06/2016	ISL23425UFRUZ-TK
ISL23425UFVZ	10/06/2015	10/12/2015	10/06/2016	ISL23425UFRUZ-TK
ISL23425UFVZ-T7A	10/06/2015	10/12/2015	10/06/2016	ISL23425UFRUZ-TK
ISL23425UFVZ-TK	10/06/2015	10/12/2015	10/06/2016	ISL23425UFRUZ-TK
ISL23428UFRUZ-T7A	10/06/2015	10/12/2015	10/06/2016	ISL23428UFRUZ-TK
ISL23428UFRUZ-TK	10/06/2015	10/12/2015	10/06/2016	ISL23428UFRUZ-TK
ISL23428UFVZ	10/06/2015	10/12/2015	10/06/2016	ISL23428UFRUZ-TK
ISL23428UFVZ-T7A	10/06/2015	10/12/2015	10/06/2016	ISL23428UFRUZ-TK
ISL23428UFVZ-TK	10/06/2015	10/12/2015	10/06/2016	ISL23428UFRUZ-TK
ISL23445TFRZ	10/06/2015	10/12/2015	10/06/2016	ISL23425TFVZ-TK
ISL23445TFRZ-T7A	10/06/2015	10/12/2015	10/06/2016	ISL23425TFVZ-TK
ISL23445TFRZ-TK	10/06/2015	10/12/2015	10/06/2016	ISL23425TFVZ-TK
ISL23445TFVZ	10/06/2015	10/12/2015	10/06/2016	ISL23425TFVZ-TK
ISL23445TFVZ-T7A	10/06/2015	10/12/2015	10/06/2016	ISL23425TFVZ-TK
ISL23445TFVZ-TK	10/06/2015	10/12/2015	10/06/2016	ISL23425TFVZ-TK
ISL23445UFRZ	10/06/2015	10/12/2015	10/06/2016	ISL23425TFVZ-TK
ISL23445UFRZ-T7A	10/06/2015	10/12/2015	10/06/2016	ISL23425TFVZ-TK
ISL23445UFRZ-TK	10/06/2015	10/12/2015	10/06/2016	ISL23425TFVZ-TK
ISL23445UFVZ	10/06/2015	10/12/2015	10/06/2016	ISL23425TFVZ-TK
ISL23445UFVZ-T7A	10/06/2015	10/12/2015	10/06/2016	ISL23425TFVZ-TK
ISL23445UFVZ-TK	10/06/2015	10/12/2015	10/06/2016	ISL23425TFVZ-TK
ISL23445WFRZ	10/06/2015	10/12/2015	10/06/2016	ISL23425TFVZ-TK
ISL23445WFRZ-T7A	10/06/2015	10/12/2015	10/06/2016	ISL23425TFVZ-TK
ISL23445WFRZ-TK	10/06/2015	10/12/2015	10/06/2016	ISL23425TFVZ-TK
ISL23445WVZ	10/06/2015	10/12/2015	10/06/2016	ISL23425TFVZ-TK
ISL23445WVZ-T7A	10/06/2015	10/12/2015	10/06/2016	ISL23425TFVZ-TK
ISL23445WVZ-TK	10/06/2015	10/12/2015	10/06/2016	ISL23425TFVZ-TK
ISL23448TFRZ	10/06/2015	10/12/2015	10/06/2016	ISL23428TFRUZ-TK
ISL23448TFRZ-T7A	10/06/2015	10/12/2015	10/06/2016	ISL23428TFRUZ-TK
ISL23448TFRZ-TK	10/06/2015	10/12/2015	10/06/2016	ISL23428TFRUZ-TK
ISL23448TFVZ	10/06/2015	10/12/2015	10/06/2016	ISL23428TFRUZ-TK
ISL23448TFVZ-T7A	10/06/2015	10/12/2015	10/06/2016	ISL23428TFRUZ-TK
ISL23448TFVZ-TK	10/06/2015	10/12/2015	10/06/2016	ISL23428TFRUZ-TK
ISL23448UFRZ	10/06/2015	10/12/2015	10/06/2016	ISL23428TFRUZ-TK
ISL23448UFRZ-T7A	10/06/2015	10/12/2015	10/06/2016	ISL23428TFRUZ-TK
ISL23448UFRZ-TK	10/06/2015	10/12/2015	10/06/2016	ISL23428TFRUZ-TK
ISL23448UFVZ	10/06/2015	10/12/2015	10/06/2016	ISL23428TFRUZ-TK
ISL23448UFVZ-T7A	10/06/2015	10/12/2015	10/06/2016	ISL23428TFRUZ-TK
ISL23448UFVZ-TK	10/06/2015	10/12/2015	10/06/2016	ISL23428TFRUZ-TK
ISL23448WFRZ	10/06/2015	10/12/2015	10/06/2016	ISL23428TFRUZ-TK
ISL23448WFRZ-T7A	10/06/2015	10/12/2015	10/06/2016	ISL23428TFRUZ-TK
ISL23448WFRZ-TK	10/06/2015	10/12/2015	10/06/2016	ISL23428TFRUZ-TK
ISL23448WVZ	10/06/2015	10/12/2015	10/06/2016	ISL23428TFRUZ-TK
ISL23448WVZ-T7A	10/06/2015	10/12/2015	10/06/2016	ISL23428TFRUZ-TK
ISL23448WVZ-TK	10/06/2015	10/12/2015	10/06/2016	ISL23428TFRUZ-TK
ISL23511UFB8Z	10/06/2015	10/12/2015	10/06/2016	None
ISL23511UFB8Z-TK	10/06/2015	10/12/2015	10/06/2016	None
ISL23511UFRU10Z-TK	10/06/2015	10/12/2015	10/06/2016	None
ISL23511WFRU10Z-TK	10/06/2015	10/12/2015	10/06/2016	None
ISL23512WFRU10Z-TK	10/06/2015	10/12/2015	10/06/2016	None
ISL23710UIU10Z	10/06/2015	10/12/2015	10/06/2016	X9015US8IZT1
ISL23710UIU10Z-T	10/06/2015	10/12/2015	10/06/2016	X9015US8IZT1

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL23710WIU10Z	10/06/2015	10/12/2015	10/06/2016	X9015US8IZT1
ISL23710WIU10Z-T	10/06/2015	10/12/2015	10/06/2016	X9015US8IZT1
ISL23711UIU10Z	10/06/2015	10/12/2015	10/06/2016	None
ISL23711UIU10Z-T	10/06/2015	10/12/2015	10/06/2016	None
ISL23711WIU10Z	10/06/2015	10/12/2015	10/06/2016	None
ISL23711WIU10Z-T	10/06/2015	10/12/2015	10/06/2016	None
ISL24002IRTZ	10/06/2015	10/12/2015	10/06/2016	None
ISL24002IRTZ-T13	10/06/2015	10/12/2015	10/06/2016	None
ISL24005IRTZ	10/06/2015	10/12/2015	10/06/2016	None
ISL24005IRTZ-T13	10/06/2015	10/12/2015	10/06/2016	None
ISL24007IRZ	10/06/2015	10/12/2015	10/06/2016	None
ISL24007IRZ-T13	10/06/2015	10/12/2015	10/06/2016	None
ISL24010IVZ	10/06/2015	10/12/2015	10/06/2016	None
ISL24010IVZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL24011VZ	10/06/2015	10/12/2015	10/06/2016	None
ISL24011VZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL24102IRTZ	10/06/2015	10/12/2015	10/06/2016	None
ISL24102IRTZ-T13	10/06/2015	10/12/2015	10/06/2016	None
ISL24103IRZ	10/06/2015	10/12/2015	10/06/2016	None
ISL24103IRZ-T13	10/06/2015	10/12/2015	10/06/2016	None
ISL24105IRZ	10/06/2015	10/12/2015	10/06/2016	None
ISL24105IRZ-T13	10/06/2015	10/12/2015	10/06/2016	None
ISL24111IRTZ	10/06/2015	10/12/2015	10/06/2016	None
ISL24111IRTZ-T13	10/06/2015	10/12/2015	10/06/2016	None
ISL24821IRTZ	10/06/2015	10/12/2015	10/06/2016	None
ISL24821IRTZ-T13	10/06/2015	10/12/2015	10/06/2016	None
ISL24822IRTZ	10/06/2015	10/12/2015	10/06/2016	None
ISL24822IRTZ-T13	10/06/2015	10/12/2015	10/06/2016	None
ISL24832IRZ	10/06/2015	10/12/2015	10/06/2016	None
ISL24832IRZR5513	10/06/2015	10/12/2015	10/06/2016	None
ISL24832IRZ-T13	10/06/2015	10/12/2015	10/06/2016	None
ISL24832IRZ-T13R5513	10/06/2015	10/12/2015	10/06/2016	None
ISL24835IRZ	10/06/2015	10/12/2015	10/06/2016	None
ISL24835IRZ-T13	10/06/2015	10/12/2015	10/06/2016	None
ISL24837IRZ	10/06/2015	10/12/2015	10/06/2016	None
ISL24837IRZ-T13	10/06/2015	10/12/2015	10/06/2016	None
ISL24867IRXZ	10/06/2015	10/12/2015	10/06/2016	None
ISL24867IRXZR5560	10/06/2015	10/12/2015	10/06/2016	None
ISL24867IRXZ-T13	10/06/2015	10/12/2015	10/06/2016	None
ISL24867IRXZT13R5560	10/06/2015	10/12/2015	10/06/2016	None
ISL25700FRUZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL25700FRUZ-T7A	10/06/2015	10/12/2015	10/06/2016	None
ISL25700FRUZ-TK	10/06/2015	10/12/2015	10/06/2016	None
ISL26310FBZ	10/06/2015	10/12/2015	10/06/2016	ISL26320FBZ
ISL26310FBZ-T	10/06/2015	10/12/2015	10/06/2016	ISL26320FBZ
ISL26310FBZ-T7A	10/06/2015	10/12/2015	10/06/2016	ISL26320FBZ
ISL26311FBZ	10/06/2015	10/12/2015	10/06/2016	ISL26321FBZ
ISL26311FBZ-T	10/06/2015	10/12/2015	10/06/2016	ISL26321FBZ
ISL26311FBZ-T7A	10/06/2015	10/12/2015	10/06/2016	ISL26321FBZ
ISL28107FBZ	10/06/2015	10/12/2015	10/06/2016	ISL28107FUZ-T7
ISL28107FBZ-T13	10/06/2015	10/12/2015	10/06/2016	ISL28107FUZ-T7
ISL28107FBZ-T7	10/06/2015	10/12/2015	10/06/2016	ISL28107FUZ-T7
ISL28107FBZ-T7A	10/06/2015	10/12/2015	10/06/2016	ISL28107FUZ-T7
ISL28107FRTZ	10/06/2015	10/12/2015	10/06/2016	ISL28107FUZ-T7
ISL28107FRTZ-T13	10/06/2015	10/12/2015	10/06/2016	ISL28107FUZ-T7
ISL28107FRTZ-T7	10/06/2015	10/12/2015	10/06/2016	ISL28107FUZ-T7
ISL28107FRTZ-T7A	10/06/2015	10/12/2015	10/06/2016	ISL28107FUZ-T7
ISL28127FBZ	10/06/2015	10/12/2015	10/06/2016	ISL28127FRTZ-T13
ISL28127FBZ-T13	10/06/2015	10/12/2015	10/06/2016	ISL28127FRTZ-T13

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL28127FBZ-T7	10/06/2015	10/12/2015	10/06/2016	ISL28127FRTZ-T13
ISL28127FBZ-T7A	10/06/2015	10/12/2015	10/06/2016	ISL28127FRTZ-T13
ISL28127FRTBZ	10/06/2015	10/12/2015	10/06/2016	ISL28127FRTZ-T13
ISL28127FRTBZ-T13	10/06/2015	10/12/2015	10/06/2016	ISL28127FRTZ-T13
ISL28127FRTBZ-T7	10/06/2015	10/12/2015	10/06/2016	ISL28127FRTZ-T13
ISL28127FRTBZ-T7A	10/06/2015	10/12/2015	10/06/2016	ISL28127FRTZ-T13
ISL28127FUBZ	10/06/2015	10/12/2015	10/06/2016	ISL28127FRTZ-T13
ISL28127FUBZ-T13	10/06/2015	10/12/2015	10/06/2016	ISL28127FRTZ-T13
ISL28127FUBZ-T7	10/06/2015	10/12/2015	10/06/2016	ISL28127FRTZ-T13
ISL28127FUBZ-T7A	10/06/2015	10/12/2015	10/06/2016	ISL28127FRTZ-T13
ISL28127FUZ	10/06/2015	10/12/2015	10/06/2016	ISL28127FRTZ-T13
ISL28127FUZ-T13	10/06/2015	10/12/2015	10/06/2016	ISL28127FRTZ-T13
ISL28127FUZ-T7	10/06/2015	10/12/2015	10/06/2016	ISL28127FRTZ-T13
ISL28127FUZ-T7A	10/06/2015	10/12/2015	10/06/2016	ISL28127FRTZ-T13
ISL28133FRUZ-T7	10/06/2015	10/12/2015	10/06/2016	ISL28133FHZ-T7
ISL28156FBZ	10/06/2015	10/12/2015	10/06/2016	None
ISL28156FBZ-T7	10/06/2015	10/12/2015	10/06/2016	None
ISL28156FHZ-T7	10/06/2015	10/12/2015	10/06/2016	None
ISL28166FHZ-T7	10/06/2015	10/12/2015	10/06/2016	None
ISL28190FHZ-T7	10/06/2015	10/12/2015	10/06/2016	None
ISL28190FRUZ-T7	10/06/2015	10/12/2015	10/06/2016	None
ISL28213FHZ-T7	10/06/2015	10/12/2015	10/06/2016	ISL28213FBZ-T7
ISL28213FHZ-T7A	10/06/2015	10/12/2015	10/06/2016	ISL28213FBZ-T7
ISL28214FHZ-T7	10/06/2015	10/12/2015	10/06/2016	ISL28214FBZ-T7
ISL28214FHZ-T7A	10/06/2015	10/12/2015	10/06/2016	ISL28214FBZ-T7
ISL28258FBZ	10/06/2015	10/12/2015	10/06/2016	ISL28158FBZ-T7
ISL28258FBZ-T7	10/06/2015	10/12/2015	10/06/2016	ISL28158FBZ-T7
ISL28258FUZ	10/06/2015	10/12/2015	10/06/2016	ISL28158FBZ-T7
ISL28258FUZ-T7	10/06/2015	10/12/2015	10/06/2016	ISL28158FBZ-T7
ISL28271FAZ	10/06/2015	10/12/2015	10/06/2016	None
ISL28271FAZ-T7	10/06/2015	10/12/2015	10/06/2016	None
ISL28273FAZ	10/06/2015	10/12/2015	10/06/2016	None
ISL28273FAZ-T7	10/06/2015	10/12/2015	10/06/2016	None
ISL28417W	10/06/2015	10/12/2015	10/06/2016	None
ISL28617FVZ	10/06/2015	10/12/2015	10/06/2016	None
ISL28617FVZ-T13	10/06/2015	10/12/2015	10/06/2016	None
ISL28617FVZ-T7	10/06/2015	10/12/2015	10/06/2016	None
ISL28617FVZ-T7A	10/06/2015	10/12/2015	10/06/2016	None
ISL29007IROZ-T7	10/06/2015	10/12/2015	10/06/2016	None
ISL29008IROZ-T7	10/06/2015	10/12/2015	10/06/2016	None
ISL29010IROZ-T7	10/06/2015	10/12/2015	10/06/2016	None
ISL3035EIRTZ	10/06/2015	10/12/2015	10/06/2016	None
ISL3035EIRTZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL3035EIRUZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL3036EIRUZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL3036EIRUZ-T7A	10/06/2015	10/12/2015	10/06/2016	None
ISL3036EIRZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL3036EIRZ-T7A	10/06/2015	10/12/2015	10/06/2016	None
ISL3036EIRZ-TK	10/06/2015	10/12/2015	10/06/2016	None
ISL31472EIPZ	10/06/2015	10/12/2015	10/06/2016	ISL32472EIBZ
ISL31483EIBZ	10/06/2015	10/12/2015	10/06/2016	ISL32483EIBZ
ISL31483EIBZ-T	10/06/2015	10/12/2015	10/06/2016	ISL32483EIBZ-T
ISL31483EIBZ-T7A	10/06/2015	10/12/2015	10/06/2016	ISL32483EIBZ-T7A
ISL31490EIRTZ	10/06/2015	10/12/2015	10/06/2016	ISL32490EIBZ
ISL31490EIRTZ-T	10/06/2015	10/12/2015	10/06/2016	ISL32490EIBZ-T
ISL31490EIRTZ-T7A	10/06/2015	10/12/2015	10/06/2016	ISL32490EIBZ-T7A
ISL31490EIUZ	10/06/2015	10/12/2015	10/06/2016	ISL32490EIUZ
ISL31490EIUZ-T	10/06/2015	10/12/2015	10/06/2016	ISL32490EIUZ-T
ISL31490EIUZ-T7A	10/06/2015	10/12/2015	10/06/2016	ISL32490EIUZ-T7A

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL31492EIPZ	10/06/2015	10/12/2015	10/06/2016	ISL32492EUIZ
ISL31492EUIZ	10/06/2015	10/12/2015	10/06/2016	ISL32492EUIZ
ISL31492EUIZ-T	10/06/2015	10/12/2015	10/06/2016	ISL32492EUIZ-T
ISL31492EUIZ-T7A	10/06/2015	10/12/2015	10/06/2016	ISL32492EUIZ-T7A
ISL31493EIBZ	10/06/2015	10/12/2015	10/06/2016	ISL32493EIBZ
ISL31493EIBZ-T	10/06/2015	10/12/2015	10/06/2016	ISL32493EIBZ-T
ISL31493EIBZ-T7A	10/06/2015	10/12/2015	10/06/2016	ISL32493EIBZ-T7A
ISL31493EUIZ	10/06/2015	10/12/2015	10/06/2016	ISL32493EUIZ
ISL31493EUIZ-T	10/06/2015	10/12/2015	10/06/2016	ISL32493EUIZ-T
ISL31493EUIZ-T7A	10/06/2015	10/12/2015	10/06/2016	ISL32493EUIZ-T7A
ISL31495EUIZ-T7A	10/06/2015	10/12/2015	10/06/2016	ISL32495EUIZ-T7A
ISL31496EUIZ	10/06/2015	10/12/2015	10/06/2016	ISL32496EUIZ
ISL31496EUIZ-T	10/06/2015	10/12/2015	10/06/2016	ISL32496EUIZ-T
ISL31496EUIZ-T7A	10/06/2015	10/12/2015	10/06/2016	ISL32496EUIZ-T7A
ISL31498EUIZ	10/06/2015	10/12/2015	10/06/2016	ISL32498EUIZ
ISL31498EUIZ-T	10/06/2015	10/12/2015	10/06/2016	ISL32498EUIZ-T
ISL31498EUIZ-T7A	10/06/2015	10/12/2015	10/06/2016	ISL32498EUIZ-T7A
ISL3178AEMBZ	10/06/2015	10/12/2015	10/06/2016	None
ISL3178AEMBZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL43121IHZ-T	10/06/2015	10/12/2015	10/06/2016	ISL43120IHZ-T
ISL43122IHZ-T	10/06/2015	10/12/2015	10/06/2016	ISL43120IHZ-T
ISL43142IBZ	10/06/2015	10/12/2015	10/06/2016	ISL43120IHZ-T
ISL43142IBZ-T	10/06/2015	10/12/2015	10/06/2016	ISL43120IHZ-T
ISL43142IVZ	10/06/2015	10/12/2015	10/06/2016	ISL43120IHZ-T
ISL43142IVZ-T	10/06/2015	10/12/2015	10/06/2016	ISL43120IHZ-T
ISL43144IRZ	10/06/2015	10/12/2015	10/06/2016	ISL43120IHZ-T
ISL43144IRZ-T	10/06/2015	10/12/2015	10/06/2016	ISL43120IHZ-T
ISL43841IRZ	10/06/2015	10/12/2015	10/06/2016	ISL43840IRZ-T
ISL43841IRZ-T	10/06/2015	10/12/2015	10/06/2016	ISL43840IRZ-T
ISL43L111IHZ-T	10/06/2015	10/12/2015	10/06/2016	ISL43L210IHZ-T
ISL43L120IRZ	10/06/2015	10/12/2015	10/06/2016	ISL43L210IHZ-T
ISL43L120IRZ-T	10/06/2015	10/12/2015	10/06/2016	ISL43L210IHZ-T
ISL43L120IUIZ	10/06/2015	10/12/2015	10/06/2016	ISL43L210IHZ-T
ISL43L120IUIZ-T	10/06/2015	10/12/2015	10/06/2016	ISL43L210IHZ-T
ISL43L121IRZ	10/06/2015	10/12/2015	10/06/2016	ISL43L210IHZ-T
ISL43L121IRZ-T	10/06/2015	10/12/2015	10/06/2016	ISL43L210IHZ-T
ISL43L121IUIZ	10/06/2015	10/12/2015	10/06/2016	ISL43L210IHZ-T
ISL43L121IUIZ-T	10/06/2015	10/12/2015	10/06/2016	ISL43L210IHZ-T
ISL43L122IRZ	10/06/2015	10/12/2015	10/06/2016	ISL43L210IHZ-T
ISL43L122IRZ-T	10/06/2015	10/12/2015	10/06/2016	ISL43L210IHZ-T
ISL43L122IUIZ	10/06/2015	10/12/2015	10/06/2016	ISL43L210IHZ-T
ISL43L122IUIZ-T	10/06/2015	10/12/2015	10/06/2016	ISL43L210IHZ-T
ISL43L122IUIZ-TS2568	10/06/2015	10/12/2015	10/06/2016	ISL43L210IHZ-T
ISL43L220IRZ	10/06/2015	10/12/2015	10/06/2016	ISL43L210IHZ-T
ISL43L220IRZ-T	10/06/2015	10/12/2015	10/06/2016	ISL43L210IHZ-T
ISL43L410IRZ	10/06/2015	10/12/2015	10/06/2016	ISL43L210IHZ-T
ISL43L410IRZ-T	10/06/2015	10/12/2015	10/06/2016	ISL43L210IHZ-T
ISL43L410IUIZ	10/06/2015	10/12/2015	10/06/2016	ISL43L210IHZ-T
ISL43L410IUIZ-T	10/06/2015	10/12/2015	10/06/2016	ISL43L210IHZ-T
ISL43L710IUIZ	10/06/2015	10/12/2015	10/06/2016	ISL43L210IHZ-T
ISL43L710IUIZ-T	10/06/2015	10/12/2015	10/06/2016	ISL43L210IHZ-T
ISL43L712IRZ	10/06/2015	10/12/2015	10/06/2016	ISL43L210IHZ-T
ISL43L712IRZ-T	10/06/2015	10/12/2015	10/06/2016	ISL43L210IHZ-T
ISL45041IRZR5486	10/06/2015	10/12/2015	10/06/2016	None
ISL45041IRZ-TR5486	10/06/2015	10/12/2015	10/06/2016	None
ISL5120CBZ	10/06/2015	10/12/2015	10/06/2016	ISL5120IHZ-T
ISL5120CBZ-T	10/06/2015	10/12/2015	10/06/2016	ISL5120IHZ-T
ISL5120IBZ	10/06/2015	10/12/2015	10/06/2016	ISL5120IHZ-T
ISL5120IBZ-T	10/06/2015	10/12/2015	10/06/2016	ISL5120IHZ-T

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL5121CBZ	10/06/2015	10/12/2015	10/06/2016	ISL5120IHZ-T
ISL5121CBZ-T	10/06/2015	10/12/2015	10/06/2016	ISL5120IHZ-T
ISL5121IBZ	10/06/2015	10/12/2015	10/06/2016	ISL5120IHZ-T
ISL5121IBZ-T	10/06/2015	10/12/2015	10/06/2016	ISL5120IHZ-T
ISL5121IHZ-T	10/06/2015	10/12/2015	10/06/2016	ISL5120IHZ-T
ISL5122CBZ	10/06/2015	10/12/2015	10/06/2016	ISL5120IHZ-T
ISL5122CBZ-T	10/06/2015	10/12/2015	10/06/2016	ISL5120IHZ-T
ISL5122IBZ	10/06/2015	10/12/2015	10/06/2016	ISL5120IHZ-T
ISL5122IBZ-T	10/06/2015	10/12/2015	10/06/2016	ISL5120IHZ-T
ISL5122IHZ-T	10/06/2015	10/12/2015	10/06/2016	ISL5120IHZ-T
ISL5123CBZ	10/06/2015	10/12/2015	10/06/2016	ISL5120IHZ-T
ISL5123CBZ-T	10/06/2015	10/12/2015	10/06/2016	ISL5120IHZ-T
ISL5123IBZ	10/06/2015	10/12/2015	10/06/2016	ISL5120IHZ-T
ISL5123IBZ-T	10/06/2015	10/12/2015	10/06/2016	ISL5120IHZ-T
ISL5123IHZ-T	10/06/2015	10/12/2015	10/06/2016	ISL5120IHZ-T
ISL5216W	10/06/2015	10/12/2015	10/06/2016	None
ISL5217W	10/06/2015	10/12/2015	10/06/2016	None
ISL5239KI	10/06/2015	10/12/2015	10/06/2016	None
ISL5239KIZ	10/06/2015	10/12/2015	10/06/2016	None
ISL53562IAR5261	10/06/2015	10/12/2015	10/06/2016	None
ISL53582AWS2571	10/06/2015	10/12/2015	10/06/2016	None
ISL54000IRTZ	10/06/2015	10/12/2015	10/06/2016	None
ISL54000IRTZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL54001IRTZ	10/06/2015	10/12/2015	10/06/2016	None
ISL54001IRTZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL54002IRTZ	10/06/2015	10/12/2015	10/06/2016	None
ISL54002IRTZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL54003IRTZ	10/06/2015	10/12/2015	10/06/2016	None
ISL54003IRTZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL54004IRTZ	10/06/2015	10/12/2015	10/06/2016	None
ISL54004IRTZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL54005IRTZ	10/06/2015	10/12/2015	10/06/2016	None
ISL54005IRTZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL54006IRTZ	10/06/2015	10/12/2015	10/06/2016	None
ISL54006IRTZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL54047IRUZ-T	10/06/2015	10/12/2015	10/06/2016	ISL54050IRUZ-T
ISL54048IRUZ-T	10/06/2015	10/12/2015	10/06/2016	ISL54050IRUZ-T
ISL54049IRUZ-T	10/06/2015	10/12/2015	10/06/2016	ISL54050IRUZ-T
ISL54054IHZ-T	10/06/2015	10/12/2015	10/06/2016	ISL54050IRUZ-T
ISL54054IRUZ-T	10/06/2015	10/12/2015	10/06/2016	ISL54050IRUZ-T
ISL54055IRUZ-T	10/06/2015	10/12/2015	10/06/2016	ISL54050IRUZ-T
ISL54056IRUZ-T	10/06/2015	10/12/2015	10/06/2016	ISL54050IRUZ-T
ISL54057IRUZ-T	10/06/2015	10/12/2015	10/06/2016	ISL54050IRUZ-T
ISL54066IRTZ	10/06/2015	10/12/2015	10/06/2016	None
ISL54066IRTZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL54066IRUZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL54105CRZ	10/06/2015	10/12/2015	10/06/2016	ISL54105ACRZ
ISL54106CRZ	10/06/2015	10/12/2015	10/06/2016	ISL54106ACRZ
ISL54205AIRUZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL54205AIRZ	10/06/2015	10/12/2015	10/06/2016	None
ISL54205AIRZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL54205BIRTZ	10/06/2015	10/12/2015	10/06/2016	None
ISL54205BIRTZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL54205BIRUZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL54206AIRTZ	10/06/2015	10/12/2015	10/06/2016	None
ISL54206AIRTZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL54206AIRUZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL54206IRUZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL54206IRZ	10/06/2015	10/12/2015	10/06/2016	None

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL54206IRZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL54207IRUZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL54207IRZ	10/06/2015	10/12/2015	10/06/2016	None
ISL54207IRZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL54208IRUZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL54208IRZ	10/06/2015	10/12/2015	10/06/2016	None
ISL54208IRZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL54209IRTZ	10/06/2015	10/12/2015	10/06/2016	None
ISL54209IRTZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL54209IRU1Z-T	10/06/2015	10/12/2015	10/06/2016	None
ISL54209IRUZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL54209IRUZ-T7A	10/06/2015	10/12/2015	10/06/2016	None
ISL54210IRTZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL54212IRTZ	10/06/2015	10/12/2015	10/06/2016	None
ISL54212IRTZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL54212IRUZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL54213IRTZ	10/06/2015	10/12/2015	10/06/2016	None
ISL54213IRTZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL54213IRUZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL54215IRUZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL54226IRTZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL54226IRTZ-T7A	10/06/2015	10/12/2015	10/06/2016	None
ISL54226IRUZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL54226IRUZ-T7A	10/06/2015	10/12/2015	10/06/2016	None
ISL54228IRTZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL54228IRTZ-T7A	10/06/2015	10/12/2015	10/06/2016	None
ISL54228IRUZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL54228IRUZ-T7A	10/06/2015	10/12/2015	10/06/2016	None
ISL54230IHZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL54230IRTZ	10/06/2015	10/12/2015	10/06/2016	None
ISL54230IRTZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL54300IRZRS258	10/06/2015	10/12/2015	10/06/2016	None
ISL54300IRZ-TR5258	10/06/2015	10/12/2015	10/06/2016	None
ISL54302IRZ	10/06/2015	10/12/2015	10/06/2016	ISL54050IRUZ-T
ISL54302IRZ-T	10/06/2015	10/12/2015	10/06/2016	ISL54050IRUZ-T
ISL54400IRUZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL54400IRZ	10/06/2015	10/12/2015	10/06/2016	None
ISL54400IRZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL54401IRUZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL54401IRZ	10/06/2015	10/12/2015	10/06/2016	None
ISL54401IRZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL54402IRUZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL54402IRUZ-TS2038	10/06/2015	10/12/2015	10/06/2016	None
ISL54402IRUZ-TS2687	10/06/2015	10/12/2015	10/06/2016	None
ISL54402IRZ	10/06/2015	10/12/2015	10/06/2016	None
ISL54402IRZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL54415IRUZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL54416IRUZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL54417IRUZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL54500IHZ-T	10/06/2015	10/12/2015	10/06/2016	ISL54050IRUZ-T
ISL54500IRUZ-T	10/06/2015	10/12/2015	10/06/2016	ISL54050IRUZ-T
ISL54501IHZ-T	10/06/2015	10/12/2015	10/06/2016	ISL54050IRUZ-T
ISL54501IRUZ-T	10/06/2015	10/12/2015	10/06/2016	ISL54050IRUZ-T
ISL54502IHZ-T	10/06/2015	10/12/2015	10/06/2016	ISL54050IRUZ-T
ISL54502IRUZ-T	10/06/2015	10/12/2015	10/06/2016	ISL54050IRUZ-T
ISL54503IHZ-T	10/06/2015	10/12/2015	10/06/2016	ISL54050IRUZ-T
ISL54503IRUZ-T	10/06/2015	10/12/2015	10/06/2016	ISL54050IRUZ-T
ISL54504IHZ-T	10/06/2015	10/12/2015	10/06/2016	ISL54050IRUZ-T
ISL54504IRUZ-T	10/06/2015	10/12/2015	10/06/2016	ISL54050IRUZ-T

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL54505IHZ-T	10/06/2015	10/12/2015	10/06/2016	ISL54050IRUZ-T
ISL54505IRUZ-T	10/06/2015	10/12/2015	10/06/2016	ISL54050IRUZ-T
ISL55020IRZ	10/06/2015	10/12/2015	10/06/2016	None
ISL55020IRZ-T13	10/06/2015	10/12/2015	10/06/2016	None
ISL55036IRTZ	10/06/2015	10/12/2015	10/06/2016	None
ISL55036IRTZ-T13	10/06/2015	10/12/2015	10/06/2016	None
ISL55119IRTZ	10/06/2015	10/12/2015	10/06/2016	None
ISL55119IRTZ-TK	10/06/2015	10/12/2015	10/06/2016	None
ISL55141IRZ	10/06/2015	10/12/2015	10/06/2016	None
ISL55141IRZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL55141IVZ	10/06/2015	10/12/2015	10/06/2016	None
ISL55141IVZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL55142IRZ	10/06/2015	10/12/2015	10/06/2016	None
ISL55142IRZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL55142IVZ	10/06/2015	10/12/2015	10/06/2016	None
ISL55142IVZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL55190IBZ	10/06/2015	10/12/2015	10/06/2016	None
ISL55190IBZ-T13	10/06/2015	10/12/2015	10/06/2016	None
ISL55290IUZ	10/06/2015	10/12/2015	10/06/2016	None
ISL55290IUZ-T13	10/06/2015	10/12/2015	10/06/2016	None
ISL5571AIBZ	10/06/2015	10/12/2015	10/06/2016	None
ISL5571AIBZS2693	10/06/2015	10/12/2015	10/06/2016	None
ISL5571AIBZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL5571AIBZ-TS2693	10/06/2015	10/12/2015	10/06/2016	None
ISL5627INZ	10/06/2015	10/12/2015	10/06/2016	None
ISL5629/2INZ	10/06/2015	10/12/2015	10/06/2016	None
ISL5629INZ	10/06/2015	10/12/2015	10/06/2016	None
ISL5727INZ	10/06/2015	10/12/2015	10/06/2016	None
ISL5729/2INZ	10/06/2015	10/12/2015	10/06/2016	None
ISL5729INZ	10/06/2015	10/12/2015	10/06/2016	None
ISL5757IBZ	10/06/2015	10/12/2015	10/06/2016	None
ISL5761/2IBZ	10/06/2015	10/12/2015	10/06/2016	ISL5761IAZ
ISL5761IBZ	10/06/2015	10/12/2015	10/06/2016	ISL5761IAZ
ISL5827INZ	10/06/2015	10/12/2015	10/06/2016	None
ISL5829/2INZ	10/06/2015	10/12/2015	10/06/2016	None
ISL5829INZ	10/06/2015	10/12/2015	10/06/2016	None
ISL58334CIZ-T7	10/06/2015	10/12/2015	10/06/2016	None
ISL58334CIZ-T7A	10/06/2015	10/12/2015	10/06/2016	None
ISL58344CIZ-T7	10/06/2015	10/12/2015	10/06/2016	None
ISL58344CIZ-T7A	10/06/2015	10/12/2015	10/06/2016	None
ISL5857IBZ	10/06/2015	10/12/2015	10/06/2016	ISL5857IAZ
ISL5861/2IBZ	10/06/2015	10/12/2015	10/06/2016	ISL5861IAZ
ISL5861IBZ	10/06/2015	10/12/2015	10/06/2016	ISL5861IAZ
ISL59112IEZ-T7	10/06/2015	10/12/2015	10/06/2016	ISL59110IEZ-T7
ISL59114IRUZ	10/06/2015	10/12/2015	10/06/2016	None
ISL59115IRUZ-T7	10/06/2015	10/12/2015	10/06/2016	None
ISL59116IIZ-T7	10/06/2015	10/12/2015	10/06/2016	None
ISL59119IBZ-T13	10/06/2015	10/12/2015	10/06/2016	None
ISL59123IIZ-T7	10/06/2015	10/12/2015	10/06/2016	None
ISL5927INZ	10/06/2015	10/12/2015	10/06/2016	None
ISL5929INZ	10/06/2015	10/12/2015	10/06/2016	None
ISL59421IUZ	10/06/2015	10/12/2015	10/06/2016	None
ISL59421IUZ-T13	10/06/2015	10/12/2015	10/06/2016	None
ISL59421IUZ-T7	10/06/2015	10/12/2015	10/06/2016	None
ISL59441IAZ	10/06/2015	10/12/2015	10/06/2016	None
ISL59441IAZ-T13	10/06/2015	10/12/2015	10/06/2016	None
ISL59441IAZ-T7	10/06/2015	10/12/2015	10/06/2016	None
ISL59442IBZ	10/06/2015	10/12/2015	10/06/2016	None
ISL59442IBZS2714	10/06/2015	10/12/2015	10/06/2016	None

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL59442IBZ-T13	10/06/2015	10/12/2015	10/06/2016	None
ISL59442IBZ-T7	10/06/2015	10/12/2015	10/06/2016	None
ISL59442IBZ-T7S2714	10/06/2015	10/12/2015	10/06/2016	None
ISL59444IBZ	10/06/2015	10/12/2015	10/06/2016	None
ISL59444IBZ-T13	10/06/2015	10/12/2015	10/06/2016	None
ISL59444IBZ-T7	10/06/2015	10/12/2015	10/06/2016	None
ISL59448IAZ	10/06/2015	10/12/2015	10/06/2016	None
ISL59448IAZ-T7	10/06/2015	10/12/2015	10/06/2016	None
ISL59448IAZ-T7S2490	10/06/2015	10/12/2015	10/06/2016	None
ISL59481IRZ	10/06/2015	10/12/2015	10/06/2016	None
ISL59481IRZ-T13	10/06/2015	10/12/2015	10/06/2016	None
ISL59530IKZ	10/06/2015	10/12/2015	10/06/2016	None
ISL5957IBZ	10/06/2015	10/12/2015	10/06/2016	ISL5957IAZ
ISL5961/2IBZ	10/06/2015	10/12/2015	10/06/2016	ISL5961/2IAZ
ISL5961IBZ	10/06/2015	10/12/2015	10/06/2016	ISL5961IAZ
ISL59831IRTZ	10/06/2015	10/12/2015	10/06/2016	None
ISL59831IRTZ-T7	10/06/2015	10/12/2015	10/06/2016	None
ISL59832IRZ	10/06/2015	10/12/2015	10/06/2016	None
ISL59921IRZ	10/06/2015	10/12/2015	10/06/2016	None
ISL59921IRZ-T7	10/06/2015	10/12/2015	10/06/2016	None
ISL59922IRZ-T7	10/06/2015	10/12/2015	10/06/2016	None
ISL59923IRZ	10/06/2015	10/12/2015	10/06/2016	None
ISL59923IRZ-T7	10/06/2015	10/12/2015	10/06/2016	None
ISL6115CBZAR5217	10/06/2015	10/12/2015	10/06/2016	ISL6115CBZA-T
ISL6115CBZAS2695	10/06/2015	10/12/2015	10/06/2016	ISL6115CBZA-T
ISL6115CBZA-TS2490S	10/06/2015	10/12/2015	10/06/2016	ISL6115CBZA-T
ISL6115CBZA-TS2490S1	10/06/2015	10/12/2015	10/06/2016	ISL6115CBZA-T
ISL6115CBZA-TS2490S2	10/06/2015	10/12/2015	10/06/2016	ISL6115CBZA-T
ISL6115CBZA-TS2490S3	10/06/2015	10/12/2015	10/06/2016	ISL6115CBZA-T
ISL6115CBZA-TS2490S4	10/06/2015	10/12/2015	10/06/2016	ISL6115CBZA-T
ISL6115CBZA-TS2568	10/06/2015	10/12/2015	10/06/2016	ISL6115CBZA-T
ISL6115CBZA-TS2695	10/06/2015	10/12/2015	10/06/2016	ISL6115CBZA-T
ISL6116CBZA	10/06/2015	10/12/2015	10/06/2016	None
ISL6116CBZAS2695	10/06/2015	10/12/2015	10/06/2016	None
ISL6116CBZA-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6116CBZA-TS2490S	10/06/2015	10/12/2015	10/06/2016	None
ISL6116CBZA-TS2695	10/06/2015	10/12/2015	10/06/2016	None
ISL6116CBZA-TS2705	10/06/2015	10/03/2016	10/03/2017	None
ISL6117CBZAR5217	10/06/2015	10/12/2015	10/06/2016	ISL6117CBZA
ISL6117CBZA-TR5217	10/06/2015	10/12/2015	10/06/2016	ISL6117CBZA-T
ISL6117CBZA-TS2490S	10/06/2015	10/12/2015	10/06/2016	ISL6117CBZA-T
ISL6118HIBZA	10/06/2015	10/12/2015	10/06/2016	None
ISL6118HIBZA-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6118HIBZA-TS2705	10/06/2015	10/03/2016	10/03/2017	None
ISL6119HIBZA-TS2568	10/06/2015	10/12/2015	10/06/2016	ISL6119HIBZA-T
ISL6119LIBZA-TS2715	10/06/2015	10/12/2015	10/06/2016	ISL6119LIBZA-T
ISL6120CBZA	10/06/2015	10/12/2015	10/06/2016	None
ISL6120CBZA-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6140IB-T	10/06/2015	10/12/2015	10/06/2016	ISL6140IBZ-T
ISL6142CBZA	10/06/2015	10/12/2015	10/06/2016	None
ISL6142CBZA-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6142IBZA	10/06/2015	10/12/2015	10/06/2016	None
ISL6142IBZA-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6144IVZA-TS2568	10/06/2015	10/12/2015	10/06/2016	ISL6144IVZA-T
ISL6150CB	10/06/2015	10/12/2015	10/06/2016	ISL6150CBZ
ISL6150IB-T	10/06/2015	10/12/2015	10/06/2016	ISL6150IBZ-T
ISL6151CBZA	10/06/2015	10/12/2015	10/06/2016	None
ISL6151CBZA-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6151IBZA	10/06/2015	10/12/2015	10/06/2016	None

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL6151IBZA-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6152CBZA	10/06/2015	10/12/2015	10/06/2016	None
ISL6152CBZA-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6152IBZA	10/06/2015	10/12/2015	10/06/2016	None
ISL6152IBZA-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6160CBZA	10/06/2015	10/12/2015	10/06/2016	None
ISL6160CBZA-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6161IBZA	10/06/2015	10/12/2015	10/06/2016	ISL6161CBZA
ISL6161IBZA-T	10/06/2015	10/12/2015	10/06/2016	ISL6161CBZA-T
ISL6207HBZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6216CAZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6217ACVZA-TS2490	10/06/2015	10/12/2015	10/06/2016	None
ISL6217ACVZ-TS2490	10/06/2015	10/12/2015	10/06/2016	None
ISL6223CAZA	10/06/2015	10/12/2015	10/06/2016	None
ISL6223CAZAR5194	10/06/2015	10/12/2015	10/06/2016	None
ISL6223CAZA-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6223CAZA-TR5194	10/06/2015	10/12/2015	10/06/2016	None
ISL6224CAZ	10/06/2015	10/12/2015	10/06/2016	None
ISL6224CAZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6225CAZ	10/06/2015	10/12/2015	10/06/2016	None
ISL6225CAZA	10/06/2015	10/12/2015	10/06/2016	None
ISL6225CAZA-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6225CAZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6225CAZ-TR5189	10/06/2015	10/12/2015	10/06/2016	None
ISL6225CAZ-TS2568	10/06/2015	10/12/2015	10/06/2016	None
ISL6237IRZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL62381CHRTZ	10/06/2015	10/12/2015	10/06/2016	None
ISL62381CHRTZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL62382CHRTZ	10/06/2015	10/12/2015	10/06/2016	None
ISL62382CHRTZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL62391CHRTZ	10/06/2015	10/12/2015	10/06/2016	None
ISL62391CHRTZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL62391CIRTZ	10/06/2015	10/12/2015	10/06/2016	None
ISL62391CIRTZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6251AHAZR5283	10/06/2015	10/12/2015	10/06/2016	None
ISL6251AHAZ-TR5283	10/06/2015	10/12/2015	10/06/2016	None
ISL6252AHAZ	10/06/2015	10/12/2015	10/06/2016	None
ISL6252AHAZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6252AHRZ	10/06/2015	10/12/2015	10/06/2016	None
ISL6252AHRZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6252HAZ	10/06/2015	10/12/2015	10/06/2016	None
ISL6252HAZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6252HRZ	10/06/2015	10/12/2015	10/06/2016	None
ISL6252HRZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6255HAZR5283	10/06/2015	10/12/2015	10/06/2016	None
ISL6255HAZ-TR5283	10/06/2015	10/12/2015	10/06/2016	None
ISL6255HRZR5283	10/06/2015	10/12/2015	10/06/2016	None
ISL6255HRZ-TR5283	10/06/2015	10/12/2015	10/06/2016	None
ISL6266HRZ	10/06/2015	10/12/2015	10/06/2016	None
ISL6266HRZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6269CRZ	10/06/2015	10/12/2015	10/06/2016	None
ISL6269CRZR5194	10/06/2015	10/12/2015	10/06/2016	None
ISL6269CRZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6269CRZ-TR5194	10/06/2015	10/12/2015	10/06/2016	None
ISL6269IRZ	10/06/2015	10/12/2015	10/06/2016	None
ISL6271ACRZR5463	10/06/2015	10/12/2015	10/06/2016	None
ISL6271ACRZ-TR5463	10/06/2015	10/12/2015	10/06/2016	None
ISL6273IRZS2695	10/06/2015	10/12/2015	10/06/2016	None
ISL6273IRZ-TS2687	10/06/2015	10/12/2015	10/06/2016	None

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL6273IRZ-TS2695	10/06/2015	10/12/2015	10/06/2016	None
ISL6274AIRZ-TR5256	10/06/2015	10/12/2015	10/06/2016	None
ISL62873HRUZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6292DCRZ	10/06/2015	10/12/2015	10/06/2016	None
ISL6292DCRZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6293-2CRZ	10/06/2015	10/12/2015	10/06/2016	None
ISL6293-2CRZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6294AIRZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6296ADHZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6296DHZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6296DHZ-TR5287	10/06/2015	10/12/2015	10/06/2016	None
ISL6296DRZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6296DRZ-TR5266	10/06/2015	10/12/2015	10/06/2016	None
ISL6296W	10/06/2015	10/12/2015	10/06/2016	None
ISL6297CRZ	10/06/2015	10/12/2015	10/06/2016	None
ISL6297CRZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6299AIRZ	10/06/2015	10/12/2015	10/06/2016	ISL9214AIRZ
ISL6299AIRZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9214AIRZ
ISL6299AIRZ-TS2697	10/06/2015	10/12/2015	10/06/2016	ISL9214AIRZ
ISL6299IRZ	10/06/2015	10/12/2015	10/06/2016	ISL9214AIRZ
ISL6299IRZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9214AIRZ
ISL6299IRZ-TS2688	10/06/2015	10/12/2015	10/06/2016	ISL9214AIRZ
ISL6312CRZ-TR5453	10/06/2015	10/12/2015	10/06/2016	None
ISL6313BCRZ-TS2568	10/06/2015	10/12/2015	10/06/2016	ISL6313BCRZ-T
ISL6313BCRZ-TS2704	10/06/2015	10/12/2015	10/06/2016	ISL6313BCRZ-T
ISL6314CRZ-TR5453	10/06/2015	10/12/2015	10/06/2016	None
ISL6328CRZ	10/06/2015	10/12/2015	10/06/2016	None
ISL6328CRZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6341CRZ-TS2568	10/06/2015	10/12/2015	10/06/2016	ISL6341BIRZ-T
ISL6364ACRZ-TS2490	10/06/2015	10/12/2015	10/06/2016	None
ISL6401CB	10/06/2015	10/12/2015	10/06/2016	ISL6401CBZ
ISL6401CB-T	10/06/2015	10/12/2015	10/06/2016	ISL6401CBZ-T
ISL6401CRZ	10/06/2015	10/12/2015	10/06/2016	ISL6401CBZ
ISL6401CRZ-T	10/06/2015	10/12/2015	10/06/2016	ISL6401CBZ-T
ISL6401CRZ-TS2705	10/06/2015	10/03/2016	10/03/2017	ISL6401CBZ-T
ISL6406IBZ	10/06/2015	10/12/2015	10/06/2016	ISL6406IVZ
ISL6406IBZ-T	10/06/2015	10/12/2015	10/06/2016	ISL6406IVZ-T
ISL6406XC	10/06/2015	10/12/2015	10/06/2016	None
ISL6410AIUZ-TKS2695	10/06/2015	10/12/2015	10/06/2016	ISL6410AIUZ
ISL6412IRZ	10/06/2015	10/12/2015	10/06/2016	None
ISL6412IRZ-TK	10/06/2015	10/12/2015	10/06/2016	None
ISL6416IAZ	10/06/2015	10/12/2015	10/06/2016	None
ISL6416IAZ-TK	10/06/2015	10/12/2015	10/06/2016	None
ISL6422BEVEZ	10/06/2015	10/12/2015	10/06/2016	ISL6422BERZ
ISL6422BEVEZ-T	10/06/2015	10/12/2015	10/06/2016	ISL6422BERZ-T
ISL6439AIBZ-TS2705	10/06/2015	10/03/2016	10/03/2017	ISL6439AIBZ-T
ISL6439CBZ	10/06/2015	10/12/2015	10/06/2016	ISL6439IBZ
ISL6439CBZ-T	10/06/2015	10/12/2015	10/06/2016	ISL6439IBZ-T
ISL6442IAZ-TKS2568	10/06/2015	10/12/2015	10/06/2016	ISL6442IAZ-TK
ISL6442IAZ-TKS2715	10/06/2015	10/12/2015	10/06/2016	ISL6442IAZ-TK
ISL6443AIVZ	10/06/2015	10/12/2015	10/06/2016	ISL6443AIRZ
ISL6443AIVZ-TK	10/06/2015	10/12/2015	10/06/2016	ISL6443AIRZ-TK
ISL6444CAZ	10/06/2015	10/12/2015	10/06/2016	None
ISL6444CAZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6504CBZ	10/06/2015	10/12/2015	10/06/2016	None
ISL6504CBZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6506BIBZ	10/06/2015	10/12/2015	10/06/2016	None
ISL6506BIBZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6506CBZ	10/06/2015	10/12/2015	10/06/2016	None

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL6506CBZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6520ACBZR5194	10/06/2015	10/12/2015	10/06/2016	None
ISL6520ACBZR5217	10/06/2015	10/12/2015	10/06/2016	None
ISL6520ACBZ-TR5194	10/06/2015	10/12/2015	10/06/2016	None
ISL6520ACBZ-TR5217	10/06/2015	10/12/2015	10/06/2016	None
ISL6520AIBZS2698	10/06/2015	10/12/2015	10/06/2016	None
ISL6520AIBZ-TS2698	10/06/2015	10/12/2015	10/06/2016	None
ISL6520BCBZR5194	10/06/2015	10/12/2015	10/06/2016	None
ISL6520BCBZ-TR5194	10/06/2015	10/12/2015	10/06/2016	None
ISL6520CBZ	10/06/2015	10/12/2015	10/06/2016	None
ISL6520CBZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6520IBZ	10/06/2015	10/12/2015	10/06/2016	None
ISL6520IBZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6521CBZ	10/06/2015	10/12/2015	10/06/2016	None
ISL6521CBZA	10/06/2015	10/12/2015	10/06/2016	None
ISL6521CBZA-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6521CBZS2698	10/06/2015	10/12/2015	10/06/2016	None
ISL6521CBZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6521CBZ-TS2568	10/06/2015	10/12/2015	10/06/2016	None
ISL6521CBZ-TS2698	10/06/2015	10/12/2015	10/06/2016	None
ISL6521IBZ	10/06/2015	10/12/2015	10/06/2016	None
ISL6521IBZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6522BCBZ	10/06/2015	10/12/2015	10/06/2016	ISL6522BIBZ
ISL6522BCBZ-T	10/06/2015	10/12/2015	10/06/2016	ISL6522BIBZ-T
ISL6522BCRZ	10/06/2015	10/12/2015	10/06/2016	ISL6535CRZ-T
ISL6522BCRZ-T	10/06/2015	10/12/2015	10/06/2016	ISL6535CRZ-T
ISL6522BIBZS2698	10/06/2015	10/12/2015	10/06/2016	ISL6522BIBZ
ISL6522BIBZ-TS2698	10/06/2015	10/12/2015	10/06/2016	ISL6522BIBZ-T
ISL6522BIRZR5190	10/06/2015	10/12/2015	10/06/2016	ISL6522BIRZ
ISL6522BIRZS2698	10/06/2015	10/12/2015	10/06/2016	ISL6522BIRZ
ISL6522BIRZ-TKS2698	10/06/2015	10/12/2015	10/06/2016	ISL6522BIRZ-TK
ISL6522BIRZ-TS2698	10/06/2015	10/12/2015	10/06/2016	ISL6522BIRZ-T
ISL6522CBZA	10/06/2015	10/12/2015	10/06/2016	ISL6522CBZ
ISL6522CBZAR5190	10/06/2015	10/12/2015	10/06/2016	ISL6522CBZ
ISL6522CBZA-T	10/06/2015	10/12/2015	10/06/2016	ISL6522CBZ-T
ISL6522CBZA-TR5190	10/06/2015	10/12/2015	10/06/2016	ISL6522CBZ-T
ISL6522CBZR5190	10/06/2015	10/12/2015	10/06/2016	ISL6522CBZ
ISL6522CBZ-TS2462	10/06/2015	10/12/2015	10/06/2016	ISL6522CBZ-T
ISL6522CBZ-TS2713	10/06/2015	10/12/2015	10/06/2016	ISL6522CBZ-T
ISL6522CRZR5190	10/06/2015	10/12/2015	10/06/2016	ISL6522CRZ
ISL6522CRZS2462	10/06/2015	10/12/2015	10/06/2016	ISL6522CRZ
ISL6522CRZ-TR5190	10/06/2015	10/12/2015	10/06/2016	ISL6522CRZ-T
ISL6522CVZ	10/06/2015	10/12/2015	10/06/2016	None
ISL6522CVZR5190	10/06/2015	10/12/2015	10/06/2016	None
ISL6522CVZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6522CVZ-TR5190	10/06/2015	10/12/2015	10/06/2016	None
ISL6522CVZ-TS2462	10/06/2015	10/12/2015	10/06/2016	None
ISL6522IBZR5190	10/06/2015	10/12/2015	10/06/2016	ISL6522IBZ
ISL6522IBZS2698	10/06/2015	10/12/2015	10/06/2016	ISL6522IBZ
ISL6522IBZ-TR5190	10/06/2015	10/12/2015	10/06/2016	ISL6522IBZ-T
ISL6522IBZ-TS2698	10/06/2015	10/12/2015	10/06/2016	ISL6522IBZ-T
ISL6522IRZR5190	10/06/2015	10/12/2015	10/06/2016	ISL6522IRZ
ISL6522IRZS2698	10/06/2015	10/12/2015	10/06/2016	ISL6522IRZ
ISL6522IRZ-TKR5190	10/06/2015	10/12/2015	10/06/2016	ISL6522IRZ-TK
ISL6522IRZ-TKS2698	10/06/2015	10/12/2015	10/06/2016	ISL6522IRZ-TK
ISL6522IRZ-TR5190	10/06/2015	10/12/2015	10/06/2016	ISL6522IRZ-T
ISL6522IRZ-TS2698	10/06/2015	10/12/2015	10/06/2016	ISL6522IRZ-T
ISL6522IVZ	10/06/2015	10/12/2015	10/06/2016	None
ISL6522IVZS2698	10/06/2015	10/12/2015	10/06/2016	None

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL6522IVZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6522IVZ-TS2698	10/06/2015	10/12/2015	10/06/2016	None
ISL6523CBZ	10/06/2015	10/12/2015	10/06/2016	None
ISL6523CBZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6524ACBZ	10/06/2015	10/12/2015	10/06/2016	None
ISL6524ACBZA-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6524ACBZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6526ACBZ	10/06/2015	10/12/2015	10/06/2016	ISL6526AIRZ
ISL6526ACBZ-T	10/06/2015	10/12/2015	10/06/2016	ISL6526AIRZ-T
ISL6526AIRZ-TKR5426	10/06/2015	10/12/2015	10/06/2016	ISL6526AIRZ-TK
ISL6526CBZR5217	10/06/2015	10/12/2015	10/06/2016	ISL6526CBZ-T
ISL6526CBZ-TR5217	10/06/2015	10/12/2015	10/06/2016	ISL6526CBZ-T
ISL6526CRZ	10/06/2015	10/12/2015	10/06/2016	ISL6526IRZ
ISL6526CRZ-T	10/06/2015	10/12/2015	10/06/2016	ISL6526IRZ-T
ISL6526IBZR5146	10/06/2015	10/12/2015	10/06/2016	ISL6526IBZ
ISL6526IBZ-TR5146	10/06/2015	10/12/2015	10/06/2016	ISL6526IBZ-T
ISL6527ACRZ	10/06/2015	10/12/2015	10/06/2016	ISL6527ACBZ
ISL6527ACRZ-T	10/06/2015	10/12/2015	10/06/2016	ISL6527ACBZ-T
ISL6527ACRZ-TS2705	10/06/2015	10/03/2016	10/03/2017	ISL6527ACBZ-T
ISL6527AIRZ	10/06/2015	10/12/2015	10/06/2016	ISL6527ACBZ
ISL6527AIRZ-T	10/06/2015	10/12/2015	10/06/2016	ISL6527ACBZ-T
ISL6527CRZ	10/06/2015	10/12/2015	10/06/2016	ISL6527ACBZ
ISL6527CRZ-T	10/06/2015	10/12/2015	10/06/2016	ISL6527ACBZ-T
ISL6527IBZ	10/06/2015	10/12/2015	10/06/2016	ISL6527ACBZ
ISL6527IBZ-T	10/06/2015	10/12/2015	10/06/2016	ISL6527ACBZ-T
ISL6527IRZ	10/06/2015	10/12/2015	10/06/2016	ISL6527ACBZ
ISL6527IRZ-T	10/06/2015	10/12/2015	10/06/2016	ISL6527ACBZ-T
ISL6528CBZ	10/06/2015	10/12/2015	10/06/2016	None
ISL6528CBZR5217	10/06/2015	10/12/2015	10/06/2016	None
ISL6528CBZS2698	10/06/2015	10/12/2015	10/06/2016	None
ISL6528CBZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6528CBZ-TR5217	10/06/2015	10/12/2015	10/06/2016	None
ISL6528CBZ-TS2698	10/06/2015	10/12/2015	10/06/2016	None
ISL6529CBZ	10/06/2015	10/12/2015	10/06/2016	None
ISL6529CBZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6530CBZ	10/06/2015	10/12/2015	10/06/2016	None
ISL6530CBZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6532CCRZ	10/06/2015	10/12/2015	10/06/2016	None
ISL6532CCRZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6545CBZ-TR5453	10/06/2015	10/12/2015	10/06/2016	None
ISL6545IRZ	10/06/2015	10/12/2015	10/06/2016	None
ISL6545IRZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6548CRZA	10/06/2015	10/12/2015	10/06/2016	None
ISL6548CRZA-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6549CAZAR5194	10/06/2015	10/12/2015	10/06/2016	None
ISL6549CBZR5194	10/06/2015	10/12/2015	10/06/2016	None
ISL6549CBZ-TR5194	10/06/2015	10/12/2015	10/06/2016	None
ISL6551ABZ	10/06/2015	10/12/2015	10/06/2016	ISL6551IBZ
ISL6551ABZ-T	10/06/2015	10/12/2015	10/06/2016	ISL6551IBZ-T
ISL6552CBZ	10/06/2015	10/12/2015	10/06/2016	None
ISL6552CBZA	10/06/2015	10/12/2015	10/06/2016	None
ISL6552CBZA-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6552CBZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6552CBZ-TS2462	10/06/2015	10/12/2015	10/06/2016	None
ISL6552CRZ-TS2462	10/06/2015	10/12/2015	10/06/2016	None
ISL6553CBZ	10/06/2015	10/12/2015	10/06/2016	None
ISL6553CBZA	10/06/2015	10/12/2015	10/06/2016	None
ISL6553CBZA-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6553CBZ-T	10/06/2015	10/12/2015	10/06/2016	None

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL6554CBZ	10/06/2015	10/12/2015	10/06/2016	None
ISL6554CBZA	10/06/2015	10/12/2015	10/06/2016	None
ISL6554CBZA-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6554CBZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6554CBZ-TR5165	10/06/2015	10/12/2015	10/06/2016	None
ISL6556ACBZ	10/06/2015	10/12/2015	10/06/2016	None
ISL6556ACBZR5208	10/06/2015	10/12/2015	10/06/2016	None
ISL6556ACBZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6556ACBZ-TR5208	10/06/2015	10/12/2015	10/06/2016	None
ISL6556BCBZ	10/06/2015	10/12/2015	10/06/2016	None
ISL6556BCBZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6557ACBZ	10/06/2015	10/12/2015	10/06/2016	None
ISL6557ACBZR5217	10/06/2015	10/12/2015	10/06/2016	None
ISL6557ACBZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6557ACBZ-TR5217	10/06/2015	10/12/2015	10/06/2016	None
ISL6558CBZAR5284	10/06/2015	10/12/2015	10/06/2016	ISL6558CBZA-T
ISL6558CBZA-TR5284	10/06/2015	10/12/2015	10/06/2016	ISL6558CBZA-T
ISL6558CBZA-TS2462	10/06/2015	10/12/2015	10/06/2016	ISL6558CBZA-T
ISL6558CBZA-TS2490S	10/06/2015	10/12/2015	10/06/2016	ISL6558CBZA-T
ISL6558CBZA-TS2490S1	10/06/2015	10/12/2015	10/06/2016	ISL6558CBZA-T
ISL6558CBZA-TS2490S2	10/06/2015	10/12/2015	10/06/2016	ISL6558CBZA-T
ISL6558CBZA-TS2490S3	10/06/2015	10/12/2015	10/06/2016	ISL6558CBZA-T
ISL6558CBZA-TS2705	10/06/2015	10/03/2016	10/03/2017	ISL6558CBZA-T
ISL6558CRZA	10/06/2015	10/12/2015	10/06/2016	ISL6558CRZ
ISL6558CRZA-T	10/06/2015	10/12/2015	10/06/2016	ISL6558CRZ-T
ISL6558CRZR5284	10/06/2015	10/12/2015	10/06/2016	ISL6558CRZ-T
ISL6558CRZ-TR5284	10/06/2015	10/12/2015	10/06/2016	ISL6558CRZ-T
ISL6558IBZ	10/06/2015	10/12/2015	10/06/2016	ISL6558CBZA
ISL6558IBZR5284	10/06/2015	10/12/2015	10/06/2016	ISL6558CBZA
ISL6558IBZ-T	10/06/2015	10/12/2015	10/06/2016	ISL6558CBZA-T
ISL6558IBZ-TR5284	10/06/2015	10/12/2015	10/06/2016	ISL6558CBZA-T
ISL6558IRZR5240	10/06/2015	10/12/2015	10/06/2016	ISL6558IRZ-T
ISL6558IRZR5284	10/06/2015	10/12/2015	10/06/2016	ISL6558IRZ
ISL6558IRZ-TKR5240	10/06/2015	10/12/2015	10/06/2016	ISL6558IRZ-TK
ISL6558IRZ-TR5240	10/06/2015	10/12/2015	10/06/2016	ISL6558IRZ-T
ISL6558IRZ-TR5284	10/06/2015	10/12/2015	10/06/2016	ISL6558IRZ-T
ISL6559CBZ	10/06/2015	10/12/2015	10/06/2016	None
ISL6559CBZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6559CRZ-TS2705	10/06/2015	10/03/2016	10/03/2017	None
ISL6560CBZ	10/06/2015	10/12/2015	10/06/2016	None
ISL6560CBZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6561CRZR5208	10/06/2015	10/12/2015	10/06/2016	None
ISL6561CRZR5284	10/06/2015	10/12/2015	10/06/2016	None
ISL6561CRZ-TR5208	10/06/2015	10/12/2015	10/06/2016	None
ISL6561CRZ-TR5284	10/06/2015	10/12/2015	10/06/2016	None
ISL6565ACBZ	10/06/2015	10/12/2015	10/06/2016	None
ISL6565ACBZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6565ACVZ	10/06/2015	10/12/2015	10/06/2016	None
ISL6565ACVZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6565BCBZ	10/06/2015	10/12/2015	10/06/2016	None
ISL6565BCBZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6565BCVZ	10/06/2015	10/12/2015	10/06/2016	None
ISL6565BCVZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6569ACBZ	10/06/2015	10/12/2015	10/06/2016	None
ISL6569ACBZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6569CBZ	10/06/2015	10/12/2015	10/06/2016	None
ISL6569CBZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6594BCBZ-T	10/06/2015	10/12/2015	10/06/2016	ISL6594ACRZ-T
ISL6596CBZ	10/06/2015	10/12/2015	10/06/2016	ISL6596CRZ

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL6596CBZ-T	10/06/2015	10/12/2015	10/06/2016	ISL6596CRZ-T
ISL6596CRZ-TS2568	10/06/2015	10/12/2015	10/06/2016	ISL6596CRZ-T
ISL6596IBZ	10/06/2015	10/12/2015	10/06/2016	ISL6596CRZ
ISL6596IBZ-T	10/06/2015	10/12/2015	10/06/2016	ISL6596CRZ-T
ISL6598DRZ	10/06/2015	10/12/2015	10/06/2016	None
ISL6598DRZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6612CBZ-TR5238	10/06/2015	10/12/2015	10/06/2016	ISL6612CBZ
ISL6700IBZ-TS2568	10/06/2015	10/12/2015	10/06/2016	ISL6700IBZ-T
ISL6700IW	10/06/2015	10/12/2015	10/06/2016	None
ISL6721AV-T	10/06/2015	10/12/2015	10/06/2016	ISL6721AVZ-T
ISL6723AABZ	10/06/2015	10/12/2015	10/06/2016	None
ISL6723AABZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6753AAZAR5388	10/06/2015	10/12/2015	10/06/2016	ISL6753AAZA
ISL6753AAZA-TR5388	10/06/2015	10/12/2015	10/06/2016	ISL6753AAZA-T
ISL6755AAZA	10/06/2015	10/12/2015	10/06/2016	None
ISL6755AAZA-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6842IRZ-T	10/06/2015	10/12/2015	10/06/2016	ISL6842IBZ-T
ISL6842IUZ	10/06/2015	10/12/2015	10/06/2016	ISL6842IBZ
ISL6842IUZ-T	10/06/2015	10/12/2015	10/06/2016	ISL6842IBZ-T
ISL6842IUZ-T7A	10/06/2015	10/12/2015	10/06/2016	ISL6842IBZ-T
ISL6843IRZ-T	10/06/2015	10/12/2015	10/06/2016	ISL6843IBZ-T
ISL6843IU-T	10/06/2015	10/12/2015	10/06/2016	ISL6843IUZ-T
ISL6881IAZ	10/06/2015	10/12/2015	10/06/2016	None
ISL6881IAZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL6884IAZ	10/06/2015	10/12/2015	10/06/2016	None
ISL6884IAZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL78200AVEZ-TR5303	10/06/2015	10/06/2016	10/12/2016	ISL78201AVEZ-TR5303
ISL78205AVEZ-TR5303	10/06/2015	10/06/2016	10/12/2016	ISL78206AVEZ-TR5303
ISL78211ARZ	10/06/2015	10/06/2016	10/12/2016	None
ISL78211ARZ-T	10/06/2015	10/06/2016	10/12/2016	None
ISL78211ARZ-TR5303	10/06/2015	10/06/2016	10/12/2016	None
ISL78223AAZ	10/06/2015	10/06/2016	10/12/2016	None
ISL78223AAZ-T	10/06/2015	10/06/2016	10/12/2016	None
ISL8009IRZ-T	10/06/2015	10/12/2015	10/06/2016	ISL8009AIRZ-T
ISL80101R18Z	10/06/2015	10/12/2015	10/06/2016	ISL80101RAJZ
ISL80101R18Z-T	10/06/2015	10/12/2015	10/06/2016	ISL80101RAJZ-T
ISL80101R18Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL80101RAJZ-TK
ISL80101R25Z	10/06/2015	10/12/2015	10/06/2016	ISL80101RAJZ
ISL80101R25Z-T	10/06/2015	10/12/2015	10/06/2016	ISL80101RAJZ-T
ISL80101R25Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL80101RAJZ-TK
ISL80101R33Z	10/06/2015	10/12/2015	10/06/2016	ISL80101RAJZ
ISL80101R33Z-T	10/06/2015	10/12/2015	10/06/2016	ISL80101RAJZ-T
ISL80101R33Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL80101RAJZ-TK
ISL80101R50Z	10/06/2015	10/12/2015	10/06/2016	ISL80101RAJZ
ISL80101R50Z-T	10/06/2015	10/12/2015	10/06/2016	ISL80101RAJZ-T
ISL80101R50Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL80101RAJZ-TK
ISL80102R18Z	10/06/2015	10/12/2015	10/06/2016	ISL80102IRAJZ
ISL80102R18Z-T	10/06/2015	10/12/2015	10/06/2016	ISL80102IRAJZ-T
ISL80102R18Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL80102IRAJZ-TK
ISL80102R25Z	10/06/2015	10/12/2015	10/06/2016	ISL80102IRAJZ
ISL80102R25Z-T	10/06/2015	10/12/2015	10/06/2016	ISL80102IRAJZ-T
ISL80102R25Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL80102IRAJZ-TK
ISL80103R18Z	10/06/2015	10/12/2015	10/06/2016	ISL80103IRAJZ
ISL80103R18Z-T	10/06/2015	10/12/2015	10/06/2016	ISL80103IRAJZ-T
ISL80103R18Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL80103IRAJZ-TK
ISL80103R25Z	10/06/2015	10/12/2015	10/06/2016	ISL80103IRAJZ
ISL80103R25Z-T	10/06/2015	10/12/2015	10/06/2016	ISL80103IRAJZ-T
ISL80103R25Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL80103IRAJZ-TK
ISL8010IUZ	10/06/2015	10/12/2015	10/06/2016	ISL80015IRZ-T

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL8010IUZ-T13	10/06/2015	10/12/2015	10/06/2016	ISL80015IRZ-T
ISL8010IUZ-T7	10/06/2015	10/12/2015	10/06/2016	ISL80015IRZ-T
ISL8013AW	10/06/2015	10/12/2015	10/06/2016	None
ISL8216MIRZ-T7A	10/06/2015	10/12/2015	10/06/2016	ISL8216MIRZ-T
ISL8323IBZ-TS2490	10/06/2015	10/12/2015	10/06/2016	ISL8323IBZ-T
ISL8324IBZ	10/06/2015	10/12/2015	10/06/2016	ISL8323IBZ-T
ISL8324IBZ-T	10/06/2015	10/12/2015	10/06/2016	ISL8323IBZ-T
ISL8325IBZ	10/06/2015	10/12/2015	10/06/2016	ISL8323IBZ-T
ISL8325IBZ-T	10/06/2015	10/12/2015	10/06/2016	ISL8323IBZ-T
ISL83384ECAZA	10/06/2015	10/12/2015	10/06/2016	ICL3222EIVZ
ISL83384ECAZA-T	10/06/2015	10/12/2015	10/06/2016	ICL3222EIVZ
ISL83385ECAZ	10/06/2015	10/12/2015	10/06/2016	ICL3222EIVZ
ISL83385ECAZ-T	10/06/2015	10/12/2015	10/06/2016	ICL3222EIVZ
ISL83385EIAZ	10/06/2015	10/12/2015	10/06/2016	ICL3222EIVZ
ISL83385EIAZ-T	10/06/2015	10/12/2015	10/06/2016	ICL3222EIVZ
ISL83385EIBZ	10/06/2015	10/12/2015	10/06/2016	ICL3222EIVZ
ISL83385EIBZ-T	10/06/2015	10/12/2015	10/06/2016	ICL3222EIVZ
ISL8394IBZ	10/06/2015	10/12/2015	10/06/2016	ISL8393IBZ-T
ISL8394IBZ-T	10/06/2015	10/12/2015	10/06/2016	ISL8393IBZ-T
ISL84052IAZ-TS2687	10/06/2015	10/12/2015	10/06/2016	ISL84052IAZ-T
ISL84053IAZ-TS2687	10/06/2015	10/12/2015	10/06/2016	ISL84052IAZ-T
ISL84523IBZ	10/06/2015	10/12/2015	10/06/2016	ISL84524IUZ-T
ISL84523IBZ-T	10/06/2015	10/12/2015	10/06/2016	ISL84524IUZ-T
ISL84523IVZ	10/06/2015	10/12/2015	10/06/2016	ISL84524IUZ-T
ISL84523IVZ-T	10/06/2015	10/12/2015	10/06/2016	ISL84524IUZ-T
ISL84541CPZ	10/06/2015	10/12/2015	10/06/2016	ISL84541CBZ-T
ISL84541IPZ	10/06/2015	10/12/2015	10/06/2016	ISL84541CBZ-T
ISL84541IUZ	10/06/2015	10/12/2015	10/06/2016	ISL84541CBZ-T
ISL84541IUZ-T	10/06/2015	10/12/2015	10/06/2016	ISL84541CBZ-T
ISL84542CBZ	10/06/2015	10/12/2015	10/06/2016	ISL84541CBZ-T
ISL84542CBZ-T	10/06/2015	10/12/2015	10/06/2016	ISL84541CBZ-T
ISL84542CPZ	10/06/2015	10/12/2015	10/06/2016	ISL84541CBZ-T
ISL84542IBZ	10/06/2015	10/12/2015	10/06/2016	ISL84541CBZ-T
ISL84542IBZ-T	10/06/2015	10/12/2015	10/06/2016	ISL84541CBZ-T
ISL84542IHZ-T	10/06/2015	10/12/2015	10/06/2016	ISL84541CBZ-T
ISL84542IPZ	10/06/2015	10/12/2015	10/06/2016	ISL84541CBZ-T
ISL84543CBZ	10/06/2015	10/12/2015	10/06/2016	ISL84544CBZ-T
ISL84543CBZ-T	10/06/2015	10/12/2015	10/06/2016	ISL84544CBZ-T
ISL84543CPZ	10/06/2015	10/12/2015	10/06/2016	ISL84544CBZ-T
ISL84543IBZ	10/06/2015	10/12/2015	10/06/2016	ISL84544CBZ-T
ISL84543IBZ-T	10/06/2015	10/12/2015	10/06/2016	ISL84544CBZ-T
ISL84543IHZ-T	10/06/2015	10/12/2015	10/06/2016	ISL84544CBZ-T
ISL84543IHZ-TS2568	10/06/2015	10/12/2015	10/06/2016	ISL84544CBZ-T
ISL84543IPZ	10/06/2015	10/12/2015	10/06/2016	ISL84544CBZ-T
ISL84544CPZ	10/06/2015	10/12/2015	10/06/2016	ISL84544CBZ-T
ISL84544IPZ	10/06/2015	10/12/2015	10/06/2016	ISL84544CBZ-T
ISL84716IHZ-T	10/06/2015	10/12/2015	10/06/2016	ISL84714IHZ-T
ISL84762IRZ	10/06/2015	10/12/2015	10/06/2016	ISL84714IHZ-T
ISL84762IRZ-T	10/06/2015	10/12/2015	10/06/2016	ISL84714IHZ-T
ISL84762IUZ	10/06/2015	10/12/2015	10/06/2016	ISL84714IHZ-T
ISL84762IUZ-T	10/06/2015	10/12/2015	10/06/2016	ISL84714IHZ-T
ISL84780IRZ	10/06/2015	10/12/2015	10/06/2016	ISL84781IRZ-T
ISL84780IRZ-T	10/06/2015	10/12/2015	10/06/2016	ISL84781IRZ-T
ISL84780IVZ	10/06/2015	10/12/2015	10/06/2016	ISL84781IRZ-T
ISL84780IVZ-T	10/06/2015	10/12/2015	10/06/2016	ISL84781IRZ-T
ISL8483EIPZ	10/06/2015	10/12/2015	10/06/2016	ICL3222EIVZ
ISL85402IRZ-TS2753	10/06/2015	10/12/2015	10/06/2016	None
ISL85403IRZ-TS2753	10/06/2015	10/12/2015	10/06/2016	None
ISL8540IVEZ	10/06/2015	10/12/2015	10/06/2016	ISL8560IRZ

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL8540IVEZ-T	10/06/2015	10/12/2015	10/06/2016	ISL8560IRZ-T
ISL88011IH522Z-T7A	10/06/2015	10/12/2015	10/06/2016	ISL88011IH544Z-T7A
ISL88011IH522Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL88011IH544Z-TK
ISL88012IH522Z-T7A	10/06/2015	10/12/2015	10/06/2016	None
ISL88012IH522Z-TK	10/06/2015	10/12/2015	10/06/2016	None
ISL88012IH523Z-T7A	10/06/2015	10/12/2015	10/06/2016	None
ISL88012IH523Z-TK	10/06/2015	10/12/2015	10/06/2016	None
ISL88012IH526Z-T7A	10/06/2015	10/12/2015	10/06/2016	None
ISL88012IH526Z-TK	10/06/2015	10/12/2015	10/06/2016	None
ISL88012IH529Z-T7A	10/06/2015	10/12/2015	10/06/2016	None
ISL88012IH529Z-TK	10/06/2015	10/12/2015	10/06/2016	None
ISL88012IH531Z-T7A	10/06/2015	10/12/2015	10/06/2016	None
ISL88012IH531Z-TK	10/06/2015	10/12/2015	10/06/2016	None
ISL88012IH544Z-T7A	10/06/2015	10/12/2015	10/06/2016	None
ISL88012IH544Z-TK	10/06/2015	10/12/2015	10/06/2016	None
ISL88012IH546Z-T7A	10/06/2015	10/12/2015	10/06/2016	None
ISL88012IH546Z-TK	10/06/2015	10/12/2015	10/06/2016	None
ISL88013IH523Z-T7A	10/06/2015	10/12/2015	10/06/2016	ISL88013IH526Z-T7A
ISL88013IH523Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL88013IH526Z-TK
ISL88013IH546Z-T7A	10/06/2015	10/12/2015	10/06/2016	ISL88013IH544Z-T7A
ISL88013IH546Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL88013IH544Z-TK
ISL88015IH5Z-T7A	10/06/2015	10/12/2015	10/06/2016	None
ISL88015IH5Z-TK	10/06/2015	10/12/2015	10/06/2016	None
ISL88016IHTZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL88016IHTZ-T7A	10/06/2015	10/12/2015	10/06/2016	None
ISL88016IHTZ-TK	10/06/2015	10/12/2015	10/06/2016	None
ISL8843AUZ	10/06/2015	10/12/2015	10/06/2016	ISL8843AAUZ
ISL8843AUZ-T	10/06/2015	10/12/2015	10/06/2016	ISL8843AAUZ-T
ISL8843MUZ	10/06/2015	10/12/2015	10/06/2016	ISL8843AMUZ
ISL8843MUZ-T	10/06/2015	10/12/2015	10/06/2016	ISL8843AMUZ-T
ISL88550AIRZ-TR5339	10/06/2015	10/12/2015	10/06/2016	None
ISL88550AIRZ-TS2568	10/06/2015	10/12/2015	10/06/2016	None
ISL88550AIRZ-TS2715	10/06/2015	10/12/2015	10/06/2016	None
ISL88694IH5ZTKS2490S	10/06/2015	10/12/2015	10/06/2016	ISL88694IH5Z-TK
ISL88705IP846Z	10/06/2015	10/12/2015	10/06/2016	ISL88705IB846Z
ISL88706IP826Z	10/06/2015	10/12/2015	10/06/2016	ISL88706IB826Z
ISL88706IP829Z	10/06/2015	10/12/2015	10/06/2016	ISL88706IB829Z
ISL88706IP831Z	10/06/2015	10/12/2015	10/06/2016	ISL88706IB831Z
ISL88706IP844Z	10/06/2015	10/12/2015	10/06/2016	ISL88706IB844Z
ISL88707IP846Z	10/06/2015	10/12/2015	10/06/2016	ISL88707IB846Z
ISL88708IP826Z	10/06/2015	10/12/2015	10/06/2016	ISL88708IB826Z
ISL88708IP829Z	10/06/2015	10/12/2015	10/06/2016	ISL88708IB829Z
ISL88708IP831Z	10/06/2015	10/12/2015	10/06/2016	ISL88708IB831Z
ISL88708IP844Z	10/06/2015	10/12/2015	10/06/2016	ISL88708IB844Z
ISL88716IP826Z	10/06/2015	10/12/2015	10/06/2016	ISL88716IB826Z
ISL88731CHRTZ-TR5453	10/06/2015	10/12/2015	10/06/2016	None
ISL88736HRTZ	10/06/2015	10/12/2015	10/06/2016	None
ISL88736HRTZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL88813IP846Z	10/06/2015	10/12/2015	10/06/2016	ISL88813IB846Z
ISL89160FBEAZ	10/06/2015	10/12/2015	10/06/2016	None
ISL89160FBEAZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL89160FBEBZ	10/06/2015	10/12/2015	10/06/2016	None
ISL89160FBEBZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL89160FRTAZ	10/06/2015	10/12/2015	10/06/2016	None
ISL89160FRTAZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL89160FRTBZ	10/06/2015	10/12/2015	10/06/2016	None
ISL89160FRTBZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL89161FBEAZ	10/06/2015	10/12/2015	10/06/2016	None
ISL89161FBEAZ-T	10/06/2015	10/12/2015	10/06/2016	None

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL89161FBEBZ	10/06/2015	10/12/2015	10/06/2016	None
ISL89161FBEBZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL89161FRTAZ	10/06/2015	10/12/2015	10/06/2016	None
ISL89161FRTAZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL89161FRTBZ	10/06/2015	10/12/2015	10/06/2016	None
ISL89161FRTBZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL89162FBEAZ	10/06/2015	10/12/2015	10/06/2016	None
ISL89162FBEAZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL89162FBEBZ	10/06/2015	10/12/2015	10/06/2016	None
ISL89162FBEBZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL89162FRTAZ	10/06/2015	10/12/2015	10/06/2016	None
ISL89162FRTAZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL89162FRTBZ	10/06/2015	10/12/2015	10/06/2016	None
ISL89162FRTBZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL89163FBECZ	10/06/2015	10/12/2015	10/06/2016	None
ISL89163FBECZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL89163FRTAZ-TR5523	10/06/2015	10/12/2015	10/06/2016	ISL89163FRTAZ-T
ISL89163FRTCZ	10/06/2015	10/12/2015	10/06/2016	None
ISL89163FRTCZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL89164FBECZ	10/06/2015	10/12/2015	10/06/2016	None
ISL89164FBECZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL89164FRTCZ	10/06/2015	10/12/2015	10/06/2016	None
ISL89164FRTCZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL89165FBECZ	10/06/2015	10/12/2015	10/06/2016	None
ISL89165FBECZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL89165FRTCZ	10/06/2015	10/12/2015	10/06/2016	None
ISL89165FRTCZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL89166FBEAZ	10/06/2015	10/12/2015	10/06/2016	None
ISL89166FBEAZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL89166FRTAZ	10/06/2015	10/12/2015	10/06/2016	None
ISL89166FRTAZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL89167FBEAZ	10/06/2015	10/12/2015	10/06/2016	None
ISL89167FBEAZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL89167FRTAZ	10/06/2015	10/12/2015	10/06/2016	None
ISL89167FRTAZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL89168FBEAZ	10/06/2015	10/12/2015	10/06/2016	None
ISL89168FBEAZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL89168FRTAZ	10/06/2015	10/12/2015	10/06/2016	None
ISL89168FRTAZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL89367FRTAZ	10/06/2015	10/12/2015	10/06/2016	None
ISL89367FRTAZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL89410IPZ	10/06/2015	10/12/2015	10/06/2016	ISL89410IBZ
ISL89412IPZ	10/06/2015	10/12/2015	10/06/2016	ISL89412IBZ
ISL9000AIRBBZ	10/06/2015	10/12/2015	10/06/2016	None
ISL9000AIRBBZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9000AIRBCZ	10/06/2015	10/12/2015	10/06/2016	None
ISL9000AIRBCZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9000AIRBJZ	10/06/2015	10/12/2015	10/06/2016	None
ISL9000AIRBJZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9000AIRBLZ	10/06/2015	10/12/2015	10/06/2016	None
ISL9000AIRBLZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9000AIRGCZ	10/06/2015	10/12/2015	10/06/2016	None
ISL9000AIRGCZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9000AIRGPZ	10/06/2015	10/12/2015	10/06/2016	None
ISL9000AIRGPZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9000AIRJ CZ	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRJBZ-T
ISL9000AIRJ CZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRJBZ-T
ISL9000AIRJMZ	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRJBZ-T
ISL9000AIRJMZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRJBZ-T

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL9000AIRJRZ	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRJNZ-T
ISL9000AIRJRZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRJNZ-T
ISL9000AIRKNZ	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRK CZ-T
ISL9000AIRKNZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRK CZ-T
ISL9000AIRKPZ	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRK CZ-T
ISL9000AIRKPZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRK CZ-T
ISL9000AIRLLZ	10/06/2015	10/12/2015	10/06/2016	None
ISL9000AIRLLZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9000AIRMMZ	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRMGZ-T
ISL9000AIRMMZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRMGZ-T
ISL9000AIRNCZ	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRNJZ
ISL9000AIRNCZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRNJZ
ISL9000AIRPLZ	10/06/2015	10/12/2015	10/06/2016	None
ISL9000AIRPLZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9000AIRPPZ	10/06/2015	10/12/2015	10/06/2016	None
ISL9000AIRPPZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9000AMRNCEP	10/06/2015	10/12/2015	10/06/2016	None
ISL9000AMRNCEP-TK	10/06/2015	10/12/2015	10/06/2016	None
ISL9000IRBBZ	10/06/2015	10/12/2015	10/06/2016	None
ISL9000IRBBZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9000IRBCZ	10/06/2015	10/12/2015	10/06/2016	None
ISL9000IRBCZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9000IRBJZ	10/06/2015	10/12/2015	10/06/2016	None
ISL9000IRBJZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9000IRBLZ	10/06/2015	10/12/2015	10/06/2016	None
ISL9000IRBLZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9000IRCCZ	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRCCZ
ISL9000IRCCZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRCCZ
ISL9000IRCJZ	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRCJZ
ISL9000IRCJZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRCJZ
ISL9000IRFCZ	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRFCZ
ISL9000IRFCZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRFCZ
ISL9000IRFDZ	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRFDZ
ISL9000IRFDZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRFDZ
ISL9000IRFJZ	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRFJZ
ISL9000IRFJZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRFJZ
ISL9000IRGCZ	10/06/2015	10/12/2015	10/06/2016	None
ISL9000IRGCZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9000IRGPZ	10/06/2015	10/12/2015	10/06/2016	None
ISL9000IRGPZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9000IRJBZ	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRJBZ
ISL9000IRJBZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRJBZ
ISL9000IRJCZ	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRJBZ-T
ISL9000IRJCZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRJBZ-T
ISL9000IRJMZ	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRJBZ-T
ISL9000IRJMZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRJBZ-T
ISL9000IRJNZ	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRJNZ
ISL9000IRJNZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRJNZ
ISL9000IRJRZ	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRJBZ-T
ISL9000IRJRZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRJBZ-T
ISL9000IRK CZ	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRK CZ
ISL9000IRK CZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRK CZ
ISL9000IRKFZ	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRKFZ
ISL9000IRKFZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRKFZ
ISL9000IRKJZ	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRKJZ
ISL9000IRKJZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRKJZ
ISL9000IRKKZ	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRKKZ
ISL9000IRKKZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRKKZ
ISL9000IRKNZ	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRKFZ

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL9000IRKNZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRKFZ-T
ISL9000IRKPZ	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRKFZ
ISL9000IRKPZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRKFZ-T
ISL9000IRLLZ	10/06/2015	10/12/2015	10/06/2016	None
ISL9000IRLLZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9000IRMGZ	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRMGZ
ISL9000IRMGZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRMGZ-T
ISL9000IRMMZ	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRMNZ
ISL9000IRMMZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRMNZ-T
ISL9000IRMNZ	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRMNZ
ISL9000IRMNZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRMNZ-T
ISL9000IRNCZ	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRNFZ
ISL9000IRNCZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRNFZ
ISL9000IRNFZ	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRNFZ
ISL9000IRNFZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRNFZ
ISL9000IRNJZ	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRNJZ
ISL9000IRNJZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRNJZ
ISL9000IRNNZ	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRNNZ
ISL9000IRNNZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRNNZ
ISL9000IRPLZ	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRCCZ
ISL9000IRPLZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRCCZ
ISL9000IRPPZ	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRCJZ
ISL9000IRPPZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9000AIRCJZ
ISL9001AIRLZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9001AIRNZ-T
ISL9001AIRMZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9001AIRRZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9001IRBZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9001IRBZ-TS2695	10/06/2015	10/12/2015	10/06/2016	None
ISL9001IRCZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9001IRCZ-TS2695	10/06/2015	10/12/2015	10/06/2016	None
ISL9001IRFZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9001AIRFZ-T
ISL9001IRFZ-TS2695	10/06/2015	10/12/2015	10/06/2016	None
ISL9001IRJZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9001AIRJZ-T
ISL9001IRJZ-TS2695	10/06/2015	10/12/2015	10/06/2016	None
ISL9001IRKZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9001AIRKZ-T
ISL9001IRKZ-TS2695	10/06/2015	10/12/2015	10/06/2016	None
ISL9001IRLZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9001IRLZ-TS2695	10/06/2015	10/12/2015	10/06/2016	None
ISL9001IRMZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9001IRMZ-TS2695	10/06/2015	10/12/2015	10/06/2016	None
ISL9001IRNZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9001AIRNZ-T
ISL9001IRNZ-TS2695	10/06/2015	10/12/2015	10/06/2016	None
ISL9001IRRZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9001IRRZ-TS2695	10/06/2015	10/12/2015	10/06/2016	None
ISL9003IEBZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9003AIEBZ-T
ISL9003IECZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9003AIECZ-T
ISL9003IEFZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9003AIEFZ-T
ISL9003IEHZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9003AIEHZ-T
ISL9003IEJZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9003AIEJZ-T
ISL9003IEKZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9003AIEKZ-T
ISL9003IEMZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9003AIEMZ-T
ISL9003IENZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9003AIENZ-T
ISL9005AIRLZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9005AIRMZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9005AIRRZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9005IRBZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9005AIRBZ-T
ISL9005IRCZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9005IRFZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9005IRJZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9005AIRJZ-T

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL9005IRKZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9005AIRKZ-T
ISL9005IRLZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9005IRMZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9005IRNZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9005AIRNZ-T
ISL9005IRRZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9008IEBZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9008AIEBZ-T
ISL9008IECZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9008AIECZ-T
ISL9008IEFZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9008AIEFZ-T
ISL9008IEHZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9008AIEHZ-T
ISL9008IEJZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9008AIEJZ-T
ISL9008IEKZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9008AIEKZ-T
ISL9008IEMZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9008AIEMZ-T
ISL9008IENZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9008AIENZ-T
ISL9011AIRBBZ	10/06/2015	10/12/2015	10/06/2016	None
ISL9011AIRBBZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9011AIRBCZ	10/06/2015	10/12/2015	10/06/2016	None
ISL9011AIRBCZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9011AIRBJZ	10/06/2015	10/12/2015	10/06/2016	None
ISL9011AIRBJZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9011AIRBLZ	10/06/2015	10/12/2015	10/06/2016	None
ISL9011AIRBLZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9011AIRGCZ	10/06/2015	10/12/2015	10/06/2016	None
ISL9011AIRGCZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9011AIRGPZ	10/06/2015	10/12/2015	10/06/2016	None
ISL9011AIRGPZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9011AIRJCZ	10/06/2015	10/12/2015	10/06/2016	ISL9011AIRJBZ-T
ISL9011AIRJCZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9011AIRJBZ-T
ISL9011AIRJMZ	10/06/2015	10/12/2015	10/06/2016	ISL9011AIRJNZ-T
ISL9011AIRJMZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9011AIRJNZ-T
ISL9011AIRJRZ	10/06/2015	10/12/2015	10/06/2016	ISL9011AIRJNZ-T
ISL9011AIRJRZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9011AIRJNZ-T
ISL9011AIRKNZ	10/06/2015	10/12/2015	10/06/2016	ISL9011AIRKKZ-T
ISL9011AIRKNZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9011AIRKKZ-T
ISL9011AIRKPZ	10/06/2015	10/12/2015	10/06/2016	ISL9011AIRKKZ-T
ISL9011AIRKPZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9011AIRKKZ-T
ISL9011AIRLLZ	10/06/2015	10/12/2015	10/06/2016	None
ISL9011AIRLLZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9011AIRMMZ	10/06/2015	10/12/2015	10/06/2016	ISL9011AIRMGZ-T
ISL9011AIRMMZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9011AIRMGZ-T
ISL9011AIRNCZ	10/06/2015	10/12/2015	10/06/2016	ISL9011AIRMNZ-T
ISL9011AIRNCZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9011AIRMNZ-T
ISL9011AIRPLZ	10/06/2015	10/12/2015	10/06/2016	None
ISL9011AIRPLZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9011AIRPPZ	10/06/2015	10/12/2015	10/06/2016	None
ISL9011AIRPPZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9011IRBBZ	10/06/2015	10/12/2015	10/06/2016	None
ISL9011IRBBZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9011IRBCZ	10/06/2015	10/12/2015	10/06/2016	None
ISL9011IRBCZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9011IRBJZ	10/06/2015	10/12/2015	10/06/2016	None
ISL9011IRBJZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9011IRBLZ	10/06/2015	10/12/2015	10/06/2016	None
ISL9011IRBLZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9011IRCCZ	10/06/2015	10/12/2015	10/06/2016	ISL9011AIRCCZ
ISL9011IRCCZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9011AIRCCZ
ISL9011IRCJZ	10/06/2015	10/12/2015	10/06/2016	ISL9011AIRCJZ
ISL9011IRCJZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9011AIRCJZ
ISL9011IRFCZ	10/06/2015	10/12/2015	10/06/2016	ISL9011AIRFCZ
ISL9011IRFCZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9011AIRFCZ

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL9011IRFDZ	10/06/2015	10/12/2015	10/06/2016	ISL9011AIRFDZ
ISL9011IRFDZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9011AIRFDZ
ISL9011IRFJZ	10/06/2015	10/12/2015	10/06/2016	ISL9011AIRFJZ
ISL9011IRFJZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9011AIRFJZ
ISL9011IRGCZ	10/06/2015	10/12/2015	10/06/2016	None
ISL9011IRGCZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9011IRGPZ	10/06/2015	10/12/2015	10/06/2016	None
ISL9011IRGPZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9011IRJBZ	10/06/2015	10/12/2015	10/06/2016	ISL9011AIRJBZ
ISL9011IRJBZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9011AIRJBZ
ISL9011IRJBZ-TS2697	10/06/2015	10/12/2015	10/06/2016	None
ISL9011IRJCZ	10/06/2015	10/12/2015	10/06/2016	ISL9011AIRJBZ
ISL9011IRJCZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9011AIRJBZ-T
ISL9011IRJMZ	10/06/2015	10/12/2015	10/06/2016	ISL9011AIRJNZ
ISL9011IRJMZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9011AIRJNZ-T
ISL9011IRJNZ	10/06/2015	10/12/2015	10/06/2016	ISL9011AIRJNZ
ISL9011IRJNZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9011AIRJNZ
ISL9011IRJRZ	10/06/2015	10/12/2015	10/06/2016	ISL9011AIRJNZ
ISL9011IRJRZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9011AIRJNZ-T
ISL9011IRK CZ	10/06/2015	10/12/2015	10/06/2016	ISL9011AIRK CZ
ISL9011IRK CZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9011AIRK CZ
ISL9011IRK FZ	10/06/2015	10/12/2015	10/06/2016	ISL9011AIRK FZ
ISL9011IRK FZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9011AIRK FZ
ISL9011IRK JZ	10/06/2015	10/12/2015	10/06/2016	ISL9011AIRK JZ
ISL9011IRK JZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9011AIRK JZ
ISL9011IRK KZ	10/06/2015	10/12/2015	10/06/2016	ISL9011AIRK KZ
ISL9011IRK KZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9011AIRK KZ
ISL9011IRK NZ	10/06/2015	10/12/2015	10/06/2016	ISL9011AIRK KZ
ISL9011IRK NZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9011AIRK KZ
ISL9011IRK PZ	10/06/2015	10/12/2015	10/06/2016	ISL9011AIRK KZ
ISL9011IRK PZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9011AIRK KZ
ISL9011IRLLZ	10/06/2015	10/12/2015	10/06/2016	None
ISL9011IRLLZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9011IRMGZ	10/06/2015	10/12/2015	10/06/2016	ISL9011AIRMGZ
ISL9011IRMGZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9011AIRMGZ
ISL9011IRMMZ	10/06/2015	10/12/2015	10/06/2016	ISL9011AIRMNZ
ISL9011IRMMZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9011AIRMNZ-T
ISL9011IRMNZ	10/06/2015	10/12/2015	10/06/2016	ISL9011AIRMNZ
ISL9011IRMNZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9011AIRMNZ
ISL9011IRNCZ	10/06/2015	10/12/2015	10/06/2016	ISL9011AIRNFZ
ISL9011IRNCZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9011AIRNFZ-T
ISL9011IRNFZ	10/06/2015	10/12/2015	10/06/2016	ISL9011AIRNFZ
ISL9011IRNFZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9011AIRNFZ
ISL9011IRNJZ	10/06/2015	10/12/2015	10/06/2016	ISL9011AIRNJZ
ISL9011IRNJZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9011AIRNJZ
ISL9011IRNNZ	10/06/2015	10/12/2015	10/06/2016	ISL9011AIRNNZ
ISL9011IRNNZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9011AIRNNZ
ISL9011IRPLZ	10/06/2015	10/12/2015	10/06/2016	None
ISL9011IRPLZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9011IRPPZ	10/06/2015	10/12/2015	10/06/2016	None
ISL9011IRPPZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9012IRBJZ	10/06/2015	10/12/2015	10/06/2016	None
ISL9012IRBJZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9012IRFJZ	10/06/2015	10/12/2015	10/06/2016	None
ISL9012IRFJZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9012IRGCZ	10/06/2015	10/12/2015	10/06/2016	None
ISL9012IRGCZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9012IRJBZ	10/06/2015	10/12/2015	10/06/2016	None
ISL9012IRJBZ-T	10/06/2015	10/12/2015	10/06/2016	None

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL9012IRJCZ	10/06/2015	10/12/2015	10/06/2016	ISL9012IRJNZ-T
ISL9012IRJCZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9012IRJNZ-T
ISL9012IRJMZ	10/06/2015	10/12/2015	10/06/2016	ISL9012IRJNZ-T
ISL9012IRJMZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9012IRJNZ-T
ISL9012IRJRZ	10/06/2015	10/12/2015	10/06/2016	ISL9012IRJNZ-T
ISL9012IRJRZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9012IRJNZ-T
ISL9012IRKCZ	10/06/2015	10/12/2015	10/06/2016	None
ISL9012IRKCZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9012IRKFZ	10/06/2015	10/12/2015	10/06/2016	None
ISL9012IRKFZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9012IRKJZ	10/06/2015	10/12/2015	10/06/2016	None
ISL9012IRKJZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9012IRKKZ	10/06/2015	10/12/2015	10/06/2016	None
ISL9012IRKKZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9012IRLLZ	10/06/2015	10/12/2015	10/06/2016	None
ISL9012IRLLZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9012IRMMZ	10/06/2015	10/12/2015	10/06/2016	ISL9012IRMNZ-T
ISL9012IRMMZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9012IRMNZ-T
ISL9012IRNFZ	10/06/2015	10/12/2015	10/06/2016	ISL9012IRNNZ-T
ISL9012IRNFZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9012IRNNZ-T
ISL9012IRNJZ	10/06/2015	10/12/2015	10/06/2016	ISL9012IRNNZ-T
ISL9012IRNJZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9012IRNNZ-T
ISL9012IRPLZ	10/06/2015	10/12/2015	10/06/2016	None
ISL9012IRPLZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9014AIRBBZ	10/06/2015	10/12/2015	10/06/2016	None
ISL9014AIRBBZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9014AIRBCZ	10/06/2015	10/12/2015	10/06/2016	None
ISL9014AIRBCZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9014AIRBJZ	10/06/2015	10/12/2015	10/06/2016	ISL9014AIRFJZ-T
ISL9014AIRBJZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9014AIRFJZ-T
ISL9014AIRBLZ	10/06/2015	10/12/2015	10/06/2016	None
ISL9014AIRBLZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9014AIRGCZ	10/06/2015	10/12/2015	10/06/2016	ISL9014AIRFJZ-T
ISL9014AIRGCZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9014AIRFJZ-T
ISL9014AIRGPZ	10/06/2015	10/12/2015	10/06/2016	None
ISL9014AIRGPZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9014AIRJCZ	10/06/2015	10/12/2015	10/06/2016	ISL9014AIRFJZ-T
ISL9014AIRJCZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9014AIRFJZ-T
ISL9014AIRJMZ	10/06/2015	10/12/2015	10/06/2016	ISL9014AIRJBZ-T
ISL9014AIRJMZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9014AIRJBZ-T
ISL9014AIRJRZ	10/06/2015	10/12/2015	10/06/2016	ISL9014AIRJBZ-T
ISL9014AIRJRZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9014AIRJBZ-T
ISL9014AIRKNZ	10/06/2015	10/12/2015	10/06/2016	ISL9014AIRKKZ-T
ISL9014AIRKNZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9014AIRKKZ-T
ISL9014AIRKPZ	10/06/2015	10/12/2015	10/06/2016	ISL9014AIRKKZ-T
ISL9014AIRKPZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9014AIRKKZ-T
ISL9014AIRLLZ	10/06/2015	10/12/2015	10/06/2016	ISL9014AIRKCZ
ISL9014AIRLLZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9014AIRKCZ
ISL9014AIRMMZ	10/06/2015	10/12/2015	10/06/2016	ISL9014AIRMGZ-T
ISL9014AIRMMZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9014AIRMGZ-T
ISL9014AIRNCZ	10/06/2015	10/12/2015	10/06/2016	ISL9014AIRMNZ-T
ISL9014AIRNCZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9014AIRMNZ-T
ISL9014AIRPLZ	10/06/2015	10/12/2015	10/06/2016	ISL9014AIRNFZ-T
ISL9014AIRPLZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9014AIRNFZ-T
ISL9014AIRPPZ	10/06/2015	10/12/2015	10/06/2016	None
ISL9014AIRPPZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL90460TIE527Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL90460TIH527Z-TK
ISL90460UIE527Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL90460TIH527Z-TK
ISL90460UIH527Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL90460TIH527Z-TK

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL90460WIE527Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL90460TIH527Z-TK
ISL90462TIH627Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL90462UIE627Z-TK
ISL90810WAU8Z	10/06/2015	10/12/2015	10/06/2016	ISL90810UAU8Z-TK
ISL90810WAU8Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL90810UAU8Z-TK
ISL90810WIU8Z	10/06/2015	10/12/2015	10/06/2016	ISL90810UAU8Z-TK
ISL90810WIU8Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL90810UAU8Z-TK
ISL9103AIRUNZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9103IRUAZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9103AIRUAZ-T
ISL9103IRUBZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9103AIRUBZ-T
ISL9103IRUCZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9103IRUDZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9103AIRUDZ-T
ISL9103IRUFZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9103AIRUFZ-T
ISL9103IRUJZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9103AIRUJZ-T
ISL9103IRUNZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9103IRUWZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9103AIRUWZ-T
ISL9109IRZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9110BIRTAZ-TR5453	10/06/2015	10/12/2015	10/06/2016	None
ISL9110IRTAZ-TR5453	10/06/2015	10/12/2015	10/06/2016	None
ISL9113ER7Z-TR5587	10/06/2015	10/12/2015	10/06/2016	None
ISL9200IRZ	10/06/2015	10/12/2015	10/06/2016	None
ISL9200IRZR5237	10/06/2015	10/12/2015	10/06/2016	None
ISL9200IRZR5239	10/06/2015	10/12/2015	10/06/2016	None
ISL9200IRZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9200IRZ-TR5237	10/06/2015	10/12/2015	10/06/2016	None
ISL9200IRZ-TR5239	10/06/2015	10/12/2015	10/06/2016	None
ISL9201IRZ	10/06/2015	10/12/2015	10/06/2016	None
ISL9201IRZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9203CRZR5220	10/06/2015	10/12/2015	10/06/2016	None
ISL9203CRZ-TR5220	10/06/2015	10/12/2015	10/06/2016	None
ISL9206ADHZR5335-060	10/06/2015	10/12/2015	10/06/2016	None
ISL9206ADRTZR5335-60	10/06/2015	10/12/2015	10/06/2016	None
ISL9206DHZ	10/06/2015	10/12/2015	10/06/2016	None
ISL9206DHZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9206DRZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9211AIRU48XZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9211BIRU58XZ-T
ISL9211AIRU58XZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9211BIRU58XZ-T
ISL9211AIRU68XZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9211BIRU58XZ-T
ISL9211IRU58XZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9211BIRU58XZ-T
ISL9211IRU68XZ-T	10/06/2015	10/12/2015	10/06/2016	ISL9211BIRU58XZ-T
ISL9212IRZ	10/06/2015	10/12/2015	10/06/2016	None
ISL9212IRZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9221IRZ	10/06/2015	10/12/2015	10/06/2016	None
ISL9221IRZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9222AIRTZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9305IRH4CFCZR5613	10/06/2015	10/12/2015	10/06/2016	None
ISL94200IRZ	10/06/2015	10/12/2015	10/06/2016	None
ISL94201IRZ	10/06/2015	10/12/2015	10/06/2016	None
ISL9491AERZ	10/06/2015	10/12/2015	10/06/2016	None
ISL9491AERZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9502CRZ	10/06/2015	10/12/2015	10/06/2016	None
ISL9502CRZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL9505AHRZ	10/06/2015	10/12/2015	10/06/2016	None
ISL9505AHRZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL95310WIU10Z	10/06/2015	10/12/2015	10/06/2016	ISL95310UIU10Z-TK
ISL95310WIU10Z-TK	10/06/2015	10/12/2015	10/06/2016	ISL95310UIU10Z-TK
ISL95311UIU10Z	10/06/2015	10/12/2015	10/06/2016	None
ISL95311UIU10Z-TK	10/06/2015	10/12/2015	10/06/2016	None
ISL95710UIU10Z	10/06/2015	10/12/2015	10/06/2016	ISL95310UIU10Z-TK
ISL95710UIU10Z-T	10/06/2015	10/12/2015	10/06/2016	ISL95310UIU10Z-TK

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL95710WIU10Z	10/06/2015	10/12/2015	10/06/2016	ISL95310UIU10Z-TK
ISL95710WIU10Z-T	10/06/2015	10/12/2015	10/06/2016	ISL95310UIU10Z-TK
ISL95711UIU10Z	10/06/2015	10/12/2015	10/06/2016	ISL95310UIU10Z-TK
ISL95711UIU10Z-T	10/06/2015	10/12/2015	10/06/2016	ISL95310UIU10Z-TK
ISL95711WIU10Z	10/06/2015	10/12/2015	10/06/2016	ISL95310UIU10Z-TK
ISL95711WIU10Z-T	10/06/2015	10/12/2015	10/06/2016	ISL95310UIU10Z-TK
ISL95810UIU8Z-TR5391	10/06/2015	10/12/2015	10/06/2016	ISL95810UIU8Z-T
ISL95811UFRTZ	10/06/2015	10/12/2015	10/06/2016	ISL95810UIU8Z-T
ISL95811UFRTZ-TK	10/06/2015	10/12/2015	10/06/2016	ISL95810UIU8Z-T
ISL95811UFUZ	10/06/2015	10/12/2015	10/06/2016	ISL95810UIU8Z-T
ISL95811UFUZ-T	10/06/2015	10/12/2015	10/06/2016	ISL95810UIU8Z-T
ISL95811UFUZ-TK	10/06/2015	10/12/2015	10/06/2016	ISL95810UIU8Z-T
ISL95811WFRTZ	10/06/2015	10/12/2015	10/06/2016	ISL95810UIU8Z-T
ISL95811WFRTZ-TK	10/06/2015	10/12/2015	10/06/2016	ISL95810UIU8Z-T
ISL95811WFUZ	10/06/2015	10/12/2015	10/06/2016	ISL95810UIU8Z-T
ISL95811WFUZ-T	10/06/2015	10/12/2015	10/06/2016	ISL95810UIU8Z-T
ISL95811WFUZ-TK	10/06/2015	10/12/2015	10/06/2016	ISL95810UIU8Z-T
ISL95831AHRTZ	10/06/2015	10/12/2015	10/06/2016	None
ISL95831AHRTZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL95838HRTZ	10/06/2015	10/12/2015	10/06/2016	None
ISL95838IRTZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL95839HRTZ	10/06/2015	10/12/2015	10/06/2016	None
ISL95839HRTZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL95874HRUZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL95874IRUZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL95875HRUZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL95875IRUZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL96017UIRT8Z	10/06/2015	10/12/2015	10/06/2016	None
ISL96017UIRT8Z-T	10/06/2015	10/12/2015	10/06/2016	None
ISL96017UIRT8Z-TK	10/06/2015	10/12/2015	10/06/2016	None
ISL96017WIRT8Z	10/06/2015	10/12/2015	10/06/2016	None
ISL96017WIRT8Z-T	10/06/2015	10/12/2015	10/06/2016	None
ISL96017WIRT8Z-TK	10/06/2015	10/12/2015	10/06/2016	None
ISL97642IRTZ	10/06/2015	10/12/2015	10/06/2016	None
ISL97642IRTZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL97648IRTZ	10/06/2015	10/12/2015	10/06/2016	None
ISL97648IRTZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL97648IRTZ-TK	10/06/2015	10/12/2015	10/06/2016	None
ISL97649AIRZ	10/06/2015	10/12/2015	10/06/2016	None
ISL97649AIRZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL97649BIRZ	10/06/2015	10/12/2015	10/06/2016	None
ISL97649BIRZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL97670IRZR5497	10/06/2015	10/12/2015	10/06/2016	None
ISL97670IRZR5595	10/06/2015	10/12/2015	10/06/2016	None
ISL97670IRZR5596	10/06/2015	10/12/2015	10/06/2016	None
ISL97670IRZ-TKR5595	10/06/2015	10/12/2015	10/06/2016	None
ISL97670IRZ-TR5497	10/06/2015	10/12/2015	10/06/2016	None
ISL97670IRZ-TR5595	10/06/2015	10/12/2015	10/06/2016	None
ISL97670IRZ-TR5596	10/06/2015	10/12/2015	10/06/2016	None
ISL97671AIRZ-TR5533	10/06/2015	10/12/2015	10/06/2016	None
ISL97671IRZ	10/06/2015	10/12/2015	10/06/2016	None
ISL97671IRZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL97671IRZ-TK	10/06/2015	10/12/2015	10/06/2016	None
ISL97672IRZ	10/06/2015	10/12/2015	10/06/2016	None
ISL97672IRZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL97672IRZ-TK	10/06/2015	10/12/2015	10/06/2016	None
ISL97674IRZ	10/06/2015	10/12/2015	10/06/2016	None
ISL97674IRZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL97674IRZ-TK	10/06/2015	10/12/2015	10/06/2016	None

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL97675IRZ	10/06/2015	10/12/2015	10/06/2016	None
ISL97675IRZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL97675IRZ-TK	10/06/2015	10/12/2015	10/06/2016	None
ISL97676IRZ	10/06/2015	10/12/2015	10/06/2016	ISL97671AIRZ
ISL97676IRZ-T	10/06/2015	10/12/2015	10/06/2016	ISL97671AIRZ
ISL97676IRZ-TK	10/06/2015	10/12/2015	10/06/2016	ISL97671AIRZ
ISL97677IRZ	10/06/2015	10/12/2015	10/06/2016	None
ISL97677IRZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL97677IRZ-TK	10/06/2015	10/12/2015	10/06/2016	None
ISL97680IRZ	10/06/2015	10/12/2015	10/06/2016	None
ISL97680IRZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL97680IRZ-TK	10/06/2015	10/12/2015	10/06/2016	None
ISL97685IRTZ	10/06/2015	10/12/2015	10/06/2016	None
ISL97685IRTZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL97801ARZ-TK	10/06/2015	10/12/2015	10/06/2016	None
ISL98012IUZ	10/06/2015	10/12/2015	10/06/2016	None
ISL98012IUZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL98012IUZ-TK	10/06/2015	10/12/2015	10/06/2016	None
ISL98602IRAAZR5453	10/06/2015	10/12/2015	10/06/2016	None
ISL98602IRAAZ-TR5453	10/06/2015	10/12/2015	10/06/2016	None
ISL98603IRAAZ	10/06/2015	10/12/2015	10/06/2016	None
ISL98603IRAAZ-T	10/06/2015	10/12/2015	10/06/2016	None
ISL98603IRAAZ-T7A	10/06/2015	10/12/2015	10/06/2016	None
ISL98603IRAAZ-TK	10/06/2015	10/12/2015	10/06/2016	None
ISL98604IRTZ	10/06/2015	10/12/2015	10/06/2016	None
ISL98604IRTZ-T	10/06/2015	10/12/2015	10/06/2016	None
KAD2708C-10Q68	10/06/2015	10/12/2015	10/06/2016	None
KAD2708C-17Q68	10/06/2015	10/12/2015	10/06/2016	None
KAD2708C-21Q68	10/06/2015	10/12/2015	10/06/2016	None
KAD2708C-27Q68	10/06/2015	10/12/2015	10/06/2016	None
KAD2708L-10Q68	10/06/2015	10/12/2015	10/06/2016	None
KAD2708L-17Q68	10/06/2015	10/12/2015	10/06/2016	None
KAD2708L-21Q68	10/06/2015	10/12/2015	10/06/2016	None
KAD2708L-27Q68	10/06/2015	10/12/2015	10/06/2016	None
KAD2708L-35Q68	10/06/2015	10/12/2015	10/06/2016	None
KAD2710C-10Q68	10/06/2015	10/12/2015	10/06/2016	None
KAD2710C-17Q68	10/06/2015	10/12/2015	10/06/2016	None
KAD2710C-21Q68	10/06/2015	10/12/2015	10/06/2016	None
KAD2710C-27Q68	10/06/2015	10/12/2015	10/06/2016	None
KAD2710L-10Q68	10/06/2015	10/12/2015	10/06/2016	None
KAD2710L-17Q68	10/06/2015	10/12/2015	10/06/2016	None
KAD2710L-21Q68	10/06/2015	10/12/2015	10/06/2016	None
KAD2710L-27Q68	10/06/2015	10/12/2015	10/06/2016	None
QHX100IQSR	10/06/2015	10/12/2015	10/06/2016	None
QHX100IQT7	10/06/2015	10/12/2015	10/06/2016	None
QHX220IQSR	10/06/2015	10/12/2015	10/06/2016	None
QHX220IQT7	10/06/2015	10/12/2015	10/06/2016	None
TW2388-LA2-GR	10/06/2015	10/12/2015	10/06/2016	TW8832S-LB1-CR
TW2840-BA1-FR	10/06/2015	10/12/2015	10/06/2016	None
TW2960-LA1-CR	10/06/2015	10/12/2015	10/06/2016	TW2964-LA2-CR, TW2964-LA2-CR128, TW2984-NA2-CR
TW5866-BA2-CR	10/06/2015	10/12/2015	10/06/2016	TW2819-BA2-CR, TW2809-BC1-GR
TW6805A-LA2-GR	10/06/2015	10/12/2015	10/06/2016	TW6865-TA1-CR, TW6869-TA1-CR
TW8806-PB2-GRR5437	10/06/2015	10/12/2015	10/06/2016	TW8806EP-PB2-GRS
TW8806-PB2-GRS	10/06/2015	10/12/2015	10/06/2016	TW8806EP-PB2-GRS
TW8816AT-LA3-GRSH	10/06/2015	10/06/2016	10/12/2016	TW8816AT-LB3-GRSH
TW8816AT-LA3-GRSHT	10/06/2015	10/06/2016	10/12/2016	TW8816AT-LB3-GRSHT
TW8816EP-LA3-GRSV	10/06/2015	10/12/2015	10/06/2016	TW8816-LB3-GRS
TW8816-LB2-GRS	10/06/2015	10/12/2015	10/06/2016	TW8816-LB3-GRS
TW8817AT-TA3-GRSH	10/06/2015	10/06/2016	10/12/2016	None

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
TW8817-TA5-GRS	10/06/2015	10/12/2015	10/06/2016	TW8817-TA3-GRS; TW8817-TA6-GRSHT
TW8817-TA5-GRSH	10/06/2015	10/12/2015	10/06/2016	TW8817-TA3-GRST; TW8817-TA6-GRSHT
TW8817-TA5-GRSHT	10/06/2015	10/12/2015	10/06/2016	TW8817-TA3-GRS; TW8817-TA6-GRSHT
TW9906-TA3-GR	10/06/2015	10/12/2015	10/06/2016	TW9906-TB2-GR, TW9912-NA3-CR
X28HC256J-12	10/06/2015	10/12/2015	10/06/2016	X28HC256JZ-12
X28HC256J-12T1	10/06/2015	10/12/2015	10/06/2016	X28HC256JZ-12T1
X28HC256J-15	10/06/2015	10/12/2015	10/06/2016	X28HC256JZ-15
X28HC256J-15T1	10/06/2015	10/12/2015	10/06/2016	X28HC256JZ-15T1
X28HC256JI-12T1	10/06/2015	10/12/2015	10/06/2016	X28HC256JIZ-12T1
X28HC256JI-15T1	10/06/2015	10/12/2015	10/06/2016	X28HC256JIZ-15T1
X28HC256JI-15T2	10/06/2015	10/12/2015	10/06/2016	X28HC256JIZ-15T1
X28HC256JI-90C7992	10/06/2015	10/12/2015	10/06/2016	X28HC256JI-90, X28HC256JIZ-90
X28HC256JI-90T1C7992	10/06/2015	10/12/2015	10/06/2016	X28HC256JI-90T1, X28HC256JIZ-90T1
X28HC256S-12	10/06/2015	10/12/2015	10/06/2016	X28HC256SZ-12
X28HC256S-90	10/06/2015	10/12/2015	10/06/2016	X28HC256SI-90, X28HC256SIZ-90
X28HC256SI-15	10/06/2015	10/12/2015	10/06/2016	X28HC256SIZ-12
X28HC256SI-15T1	10/06/2015	10/12/2015	10/06/2016	X28HC256SIZ-12
X28HC256SIZ-15	10/06/2015	10/12/2015	10/06/2016	X28HC256SIZ-12
X28HC64J-12	10/06/2015	10/12/2015	10/06/2016	X28HC64JZ-12
X28HC64J-12T1	10/06/2015	10/12/2015	10/06/2016	X28HC64JZ-12T1
X28HC64J-70	10/06/2015	10/12/2015	10/06/2016	X28HC64JZ-70
X28HC64J-70T1	10/06/2015	10/12/2015	10/06/2016	X28HC64JZ-70T1
X28HC64J-90	10/06/2015	10/12/2015	10/06/2016	X28HC64JIZ-90
X28HC64J-90T1	10/06/2015	10/12/2015	10/06/2016	X28HC64JIZ-90T1
X28HC64JI-12	10/06/2015	10/12/2015	10/06/2016	X28HC64JIZ-12
X28HC64JI-12T1	10/06/2015	10/12/2015	10/06/2016	X28HC64JIZ-12T1
X28HC64JI-70	10/06/2015	10/12/2015	10/06/2016	X28HC64JIZ-70
X28HC64JI-70T1	10/06/2015	10/12/2015	10/06/2016	X28HC64JIZ-70T1
X28HC64JI-90	10/06/2015	10/12/2015	10/06/2016	X28HC64JIZ-90
X28HC64JI-90T1	10/06/2015	10/12/2015	10/06/2016	X28HC64JIZ-90T1
X28HC64JI-90T2	10/06/2015	10/12/2015	10/06/2016	X28HC64JIZ-90T1
X28HT010W	10/06/2015	10/12/2015	10/06/2016	None
X40020S14IZ-A	10/06/2015	10/12/2015	10/06/2016	None
X40020S14IZ-AT1	10/06/2015	10/12/2015	10/06/2016	None
X40020S14IZ-B	10/06/2015	10/12/2015	10/06/2016	None
X40020S14IZ-BT1	10/06/2015	10/12/2015	10/06/2016	None
X40020S14Z-A	10/06/2015	10/12/2015	10/06/2016	None
X40020S14Z-AT1	10/06/2015	10/12/2015	10/06/2016	None
X40020S14Z-B	10/06/2015	10/12/2015	10/06/2016	None
X40020S14Z-BT1	10/06/2015	10/12/2015	10/06/2016	None
X40021S14IZ-A	10/06/2015	10/12/2015	10/06/2016	None
X40021S14IZ-AT1	10/06/2015	10/12/2015	10/06/2016	None
X40021S14IZ-B	10/06/2015	10/12/2015	10/06/2016	None
X40021S14IZ-BT1	10/06/2015	10/12/2015	10/06/2016	None
X40021S14Z-A	10/06/2015	10/12/2015	10/06/2016	None
X40021S14Z-AT1	10/06/2015	10/12/2015	10/06/2016	None
X40021S14Z-B	10/06/2015	10/12/2015	10/06/2016	None
X40021S14Z-BT1	10/06/2015	10/12/2015	10/06/2016	None
X40030S14IZ-A	10/06/2015	10/12/2015	10/06/2016	None
X40030S14IZ-AT1	10/06/2015	10/12/2015	10/06/2016	None
X40030S14IZ-B	10/06/2015	10/12/2015	10/06/2016	None
X40030S14IZ-BT1	10/06/2015	10/12/2015	10/06/2016	None
X40030S14Z-A	10/06/2015	10/12/2015	10/06/2016	None
X40030S14Z-AT1	10/06/2015	10/12/2015	10/06/2016	None
X40030S14Z-B	10/06/2015	10/12/2015	10/06/2016	None
X40030S14Z-BT1	10/06/2015	10/12/2015	10/06/2016	None
X40031S14IZ-A	10/06/2015	10/12/2015	10/06/2016	None
X40031S14IZ-AT1	10/06/2015	10/12/2015	10/06/2016	None
X40031S14IZ-B	10/06/2015	10/12/2015	10/06/2016	None

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
X40031S14IZ-BT1	10/06/2015	10/12/2015	10/06/2016	None
X40031S14Z-A	10/06/2015	10/12/2015	10/06/2016	None
X40031S14Z-AT1	10/06/2015	10/12/2015	10/06/2016	None
X40031S14Z-B	10/06/2015	10/12/2015	10/06/2016	None
X40031S14Z-BT1	10/06/2015	10/12/2015	10/06/2016	None
X4003M8IZ	10/06/2015	10/12/2015	10/06/2016	None
X4003M8IZ-2.7	10/06/2015	10/12/2015	10/06/2016	None
X4003M8IZ-2.7A	10/06/2015	10/12/2015	10/06/2016	None
X4003M8IZ-4.5A	10/06/2015	10/12/2015	10/06/2016	None
X4003M8Z	10/06/2015	10/12/2015	10/06/2016	None
X4003M8Z-2.7	10/06/2015	10/12/2015	10/06/2016	None
X4003M8Z-2.7A	10/06/2015	10/12/2015	10/06/2016	None
X4003M8Z-4.5A	10/06/2015	10/12/2015	10/06/2016	None
X4003S8IZ	10/06/2015	10/12/2015	10/06/2016	None
X4003S8IZ-2.7	10/06/2015	10/12/2015	10/06/2016	None
X4003S8IZ-2.7A	10/06/2015	10/12/2015	10/06/2016	None
X4003S8IZ-4.5A	10/06/2015	10/12/2015	10/06/2016	None
X4003S8Z	10/06/2015	10/12/2015	10/06/2016	None
X4003S8Z-2.7	10/06/2015	10/12/2015	10/06/2016	None
X4003S8Z-2.7A	10/06/2015	10/12/2015	10/06/2016	None
X4003S8Z-4.5A	10/06/2015	10/12/2015	10/06/2016	None
X4005M8IZ	10/06/2015	10/12/2015	10/06/2016	None
X4005M8IZ-2.7	10/06/2015	10/12/2015	10/06/2016	None
X4005M8IZ-2.7A	10/06/2015	10/12/2015	10/06/2016	None
X4005M8IZ-4.5A	10/06/2015	10/12/2015	10/06/2016	None
X4005M8Z	10/06/2015	10/12/2015	10/06/2016	None
X4005M8Z-2.7	10/06/2015	10/12/2015	10/06/2016	None
X4005M8Z-2.7A	10/06/2015	10/12/2015	10/06/2016	None
X4005M8Z-4.5A	10/06/2015	10/12/2015	10/06/2016	None
X4005S8IZ	10/06/2015	10/12/2015	10/06/2016	None
X4005S8IZ-2.7	10/06/2015	10/12/2015	10/06/2016	None
X4005S8IZ-2.7A	10/06/2015	10/12/2015	10/06/2016	None
X4005S8IZ-4.5A	10/06/2015	10/12/2015	10/06/2016	None
X4005S8Z	10/06/2015	10/12/2015	10/06/2016	None
X4005S8Z-2.7	10/06/2015	10/12/2015	10/06/2016	None
X4005S8Z-2.7A	10/06/2015	10/12/2015	10/06/2016	None
X4005S8Z-4.5A	10/06/2015	10/12/2015	10/06/2016	None
X40415V8IZ-BT1	10/06/2015	10/12/2015	10/06/2016	None
X40420S14IZ-A	10/06/2015	10/12/2015	10/06/2016	None
X40420S14IZ-AT1	10/06/2015	10/12/2015	10/06/2016	None
X40420S14IZ-B	10/06/2015	10/12/2015	10/06/2016	None
X40420S14IZ-BT1	10/06/2015	10/12/2015	10/06/2016	None
X40420S14Z-A	10/06/2015	10/12/2015	10/06/2016	None
X40420S14Z-AT1	10/06/2015	10/12/2015	10/06/2016	None
X40420S14Z-B	10/06/2015	10/12/2015	10/06/2016	None
X40420S14Z-BT1	10/06/2015	10/12/2015	10/06/2016	None
X40421S14IZ-AT1	10/06/2015	10/12/2015	10/06/2016	None
X40421S14IZ-B	10/06/2015	10/12/2015	10/06/2016	None
X40421S14IZ-BT1	10/06/2015	10/12/2015	10/06/2016	None
X40421S14Z-A	10/06/2015	10/12/2015	10/06/2016	None
X40421S14Z-AT1	10/06/2015	10/12/2015	10/06/2016	None
X40421S14Z-B	10/06/2015	10/12/2015	10/06/2016	None
X40421S14Z-BT1	10/06/2015	10/12/2015	10/06/2016	None
X40430S14IZ-A	10/06/2015	10/12/2015	10/06/2016	None
X40430S14IZ-AT1	10/06/2015	10/12/2015	10/06/2016	None
X40430S14IZ-B	10/06/2015	10/12/2015	10/06/2016	None
X40430S14IZ-BT1	10/06/2015	10/12/2015	10/06/2016	None
X40430S14Z-A	10/06/2015	10/12/2015	10/06/2016	None
X40430S14Z-AT1	10/06/2015	10/12/2015	10/06/2016	None

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
X40430S14Z-B	10/06/2015	10/12/2015	10/06/2016	None
X40430S14Z-BT1	10/06/2015	10/12/2015	10/06/2016	None
X40431S14IZ-A	10/06/2015	10/12/2015	10/06/2016	None
X40431S14IZ-AT1	10/06/2015	10/12/2015	10/06/2016	None
X40431S14IZ-B	10/06/2015	10/12/2015	10/06/2016	None
X40431S14IZ-BT1	10/06/2015	10/12/2015	10/06/2016	None
X40431S14Z-A	10/06/2015	10/12/2015	10/06/2016	None
X40431S14Z-AT1	10/06/2015	10/12/2015	10/06/2016	None
X40431S14Z-B	10/06/2015	10/12/2015	10/06/2016	None
X40431S14Z-BT1	10/06/2015	10/12/2015	10/06/2016	None
X4043PIZ	10/06/2015	10/12/2015	10/06/2016	X4043M8IZ
X4043PIZ-2.7	10/06/2015	10/12/2015	10/06/2016	X4043M8IZ-2.7
X4043PIZ-2.7A	10/06/2015	10/12/2015	10/06/2016	X4043M8IZ-2.7A
X4043PIZ-4.5A	10/06/2015	10/12/2015	10/06/2016	X4043M8IZ-4.5A
X4043PZ	10/06/2015	10/12/2015	10/06/2016	X4043M8Z
X4043PZ-2.7	10/06/2015	10/12/2015	10/06/2016	X4043M8Z-2.7
X4043PZ-2.7A	10/06/2015	10/12/2015	10/06/2016	X4043M8Z-2.7A
X4043PZ-4.5A	10/06/2015	10/12/2015	10/06/2016	X4043M8Z-4.5A
X4045M8IZ	10/06/2015	10/12/2015	10/06/2016	X4045S8IZ
X4045M8IZ-2.7	10/06/2015	10/12/2015	10/06/2016	X4045S8IZ-2.7
X4045M8IZ-2.7A	10/06/2015	10/12/2015	10/06/2016	X4045S8IZ-2.7A
X4045M8IZ-4.5A	10/06/2015	10/12/2015	10/06/2016	X4045S8IZ-4.5A
X4045M8Z	10/06/2015	10/12/2015	10/06/2016	X4045S8Z
X4045M8Z-2.7	10/06/2015	10/12/2015	10/06/2016	X4045S8Z-2.7
X4045M8Z-2.7A	10/06/2015	10/12/2015	10/06/2016	X4045S8Z-2.7A
X4045M8Z-4.5A	10/06/2015	10/12/2015	10/06/2016	X4045S8Z-4.5A
X4045PIZ	10/06/2015	10/12/2015	10/06/2016	X4045S8IZ
X4045PIZ-2.7	10/06/2015	10/12/2015	10/06/2016	X4045S8IZ-2.7
X4045PIZ-2.7A	10/06/2015	10/12/2015	10/06/2016	X4045S8IZ-2.7A
X4045PIZ-4.5A	10/06/2015	10/12/2015	10/06/2016	X4045S8IZ-4.5A
X4045PZ	10/06/2015	10/12/2015	10/06/2016	X4045S8Z
X4045PZ-2.7	10/06/2015	10/12/2015	10/06/2016	X4045S8Z-2.7
X4045PZ-2.7A	10/06/2015	10/12/2015	10/06/2016	X4045S8Z-2.7A
X4045PZ-4.5A	10/06/2015	10/12/2015	10/06/2016	X4045S8Z-4.5A
X5001PIZ	10/06/2015	10/12/2015	10/06/2016	None
X5001PIZ-2.7	10/06/2015	10/12/2015	10/06/2016	None
X5001PIZ-2.7A	10/06/2015	10/12/2015	10/06/2016	None
X5001PIZ-4.5A	10/06/2015	10/12/2015	10/06/2016	None
X5001PZ-2.7	10/06/2015	10/12/2015	10/06/2016	None
X5001PZ-2.7A	10/06/2015	10/12/2015	10/06/2016	None
X5001S8IZ	10/06/2015	10/12/2015	10/06/2016	None
X5001S8IZ-2.7	10/06/2015	10/12/2015	10/06/2016	None
X5001S8IZ-2.7A	10/06/2015	10/12/2015	10/06/2016	None
X5001S8IZ-4.5A	10/06/2015	10/12/2015	10/06/2016	None
X5001S8Z	10/06/2015	10/12/2015	10/06/2016	None
X5001S8Z-2.7	10/06/2015	10/12/2015	10/06/2016	None
X5001S8Z-2.7A	10/06/2015	10/12/2015	10/06/2016	None
X5001S8Z-4.5A	10/06/2015	10/12/2015	10/06/2016	None
X5043V14IZ	10/06/2015	10/12/2015	10/06/2016	X5043M8IZ
X5045M8IZ	10/06/2015	10/12/2015	10/06/2016	X5045S8IZ-2.7
X5045M8IZ-2.7	10/06/2015	10/12/2015	10/06/2016	X5045S8IZ-2.7
X5045M8IZ-2.7A	10/06/2015	10/12/2015	10/06/2016	X5045S8IZ-2.7A
X5045M8IZ-4.5A	10/06/2015	10/12/2015	10/06/2016	X5045S8IZ-4.5A
X5045M8Z	10/06/2015	10/12/2015	10/06/2016	X5045S8Z
X5045M8Z-2.7	10/06/2015	10/12/2015	10/06/2016	X5045S8Z-2.7
X5045M8Z-2.7A	10/06/2015	10/12/2015	10/06/2016	X5045S8Z-2.7A
X5045M8Z-4.5A	10/06/2015	10/12/2015	10/06/2016	X5045S8Z-4.5A
X5045W-2.7A	10/06/2015	10/12/2015	10/06/2016	None
X5083PIZ	10/06/2015	10/12/2015	10/06/2016	None

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
X5083PIZ-2.7	10/06/2015	10/12/2015	10/06/2016	None
X5083PIZ-2.7A	10/06/2015	10/12/2015	10/06/2016	None
X5083PIZ-4.5A	10/06/2015	10/12/2015	10/06/2016	None
X5083PZ	10/06/2015	10/12/2015	10/06/2016	None
X5083PZ-2.7	10/06/2015	10/12/2015	10/06/2016	None
X5083PZ-2.7A	10/06/2015	10/12/2015	10/06/2016	None
X5083PZ-4.5A	10/06/2015	10/12/2015	10/06/2016	None
X5083V8IZ	10/06/2015	10/12/2015	10/06/2016	X5083S8IZ
X5083V8IZ-2.7	10/06/2015	10/12/2015	10/06/2016	X5083S8IZ-2.7
X5163PIZ	10/06/2015	10/12/2015	10/06/2016	X5163S8IZ
X5163PIZ-2.7	10/06/2015	10/12/2015	10/06/2016	X5163S8IZ-2.7
X5163PIZ-2.7A	10/06/2015	10/12/2015	10/06/2016	X5163S8IZ-2.7A
X5163PIZ-4.5A	10/06/2015	10/12/2015	10/06/2016	X5163S8IZ-4.5A
X5163PZ	10/06/2015	10/12/2015	10/06/2016	X5163S8Z
X5163PZ-2.7	10/06/2015	10/12/2015	10/06/2016	X5163S8Z-2.7
X5163PZ-2.7A	10/06/2015	10/12/2015	10/06/2016	X5163S8Z-2.7A
X5163PZ-4.5A	10/06/2015	10/12/2015	10/06/2016	X5163S8Z-4.5A
X5165PIZ	10/06/2015	10/12/2015	10/06/2016	None
X5165PIZ-2.7	10/06/2015	10/12/2015	10/06/2016	None
X5165PIZ-2.7A	10/06/2015	10/12/2015	10/06/2016	None
X5165PIZ-4.5A	10/06/2015	10/12/2015	10/06/2016	None
X5165PZ	10/06/2015	10/12/2015	10/06/2016	None
X5165PZ-2.7	10/06/2015	10/12/2015	10/06/2016	None
X5165PZ-2.7A	10/06/2015	10/12/2015	10/06/2016	None
X5165PZ-4.5A	10/06/2015	10/12/2015	10/06/2016	None
X5165S8IZ	10/06/2015	10/12/2015	10/06/2016	None
X5165S8IZ-2.7	10/06/2015	10/12/2015	10/06/2016	None
X5165S8IZ-2.7A	10/06/2015	10/12/2015	10/06/2016	None
X5165S8IZ-2.7T1	10/06/2015	10/12/2015	10/06/2016	None
X5165S8IZ-4.5A	10/06/2015	10/12/2015	10/06/2016	None
X5165S8IZT1	10/06/2015	10/12/2015	10/06/2016	None
X5165S8Z	10/06/2015	10/12/2015	10/06/2016	None
X5165S8Z-2.7	10/06/2015	10/12/2015	10/06/2016	None
X5165S8Z-2.7A	10/06/2015	10/12/2015	10/06/2016	None
X5165S8Z-2.7T1	10/06/2015	10/12/2015	10/06/2016	None
X5165S8Z-4.5A	10/06/2015	10/12/2015	10/06/2016	None
X5165S8ZT1	10/06/2015	10/12/2015	10/06/2016	None
X5168PIZ	10/06/2015	10/12/2015	10/06/2016	None
X5168PIZ-2.7	10/06/2015	10/12/2015	10/06/2016	None
X5168PIZ-2.7A	10/06/2015	10/12/2015	10/06/2016	None
X5168PIZ-4.5A	10/06/2015	10/12/2015	10/06/2016	None
X5168PZ	10/06/2015	10/12/2015	10/06/2016	None
X5168PZ-2.7	10/06/2015	10/12/2015	10/06/2016	None
X5168PZ-2.7A	10/06/2015	10/12/2015	10/06/2016	None
X5168PZ-4.5A	10/06/2015	10/12/2015	10/06/2016	None
X5168S8IZ	10/06/2015	10/12/2015	10/06/2016	None
X5168S8IZ-2.7	10/06/2015	10/12/2015	10/06/2016	None
X5168S8IZ-2.7A	10/06/2015	10/12/2015	10/06/2016	None
X5168S8IZ-2.7T1	10/06/2015	10/12/2015	10/06/2016	None
X5168S8IZ-4.5A	10/06/2015	10/12/2015	10/06/2016	None
X5168S8IZ-4.5AT1	10/06/2015	10/12/2015	10/06/2016	None
X5168S8IZT1	10/06/2015	10/12/2015	10/06/2016	None
X5168S8Z	10/06/2015	10/12/2015	10/06/2016	None
X5168S8Z-2.7	10/06/2015	10/12/2015	10/06/2016	None
X5168S8Z-2.7A	10/06/2015	10/12/2015	10/06/2016	None
X5168S8Z-2.7AT1	10/06/2015	10/12/2015	10/06/2016	None
X5168S8Z-2.7T1	10/06/2015	10/12/2015	10/06/2016	None
X5168S8Z-4.5A	10/06/2015	10/12/2015	10/06/2016	None
X5168S8ZT1	10/06/2015	10/12/2015	10/06/2016	None

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
X5169PIZ	10/06/2015	10/12/2015	10/06/2016	None
X5169PIZ-2.7	10/06/2015	10/12/2015	10/06/2016	None
X5169PIZ-2.7A	10/06/2015	10/12/2015	10/06/2016	None
X5169PIZ-4.5A	10/06/2015	10/12/2015	10/06/2016	None
X5169PZ	10/06/2015	10/12/2015	10/06/2016	None
X5169PZ-2.7	10/06/2015	10/12/2015	10/06/2016	None
X5169PZ-2.7A	10/06/2015	10/12/2015	10/06/2016	None
X5169PZ-4.5A	10/06/2015	10/12/2015	10/06/2016	None
X5169S8IZ	10/06/2015	10/12/2015	10/06/2016	None
X5169S8IZ-2.7	10/06/2015	10/12/2015	10/06/2016	None
X5169S8IZ-2.7A	10/06/2015	10/12/2015	10/06/2016	None
X5169S8IZ-2.7T1	10/06/2015	10/12/2015	10/06/2016	None
X5169S8IZ-4.5A	10/06/2015	10/12/2015	10/06/2016	None
X5169S8IZT1	10/06/2015	10/12/2015	10/06/2016	None
X5169S8Z	10/06/2015	10/12/2015	10/06/2016	None
X5169S8Z-2.7	10/06/2015	10/12/2015	10/06/2016	None
X5169S8Z-2.7A	10/06/2015	10/12/2015	10/06/2016	None
X5169S8Z-2.7T1	10/06/2015	10/12/2015	10/06/2016	None
X5169S8Z-4.5A	10/06/2015	10/12/2015	10/06/2016	None
X5169S8ZT1	10/06/2015	10/12/2015	10/06/2016	None
X5323PIZ	10/06/2015	10/12/2015	10/06/2016	X5323S8IZ
X5323PIZ-2.7	10/06/2015	10/12/2015	10/06/2016	X5323S8IZ-2.7
X5323PIZ-2.7A	10/06/2015	10/12/2015	10/06/2016	X5323S8IZ-2.7A
X5323PIZ-4.5A	10/06/2015	10/12/2015	10/06/2016	X5323S8IZ-4.5A
X5323PZ	10/06/2015	10/12/2015	10/06/2016	X5323S8Z
X5323PZ-2.7	10/06/2015	10/12/2015	10/06/2016	X5323S8Z-2.7
X5323PZ-2.7A	10/06/2015	10/12/2015	10/06/2016	X5323S8Z-2.7A
X5323PZ-4.5A	10/06/2015	10/12/2015	10/06/2016	X5323S8Z-4.5A
X5328PIZ	10/06/2015	10/12/2015	10/06/2016	X5328S8IZ
X5328PIZ-2.7	10/06/2015	10/12/2015	10/06/2016	X5328S8IZ-2.7
X5328PIZ-2.7A	10/06/2015	10/12/2015	10/06/2016	X5328S8IZ-2.7A
X5328PIZ-4.5A	10/06/2015	10/12/2015	10/06/2016	X5328S8IZ-4.5A
X5328PZ	10/06/2015	10/12/2015	10/06/2016	X5328S8Z
X5328PZ-2.7	10/06/2015	10/12/2015	10/06/2016	X5328S8Z-2.7
X5328PZ-2.7A	10/06/2015	10/12/2015	10/06/2016	X5328S8Z-2.7A
X5328PZ-4.5A	10/06/2015	10/12/2015	10/06/2016	X5328S8Z-4.5A
X5329S8IZ-2.7	10/06/2015	10/12/2015	10/06/2016	X5329S8Z-2.7
X5329S8IZ-2.7A	10/06/2015	10/12/2015	10/06/2016	X5329S8Z-2.7A
X60003DIG3Z-41	10/06/2015	10/12/2015	10/06/2016	X60003BIG3Z-41T1
X60003DIG3Z-41T1	10/06/2015	10/12/2015	10/06/2016	X60003BIG3Z-41T1
X9015UW	10/06/2015	10/12/2015	10/06/2016	None
X9015WS8Z	10/06/2015	10/12/2015	10/06/2016	X9015US8Z
X9015WS8Z-2.7	10/06/2015	10/12/2015	10/06/2016	X9015US8Z-2.7
X9015WS8Z-2.7T1	10/06/2015	10/12/2015	10/06/2016	X9015US8Z-2.7T1
X9015WS8ZT1	10/06/2015	10/12/2015	10/06/2016	X9015US8ZT1
X9221AWPIZ	10/06/2015	10/12/2015	10/06/2016	X9221AWSZT1
X9221AWPZ	10/06/2015	10/12/2015	10/06/2016	X9221AWSZT1
X9241AMPIZ	10/06/2015	10/12/2015	10/06/2016	X9241AMSZT1
X9241AMPZ	10/06/2015	10/12/2015	10/06/2016	X9241AMSZT1
X9241AUVZ	10/06/2015	10/12/2015	10/06/2016	X9241AMSZT1
X9241AUVZT1	10/06/2015	10/12/2015	10/06/2016	X9241AUSZT1
X9241AWW	10/06/2015	10/12/2015	10/06/2016	None
X9241AYPIZ	10/06/2015	10/12/2015	10/06/2016	X9241AYSIZ
X9241AYPZ	10/06/2015	10/12/2015	10/06/2016	X9241AYSIZ
X9241AYVZ	10/06/2015	10/12/2015	10/06/2016	X9241AYSIZ
X9241AYVZT1	10/06/2015	10/12/2015	10/06/2016	X9241AYVIZT1
X9241AYW	10/06/2015	10/12/2015	10/06/2016	None
X9271UV14Z-2.7	10/06/2015	10/12/2015	10/06/2016	X9271UV14IZ-2.7T1
X9271UV14Z-2.7T1	10/06/2015	10/12/2015	10/06/2016	X9271UV14IZ-2.7T1

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
X9271UV14ZT1	10/06/2015	10/12/2015	10/06/2016	X9271UV14IZ-2.7T1
X9313UPZ	10/06/2015	10/12/2015	10/06/2016	X9313UMIZT1
X9313WPZ-3	10/06/2015	10/12/2015	10/06/2016	X9313UMIZ-3T1
X9313ZPIZ	10/06/2015	10/12/2015	10/06/2016	X9313ZSIZT1
X9313ZPZ-3	10/06/2015	10/12/2015	10/06/2016	X9313ZSIZ-3T1
X93154UM8IZ-3	10/06/2015	10/12/2015	10/06/2016	None
X93154UM8IZ-3T1	10/06/2015	10/12/2015	10/06/2016	None
X93155UM8IZ	10/06/2015	10/12/2015	10/06/2016	None
X93155UM8IZT1	10/06/2015	10/12/2015	10/06/2016	None
X93156UM8IZ-2.7	10/06/2015	10/12/2015	10/06/2016	None
X93156UM8IZ-2.7T1	10/06/2015	10/12/2015	10/06/2016	None
X93156WM8IZ	10/06/2015	10/12/2015	10/06/2016	None
X93156WM8IZ-2.7	10/06/2015	10/12/2015	10/06/2016	None
X93156WM8IZ-2.7T1	10/06/2015	10/12/2015	10/06/2016	None
X9317WW	10/06/2015	10/12/2015	10/06/2016	None
X9319WW	10/06/2015	10/12/2015	10/06/2016	None
X9400WS24IZ2.7TS2705	10/06/2015	10/03/2016	10/03/2017	X9400WS24IZT1
X9400WS24IZ27T1S2705	10/06/2015	10/03/2016	10/03/2017	X9400WS24IZT1
X9400WS24ZT1	10/06/2015	10/12/2015	10/06/2016	X9400WS24IZT1
X9400WV24IZ-2.7	10/06/2015	10/12/2015	10/06/2016	X9400WS24IZT1
X9400WV24IZ-2.7T1	10/06/2015	10/12/2015	10/06/2016	X9400WS24IZT1
X9400WV24Z	10/06/2015	10/12/2015	10/06/2016	X9400WS24IZT1
X9400WV24Z-2.7	10/06/2015	10/12/2015	10/06/2016	X9400WS24IZT1
X9400WV24Z-2.7T1	10/06/2015	10/12/2015	10/06/2016	X9400WS24IZT1
X9400WV24ZT1	10/06/2015	10/12/2015	10/06/2016	X9400WS24IZT1
X9401WS24IZ	10/06/2015	10/12/2015	10/06/2016	X9401WS24IZ-2.7T1
X9401WS24IZT1	10/06/2015	10/12/2015	10/06/2016	X9401WS24IZ-2.7T1
X9401WS24Z	10/06/2015	10/12/2015	10/06/2016	X9401WS24IZ-2.7T1
X9401WS24Z-2.7	10/06/2015	10/12/2015	10/06/2016	X9401WS24IZ-2.7T1
X9401WS24Z-2.7T1	10/06/2015	10/12/2015	10/06/2016	X9401WS24IZ-2.7T1
X9401WS24ZT1	10/06/2015	10/12/2015	10/06/2016	X9401WS24IZ-2.7T1
X9401WV24IZ	10/06/2015	10/12/2015	10/06/2016	X9401WV24IZ-2.7T1
X9401WV24IZT1	10/06/2015	10/12/2015	10/06/2016	X9401WV24IZ-2.7T1
X9401WV24Z	10/06/2015	10/12/2015	10/06/2016	X9401WV24IZ-2.7T1
X9401WV24Z-2.7	10/06/2015	10/12/2015	10/06/2016	X9401WV24IZ-2.7T1
X9401WV24Z-2.7T1	10/06/2015	10/12/2015	10/06/2016	X9401WV24IZ-2.7T1
X9401WV24ZT1	10/06/2015	10/12/2015	10/06/2016	X9401WV24IZ-2.7T1
X9409WV24IZ	10/06/2015	10/12/2015	10/06/2016	X9401WV24IZ-2.7T1
X9409WV24IZT1	10/06/2015	10/12/2015	10/06/2016	X9401WV24IZ-2.7T1
X9409WV24Z	10/06/2015	10/12/2015	10/06/2016	X9401WV24IZ-2.7T1
X9409WV24Z-2.7	10/06/2015	10/12/2015	10/06/2016	X9401WV24IZ-2.7T1
X9409WV24Z-2.7T1	10/06/2015	10/12/2015	10/06/2016	X9401WV24IZ-2.7T1
X9409WV24ZT1	10/06/2015	10/12/2015	10/06/2016	X9401WV24IZ-2.7T1
X9418YS24IZ	10/06/2015	10/12/2015	10/06/2016	None
X9418YS24IZ-2.7	10/06/2015	10/12/2015	10/06/2016	None
X9418YS24Z	10/06/2015	10/12/2015	10/06/2016	None
X9418YS24Z-2.7	10/06/2015	10/12/2015	10/06/2016	None
X9418YV24IZ	10/06/2015	10/12/2015	10/06/2016	None
X9418YV24IZ-2.7	10/06/2015	10/12/2015	10/06/2016	None
X9418YV24IZ-2.7T1	10/06/2015	10/12/2015	10/06/2016	None
X9418YV24IZ-2.7T2	10/06/2015	10/12/2015	10/06/2016	None
X9418YV24Z	10/06/2015	10/12/2015	10/06/2016	None
X9418YV24Z-2.7	10/06/2015	10/12/2015	10/06/2016	None
X9429WS16IZ-2.7	10/06/2015	10/12/2015	10/06/2016	X9429WS16IZT1
X9429WS16IZ-2.7T1	10/06/2015	10/12/2015	10/06/2016	X9429WS16IZT1
X9429WS16Z	10/06/2015	10/12/2015	10/06/2016	X9429WS16IZT1
X9429WS16Z-2.7	10/06/2015	10/12/2015	10/06/2016	X9429WS16IZT1
X9429WS16Z-2.7T1	10/06/2015	10/12/2015	10/06/2016	X9429WS16IZT1
X9429WS16ZT1	10/06/2015	10/12/2015	10/06/2016	X9429WS16IZT1

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
X9C102W	10/06/2015	10/12/2015	10/06/2016	None
X9C103W	10/06/2015	10/12/2015	10/06/2016	None
ZL2103ALAF	10/06/2015	10/12/2015	10/06/2016	ZL2102ALAFTK
ZL2103ALAFT	10/06/2015	10/12/2015	10/06/2016	ZL2102ALAFTK
ZL2103ALAFTK	10/06/2015	10/12/2015	10/06/2016	ZL2102ALAFTK