

## Product Change Notice

PCN#: EE-PCN25054

July 10<sup>th</sup>, 2025

### CLASSIFICATION OF CHANGE:

An additional manufacturing line to increase capacity and supply resiliency.

### DESCRIPTION OF CHANGE:

Expand existing Eaton line locations to cover full **PB / PM / PHB / PHV / PHVL / PTV** cylindrical pack series.

| Product Series | Existing COO | New COO     |
|----------------|--------------|-------------|
| PB             | China        | Philippines |
| PM             | China        | Philippines |
| PHB            | China        | Philippines |
| PHV            | China        | Philippines |
| PHVL           | China        | Philippines |
| PTV            | China        | Philippines |

### REASON FOR CHANGE:

Expand existing Eaton dual manufacturing capability in China and Philippines

### EXPECTED INFLUENCE ON QUALITY, RELIABILITY, AND PERFORMANCE:

There will be no revision change, nor effect on the quality, reliability, or performance. There are no changes to form, fit, and function of the devices.

### PARTS FAMILIES AFFECTED:

See the following page for part number list.

### TIME SCHEDULE:

Effective Date: July 21<sup>st</sup>, 2025

### SAMPLE AVAILABILITY:

Available upon request

### QUALIFICATION DATA:

Available upon request

### ISSUED BY:

Global Product Manager: Penn Yan

### CONTACT INFORMATION:

For questions or comments, please [Contact us](#)

**Part Numbers Affected**

| Material     | Material     | Material      | Material      | Material       | Material      |
|--------------|--------------|---------------|---------------|----------------|---------------|
| PB-5R0H104-R | PM-5R0H104-R | PHB-5R0H155-R | PHV-5R4H474-R | PHVL-3R9H474-R | PTV-6R0H165-R |
| PB-5R0H474-R | PM-5R0H474-R | PHB-5R0H255-R | PHV-5R4H155-R | PHVL-3R9H155-R | PTV-6R0H305-R |
| PB-5R0H105-R | PM-5R0H105-R | PHB-5R0H305-R | PHV-5R4H255-R | PHVL-3R9H255-R | PTV-6R0H505-R |
| PB-5R0V104-R | PM-5R0H155-R | PHB-5R0H505-R | PHV-5R4H305-R | PHVL-3R9H305-R | PTV-6R0V165-R |
| PB-5R0V474-R | PM-5R0H305-R | PHB-5R0V155-R | PHV-5R4H505-R | PHVL-3R9H505-R | PTV-6R0V305-R |
| PB-5R0V105-R | PM-5R0V104-R | PHB-5R0V255-R | PHV-5R4V474-R | PHVL-3R9V474-R | PTV-6R0V505-R |
|              | PM-5R0V474-R | PHB-5R0V305-R | PHV-5R4V155-R | PHVL-3R9V155-R |               |
|              | PM-5R0V105-R | PHB-5R0V505-R | PHV-5R4V255-R | PHVL-3R9V255-R |               |
|              | PM-5R0V155-R |               | PHV-5R4V305-R | PHVL-3R9V305-R |               |
|              | PM-5R0V305-R |               | PHV-5R4V505-R | PHVL-3R9V505-R |               |
|              |              |               | PHV-5R4H505-2 |                |               |