

ID No. 829	Product/Process Change Notification	Date 22.06.2020
Product	Ordering Code	
ELS61-US Rel.2	L30960N4400A200	
ELS61-USA Rel.2	L30960N4420A200	
Ordering Code changes:	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Product	New Ordering Code	

Reason of Change:

- | | |
|--|--|
| <input checked="" type="checkbox"/> Technical requirement
<input type="checkbox"/> Customer requirement
<input type="checkbox"/> Quality improvement | <input type="checkbox"/> Change of production process/logistical changes
<input type="checkbox"/> Location of production moved
<input type="checkbox"/> Other: |
|--|--|

Description of change:	<p>THALES DIS AIS Deutschland GmbH is going to introduce a minor improvement to the production configuration. The implemented changes are pre-loading a certificate into module during production, and SLAE MIDlet updating to v2.3.0, in order to enable secure interworking with device management platform, called Cinterion® IoT Suite.</p> <p>These changes are not approval relevant. There are no changes to firmware, so there is no impact to customers. Accordingly, SVN, RN, ARN, P/N remain same.</p> <p>If there are further questions, our FAE team who offers comprehensive customer support, should be contacted.</p>
Schedule details:	CW/YEAR
Availability of SW for evaluation:	CW25/2021
Availability of modules ex THALES DIS AIS Deutschland warehouse:	CW40/2021
Timing note:	If THALES DIS AIS Deutschland GmbH does not receive a notification to the contrary within a period of 6 weeks, THALES DIS AIS Deutschland GmbH assumes that the customer agrees to the change.

Quality assurance measurements:	The new version fulfils all internal test requirements according to our Quality Management process and philosophy.
--	--

Attachments:

6/22/2021

22.06.2021

X 

Product Program Manager
Signed by: SUN Xiao-Lin

X 

Vice President Quality Management
Signed by: ERDMANN Joerg