## THALES

<b>ID No.</b> 901	Product/	Process Change Notification	Date 01.06.2022
Product		Ordering Code	L
PLS62-W Rel.1		L30960N4600A100	
Ordering Code changes:		Yes No	
Product		New Ordering Code	
Reason of Change:			
☐ Technical requirement	t	☐ Change of production process	s/logistical changes
☐ Customer requirement		☐ Location of production moved	
☐ Quality improvement		○ Other: Introduction of second source factories	
capa		er to reduce potential supply risks and to increcity for our continuous growing business, Thaleonal production site located in Vietnam.	
	Singa	dditional Foxconn factory in Vietnam: Cloud N pore Pte. Ltd. operates on same standards as facturing source Foxconn Shanghai.	
Ord		dering codes remain same with no change.	
s		SW remains same: Rev 02.010 ARN 01.000.05	
		acts manufactured at the additional factory will in Vietnam V"	be labelled with
		se of further questions, please contact your loc comprehensive customer support if required.	al FAE team who
Availability ex warehouse: CW22		2 2022	
the co		ALES DIS AIS Deutschland GmbH does not receive a notification to ontrary within a period of 6 weeks, Thales assumes that customer es to the change.	
		ew version fulfils all internal test requirements according to our y Management process and philosophy.	
Attachments:			
	6/1/2022	0	3.06.2022
X 3 A A A A		X i. Voi Aucem	
Product Program Manager Signed by: SUN Xiao-Lin		Head of Quality Management IoT Signed by: ERDMANN Joerg	