

Engineering Change Notice

Part No. <u>3522-2</u>	ECN No. <u>21-031</u>
Part Name <u>AUTO-FUSE PC SOCKET</u>	Date <u>3.30.21</u>
Rev. <u>H</u>	ECR No. <u>—</u>

Description of Change: Drawing Attached

MATERIAL HAS BEEN CHANGED FROM 80/20 MIX. VYDYNE 909 25% GLASS-FILLED 6/6 WITH 80% VYDYNE 344 UNFILLED 6/6 UL94V-0, COLOR BLACK TO NYLON 66, 20% GLASS-FILLED BLACK COLOR, ROHS COMPLAINTS PER BASE REV. E (ECN 19-073)

Solution: Tooling Change Required

REVISE C+M

Disposition of Parts:

U.A.I.

Signed LN Date 8.25.21

Required Distribution:

Engineering Quality Control Purchasing Manufacturing/Supplier

Chief Engineer: _____ Remarks: _____

Signed LN Date 8.25.21

Document Control: _____ Rev. J

Change Incorporated Signed NATASHA T. Date 8.25.21