



Expertise Applied | Answers Delivered

Jul 14th,2021

Notification of Schottky Barrier and Ultrafast Recovery Rectifier Plating Change _Jul 14th 2021

To whom it may concern,

This is a declaration letter to state that Littelfuse will change the plating of below parts from Light Tin to Matte Tin (See attached photos) aligning to manufacture requirement, effect from Aug 15th, 2021.


There will be no change on product fit, form, function.

Detail affected part number list refer to Appendix.

We value your business and look forward to assisting you whenever possible.
Thank you!



Before: Light-Tin



After: Matte-Tin

Sincerely and Best Regards,

Sophia Lv
Global Product Manager
Thyristor and Rectifier Diode
Semiconductor Business Unit, Wuxi, China
+86 510 85277701 - 7967
slv@littelfuse.com

Appendix --- Plating Change Table for Affected Products

Part ID	Package Type
DST2045C	TO-220AB
DST2060C	TO-220AB
DST20100C	TO-220AB
DST40100C	TO-220AB
DST2080C	TO-220AB
DST5200	TO-220AC
DSTF40120C-T	ITO-220AB
DSTF40150C-T	ITO-220AB
DSTF60100C	ITO-220AB
DSTF4060C-T	ITO-220AB
DSTF30100C-T	ITO-220AB
DSTF40100C-T	ITO-220AB
DSTF30200C-T	ITO-220AB
DSTF30150C-T	ITO-220AB
DSTF30120C-T	ITO-220AB
DSTF2045C	ITO-220AB
DSTF2060C	ITO-220AB
DSTF20120CR	ITO-220AB
DSTF20120C	ITO-220AB
DSTF3060CR	ITO-220AB
DSTF2080C	ITO-220AB
DSTF3045C	ITO-220AB
DSTF3080C	ITO-220AB
DSTF10200C	ITO-220AB
MBR1045	TO-220AC
MBR2060CT	TO-220AB
MBR20100CTP	TO-220AB
MBRF10150CTL	ITO-220AB
MBRF30200CT	ITO-220AB
MBRF10100CTL	ITO-220AB
MBRF10200CT	ITO-220AB
MBRF20150CT	ITO-220AB
MBRF20200CT	ITO-220AB
MBRF3060CT	ITO-220AB
MBRF2060CT	ITO-220AB
MBRF30100CTP	ITO-220AB
MBR1060CTL	TO-220AB
DURF840	ITO-220AC
DURF1060-T	ITO-220AC
DUR2030CT	TO-220AB
DURF2040CT	ITO-220AB
DURF1030CT	ITO-220AB
DUR3060CT	TO-220AB
DUR3060CT	TO-220AB
DURF3060CT	ITO-220AB