



Expertise Applied | Answers Delivered

8755 W. Higgins Road  
Suite 500  
Chicago, IL 60631

[www.littelfuse.com](http://www.littelfuse.com)

## Product Change Notice (PCN)

---

July 18<sup>th</sup>, 2022

### Product Change Notification for LSP05, LSP05G, LSP10, LSP10GIHP Module Series' MLV (Measured Limiting Voltage) rating update based on the latest UL 1449 test result. LFPCN 6065E

To whom it may concern,

Littelfuse would like to notify you of a change regarding LSP05, LSP05G, LSP10, LSP10GIHP Module Series' MLV rating based on the latest UL1449 test result. This MLV rating update will not impact/change LSP product's all other electrical parameters, mechanical/dimensional specification, quality, reliability, performance, and part number.

This MLV rating update will be implemented starting from **September 19<sup>th</sup>, 2022**, during the change transition period, customers are expected to receive the products with current and new MLV rating (MLV on product label) until current product inventory in Littelfuse warehouses and distribution channels are depleted.

Please see attached the affected part number list & MLV update summary, and respond to us by **August 18<sup>th</sup>, 2022**, to acknowledge this product change notification. If we do not hear from you, we will expect that this product change notification has been accepted and no further action is required.

If you have additional questions or concerns, please contact your Regional Sales Manager.  
Thank you very much for your continued support.

Best Regards,  
Johnny Chang  
Director, Product Management  
Littelfuse, Inc.