

OMRON

Issue Date September 28, 2022

No. 20220928_PDC_00001

MOS FET Relays

Modifications Notices

Modification Notice of packing form by adding tape reel protective cover for G3VM MOS FET relay

[Effective Date]

Effective as of our production in December, 2022.


[Model name]

G3VM Series

< Refer to the " [Details of applicable model] " . >

[Reason for change]

To improve or to change our production system



[Changes]

| Before the change | After the change |
|--|--|
| VSON / S-VSON : package with 500 pcs/ reel _ Modification of packing form | |
| *Empty reel winding | *Abolished empty reel winding and added protective cover |
| | |
| * Empty reel winding (2,500P) (2,500P) Products (500 pcs.) | Protective cover Products (500P) |
| *Empty reel winding: empty carrier tape without products | |
| | |

OMRON

[Details of applicable model]

| Models / Specification |
|------------------------|
| G3VM-21UR1(TR05) |
| G3VM-21UR10(TR05) |
| G3VM-21UR11(TR05) |
| G3VM-41UR10(TR05) |
| G3VM-41UR11(TR05) |
| G3VM-41UR12(TR05) |
| G3VM-51UR(TR05) |
| G3VM-61UR(TR05) |
| G3VM-61UR1(TR05) |
| G3VM-81UR(TR05) |
| G3VM-81UR1(TR05) |
| G3VM-101UR(TR05) |
| G3VM-21UV11(TR05) |

| Models / Specification |
|------------------------|
| G3VM-51UV(TR05) |
| G3VM-61UV(TR05) |
| G3VM-31QR(TR05) |
| G3VM-41QR10(TR05) |
| G3VM-61QR(TR05) |
| G3VM-61QR2(TR05) |
| G3VM-101QR1(TR05) |
| G3VM-31QVH(TR05) |
| G3VM-31QVL(TR05) |
| G3VM-61QV2H(TR05) |
| G3VM-61QV2L(TR05) |
| G3VM-61QVH(TR05) |

Specifications in this product news are as of the issue date and are subject to change without notice. Only main changes in specifications are described in this document. Please be sure to read the relevant catalogs, datasheets, product specifications, instructions, and manuals for precautions and necessary information when using products.