

Product Change Notice

Issue Date: 18 Feb 2014

Change Type:

Introduction of replacement die source for Chiplid part numbers listed below:

Parts Affected:

List of part number:

| | | | |
|-----------|-----------|-----------|-----------|
| HSMF-C113 | HSMR-C150 | QSMN-C124 | QSMW-B123 |
| HSMF-C115 | HSMR-C170 | QSMN-C185 | QSMW-B193 |
| HSMF-C114 | HSMR-C190 | QSMN-C186 | QSMW-C12C |
| HSMF-C118 | HSMR-C191 | QSMN-C194 | QSMW-C12E |
| HSMF-C164 | HSMR-C197 | QSMN-C199 | QSMW-C12G |
| HSMF-C169 | HSMR-C265 | QSMR-C12D | QSMW-C19M |
| HSMN-C110 | HSMW-B191 | QSMR-C13Z | QSMW-C19N |
| HSMN-C120 | HSMW-C120 | QSMR-C153 | QSMW-C13B |
| HSMN-C150 | HSMW-C130 | QSMR-C19B | |
| HSMN-C170 | HSMW-C191 | QSMR-C19J | |
| HSMN-C190 | HSMW-C265 | QSMR-C19N | |
| HSMN-C191 | QSMF-C11H | QSMR-C19Q | |
| HSMR-C110 | QSMF-C11K | QSMR-C262 | |
| HSMR-C120 | QSMF-C120 | QSMR-C264 | |
| HSMR-C130 | QSMF-C11Q | QSMW-B121 | |

Description and Extent of Changes:

The selected die source (InGaN blue) met Avago qualification requirement.

Reasons for Change:

To ensure assurance of supply

Effect of Change on Fit, Form, Function, Quality, or Reliability:

There is no change on fit, form and function as per datasheet.

Effective Date of Change:

Shipment may contain both die sources starting 18 May 2014. No sorting is required.

Qualification Data:

Qualification data will be made available upon request.

These changes have been reviewed and approved by Avago Technologies engineers and managers per Avago Technologies procedure: Change Control and Customer Notification, A-5962-6052-80.

Please contact your Avago Technologies field sales engineer or Contact Center (<http://www.avagotech.com/contact/>) for any questions or support requirements.