



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1107

Issue Date: 11/18/2025

Parts Affected	ELM 2-030	Old Rev.	R	New Rev.	T
	ELM 2-035		R		T
	ELM 2-040		R		T
	ELM 2-045		R		T
	ELM 2-050		R		T
	ELM 2-055		R		T
	ELM 2-060		R		T
	ELM 2-065		R		T
	ELM 2-070		R		T
	ELM 2-075		R		T
	ELM 2-080		R		T
	ELM 2-085		R		T
	ELM 2-090		R		T
	ELM 2-095		R		T
	ELM 2-1.000		R		T
	ELM 2-1.020		R		T
	ELM 2-1.025		R		T
	ELM 2-1.030		R		T
	ELM 2-1.035		R		T
	ELM 2-1.040		R		T
	ELM 2-1.045		R		T
	ELM 2-1.050		R		T
	ELM 2-1.055		R		T
	ELM 2-1.060		R		T
	ELM 2-1.065		R		T
	ELM 2-1.070		R		T
	ELM 2-1.075		R		T
	ELM 2-1.080		R		T
	ELM 2-1.085		R		T

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1107

Issue Date: 11/18/2025

Parts Affected	ELM 2-1.090	Old Rev.	R	New Rev.	T
	ELM 2-1.095		R		T
	ELM 2-1.100		R		T
	ELM 2-1.105		R		T
	ELM 2-1.110		R		T
	ELM 2-1.115		R		T
	ELM 2-1.120		R		T
	ELM 2-1.125		R		T
	ELM 2-1.130		R		T
	ELM 2-1.135		R		T
	ELM 2-1.140		R		T
	ELM 2-1.145		R		T
	ELM 2-1.150		R		T
	ELM 2-1.155		R		T
	ELM 2-1.160		R		T
	ELM 2-1.165		R		T
	ELM 2-1.170		R		T
	ELM 2-1.175		R		T
	ELM 2-1.180		R		T
	ELM 2-1.185		R		T
	ELM 2-1.190		R		T
	ELM 2-1.195		R		T
	ELM 2-1.200		R		T
	ELM 2-1.205		R		T
	ELM 2-1.210		R		T
	ELM 2-1.215		R		T
	ELM 2-1.220		R		T
	ELM 2-1.225		R		T
	ELM 2-1.230		R		T

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1107

Issue Date: 11/18/2025

Parts Affected		Old Rev.	New Rev.
	ELM 2-1.235	R	T
	ELM 2-1.240	R	T
	ELM 2-1.245	R	T
	ELM 2-1.250	R	T
	ELM 2-1.500	R	T
	ELM 2-1.5MM	R	T
	ELM 2-100	R	T
	ELM 2-105	R	T
	ELM 2-10MM	R	T
	ELM 2-11.5MM	R	T
	ELM 2-110	R	T
	ELM 2-115	R	T
	ELM 2-11MM	R	T
	ELM 2-120	R	T
	ELM 2-125	R	T
	ELM 2-12MM	R	T
	ELM 2-130	R	T
	ELM 2-135	R	T
	ELM 2-13MM	R	T
	ELM 2-140	R	T
	ELM 2-145	R	T
	ELM 2-14MM	R	T
	ELM 2-150	R	T
	ELM 2-155	R	T
	ELM 2-15MM	R	T
	ELM 2-160	R	T
	ELM 2-165	R	T
	ELM 2-16MM	R	T
	ELM 2-170	R	T

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1107

Issue Date: 11/18/2025

Parts Affected		Old Rev.	New Rev.
	ELM 2-175	R	T
	ELM 2-177	R	T
	ELM 2-17MM	R	T
	ELM 2-180	R	T
	ELM 2-185	R	T
	ELM 2-18MM	R	T
	ELM 2-190	R	T
	ELM 2-195	R	T
	ELM 2-19MM	R	T
	ELM 2-1MM	R	T
	ELM 2-2.5MM	R	T
	ELM 2-200	R	T
	ELM 2-205	R	T
	ELM 2-20MM	R	T
	ELM 2-210	R	T
	ELM 2-215	R	T
	ELM 2-21MM	R	T
	ELM 2-220	R	T
	ELM 2-225	R	T
	ELM 2-22MM	R	T
	ELM 2-230	R	T
	ELM 2-235	R	T
	ELM 2-23MM	R	T
	ELM 2-240	R	T
	ELM 2-245	R	T
	ELM 2-24MM	R	T
	ELM 2-250	R	T
	ELM 2-255	R	T
	ELM 2-25MM	R	T

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1107

Issue Date: 11/18/2025

Parts Affected		Old Rev.	New Rev.
	ELM 2-260	R	T
	ELM 2-265	R	T
	ELM 2-26MM	R	T
	ELM 2-270	R	T
	ELM 2-275	R	T
	ELM 2-27MM	R	T
	ELM 2-280	R	T
	ELM 2-285	R	T
	ELM 2-28MM	R	T
	ELM 2-290	R	T
	ELM 2-295	R	T
	ELM 2-29MM	R	T
	ELM 2-2MM	R	T
	ELM 2-300	R	T
	ELM 2-305	R	T
	ELM 2-30MM	R	T
	ELM 2-310	R	T
	ELM 2-315	R	T
	ELM 2-31MM	R	T
	ELM 2-320	R	T
	ELM 2-325	R	T
	ELM 2-330	R	T
	ELM 2-335	R	T
	ELM 2-340	R	T
	ELM 2-345	R	T
	ELM 2-350	R	T
	ELM 2-355	R	T
	ELM 2-360	R	T
	ELM 2-365	R	T

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1107

Issue Date: 11/18/2025

Parts Affected	ELM 2-370	Old Rev.	R	New Rev.	T
	ELM 2-374		R		T
	ELM 2-375		R		T
	ELM 2-380		R		T
	ELM 2-385		R		T
	ELM 2-390		R		T
	ELM 2-395		R		T
	ELM 2-3MM		R		T
	ELM 2-400		R		T
	ELM 2-405		R		T
	ELM 2-410		R		T
	ELM 2-415		R		T
	ELM 2-420		R		T
	ELM 2-425		R		T
	ELM 2-430		R		T
	ELM 2-435		R		T
	ELM 2-440		R		T
	ELM 2-445		R		T
	ELM 2-450		R		T
	ELM 2-455		R		T
	ELM 2-460		R		T
	ELM 2-465		R		T
	ELM 2-470		R		T
	ELM 2-475		R		T
	ELM 2-480		R		T
	ELM 2-485		R		T
	ELM 2-490		R		T
	ELM 2-495		R		T
	ELM 2-4MM		R		T

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1107

Issue Date: 11/18/2025

Parts Affected	ELM 2-5.5MM	Old Rev.	R	New Rev.	T
	ELM 2-500		R		T
	ELM 2-505		R		T
	ELM 2-510		R		T
	ELM 2-515		R		T
	ELM 2-520		R		T
	ELM 2-525		R		T
	ELM 2-530		R		T
	ELM 2-535		R		T
	ELM 2-540		R		T
	ELM 2-545		R		T
	ELM 2-550		R		T
	ELM 2-555		R		T
	ELM 2-560		R		T
	ELM 2-565		R		T
	ELM 2-570		R		T
	ELM 2-575		R		T
	ELM 2-580		R		T
	ELM 2-585		R		T
	ELM 2-590		R		T
	ELM 2-595		R		T
	ELM 2-5MM		R		T
	ELM 2-600		R		T
	ELM 2-605		R		T
	ELM 2-610		R		T
	ELM 2-615		R		T
	ELM 2-620		R		T
	ELM 2-625		R		T
	ELM 2-630		R		T

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1107

Issue Date: 11/18/2025

Parts Affected		Old Rev.	New Rev.
	ELM 2-635	R	T
	ELM 2-640	R	T
	ELM 2-645	R	T
	ELM 2-650	R	T
	ELM 2-655	R	T
	ELM 2-660	R	T
	ELM 2-665	R	T
	ELM 2-670	R	T
	ELM 2-675	R	T
	ELM 2-680	R	T
	ELM 2-685	R	T
	ELM 2-690	R	T
	ELM 2-695	R	T
	ELM 2-6MM	R	T
	ELM 2-700	R	T
	ELM 2-705	R	T
	ELM 2-710	R	T
	ELM 2-715	R	T
	ELM 2-720	R	T
	ELM 2-725	R	T
	ELM 2-730	R	T
	ELM 2-735	R	T
	ELM 2-740	R	T
	ELM 2-745	R	T
	ELM 2-750	R	T
	ELM 2-755	R	T
	ELM 2-760	R	T
	ELM 2-765	R	T
	ELM 2-770	R	T

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1107

Issue Date: 11/18/2025

Parts Affected	ELM 2-775	Old Rev.	R	New Rev.	T
	ELM 2-780		R		T
	ELM 2-785		R		T
	ELM 2-790		R		T
	ELM 2-795		R		T
	ELM 2-7MM		R		T
	ELM 2-800		R		T
	ELM 2-805		R		T
	ELM 2-810		R		T
	ELM 2-815		R		T
	ELM 2-820		R		T
	ELM 2-825		R		T
	ELM 2-830		R		T
	ELM 2-835		R		T
	ELM 2-840		R		T
	ELM 2-845		R		T
	ELM 2-850		R		T
	ELM 2-855		R		T
	ELM 2-860		R		T
	ELM 2-865		R		T
	ELM 2-870		R		T
	ELM 2-875		R		T
	ELM 2-880		R		T
	ELM 2-885		R		T
	ELM 2-890		R		T
	ELM 2-895		R		T
	ELM 2-8MM		R		T
	ELM 2-900		R		T
	ELM 2-905		R		T

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1107

Issue Date: 11/18/2025

Parts Affected	ELM 2-910	Old Rev.	R	New Rev.	T
	ELM 2-915		R		T
	ELM 2-920		R		T
	ELM 2-925		R		T
	ELM 2-930		R		T
	ELM 2-935		R		T
	ELM 2-940		R		T
	ELM 2-945		R		T
	ELM 2-950		R		T
	ELM 2-955		R		T
	ELM 2-960		R		T
	ELM 2-965		R		T
	ELM 2-970		R		T
	ELM 2-975		R		T
	ELM 2-980		R		T
	ELM 2-985		R		T
	ELM 2-990		R		T
	ELM 2-995		R		T
	ELM 2-9MM		R		T

### Change Will Affect:

The product form, fit and function.

### Description of Change:

The drawing has been updated to refine the pitch of the LED lead pockets, improving placement accuracy and consistency. The distance between the cavities has been adjusted from 0.078" to 0.071".

### Effective Date of Change:

 November 18, 2025

### Reason for Change:

 Design modifications were made to ensure better alignment and product performance.

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122