



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1114

Issue Date: 3/2/2026

Parts Affected	ELM 2-030	Old Rev.	U	New Rev.	V
	ELM 2-035		U		V
	ELM 2-040		U		V
	ELM 2-045		U		V
	ELM 2-050		U		V
	ELM 2-055		U		V
	ELM 2-060		U		V
	ELM 2-065		U		V
	ELM 2-070		U		V
	ELM 2-075		U		V
	ELM 2-080		U		V
	ELM 2-085		U		V
	ELM 2-090		U		V
	ELM 2-095		U		V
	ELM 2-1.000		U		V
	ELM 2-1.020		U		V
	ELM 2-1.025		U		V
	ELM 2-1.030		U		V
	ELM 2-1.035		U		V
	ELM 2-1.040		U		V
	ELM 2-1.045		U		V
	ELM 2-1.050		U		V
	ELM 2-1.055		U		V
	ELM 2-1.060		U		V
	ELM 2-1.065		U		V
	ELM 2-1.070		U		V
	ELM 2-1.075		U		V
	ELM 2-1.080		U		V
	ELM 2-1.085		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1114

Issue Date: 3/2/2026

Parts Affected	ELM 2-1.090	Old Rev.	U	New Rev.	V
	ELM 2-1.095		U		V
	ELM 2-1.100		U		V
	ELM 2-1.105		U		V
	ELM 2-1.110		U		V
	ELM 2-1.115		U		V
	ELM 2-1.120		U		V
	ELM 2-1.125		U		V
	ELM 2-1.130		U		V
	ELM 2-1.135		U		V
	ELM 2-1.140		U		V
	ELM 2-1.145		U		V
	ELM 2-1.150		U		V
	ELM 2-1.155		U		V
	ELM 2-1.160		U		V
	ELM 2-1.165		U		V
	ELM 2-1.170		U		V
	ELM 2-1.175		U		V
	ELM 2-1.180		U		V
	ELM 2-1.185		U		V
	ELM 2-1.190		U		V
	ELM 2-1.195		U		V
	ELM 2-1.200		U		V
	ELM 2-1.205		U		V
	ELM 2-1.210		U		V
	ELM 2-1.215		U		V
	ELM 2-1.220		U		V
	ELM 2-1.225		U		V
	ELM 2-1.230		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1114

Issue Date: 3/2/2026

Parts Affected	ELM 2-1.235	Old Rev.	U	New Rev.	V
	ELM 2-1.240		U		V
	ELM 2-1.245		U		V
	ELM 2-1.250		U		V
	ELM 2-1.500		U		V
	ELM 2-1.5MM		U		V
	ELM 2-100		U		V
	ELM 2-105		U		V
	ELM 2-10MM		U		V
	ELM 2-11.5MM		U		V
	ELM 2-110		U		V
	ELM 2-115		U		V
	ELM 2-11MM		U		V
	ELM 2-120		U		V
	ELM 2-125		U		V
	ELM 2-12MM		U		V
	ELM 2-130		U		V
	ELM 2-135		U		V
	ELM 2-13MM		U		V
	ELM 2-140		U		V
	ELM 2-145		U		V
	ELM 2-14MM		U		V
	ELM 2-150		U		V
	ELM 2-155		U		V
	ELM 2-15MM		U		V
	ELM 2-160		U		V
	ELM 2-165		U		V
	ELM 2-16MM		U		V
	ELM 2-170		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1114

Issue Date: 3/2/2026

Parts Affected	ELM 2-175	Old Rev.	U	New Rev.	V
	ELM 2-177		U		V
	ELM 2-17MM		U		V
	ELM 2-180		U		V
	ELM 2-185		U		V
	ELM 2-18MM		U		V
	ELM 2-190		U		V
	ELM 2-195		U		V
	ELM 2-19MM		U		V
	ELM 2-1MM		U		V
	ELM 2-2.5MM		U		V
	ELM 2-200		U		V
	ELM 2-205		U		V
	ELM 2-20MM		U		V
	ELM 2-210		U		V
	ELM 2-215		U		V
	ELM 2-21MM		U		V
	ELM 2-220		U		V
	ELM 2-225		U		V
	ELM 2-22MM		U		V
	ELM 2-230		U		V
	ELM 2-235		U		V
	ELM 2-23MM		U		V
	ELM 2-240		U		V
	ELM 2-245		U		V
	ELM 2-24MM		U		V
	ELM 2-250		U		V
	ELM 2-255		U		V
	ELM 2-25MM		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1114

Issue Date: 3/2/2026

Parts Affected	ELM 2-260	Old Rev.	U	New Rev.	V
	ELM 2-265		U		V
	ELM 2-26MM		U		V
	ELM 2-270		U		V
	ELM 2-275		U		V
	ELM 2-27MM		U		V
	ELM 2-280		U		V
	ELM 2-285		U		V
	ELM 2-28MM		U		V
	ELM 2-290		U		V
	ELM 2-295		U		V
	ELM 2-29MM		U		V
	ELM 2-2MM		U		V
	ELM 2-300		U		V
	ELM 2-305		U		V
	ELM 2-30MM		U		V
	ELM 2-310		U		V
	ELM 2-315		U		V
	ELM 2-31MM		U		V
	ELM 2-320		U		V
	ELM 2-325		U		V
	ELM 2-330		U		V
	ELM 2-335		U		V
	ELM 2-340		U		V
	ELM 2-345		U		V
	ELM 2-350		U		V
	ELM 2-355		U		V
	ELM 2-360		U		V
	ELM 2-365		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1114

Issue Date: 3/2/2026

Parts Affected	ELM 2-370	Old Rev.	U	New Rev.	V
	ELM 2-374		U		V
	ELM 2-375		U		V
	ELM 2-380		U		V
	ELM 2-385		U		V
	ELM 2-390		U		V
	ELM 2-395		U		V
	ELM 2-3MM		U		V
	ELM 2-400		U		V
	ELM 2-405		U		V
	ELM 2-410		U		V
	ELM 2-415		U		V
	ELM 2-420		U		V
	ELM 2-425		U		V
	ELM 2-430		U		V
	ELM 2-435		U		V
	ELM 2-440		U		V
	ELM 2-445		U		V
	ELM 2-450		U		V
	ELM 2-455		U		V
	ELM 2-460		U		V
	ELM 2-465		U		V
	ELM 2-470		U		V
	ELM 2-475		U		V
	ELM 2-480		U		V
	ELM 2-485		U		V
	ELM 2-490		U		V
	ELM 2-495		U		V
	ELM 2-4MM		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1114

Issue Date: 3/2/2026

Parts Affected	ELM 2-5.5MM	Old Rev.	U	New Rev.	V
	ELM 2-500		U		V
	ELM 2-505		U		V
	ELM 2-510		U		V
	ELM 2-515		U		V
	ELM 2-520		U		V
	ELM 2-525		U		V
	ELM 2-530		U		V
	ELM 2-535		U		V
	ELM 2-540		U		V
	ELM 2-545		U		V
	ELM 2-550		U		V
	ELM 2-555		U		V
	ELM 2-560		U		V
	ELM 2-565		U		V
	ELM 2-570		U		V
	ELM 2-575		U		V
	ELM 2-580		U		V
	ELM 2-585		U		V
	ELM 2-590		U		V
	ELM 2-595		U		V
	ELM 2-5MM		U		V
	ELM 2-600		U		V
	ELM 2-605		U		V
	ELM 2-610		U		V
	ELM 2-615		U		V
	ELM 2-620		U		V
	ELM 2-625		U		V
	ELM 2-630		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1114

Issue Date: 3/2/2026

Parts Affected	ELM 2-635	Old Rev.	U	New Rev.	V
	ELM 2-640		U		V
	ELM 2-645		U		V
	ELM 2-650		U		V
	ELM 2-655		U		V
	ELM 2-660		U		V
	ELM 2-665		U		V
	ELM 2-670		U		V
	ELM 2-675		U		V
	ELM 2-680		U		V
	ELM 2-685		U		V
	ELM 2-690		U		V
	ELM 2-695		U		V
	ELM 2-6MM		U		V
	ELM 2-700		U		V
	ELM 2-705		U		V
	ELM 2-710		U		V
	ELM 2-715		U		V
	ELM 2-720		U		V
	ELM 2-725		U		V
	ELM 2-730		U		V
	ELM 2-735		U		V
	ELM 2-740		U		V
	ELM 2-745		U		V
	ELM 2-750		U		V
	ELM 2-755		U		V
	ELM 2-760		U		V
	ELM 2-765		U		V
	ELM 2-770		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1114

Issue Date: 3/2/2026

Parts Affected	ELM 2-775	Old Rev.	U	New Rev.	V
	ELM 2-780		U		V
	ELM 2-785		U		V
	ELM 2-790		U		V
	ELM 2-795		U		V
	ELM 2-7MM		U		V
	ELM 2-800		U		V
	ELM 2-805		U		V
	ELM 2-810		U		V
	ELM 2-815		U		V
	ELM 2-820		U		V
	ELM 2-825		U		V
	ELM 2-830		U		V
	ELM 2-835		U		V
	ELM 2-840		U		V
	ELM 2-845		U		V
	ELM 2-850		U		V
	ELM 2-855		U		V
	ELM 2-860		U		V
	ELM 2-865		U		V
	ELM 2-870		U		V
	ELM 2-875		U		V
	ELM 2-880		U		V
	ELM 2-885		U		V
	ELM 2-890		U		V
	ELM 2-895		U		V
	ELM 2-8MM		U		V
	ELM 2-900		U		V
	ELM 2-905		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1114

Issue Date: 3/2/2026

Parts Affected	ELM 2-910	Old Rev.	U	New Rev.	V
	ELM 2-915		U		V
	ELM 2-920		U		V
	ELM 2-925		U		V
	ELM 2-930		U		V
	ELM 2-935		U		V
	ELM 2-940		U		V
	ELM 2-945		U		V
	ELM 2-950		U		V
	ELM 2-955		U		V
	ELM 2-960		U		V
	ELM 2-965		U		V
	ELM 2-970		U		V
	ELM 2-975		U		V
	ELM 2-980		U		V
	ELM 2-985		U		V
	ELM 2-990		U		V
	ELM 2-995		U		V
	ELM 2-9MM		U		V

Change Will Affect:

The product specifications on the drawing.

Description of Change:

The drawing has been updated to:

1. Refine the pitch of the LED lead pockets, improving placement accuracy and consistency. The distance between the cavities has been adjusted from 0.071" to 0.080".
2. Remove several dimensions from the drawing as they were not required for the definition or control of the part.
3. Add specific tolerances to improve measurement clarity and ensure the desired level of precision.

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1114

Issue Date: 3/2/2026

Effective Date of Change: March 2, 2026

Reason for Change: Design modifications were implemented to improve alignment and overall product performance. Additional changes were made to enhance the precision and clarity of the drawing.

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122