



PRODUCT CHANGE NOTIFICATION

RIEDON™ RESISTORS BY BOURNS



Select Riedon™ Resistors By Bourns

Date Code Marking Change

Riverside, California – June 2, 2025 - Effective August 14, 2025, Bourns will add the date code (i.e., 2523) to select Riedon™ Resistors By Bourns. This change will improve traceability of the affected parts. A list of affected part numbers is included below.

Affected Part Numbers				
RSA-100-100	RSC-1200-100	RSN-300-100B	RSA-75-100-S	RSJ-2500-100-S
RSA-100-50	RSC-1200-50	RSN-400-100B	RSA-80-50-S	RSJ-4000-50-S
RSA-10-100	RSC-800-50	RSN-500-100B	RSB-200-100-S	RSJ-5000-50-S
RSA-10-50	RSH-100-100	RSN-500-50B	RSB-200-50-NB-S	RSK-2000-50-S
RSA-150-100	RSH-15-50	RSN-50-100B	RSB-200-50-S	RSN-100-100B-S
RSA-150-50	RSH-300-50	RSN-50-50B	RSB-250-100-S	RSN-100-50B-S
RSA-15-100	RSH-400-100	RSN-5-100B	RSB-300-50-S	RSN-10-100B-S
RSA-20-100	RSH-500-100	RSW-100-50	RSB-400-100-S	RSN-1-100B-S
RSA-20-100-NB	RSH-50-100	RSW-150-50	RSB-400-50-S	RSN-150-100B-S
RSA-20-50	RSH-50-50	RSW-200-50	RSB-500-100-S	RSN-150-50B-S
RSA-30-100	RSH-600-50	RSW-25-50	RSB-500-50-NB-S	RSN-200-50B-S
RSA-30-100-NB	RSI-1000-50	RSW-350-20	RSB-500-50-S	RSN-20-100B-S
RSA-30-50	RSI-1200-50	RSW-50-50	RSB-600-50-S	RSN-20-50B-S
RSA-50-100	RSI-300-50	RSW-5-50	RSC-1000-100-S	RSN-2-100B-S
RSA-50-50	RSI-400-50	RSW-60-50	RSC-1000-50-S	RSN-250-100B-S
RSA-5-100	RSI-600-100	RSA-100-100-S	RSC-1200-100-S	RSN-250-50B-S

N2507

RSA-5-50	RSJ-1000-50	RSA-100-50-S	RSC-1200-50-S	RSN-300-100B-S
RSA-60-100	RSJ-1500-50	RSA-10-100-S	RSC-800-50-S	RSN-400-100B-S
RSA-75-100	RSJ-2000-100	RSA-10-50-S	RSH-100-100-S	RSN-500-100B-S
RSA-75-100-NB	RSJ-2500-100	RSA-150-100-S	RSH-15-50-S	RSN-500-50B-S
RSA-80-50	RSJ-4000-50	RSA-150-50-S	RSH-300-50-S	RSN-50-100B-S
RSB-200-100	RSJ-5000-50	RSA-15-100-S	RSH-400-100-S	RSN-50-50B-S
RSB-200-50	RSN-100-100B	RSA-20-100-NB-S	RSH-500-100-S	RSN-5-100B-S
RSB-200-50-NB	RSN-100-50B	RSA-20-100-S	RSH-50-100-S	RSW-100-50-S
RSB-250-100	RSN-10-100B	RSA-20-50-S	RSH-50-50-S	RSW-150-50-S
RSB-300-50	RSN-1-100B	RSA-30-100-NB-S	RSH-600-50-S	RSW-200-50-S
RSB-400-100	RSN-150-100B	RSA-30-100-S	RSI-1000-50-S	RSW-25-50-S
RSB-400-50	RSN-150-50B	RSA-30-50-S	RSI-1200-50-S	RSW-50-50-S
RSB-500-100	RSN-200-50B	RSA-50-100-S	RSI-300-50-S	RSW-5-50-S
RSB-500-50	RSN-20-100B	RSA-50-50-S	RSI-400-50-S	RSW-60-50-S
RSB-500-50-NB	RSN-20-50B	RSA-5-100-S	RSI-600-100-S	
RSB-600-50	RSN-2-100B	RSA-5-50-S	RSJ-1000-50-S	
RSC-1000-100	RSN-250-100B	RSA-60-100-S	RSJ-1500-50-S	
RSC-1000-50	RSN-250-50B	RSA-75-100-NB-S	RSJ-2000-100-S	

The form of the affected parts will change slightly due to the additional of the marking. The fit, function, quality and reliability of the affected Riedon™ Resistors By Bourns will remain the same. Traceability will be maintained through lot code and date code.

Samples are available upon request. Bourns recommends that customers test the affected part numbers in their specific applications for verification of satisfactory performance.

If you have any questions or need additional information, please feel free to [contact Customer Service/Inside Sales](#).

"Bourns" is a registered trademark of Bourns, Inc. in the United States and other countries.

In April 2023, BE Services Company, Inc., a subsidiary of Bourns, Inc., purchased certain assets of Riedon, Inc., including its logo and trademarks and the right to continue to manufacture former Riedon™ products.

"Riedon Logo" is a registered trademark of BE Services Company, Inc. in the United States.

"Riedon" is a trademark of BE Services Company, Inc.

Users should verify that the described changes will not impact the performance of the product in their specific applications.