



Date : 2024.2.29

Dear Sirs & Madams,

Please be informed that the following technical changes will be implemented to the products you are currently purchasing.

## 1. Content of change

Item	Current	New
R-T/P FPC contact	Tin plating	Gold plating
		

## 2. Product

Part Name	Revision		Implement schedule
	Current	New	
TX14D203VM0BPA, TX14D204VM0BPA	A		Apr. 2024

## 3. Reason of Change

Current R-T/P tail contact (Tin plating) is discontinued, the replacement (Gold plating) has been sourced and qualified to ensure the continuity of our product supply.

## 4. Impact on Product Specification

Key specifications (pitch, pin configuration, location) remains unchanged, thickness of R-T/P FPC contact (with Stiffener) remains unchanged as well.

## 5. Schedule

Implementation schedule (Apr. 2024) is estimated. The actual cut-in lot may be changed with the varied demand and the consumption of current components. Exact introduction will be provided in the future product notice.

In case of further questions, please contact your sales representative. Thank you.

Proposed by:   
 Alex Lee / Senior Manager  
 Electrical Design Section  
 Engineering Development Dept.