

Littelfuse, Inc. 8755 West Higgins Road, Suite 500 Chicago, IL 60631 USA (773) 628-1000

July 30th, 2025

## PCN EIC-1154 Lead frame change for selected DIP- 4 products

## **Detailed Description of Change**

Littelfuse IXYS Integrated Circuits Division (ICD) would like to inform you that we have qualified a new lead frame that will result in enhanced solder reflow performance and product reliability. This change is a result of our ongoing effort and commitment to continuous quality improvement of our products.

## Affected PN list is below:

Affected PN list			
CPC1303G	CPC1303GR	CPC1303GRTR	
CPC1330G	CPC1330GR	CPC1330GRTR	
CPC1333G	CPC1333GR	CPC1333GRTR	
CPC1390G	CPC1390GR	CPC1390GRTR	CPC1390GV
CPC1393G	CPC1393GR	CPC1393GRTR	CPC1393GV

The affected product is fully qualified in accordance with established performance and reliability criteria.

Form, fit, function changes: None Part number changes: None Effective date: 2025-08-30 Replacement products: N/A

Last time buy: N/A

The PCN number assigned to this action is **PCN EIC-1154** and must be referenced in any correspondence related to the change.

If you have any other questions or concerns, please contact your local Littelfuse sales representative or Product Manager below for further assistance.

Juste Valentiniene Product Manager Solid State Relays (SSR) Tel: +370 (612) 49707 jvalentiniene@littelfuse.com

