



PRODUCT CHANGE NOTICE

Expertise Applied | Answers Delivered

PCN486: Insource Rocker Bezel Molding
Issue Date: February 28th, 2024

Dear Valued Customer,

This notice is to inform you of the insourcing of a component affecting selected Littelfuse items that you have purchased.

Description of the Change:

We will be insourcing the molding operation for the Bezel utilized in certain Rocker Switches. The part numbers affected by this change are mentioned in the attached list.

Reason for The Change:

Littelfuse is insourcing the mold to improve supply chain consistency.

Effective Date of the Change:

This will be conducted as a running change, effective no later than the end June 2024.

What You Need to Do:

No action is required on your behalf. Based on our analysis, this change is considered low risk and will not affect fit, form, or function of the products.

If you have any questions, please contact your Customer Service or Inside Sales Representative. We appreciate your business and our continued partnership.

Sincerely,

Luisa Cuevas
Associate Product Manager
Littelfuse Commercial Vehicle Products