## THALES

<b>ID No.</b> 867	Product/Process Change Notification			Date 08.02.2022	
Product		Orderir	Ordering Code		
EXS82-W Rel.1.3		L30960N	L30960N6200A130		
EXS62-W Rel.1.3		L30960N	6250A130		
Ondering Onder de la compa			□ Vaa		
Ordering Code changes:		Yes			
Product		inew Or	New Ordering Code		
Reason of Change:					
☐ Technical requirement			☐ Change of production process/logistical changes		
Customer requirement			☐ Location of production moved		
☐ Quality improvement			Other:		
Tha imp		Dear customer,			
		Thales will introduce a new firmware that considers stability and functional improvements. For details please refer to the corresponding Release Note (exs62_exs82_rn_v01.200bb.pdf).			
	S	SW Revision is (	01.200, no change.		
The The		The application revision string (ARN) is changed to 01.000.09			
		The changes are not approval relevant.			
		The changes are not approval relevant.			
		Part number will	number will not change.		
Availability of SW for evaluation:	F	Firmware is available since CW04/2022			
Availability of modules ex THALES DIS AIS Deutschland warehouse:		First modules wi	modules with the new FW are available in February 2022.		
the co		he contrary with	ALES DIS AIS Deutschland GmbH does not receive a notification to ontrary within a period of 6 weeks, .ES DIS AIS Deutschland GmbH assumes that the customer agrees change.		
			ew version fulfils all internal test requirements according to our y Management process and philosophy.		

## Attachments:

## THALES

15.02.2022 15.02.2022

X Owonne Krings

Product Program Manager Signed by: KRUEGER Ivonne X i. Voi duam

Vice President Quality Management Signed by: ERDMANN Joerg