THALES

ID No. 925	Product/Process Change Notification			Date 12.Oct.2022
Product		Ordering Code		
mPLS83-W B		L30960-N7010-B100		
Ordering Code changes:			⊠ No	
Ordening Code change	ნ ბ.	∐ Yes	<u></u> INU	
Reason of Change:				
☐ Technical requirement			☐ Change of production proces	s/logistical changes
Customer requirement		Location of production moved		
Quality improvement		Other: introduction of add. manufacturing site		
Description of change:		To increase production capacity for our continuous growing business and to reduce supply risks, Thales introduce an additional production site located in Vietnam.		
	Sing	apore Pte. Ltd	cconn factory in Vietnam: Cloud N d. operates on same standards as irce Foxconn Shanghai.	
		Ordering codes remain same with no change.		
		lucts manufac de in Vietnam	tured at the additional factory will V".	be labelled with
	In ca	se of further o	questions, please contact your loc	al FAE team.
Schedule	CW	/ YEAR		
Products available ex ware	house 49 /	2022		
the co		HALES DIS AIS Deutschland GmbH does not receive a notification to contrary within a period of 6 weeks, Thales assumes that customer ees to the change.		
Quality assurance measurements:		The new version fulfils all internal test requirements according to our Quality Management process and philosophy.		
Attachments:				
12.10.2022				12.10.2022
X Armin Dimai			X i. Voi Anam	
Product Program Manager Signed by: DIMAI Armin			Head of Quality Management IoT Signed by: ERDMANN Joerg	