

1 Products affected

| Product hierarchy no. * | | | | Part no. | SBU | Product Type | Customer part no. |
|-------------------------|-----|-----|------------|--------------------|-----|--------------|-------------------|
| SBU | PG | PUG | Type | | | | |
| 02 | 007 | 012 | 0000002047 | See appendix below | | 6600-3 | |
| 02 | 007 | 012 | 0000002048 | See appendix below | | 6600-4 | |

*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

2 Type of change

- Change of label
- Change of configuration code

3 Detailed description of change

| Current label | New label |
|---|--|
| <p>Current label details: P/N 6600.4312 Type 6600-4. Configuration code: 6600 - X X X X - X X X X X - X X I X X</p> | <p>New label details: P/N 6600.4312 Type 6600-4. Configuration code: 6600 - X X X X - X X X X X - X X 0 - XX</p> |

- Change of Configuration Code and therefore change on label

4 Reason of change

- Added digit to the Configuration Code for enlargement of product range in the future.

5 Release date

The change takes effect in ww 13/2023 (Date code 2313 or higher on label).
Parts on stock will be used upon depletion.

6 Impact of change and recommended action

- Form
- Fit
- Function
- Manufacturing
- Label New Configuration Code on label
- Packaging

| Product Change Notification | | | | | PCN 660x - Change of Configuration Code | | |
|-----------------------------|---------------|--------------|-------------|--------------|---|--------|-------------|
| owner | creation date | release date | released by | change order | rev | page | D10-069-963 |
| kesslema | 12.12.2022 | 10.01.2023 | muehlema | 2025296 | A | 1 of 2 | |

7 Reference Documents

| Kind of document | Document Title |
|------------------|-----------------------------------|
| Data Sheet | Data Sheet 6600-3 |
| Data Sheet | Data Sheet 6600-4 |

8 Appendix

| List of part numbers affected for type 6600-3 | | | | |
|---|--------------|--------------|-----------|--------------|
| 6600.3100 | 6600.3100.10 | 6600.3100.21 | 6600.3200 | 6600.3200.21 |
| 6600.3300 | 6600.3300.10 | 6600.3300.21 | | |

| List of part numbers affected for type 6600-4 | | | | |
|---|--------------|--------------|--------------|--------------|
| 6600.4110 | 6600.4110.21 | 6600.4112 | 6600.4112.21 | 6600.4115 |
| 6600.4115.10 | 6600.4115.21 | 6600.4120 | 6600.4120.21 | 6600.4125 |
| 6600.4125.21 | 6600.4130 | 6600.4130.21 | 6600.4210 | 6600.4210.21 |
| 6600.4212 | 6600.4212.21 | 6600.4215 | 6600.4215.21 | 6600.4215.24 |
| 6600.4220 | 6600.4220.21 | 6600.4225 | 6600.4225.21 | 6600.4230 |
| 6600.4230.21 | 6600.4310 | 6600.4310.15 | 6600.4310.21 | 6600.4312 |
| 6600.4312.21 | 6600.4315 | 6600.4315.10 | 6600.4315.21 | 6600.4320 |
| 6600.4320.15 | 6600.4320.21 | 6600.4325 | 6600.4325.15 | 6600.4325.21 |
| 6600.4325.22 | 6600.4330 | 6600.4330.15 | 6600.4330.21 | |

| Product Change Notification | | | | | PCN 660x - Change of Configuration Code | | |
|-----------------------------|---------------|--------------|-------------|--------------|---|--------|-------------|
| owner | creation date | release date | released by | change order | rev | page | D10-069-963 |
| kesslema | 12.12.2022 | 10.01.2023 | muehlema | 2025296 | A | 2 of 2 | |