



1 Products affected

Product hierarchy no.				Part no.	SBU	Product Type	Customer part no.
SBU	PG	PUG	Type				
01	002	022	0000000519	See list below	Circuit Protection	OGN	-

2 Type of change

- Additional production location
- Change of label

3 Detailed description of change

Packaging label production site Czech Republic	Packaging label production site Switzerland
 <p>SCHURTER UKRAINE SCHURTER AG CH-6002 Luzern P/N 3-132-873 Type OGN OGN for THR standard 5x20 OGN-260-11-0 Qty 100 UL 500V / 16A VDE 250VAC / 4W / 10A VDE 500VAC / 4W / 16A Lot PCN Date Code 2306 FC ST CoO CZ</p>	 <p>SCHURTER UKRAINE SCHURTER AG CH-6002 Luzern P/N 3-132-873 Type OGN OGN for THR standard 5x20 OGN-260-11-0 Qty 100 UL 500V / 16A VDE 250VAC / 4W / 10A VDE 500VAC / 4W / 16A Lot PCN Date Code 2306 FC SE CoO CH</p>

- Country of origin (CZ or CH) and factory code (ST or SE) change, depending on the manufacturing site.

4 Reason of change

- Additional manufacturing site in Czech Republic and Switzerland

5 Release date

The change takes effect in week 06/2023 (Date code 2306 or higher on label).
Parts on stock will be used upon depletion.

6 Impact of change and recommended action

- Form
- Fit
- Function
- Manufacturing Note new manufacturing site
- Label No action required, as technical specification not changed
- Packaging

7 Reference Documents

Kind of document	Document Title
Data Sheet	OGN
Data Sheet	OGN pre-assembled

Product Change Notification					PCN OGN 2nd Production Site		
owner	creation date	release date	released by	change order	rev	page	D10-070-757
zeierjo	18.01.2023	20.01.2023	schulejo	2025354	A	1 of 2	

8 Appendix

List of part numbers affected for type OGN for SMT				
0031.8221	0031.8222	0031.8225	0031.8263	0031.8264
0031.8265	0031.8273	0031.8274	0031.8275	

List of part numbers affected for type OGN for SMT pre-assembled				
0031.8324	0031.8320	0031.9015	3-129-099	0031.8468
0031.8322	0031.8465	0031.9012	0031.9017	0031.8326
0031.8553	0031.8476	0031.8561	0031.8418	0031.8415
0031.8426	0031.8567	0031.8564	0031.8421	3-101-953
0031.8506	0031.8510	0031.9003	0031.8515	0031.8920
0031.8925	0031.8355	0031.8469.C1	0031.8505	0031.8360
3-129-125	3-129-132	0031.8363	0031.8508	3-129-130
0031.8517	0031.8366	3-129-129	0031.8310	0031.8263
0031.8264	0031.8374	0031.8265	0031.8371	3-129-096
0031.9014	0031.8377	0031.8318	0031.8414	0031.8316
0031.8467	3-129-100	3-129-115	3-129-101	0031.8473
3-129-112	0031.8470	3-129-113	0031.8552	0031.8558
0031.8555	0031.8563	0031.8419	0031.8424	0031.8566
0031.8569	0031.8507	0031.8518	0031.8513	0031.8998
0031.8996	0031.9000	0031.9002	0031.8357	0031.8367.C1
0031.8354	0031.8471.C2	0031.8362	3-129-127	3-129-126
3-129-118	3-129-121	0031.8514	0031.8368	0031.8365
0031.8305	0031.8373	0031.8304	0031.8273	0031.8274
0031.8275	0031.9008	0031.8307	0031.8314	0031.8376
0031.8311	0031.8323	0031.9011	3-129-114	0031.8464
3-129-093	0031.8321	0031.9016	3-129-104	3-129-095
0031.8325	3-129-116	0031.8472	0031.8469	0031.8327
0031.8554	0031.8475	0031.8560	0031.8416	0031.8557
0031.8413	0031.8425	0031.8422	0031.8568	0031.8503
0031.8516	0031.8923	0031.8471.C1	0031.8356	0031.8364
0031.8359	3-129-128	0031.8511	3-129-122	3-129-131
3-129-120	3-129-119	0031.8370	0031.8993	0031.8367
0031.8995	0031.8994	0031.8222	0031.8221	0031.8375
0031.8312	0031.9010	0031.8308	0031.8319	0031.8317
3-129-097	0031.9013	0031.8466	0031.8463	3-129-098
0031.8471	3-124-650	3-129-094	0031.8474	0031.8551
0031.8556	0031.8417	0031.8559	0031.8423	0031.8420
0031.8565	0031.8562	0031.8512	0031.8504	0031.8509
0031.8519	0031.8999	0031.8997	0031.9001	0031.8358
0031.8502	3-129-117	0031.8361	3-129-133	3-129-123
3-129-124	0031.8369	0031.9009	0031.9007	0031.8372
0031.8315	0031.8309	0031.8306	0031.8501	0031.8225
0031.8313				

List of part numbers affected for type OGN for THR				
3-132-873	3-132-874			

Product Change Notification					PCN OGN 2nd Production Site		
owner	creation date	release date	released by	change order	rev	page	D10-070-757
zeierjo	18.01.2023	20.01.2023	schulejo	2025354	A	2 of 2	