



Title / short description Affected article category Parallel production of the FDX20 splice box in China

ffected article category Connectors

Change categoryProduction locationChange numberPAB180011-00

Reason for PCN/PDN Revision

## Purpose/objective of the change

Since their introduction in 2018, the FO splice boxes of the FDX20 series for the DIN rail have been very successful internationally. Due to growing demand and limited production capacity at our Blomberg site, another production location in Nanjing has been qualified and approved for the products in the item list.

### Detailed description of the change

In future, customers from the following countries who order the splice boxes from the attached item list shall be supplied directly from Nanjing: Singapore, Korea, Malaysia, Thailand, Indonesia, Taiwan, Japan, Australia, New Zealand, and India. We ask that our subsidiaries please take this into consideration for such orders. In future, the changes to the items will apply to both production locations, so the high quality of the items can be ensured in the long term, regardless of the location.

# **Identifying characteristics**

"China" will appear as the production location on the item labels.

Start of Production (SOP)	-	Last Time Delivery (LTD)	-
Effective date (EOP)	2019-11-01	End of Service (EOSR)	-
End of Sales (EOS)	-		

# Short-term change (< 6 months) or discontinuation (< 12 months), due to:

Software / Firmware Bugfix		Short-term delivery stop by supplier	☐ Short-term recall by supplier
☐ Force majeure		Product improvement with customer benefits	
Others			
We were able to approve the produ	ctio	location back in November 20	19 The subsidiaries are now being

We were able to approve the production location back in November 2019. The subsidiaries are now being informed again centrally via this PCN.

#### **Attachments**

- PAB180011-GER.png
- PAB180011-CN.png
- Material\_list.csv
- PCN-PAB180011-00 Parallelproduktion der Splicebox FDX20 in China\_DE
- PCN-PAB180011-00 Parallel production of the FDX20 splice box in China\_EN



# **Material list**

	Article	Hardware / Firmware			Substitute item
Item	Туре	old	new	Item	Туре
1019710	FOC-FDX20-PP-LCD6-MM	01			
1019713	FOC-FDX20-PP-LCD6-OM2-PT9	01			
1019712	FOC-FDX20-PP-LCD6-OM4-PT9	01			
1019711	FOC-FDX20-PP-LCD6-OSP-PT9	01			
1019705	FOC-FDX20-PP-LCQ6-MM	01			
1019709	FOC-FDX20-PP-LCQ6-OM2-PT9	01			
1019708	FOC-FDX20-PP-LCQ6-OM4-PT9	01			
1019707	FOC-FDX20-PP-LCQ6-OSP-PT9	01			
1019686	FOC-FDX20-PP-SCD6-MM	01			
1019700	FOC-FDX20-PP-SCD6-OM2-PT9	01			
1019698	FOC-FDX20-PP-SCD6-OM4-PT9	01			
1019692	FOC-FDX20-PP-SCD6-OSP-PT9	01			
1019681	FOC-FDX20-PP-STD6-MM	01			
1019684	FOC-FDX20-PP-STD6-OM1-PT9	01			
1019683	FOC-FDX20-PP-STD6-OM2-PT9	01			
1019682	FOC-FDX20-PP-STD6-OSP-PT9	01			