

.

June 13th, 2025

LFPCN# 41553

Product Change Notification for 2Pro Product Series - Epoxy Coating Change

To whom it may concern,

Littelfuse would like to notify you of a change related to the epoxy coating of the 2Pro product series. Due to obsolescence of the current epoxy coating by our supplier, Littelfuse has qualified alternative epoxy coating material. This change has no impact to product's original electrical parameters, dimensions, quality, reliability and part numbers.

This change will be implemented starting from **September 15**th, **2025**. During the change transition period, customers are expected to receive current and new products until current product inventory in Littelfuse warehouses and distribution channels are depleted.

Please see the affected part number list and respond to us by **July 30th**, **2025** to acknowledge this product change notification. If we do not hear from you, we will expect this product change notification has been accepted and no further action is required.

Affected Part Number List	
Part Number	Description
RF4127-000	TM2P-10271
RF4128-000	TM2P-10271-2
RF4130-000	LVM2P-015R10431
RF4425-000	LVM2P-015R10431-0.118
RF4131-000	LVM2P-015R10431E25
RF4134-000	PSR-26903-0.157
RF4132-000	LVM2P-035R14431
RF4135-000	PSR-27632
RF4136-000	PSR-27747
RF4133-000	LVM2P-075R14431
RF4930-000	LVM2P-075R14431E51
RF4137-000	PSR-28369
RF4145-000	PSR-28369-0.75

Best Regards, Amy Chu Global Product Manager Littelfuse, Inc.