



Product/Process Change Notice - PCN 17_0190 Rev. -

Analog Devices, Inc. Three Technology Way Norwood, Massachusetts 02062-9106

This notice is to inform you of a change that will be made to certain ADI products (see Appendix A) that you may have purchased in the last 2 years. **Any inquiries or requests with this PCN (additional data or samples) must be sent to ADI within 30 days of publication date.** ADI contact information is listed below.

PCN Title: AD7770/1/9 Metal Mask Edit

Publication Date: 29-Nov-2017

Effectivity Date: 03-Mar-2018 *(the earliest date that a customer could expect to receive changed material)*

Revision Description:

Initial Release

Description Of Change

AD7770, AD7771 and AD7779 minor metal mask edit.

Reason For Change

To improve recovery time when the PGA experiences an over range condition on the output.

Impact of the change (positive or negative) on fit, form, function & reliability

There will be no change to fit, form, function, quality or reliability of the device.

Product Identification *(this section will describe how to identify the changed material)*

This change is effective from date code 1740

Summary of Supporting Information

This change has been verified through evaluation testing.

Comments

Supporting Documents None

For questions on this PCN, please send an email to the regional contacts below or contact your local ADI sales representatives.

Americas: PCN_Americas@analog.com

Europe: PCN_Europe@analog.com

Japan: PCN_Japan@analog.com

Rest of Asia: PCN_ROA@analog.com

Appendix A - Affected ADI Models				
Added Parts On This Revision - Product Family / Model Number (6)				
AD7770 / AD7770ACPZ	AD7770 / AD7770ACPZ-RL	AD7771 / AD7771BCPZ	AD7771 / AD7771BCPZ-RL	AD7779 / AD7779ACPZ
AD7779 / AD7779ACPZ-RL				

Appendix B - Revision History			
Rev	Publish Date	Effectivity Date	Rev Description
Rev. -	29-Nov-2017	03-Mar-2018	Initial Release

Analog Devices, Inc.

DocId:4253 Parent DocId:None Layout Rev:7