

Product Change Notification

Type of Change: SR4L034 L&R 'Inversa' antenna side plating change

Detailed Description of Change:

This notification is to inform you that the SR4L034 L&R antenna from date code 1901 onwards will have a different side plating design as shown below:



Reason for Change:

This change is being made to improve the manufacturing process

Parts Affected:

SR4L034-L and SR4L034-R

Key Milestones:

Parts manufactured in 2019 and with date code 1901 onwards will have the new edge plating design

Antenova Limited

2nd Floor, Titan Court, 3 Bishop Square, Hatfield, Herts, AL10 9NA, UK

t: +44 (0)1223 810600

info@antenova.com www.antenova.com





Impact of Change and Recommendations:

Other than a visual change, the antenna form, fit, function and performance remain the same. The antenna material and manufacturing use the same process

Reference Documents:

No change was required to the Product Specification. The current version, PS-1.11 January 2018 can be downloaded from our web site: http://www.antenova.com/products/

PLEASE NOTE: there is no revision change to the part number because the device remains the same. This is because the change is merely a visual one. Please be assured of our best and continued support and if you have any questions then please contact your local Antenova representative