

Product Change Notification

INDUCTIVE COMPONENTS




February, 2016

Bourns® Model SRP1770TA Series Shielded Power Inductors

Change to Product Dimension

Due to the operational limitation of our equipment, the bending radius of the solder terminal for the [Model SRP1770TA Series Shielded Power Inductors](#) cannot be formed as small as originally expected on some assembly lines. As a result, the length of the inductor will be revised from 17.3 ± 0.4 mm to 17.6 ± 0.4 mm. While there is a change to the products' fit, the products' form, function, quality and reliability will remain the same.



| Affected Part Numbers | | | |
|-----------------------|----------------|----------------|----------------|
| SRP1770TA-1R0M | SRP1770TA-5R6M | SRP1770TA-150M | SRP1770TA-470M |
| SRP1770TA-1R5M | SRP1770TA-6R8M | SRP1770TA-220M | SRP1770TA-560M |
| SRP1770TA-2R2M | SRP1770TA-8R2M | SRP1770TA-330M | SRP1770TA-680M |
| SRP1770TA-3R3M | SRP1770TA-100M | SRP1770TA-390M | SRP1770TA-101M |
| SRP1770TA-4R7M | | | |

Implementation dates are as follows:

First date code using the above changes: 1632

Date that manufacturing of existing products will cease: July 31, 2016

Date that deliveries of modified products will begin: August 1, 2016

If you have any questions or need additional information, please feel free to contact [Customer Service/ Inside Sales](#).