



ID No. 00379	Product/Process Change Notification	Date 12 February 2016
Product	BGS2	
Ordering Code	L30960-N2210-A200 L30960-N2200-A200	
	Ordering No. changes: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
	New Ordering Code:	

Reason of Change:

- | | |
|--|--|
| <input type="checkbox"/> Technical requirement | <input type="checkbox"/> Change of production process/logistical changes |
| <input type="checkbox"/> Customer requirement | <input type="checkbox"/> Location of production moved |
| <input type="checkbox"/> Quality improvement | <input checked="" type="checkbox"/> Other: 2 nd source |

Description of change:	<p>To secure the supply of the above mentioned products Gemalto M2M is introducing a 2nd source flash from JSC, additionally to the existing flash from Micron. The 2nd source flash is mechanically and electrically compatible to the current single source flash.</p> <p>To allow SW handling of the JSC memory the boot loader had to be adjusted. This is reflected by an updated ARN 01.000.17. Functional firmware has not been changed, i.e. there is NO functional change.</p> <p>The existing approvals are not affected.</p>
Scheduled date of introduction (cw/year):	Start of shipments ex warehouse week commencing 2 nd May 2016
Timing note:	-

Quality assurance measurements:	The new version fulfills all internal test requirements according to our Quality Management process and philosophy.
--	---

Product Lifecycle Manager/Name: Signature:	 Frank Ryll
Quality Management/Name: Signature:	Jörg Erdmann 

Attachments: