

ID No. 00450	<b>Product/Process Change Notification</b>	Date 24 February 2017
<b>Product</b> BGS5	<b>Ordering Code</b> L30960N3300A100	
Ordering No. changes:	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
New Ordering Code:		

**Reason of Change:**

- |   |  |
|---|--|
| <input type="checkbox"/> Technical requirement          | <input type="checkbox"/> Change of production process/logistical changes |
| <input type="checkbox"/> Customer requirement           | <input type="checkbox"/> Location of production moved                    |
| <input checked="" type="checkbox"/> Quality improvement | <input type="checkbox"/> Other:  |

<b>Description of change:</b>	<p>Gemalto M2M would like to inform customers of a new firmware (FW). This new firmware includes improved:</p> <ul style="list-style-type: none"> <li>- IP Packet Handling</li> <li>- Midlet integrity check</li> <li>- IP connection handling</li> <li>- Clock functionality</li> </ul> <p>A Release Note (BGS5_rn_v01100f) describes the issues in more details. This application related change is not approval relevant. The application revision string of SW 01.100 is: ARN = 00.000.31</p>
<b>Scheduled date of introduction (cw/year):</b>	CW 15/2017
<b>Timing note:</b>	If Gemalto M2M GmbH does not receive a notification to the contrary within a period of 6 weeks Gemalto M2M GmbH assumes that the customer agrees to the change.

<b>Quality assurance measurements:</b>	The new version fulfils all internal test requirements according to our Quality Management process and philosophy.
--	--

27.02.2017

27.02.2017

**X** Peter Shaffer

Peter Shaffer  
Product Manager  
Signed by: Peter Shaffer 10022570

**X** i.A. Clemens Schultz

Jörg Erdmann  
Vice President Quality Management M2M  
Signed by: Clemens Schultz 10015121

**Attachments:**

-