

ID No. 00474	Product/Process Change Notification	Date 13 March 2017
Product	Ordering Code	
BGS2-E Rel.3	L30960N2200A300	
BGS2-W Rel.3	L30960N2210A300	
Ordering No. changes:	<input type="checkbox"/> Yes <input type="checkbox"/> No	
New Ordering Code:		

Reason of Change:

- | | |
|---------------------------------------------------------|--------------------------------------------------------------------------|
| <input type="checkbox"/> Technical requirement | <input type="checkbox"/> Change of production process/logistical changes |
| <input type="checkbox"/> Customer requirement | <input type="checkbox"/> Location of production moved |
| <input checked="" type="checkbox"/> Quality improvement | <input type="checkbox"/> Other: |

Description of change:	To further improve the factory efficiency and yield rate Gemalto M2M GmbH introduces some minor changes in the factory configuration. To link module firmware with factory configuration a new ARN 01.000.11 will be effective from now on. Aside this ARN change the module firmware has not been changed and no impact on approvals are given.
Scheduled date of introduction (cw/year):	Start of Shipments ex-factory from cw12 onwards.
Timing note:	Due to the fact that firmware software has not been changed this modification on factory setting is immediately effective.

Quality assurance measurements:	The new version fulfills all internal test requirements according to our Quality Management process and philosophy.
----------------------------------------	---------------------------------------------------------------------------------------------------------------------

17.03.2017

20.03.2017

X *i.V. A. Dimai*

Armin Dimai
Product Manager
Signed by: Armin Dimai 10015210

X *i. Jörg Erdmann*

Jörg Erdmann
Vice President Quality Management
Signed by: Joerg Erdmann 10015214

Attachments:

-