

ID No. 00547	Product/Process Change Notification	Date 13 Feb 2018
Product	Ordering Code	
PH8 REL.3.3	L30960N190*A330	
PH8-P REL.3.3	L30960N191*A330	
PHS8-E REL.3.3	L30960N2440A330	
PHS8-P REL.3.3	L30960N241*A330	
PHS8-USA REL.3.3	L30960N242*A330	
PHS8-US REL.3.3	L30960N240*A330	
PVS8 REL.3.3	L30960N2650A330	
PXS8 REL.3.3	L30960N26**A330	
Ordering Number changes: 🗌 Yes 🖂 No		

Reason of Change:

- Technical requirement
- Customer requirement
- Quality improvement

Change of production process/logistical changes

Location of production moved

Other:

Description of change:	 Gemalto M2M would like to inform customers of a new software for the above mentioned product variant: Quality improvements SW Revision is same with previous one, i.e.: 03.320 Bootloader is changed from 4.24 to 4.26 The application revision string of ARN is changed from 01.000.06 to 01.000.14 This application related change is not approval relevant
Scheduled date of introduction (cw/year):	 Availability of SW and samples for evaluation: March 2018 Start of first shipments ex warehouse: Not before April 2018
Timing note:	If Gemalto M2M GmbH does not receive a notification to the contrary within a period of 6 weeks, Gemalto will M2M GmbH assume that the customer agrees to the change.

The new version fulfills all internal test requirements according to our Quality Management process and philosophy.



28.02.2018

anday

Ganda WIJAYA Product Lifecycle Manager Signed by: Wijaya Ganda 172390 <u>Attachments</u>: - Auaun

28.02.2018

Jörg Erdmann Vice President Quality Management Signed by: Joerg Erdmann 10015214