

ID No. 0625	Product/Process Change Notification	Date 9th Jan 2019
Product	Ordering Code	
ELS61_USA R2	L30960N4420A200	
ELS61_US R2	L30960N4400A200	
Ordering No. change	es: 🗌 Yes 🖾 No	
New Ordering Code	:	

## **Reason of Change:**

Technical requirement	Change of production process/logistical changes
Customer requirement	Location of production moved
🛛 Quality improvement	Other:

Description of change:	Gemalto M2M GmbH is going to introduce a new FW to improve the overall system performance of the product.		
	Following modifications have been implemented:		
	<ul> <li>change one configuration parameter of the Power Management Unit to avoid component damage caused by unintended current in rare stress test case.</li> </ul>		
	SW revision remains the same, 02.002.		
	The application revision (ARN) is changed to 01.000.04		
	This change is not approval relavant.		
	In case of questions about support of previous versions please contact local sales organization.		
Scheduled date of introduction (cw/year):	CW9 2019		
Timing note:	If Gemalto M2M GmbH does not receive a notification to the contrary within a period of 6 weeks, Gemalto M2M GmbH assumes that the customer agrees to the change.		

The new version fulfils all internal test requirements according to our Quality Management process and philosophy.	
Quality Management proceed and princeophy.	

Attachments:

24.01.2019

24.01.2019

X Ivonne Krüger

Krueger Ivonne Product Lifecycle Manager Signed by: Ivonne Krueger 10015065

i. Voi duam Х

Jörg Erdmann Vice President Quality Management Signed by: Joerg Erdmann 10015214